


2024-2025 Report Automated Work Zone Speed Enforcement



Department of Transportation
Thruway Authority

ACKNOWLEDGEMENTS

The Automated Work Zone Speed Enforcement (AWZSE) program is the result of legislation passed by the Senate and Assembly during the 2021 legislative session and signed into law by Governor Hochul in September 2021. This demonstration program is a joint effort by the New York State Department of Transportation (NYSDOT) and the New York State Thruway Authority (NYSTA).

[New York Vehicle & Traffic Law \(VTL\) § 1180-E](#) authorizes the establishment of an Automated Work Zone Speed Enforcement (AWZSE) demonstration program. NYSDOT and NYSTA may impose a monetary liability on the registered owner of a vehicle speeding in a work zone on a controlled access highway. The Agencies initiated the program in close partnership with New York State Police, NYS Department of Motor Vehicles, NYS Office of the Comptroller, and individual adjudicatory bodies across New York State.

The statute requires a study and report delivered on or before May 1, 2024 and every two years thereafter to the Governor, the Temporary President of the Senate, and the Speaker of the Assembly on the results of the program. The law also requires the posting of the report on the NYSDOT and NYSTA websites.

The Agencies are grateful for the participation of the multitudes of construction, maintenance, traffic, legal, accounting and finance, communications, and other staff within the Agencies as well as the New York State Police, NYS Department of Motor Vehicles, NYS Office of the Comptroller, Traffic Violations Bureaus (TVBs) and individual Courts across NY State for their roles in the program. The efforts of these parties, along with the AWZSE contractor, construction contractors, and additional individual staff provide the foundation for the overall success of this program.



Table of Contents

EXECUTIVE SUMMARY	1
PROGRAM OVERVIEW	3
1.1 Introduction.....	3
1.2 Deployment History.....	3
1.3 Work Zone Safety	3
1.4 Work Zone Travel Speeds	4
1.5 Program Status	5
1.5.1 <i>Field Deployment Requirements</i>	5
1.5.2 <i>Program Goals</i>	5
NYS VEHICLE AND TRAFFIC LAW §1180-E MANDATED REPORTING	6
2.1 Work Zone Crash Information	7
2.2 Speed and Violation Data	9
2.2.1 <i>DMV Data</i>	9
2.2.2 <i>NYSDOT and NYSTA Data</i>	10
2.3 Program Fines.....	12
2.4 Program Expenditures	13
AWZSE PROGRAM OPERATION	15
3.1 Deployment Process.....	15
3.1.1 <i>Deployment Approach</i>	15
3.2 New York State Department of Transportation Deployment.....	16
3.3 New York State Thruway Authority Deployment.....	17
VIOLATION PROCESSING	17
4.1 Event Validation	17
4.2 Violation Dispensation.....	18
APPENDIX A: DEPLOYMENTS LIST.....	20

List of Tables

Table 1, Acronyms and Terms	iii
Table 2, Summary of Reporting Requirements.....	6
Table 3, Work Zone Crash Data, All Work Zones 2021-2025	7
Table 4, Crashes Involving Injuries, All Work Zones 2021-2025	7
Table 5, State and Local Police Issued Citations in Work Zones, 2020-2025	9
Table 6, AWZSE Violation Summary, 2024-2025.....	10
Table 7, Overall Program Violation Summary, 2024-2025	11
Table 8, NYSDOT Notices of Liability Issued Over Speed Limit, 2024-2025	11
Table 9, NYSTA Notices of Liability Issued Over Speed Limit, 2024-2025	11
Table 10, Issued Notice Distribution by Agency*, 2024-2025.....	12
Table 11, AWZSE Contract Expenditures by Vendor to 12/31/2025	13
Table 12, Income and Expenditure, Overall Program, 2021-2025	14
Table 13, Work Zone Safety Project Expenditures, 2021 - 2025.....	14
Table 14, Deployment Distribution by Region, 2024-2025	16
Table 15, NYSDOT Program Violation Summary, 2024--2025	17
Table 16, NYSTA Program Violation Summary, 2024 - 2025.....	18
Table 17, Contested Violation Data, 2024 - 2025	18
Table 18, Hearing Request Data, 2024 - 2025	18

List of Figures

Figure 1, NYSDOT Intrusion Data, 1999-2025	8
Figure 2, NYSTA Work Zone Crash Data, 2001-2025.....	8
Figure 3, State and Local Police Issued Citations by Speed Classification, 2020-2025	9
Figure 4, NYSDOT and NYSTA Notice of Liability Repeat Offenders, 2024-2025.....	10
Figure 5, Percent of Vehicles Violating Speed Limit, By Month 2023-2025	12
Figure 6, Approved Deployments by Agency by Month, 2024 and 2025	15
Figure 7, Eligible Segments for Automated Speed Enforcement	16
Figure 8, 2024-2025 Deployment Map	20
Figure 9, NYSDOT Location Code.....	21
Figure 10, NYSTA Location Code.....	21

TABLE 1, ACRONYMS AND TERMS

Acronym / Term	Definition
Agencies	New York State Department of Transportation and the New York State Thruway Authority
AWZSE	Automated Work Zone Speed Enforcement
AWZSE Contractor	The contractor hired by the Agencies to provide Automated Work Zone Speed Enforcement services, including field enforcement photo captures, mailings, payment collection, and Court support
Construction Contractor	The contractor hired by the Agencies to provide maintenance and construction work on a state highway
Controllable Reject	An event that was rejected due to a circumstance that was within the AWZSE contractor's control, such as a camera or deployment issue
Controllable Issuance Rate	A calculation that equals the number of NOLs issued divided by (the number of Events minus the number of Uncontrollable Rejects)
CLEAR	Crash Location and Engineering Analysis Repository, a database of crash report information as gathered by law enforcement and submitted to the NYS DMV
Deployment	The daily assigned location per enforcement unit that resulted in viable data in a work zone
Dispute Rejection Letter	A letter indicating that a disputed NOL has been rejected because documentation that is provided does not support dismissal
EIC	Engineer in Charge
Event	A vehicle captured that triggered the violation process to begin
Excessive Speeding	Any speed that is more than 10 miles over the posted speed limit
Fatal Crash	A motor vehicle crash in which at least one person was killed. One fatal crash may involve more than one vehicle and more than one fatality
Highway Work Area	Refers to highway work that includes major traffic pattern changes, flaggers or temporary lights, impact vehicles, detours
Maintenance Work Area	Refers to road work that usually temporary with some minor traffic control
Moderate Injury	Moderate injuries include visible injuries such as a "lump" on the head, abrasions, and minor lacerations
Non-Violation Reject	Events that were rejected where no possible violation occurred
Notice of Liability (NOL)	A violation document that has been certified and issued to the owner of a vehicle that has been found to be speeding more than 10 miles over the posted speed limit sent via US mail, stating liability to the owner of \$50 or more
NPMRDS	National Performance Management Research Data Set, a free data source offered to state and local transportation agencies for monitoring and reporting transportation system performance measures, as well as for setting and meeting mobility objectives and targets
NYS DMV	New York State Department of Motor Vehicles
NYSDOT	New York State Department of Transportation

Acronym / Term	Definition
NYSP	New York State Police
NYSTA	New York State Thruway Authority
Renominated	The transfer of liability to a registered driver that had signed a vehicle leasing contract with a leasing company, as allowed by Vehicle and Traffic Law (VTL) Section 1180-E
Serious Injury	Serious injuries include skull fractures, internal injuries, broken or distorted limbs, unconsciousness, severe lacerations, severe burns, and unable to leave the scene without assistance
STC	Surface Transportation Control is NYSDOT's coordination of work at, and police presence within, a work zone
TVB	Traffic Violations Bureau
Uncontrollable Reject	An event that was rejected due to a circumstance that was outside of the AWZSE contractor's control, such as an obstruction, inclement weather, etc.
Utility Work Area	Refers to cable/electricity work on the poles at the side of the road
Violation	An event that has been certified that a speed violation has occurred involving a vehicle
VTL	Vehicle and Traffic Law
Warning	A warning document that has been certified and issued to the owner of a vehicle that has been found to be speeding more than 10 miles over the posted speed limit sent via US mail with no monetary penalty issued during the first 30 days of the AWZSE program
Work Zone Crash	A crash that occurs within the limits of the work zone but not necessarily within the portion of the roadway that is closed due to construction or maintenance activity
Work Zone Intrusion	An incident where a motor vehicle has entered a portion of the roadway that is closed due to construction or maintenance activity

Executive Summary

In 2023, New York State established a demonstration program for Automated Work Zone Speed Enforcement (AWZSE). This program is focused on improving safety by reducing excessive speeds in work zones on select NYSDOT controlled-access roadways and NYSTA operated roadways. The program uses mobile field units also referred to mobile units, AWZSE Units, or Enforcement Units as automated speed enforcement systems to address failure to comply with the maximum posted speed limits in highway construction or maintenance work areas, as provided in Section 1180-E of the VTL.



In April 2023, the program launched with these stated goals:

- **Save worker and traveler lives.** According to the Fatality Analysis Reporting Systems (FARS) from the National Highway Traffic Safety Administration, in 2023, 898 people died in crashes in work zones nationally, marking a 10-year high for deaths and crashes in road construction areas. These deaths occur not only to workers within the work zone, but also to the motorists involved in the crash. This program was established to reduce excessive speeds in work zones, in turn, reducing the number of work zone fatalities.
- **Promote Work Zone Safety.** During 2025, there were nearly 600 work zone crashes on New York State roads maintained by NYSDOT and NYSTA according to agency crash data. Drivers must pay extra attention, adjust speeds accordingly and take every precaution in highway work zones to keep themselves and highway construction and maintenance workers safe so that everyone can go home safely at the end of the day.¹ NYSDOT and NYSTA have ongoing public service awareness messaging that promotes work zone safety.
- **Reduce speeds in work zones.** Historical data from several states' automated enforcement programs shows the value of these programs in reducing excessive speeds in work zones.² During the first two and a half years of this program (April 2023 – December 2025), the average percentage of vehicles traveling in AWZSE-enforced work zones at speeds more than 10 MPH over the posted speed peaked at 3.54% in the month of October, 2024, but overall has been trending downwards.
- **Improve driver behaviors in work zones.** Continuous and ongoing education and awareness via multiple communications/social media platforms [Facebook, Instagram, X (formerly Twitter), LinkedIn, Agency websites] are important tools that help this program improve driver behaviors and awareness in work zones. Educating travelers and helping them understand the significance

¹[Work Zone Safety Campaign | FMCSA \(dot.gov\)](#)

²[Work Zone Speed Management - FHWA Work Zone \(dot.gov\)](#)

of their actions in work zones and the associated penalties for not complying will help the Agencies advance the goals of this program.

- **Complement existing work zone enforcement by state and local Police.** The Agencies work closely with State and local police as applicable to enforce proper driver behavior in work zones. In addition to providing police presence in a select number of work zones each day, the Agencies work closely with police on periodic enforcement details as part of Operation Hardhat, where police dress as highway maintenance workers in active work zones and identify and ticket motorists for speeding or disobeying a flagging direction.

In the first three seasons of the program, the Agencies have seen the following:

- Over 600,000 Notices of Liability issued from over 8,900 deployments;
- A payment rate in excess of 80%;
- A decrease in overall speeds in work zones with AWZSE; and
- About 7% of motorists captured violating the speed limit were captured traveling at 21+ MPH over the posted speed.

Program Overview

1.1 Introduction

[VTL § 1180-E](#) authorized the implementation of the AWZSE program.

The program is the result of legislation signed into law by Governor Hochul in September 2021 (see, Chapter 421 of the Laws of 2021). This five-year program was established to enhance the state's ongoing efforts to slow motorist speeds in work zones and to make New York State highways safer and was extended in 2025 for an additional five years to 2031 and increased the number of mobile units that may be deployed (Chapter 58 of the Laws of 2025).



1.2 Deployment History

As originally authorized in VTL § 1180-E, New York State has a total of 30 AWZSE mobile units available for deployment (20 mobile units for NYSDOT and 10 mobile units for NYSTA). These mobile units are AWZSE contractor-staffed vehicles that can be deployed simultaneously across the state on controlled-access highways. Increasing the mobile units is anticipated under new contracts.

Since the launch of the program in April 2023, the program has had 9,163 deployments and has issued over 600,000 NOLs, an average of 278 deployments and 18,500 violations per month. Figure 4 in Section 2.2.2 displays a breakdown of the number of violations for the program in 2024 and 2025.

1.3 Work Zone Safety

According to the Federal Highway Administration (FHWA), speeding is the number one cause of work zone intrusions causing injury and death. The New York State Police have stated that the average speed of citations issued in work zones is over 83 MPH. A work zone intrusion is defined as an incident where a motor vehicle has entered a portion of the roadway that is closed due to construction or maintenance activity.

The AWZSE program is essential to make our work zones safe for the motorists that travel New York's roadways and the workers who build and maintain them. Zero violations issued in work zones across the state is the goal of the AWZSE program, indicating that motorists are driving at or close to the posted speed limit.

To accomplish this goal, New York State has been furthering programs educating the public and raising awareness of the impact that speeding and associated crashes have on motorists' lives and the lives of highway construction and maintenance workers. As indicated in Section 2.1 below, there has been a trend in reducing work zone related crashes and injuries since the beginning of the program.

Crashes and intrusions into New York work zones increased from 2018 through 2021, though fatalities and injuries were down. In 2020, NYSDOT experienced 401 work zone intrusions. See Figure 1 in Section 2.1 below for more information.

1.4 Work Zone Travel Speeds

In April 2023 the AWZSE program began deploying enforcement units in work zones on selected controlled access highways across the state.

- The average monthly percentage of vehicles traveling in AWZSE-enforced work zones at speeds more than 10 MPH over the posted speed peaked at 2.95% in the month of July 2023.
- The average annual percentage of vehicles traveling in AWZSE-enforced work zones at speeds more than 10 MPH over the posted speed declined to 2.13% by the end of December 2024.
- The average annual percentage of vehicles traveling in AWZSE-enforced work zones at speeds more than 10 MPH over the posted speed declined to 1.5% by the end of December 2025.



The top three speeds throughout the first season were all captured in a work zone on NY 104 in Monroe County – 139 MPH, 117 MPH, and 110 MPH.

The Agencies continue to use the AWZSE units and Operation Hardhat details in coordination with the New York State Police and local law enforcement to monitor and enforce speed limits in work zones.

1.5 Program Status

The program began enforcement on April 17, 2023, at the start of National Work Zone Awareness Week. Some highlights of enforcement include:

- **9,163** deployments were completed in support of both construction and maintenance activities;
- issuance of over **600,000** Notices of Liability (NOLs) to registered owners; and
- over **38.9 million** vehicles passed through deployments between April 2023 and December 2025.

1.5.1 Field Deployment Requirements

The field deployment requirements are as follows:

- The contractor provides enforcement units for the program statewide; the current contract allows for 20 units for NYSDOT and 10 units for NYSTA;
- deployment availability 7 days a week, 24 hours a day on controlled access highways in NYSDOT and NYSTA jurisdictions, with a maximum duration of 8 hours per 24-hour period for each deployment;
- both construction and maintenance activities are included;
- both long-term and short-term work zones are included;
- deployment location selection considers road grade, curvature of the road, and visibility for coming traffic (at a minimum);
- workers must be present in the work zone; and
- signage informing drivers of the work zone speed limit and the use of photo speed violation monitoring systems at each area of deployment.

1.5.2 Program Goals

The goals of the AWZSE program are:

- reducing average operating speeds in highway work zones;
- reducing the number of NOLs issued due to speed limit compliance;
- reducing the number of repeat offenders;
- applying excess program revenue to work zone safety initiatives; and
- increasing awareness of the dangers of speeding in work zones.

NYS Vehicle and Traffic Law §1180-E

Mandated Reporting

Section 1180-E of the VTL calls for a report of the results of the use of the AWZSE photo devices, along with itemized report elements, listed below.

TABLE 2, SUMMARY OF REPORTING REQUIREMENTS

VTL 1180-E Report Requirement	Legislative Requirements	Document Location
VTL 1180-E(m)(a)(1)	Include the locations where and dates when photo speed violation monitoring systems were used	Appendix A
VTL 1180-E(m)(a)(2)	Include the aggregate number, type and severity of crashes, fatalities, injuries and property damage reported within all highway construction or maintenance work areas on controlled access highways or on the thruway*	Section 2.1, Table 3
VTL 1180-E(m)(a)(3)	Include the aggregate number, type and severity of crashes, fatalities, injuries and property damage reported within highway construction or maintenance work areas where photo speed violation monitoring systems were used*	Section 2.1
VTL 1180-E(m)(a)(4)	Include the number of violations recorded within all highway construction or maintenance work areas on controlled-access highways or on the thruway, in the aggregate on a daily, weekly and monthly basis*	Section 2.2.1, Table 5
VTL 1180-E(m)(a)(5)	Include the number of violations recorded within each highway construction or maintenance work area where a photo speed violation monitoring system is used, in the aggregate on a daily, weekly and monthly basis*	Section 2.2.2, Table 6
VTL 1180-E(m)(a)(6)	Include the number of violations recorded within all highway construction or maintenance work areas on controlled-access highways or on the thruway that were: (i) 11-20 miles per hour over the posted speed limit; (ii) 21-30 miles per hour over the posted speed limit; (iii) 31-40 miles per hour over the posted speed limit; and (iv) 41+ miles per hour over the posted speed limit*	Section 2.2.1, Table 5
VTL 1180-E(m)(a)(7)	Include the number of violations recorded within each highway construction or maintenance work area where a photo speed violation monitoring system is used that were: (i) 11-20 miles per hour over the posted speed limit; (ii) 21-30 miles per hour over the posted speed limit; (iii) 31-40 miles per hour over the posted speed limit; and (iv) 41+ miles per hour over the posted speed limit*	Section 2.2.2, Table 8, 9
VTL 1180-E(m)(a)(8)	Include the total number of notices of liability issued for violations	Section 2.2.2, Table 6
VTL 1180-E(m)(a)(9)	Include the number of fines and total amount of fines paid after the first notice of liability issued for violations recorded by [AWZSE] systems*	Section 2.3

VTL 1180-E Report Requirement	Legislative Requirements	Document Location
VTL 1180-E(m)(a)(10)	Include the number of violations adjudicated and the results of such adjudications including breakdowns of dispositions made for violations recorded by [AWZSE] systems*	Section 4.2
VTL 1180-E(m)(a)(11)	Include the total amount of revenue realized by the state or Thruway Authority in connection with the program	Section 2.4, Table 12
VTL 1180-E(m)(a)(12)	Include the expenses incurred by the state or the Thruway Authority in connection with the program	Section 2.4, Table 12
VTL 1180-E(m)(a)(13)	Include an itemized list of expenditures made by the state and the Thruway Authority on work zone safety projects undertaken	Section 2.4, Table 11
VTL 1180-E(m)(a)(14)	Include the quality of the adjudication process and its results*	Section 4.2

*To the extent the information is maintained by the commissioner, chair, or the department of motor vehicles of this state

2.1 Work Zone Crash Information

From 2021 through the end of 2025, there were **7,001 crashes** within all types of work zones across the state. **A total of 327 or 4.7% of those crashes involved injuries. Fifteen (15) of those crashes resulted in fatal injuries.**

Below is a representation of the number of crashes and the severity within ALL work zones (not just AWZSE work zones) across all jurisdictions of New York State.

TABLE 3, WORK ZONE CRASH DATA, ALL WORK ZONES 2021-2025

Work Zone Classification	Crashes					TOTAL 2021 - 2025
	2021	2022	2023	2024	2025	
Highway Work Area	1,238	1,173	1,260	1,136	1,113	5,920
Maintenance Work Area	136	150	162	167	146	761
Utility Work Area	60	63	70	67	60	320
Total	1,434	1,386	1,492	1,370	1,319	7,001

Source: New York State Department of Motor Vehicles

TABLE 4, CRASHES INVOLVING INJURIES, ALL WORK ZONES 2021-2025

DMV Crash Classification	Crashes					TOTAL 2021 - 2025
	2021	2022	2023	2024	2025	
Fatality	2	2	2	4	5	15
Injury	76	65	74	73	24	312
Property Damage	254	233	265	263	201	1,216
TOTAL	332	300	341	340	230	1,543

Source: New York State Department of Motor Vehicles

NYSDOT tracks incidents in active work zones as work zone intrusions, and NYSTA tracks crashes in work zones. In 2024 and 2025, there were a total of 690 work zone intrusions in NYSDOT work zones and 384 crashes in NYSTA work zones.

There was one intrusion reported within a work zone that had automated enforcement in 2023, which did not result in a documented injury. Across all work zones in New York State, including local roads, there were 4 fatalities in 2024 and five in 2025, however, these fatalities did not occur in a work zone that had an automated enforcement deployment. Two NYSTA highway workers were killed working on the Thruway in 2024. In 2025, NYSDOT also experienced two fatalities – one NYSDOT employee and one contractor. There were three documented work zone intrusions where the automated enforcement unit was deployed from 2024 - 2025.

FIGURE 1, NYSDOT INTRUSION DATA, 1999-2025





FIGURE 2, NYSTA WORK ZONE CRASH DATA, 2001-2025



2.2 Speed and Violation Data

2.2.1 DMV Data

New York State DMV provided the following historical data for citations issued by state and local Law Enforcement from 2020 through 2025 in work zones across the state. This highlights the problem of speeding in work zones across all roadways in New York.


The Table below includes corrected values from the 2023 Report using NYS DMV data for violations of Vehicle and Traffic Law Section 1180F – Speed in Work Zone. It is likely other citations have been given in Work Zones but were coded differently, such as violations of Section 1180D – Speed in Zone (which may refer to a work zone, school zone, or any other special speed zone) or Section 1180A – Speed not Reasonable and Prudent.

TABLE 5, STATE AND LOCAL POLICE ISSUED CITATIONS IN WORK ZONES, 2020-2025

Year	Total Citations Issued	0 to 10 Over	11 to 20 Over	21 to 30 Over	31 to 40 Over	41+ Over
2025	4,567	347	2,596	1,340	226	58
2024	3,929	502	2,125	1,087	174	41
2023	3,390	605	1,846	734	151	54
2022	2,741	587	1,279	694	130	51
2021	2,858	419	1,108	938	302	91
2020	2,971	270	1,236	958	387	120
TOTAL	20,456	2,730	10,190	5,751	1,370	415

Source: New York State Department of Motor Vehicles

FIGURE 3, STATE AND LOCAL POLICE ISSUED CITATIONS BY SPEED CLASSIFICATION, 2020-2025



Note: The above data is derived from information provided from speeding citations issued as recorded by New York State DMV for 2020 - 2025. This summary is an aggregated interpretation from individual ticketing data.

2.2.2 NYSDOT and NYSTA Data


Below is information specifically related to the Automated Work Zone Speed Enforcement program, broken down by agency.

TABLE 6, AWZSE VIOLATION SUMMARY, 2024-2025

Category	NYSDOT	NYSTA	Combined
Deployments	4,645	2,196	6,841
Total Events	313,223	224,610	537,833
Rejected Events	37,880	36,451	74,331
Warnings Issued	0	0	0
NOLs Issued	273,404	187,840	461,244
1 Violation	215,588	165,486	381,074
*2 Violations	18,965	8,646	27,611
*3+ Violations	5,621	1,500	7,121

**Applies to individual motor vehicle owners by violation date with multiple NOLs received*

FIGURE 4, NYSDOT AND NYSTA NOTICE OF LIABILITY REPEAT OFFENDERS, 2024-2025



Of the registered owners receiving notices, 34,732 (9.48%) were repeat violators, incurring fines for 2nd and subsequent violations of the statute. Although the average speed in NYSTA and NYSDOT work zones is below the posted speed limit, more than 10,146 (5.78%) of all NYSTA and 24,586 (10.24%) of NYSDOT speed violations were repeat offenders.

Table 7 shows the percentage of motorists issued NOLs at 11 MPH or more over the posted speed limit. Motorists travelling between 0-10 MPH over the speed limit were not captured in this table.

TABLE 7, OVERALL PROGRAM VIOLATION SUMMARY, 2024-2025

Agency	% 11-20 MPH Over Speed Limit	% 21-30 MPH Over Speed Limit	% 31-40 MPH Over Speed Limit	% 41-50 MPH Over Speed Limit
NYSDOT	92.52%	6.98%	0.45%	0.06%
NYSTA	93.51%	6.28%	0.19%	0.01%

TABLE 8, NYSDOT NOTICES OF LIABILITY ISSUED OVER SPEED LIMIT, 2024-2025

Month	Events	Issued	11-20 Over	21-30 Over	31-40 Over	41+ Over
January	6,749	6,055	5,639	374	16	3
February	7,245	6,770	6,159	584	45	5
March	11,411	10,091	9,075	926	82	8
April	24,980	22,131	20,352	1,678	91	10
May	29,488	26,054	24,812	1,185	52	5
June	26,754	22,857	21,674	1,124	42	8
July	39,301	33,797	30,417	3,165	205	19
August	33,270	28,760	26,897	1,768	86	9
September	41,825	36,459	33,406	2,787	217	37
October	57,621	51,121	48,040	2,873	188	24
November	24,895	20,735	18,974	1,638	121	10
December	9,684	8,574	7,504	976	80	14
TOTAL	313,223	273,404	252,949	19,078	1,225	152
		87.29%	92.52%	6.98%	0.45%	0.06%


* Issued is a percentage of Events. Over speed limit categories are a percentage of issued NOLs.

TABLE 9, NYSTA NOTICES OF LIABILITY ISSUED OVER SPEED LIMIT, 2024-2025

Month	Events	Issued	11-20 Over	21-30 Over	31-40 Over	41+ Over
January	6,061	5,108	4,720	366	20	2
February	5,639	4,493	4,186	295	10	2
March	5,381	4,661	4,263	375	22	1
April	15,193	12,978	12,118	833	25	2
May	30,621	26,325	24,230	2,023	70	2
June	20,388	17,193	16,252	905	33	3
July	15,242	12,792	12,235	541	15	1
August	28,973	23,973	22,568	1,374	30	1
September	30,829	25,198	23,587	1,576	34	1
October	42,407	35,271	33,054	2,156	56	5
November	15,000	12,323	11,641	653	28	1
December	8,876	7,525	6,802	699	23	1
TOTAL	224,610	187,840	175,656	11,796	366	22
		83.63%*	93.51%	6.28%	0.19%	0.01%

* Issued is a percentage of Events. Over speed limit categories are a percentage of issued NOLs.

FIGURE 5, PERCENT OF VEHICLES VIOLATING SPEED LIMIT, BY MONTH 2023-2025



Note: The data shown above is for vehicles traveling within AWZSE-deployed work zones at more than 10 MPH over the posted speed.

The average percentage of vehicles traveling in AWZSE-enforced work zones at speeds more than 10 MPH over the posted speed peaked at 3.54% in the month of October, 2024 with a low of 0.95% in June, 2024.

2.3 Program Fines

The agencies collected approximately **\$11,633,357.00** in 2024 and **\$11,199,982.00** in 2025 for fine remittance, combined. The average payment collection rate for both agencies for 2024 and 2025 combined averaged approximately 81.6%.

TABLE 10, ISSUED NOTICE DISTRIBUTION BY AGENCY*, 2024-2025

Agency	1 st Violation (\$50)	2 nd Violation (\$75)	3 rd + Violation (\$100)	NOLs Issued
NYSDOT	240,798	28,468	11,191	280,457
NYSTA	178,092	11,094	2,299	191,485
TOTAL	418,890	39,562	13,490	471,942

*Note: Data is provided by mailing date, not violation date, and may include violations from 2023.

2.4 Program Expenditures

NYSDOT and NYSTA have contracted with several firms to develop and deploy this program. Additionally, NYSDOT and NYSTA hired full time staff to assist in the evaluation and certification of events captured in the automated work zone enforcement deployments. The following assistance has been engaged since the bill was enacted through the end of 2025, and the amounts paid for contracts related to the program are as follows:

- Pre- and Post- Award Consulting – hired to support the development of a formal Request for Information to gain insight into program operations as well as the development of the Request for Proposals that was used to select a vendor for the program. Finally, this firm was hired to assist the Agencies in drafting of the report due by May 1, 2024.
- AWZSE Contractor – hired to provide overall AWZSE services, including speed enforcement, payment management, court tracking, website management, and other program related tasks.
- Staff and Administration – the Agencies have dedicated staff that provide overall program management and certification of all Notices of Liability. The agencies have legal, contract, accounting and finance staff that have full and part-time responsibilities in coordination with the program.
- Work Zone Safety Projects – expenditures made for new work zone safety projects. These expenditures do not supplement existing projects.
- Other Miscellaneous Costs – includes administrative costs necessary to support the program.

TABLE 11, AWZSE CONTRACT EXPENDITURES BY VENDOR TO 12/31/2025

Vendor	NYSDOT Amount	NYSTA Amount	Total
AWZSE Contractor	\$7,450,535.42	\$5,145,568.50	\$12,596,103.92
Pre- and Post- Award Consulting	\$347,681.56	\$0.00	\$347,681.56
Staff and Administration (includes fringe and benefits)	\$1,258,143.96	\$1,133,752.47	\$2,391,896.43
Work Zone Safety Projects	\$477,593.72	\$234,774.46	\$712,368.18
Other Miscellaneous Costs	\$39,804.41	\$18,752.52	\$58,556.93
TOTAL	\$9,573,759.07	\$6,532,847.95	\$16,106,607.02

It should be noted that the agencies did not have excess revenue for spending on Work Zone Safety projects until the end of 2024. Funds will be allocated toward allowable expenditures going forward.

TABLE 12, INCOME AND EXPENDITURE, OVERALL PROGRAM, 2021-2025

NYSDOT	Income	Expenditures*	Annual Net	Cumulative Net
2021	\$0.00	\$0.00	\$0.00	\$0.00
2022	\$0.00	\$602,823.24	(\$602,823.24)	(\$602,823.24)
2023	\$3,745,432.45	\$2,337,119.93	\$1,408,312.52	\$805,489.28
2024	\$7,766,650.22	\$4,436,562.88	\$3,330,087.34	\$4,135,576.62
2025	\$5,772,307.20	\$2,197,253.02	\$3,575,054.18	\$7,710,630.80
NYSTA	Income	Expenditures	Annual Net	Cumulative Net
2021	\$0.00	\$25,661.72	(\$25,661.72)	(\$25,661.72)
2022	\$0.00	\$342,048.35	(\$342,048.35)	(\$367,710.07)
2023	\$1,651,137.65	\$1,348,936.61	\$302,201.04	(\$65,509.03)
2024	\$3,866,706.86	\$2,138,282.74	\$1,728,424.12	\$1,662,915.09
2025	\$5,427,675.00	\$2,415,242.84	\$3,012,432.16	\$4,675,347.25
Overall	Income	Expenditures	Annual Net	Cumulative Net
2021	\$0.00	\$25,661.72	(\$25,661.72)	(\$25,661.72)
2022	\$0.00	\$944,871.59	(\$944,871.59)	(\$970,533.31)
2023	\$5,396,570.10	\$3,686,056.54	\$1,710,513.56	\$739,980.25
2024	\$11,633,357.08	\$6,574,845.62	\$5,058,511.46	\$5,798,491.71
2025	\$11,199,982.20	\$4,612,495.86	\$6,587,486.34	\$12,385,978.05

* Corrected values from 2023; Table represents costs paid through December 2025.

Section 1803 of the VTL requires that no less than 60% of the revenue from the AWZSE program be dedicated to funding new work zone safety projects, after deducting the expenses necessary to administer the program. An itemized list of these projects is listed below.


TABLE 13, WORK ZONE SAFETY PROJECT EXPENDITURES, 2021 - 2025

NYSDOT	2023	2024	2025	TOTAL
AWZSE Awareness Campaign	\$477,593.72	\$0.00	\$0.00	\$477,593.72
TOTAL	\$477,593.72	\$0.00	\$0.00	\$477,593.72
NYSTA	2023	2024	2025	TOTAL
Trailer-Mounted Lighting	\$0.00	\$50,589.32	\$0.00	\$50,589.32
Motorist Alerting Systems	\$0.00	\$13,740.00	\$35,340.00	\$49,080.00
Radar Arrow Board	\$0.00	\$49,440.44	\$12,622.65	\$62,063.09
Safety Clothing	\$0.00	\$0.00	\$10,759.50	\$10,759.50
Halo Lighting	\$0.00	\$0.00	\$39,864.10	\$39,864.10
Delineation Lighting	\$0.00	\$0.00	\$2,550.92	\$2,550.92
Employee Signage	\$0.00	\$0.00	\$8,315.47	\$8,315.47
Vehicle Reflective Markings	\$0.00	\$0.00	\$11,552.06	\$11,552.06
TOTAL	\$0.00	\$113,769.76	\$121,004.70	\$234,774.46
Overall	2023	2024	2025	TOTAL
TOTAL	\$477,593.72	\$113,769.76	\$121,004.70	\$712,368.18

AWZSE Program Operation

3.1 Deployment Process


FIGURE 6, APPROVED DEPLOYMENTS BY AGENCY BY MONTH, 2024 AND 2025



3.1.1 Deployment Approach

NYSDOT and NYSTA, in partnership with the awarded AWZSE contractor, developed a geographic, regionalized approach to establish depots in four macro regions across NY State, allowing for efficiencies in resources, staff, and fuel expenditures. This saves time and effort in the deployment process.

FIGURE 7, ELIGIBLE SEGMENTS FOR AUTOMATED SPEED ENFORCEMENT



The AWZSE Depots were selected to maximize program efficiencies and reduce costs. Table 14 shows where the depots are located and how many vehicles are assigned to each depot, by agency.

TABLE 14, DEPLOYMENT DISTRIBUTION BY REGION, 2024-2025

AWZSE Depots	NYSDOT Units	NYSTA Units
Buffalo	4	2
Rochester	4	3
Albany	4	3
Yonkers	8	2

3.2 New York State Department of Transportation Deployment

NYSDOT deploys AWZSE on controlled access highways across NY State, specifically along interstates, parkways, and other limited access highways. These deployments are coordinated with the 11 NYSDOT regional STC staff, EICs and maintenance supervisors.

The deployment of the AWZSE units considers many factors, with safety being the most important element. Verification of each deployment is done via the EIC 24 hours in advance. Deployments are requested by the STC, scheduled, and the EIC is informed. The request then goes to the AWZSE contractor via a spreadsheet emailed daily to the project manager. The AWZSE operator assesses the site and deploys the AWZSE vehicle according to program safety protocols.

As required by VTL § 1180-E(m)(a)(1), all deployments must be listed with the locations and dates when photo speed violation monitoring systems were used. The list of dates and locations is included in Appendix A.

3.3 New York State Thruway Authority Deployment

NYSTA deployed units in AWZSE across five highways– I-90, I-87, I-287, I-95, and I-190. These roads cover areas around Buffalo, Syracuse, Albany, and portions of downstate.

The deployment of the NYSTA AWZSE units considers many factors, with safety being the most important element. Verification of each deployment is done via the EIC 24 hours in advance. Deployments are requested by the Division Traffic Supervisor, scheduled, and the approved deployments are sent back to the Division Traffic Supervisor who then informs the Maintenance Supervisor or EIC. Requested deployments are determined in conjunction with the corresponding division engineer, maintenance supervisors and division traffic personnel and are then requested online through an automated system to schedule deployments with the AWZSE contractor. The approved requests are forwarded to the AWZSE contractor via a spreadsheet emailed weekly to the Project and Operations Manager. The AWZSE operator assesses the site and deploys the AWZSE vehicle according to program safety protocols and locations approved.

For a list of all Deployments, please refer to Appendix A.

Violation Processing

4.1 Event Validation

TABLE 15, NYSDOT PROGRAM VIOLATION SUMMARY, 2024--2025

NYSDOT Region	Events	Non-Violation Rejects	Uncontrollable Rejects	Controllable Rejects	Issued	Controllable Issuance Rate (%)
Region 1	19,730	1	4,419	148	15,162	99.03%
Region 2	328	0	16	0	312	100.00%
Region 3	95,519	29	10,764	885	83,840	98.95%
Region 4	64,359	1,249	5,244	872	56,994	98.49%
Region 5	31,103	3	4,613	468	26,019	98.23%
Region 6	74	0	12	1	61	98.39%
Region 7	181	0	29	0	152	100.00%
Region 8	7,750	0	297	24	7,429	99.68%
Region 9	4,655	0	444	69	4,142	98.36%
Region 10	36,522	625	1,840	753	33,304	97.79%
Region 11	53,002	31	4,996	1,986	45,989	95.86%
TOTAL	313,223	1,938	32,674	5,206	273,404	98.62%

TABLE 16, NYSTA PROGRAM VIOLATION SUMMARY, 2024 – 2025

NYSTA Division	Events	Non-Violation Rejects	Uncontrollable Rejects	Controllable Rejects	Issued	Controllable Issuance Rate (%)
New York	58,533	207	7,068	1,876	49,382	96.34%
Albany	62,581	23	9,024	1,528	52,006	97.15%
Syracuse	76,925	55	11,531	1,683	63,624	97.38%
Buffalo	26,571	2	2,997	744	22,828	96.84%
TOTAL	224,610	287	30,620	5,831	187,840	96.93%

4.2 Violation Dispensation

The data below reports disputes dispensed by the Agencies.

TABLE 17, CONTESTED VIOLATION DATA, 2024 - 2025

Agency	Violations Disputed	Disputes Accepted	Disputes Rejected	Disputes Pending
2024				
NYSDOT	6,179	432	5,744	3
NYSTA	2,536	346	2,190	0
TOTAL	8,715	1,283	7,429	3
2025				
NYSDOT	3,136	583	2,553	0
NYSTA	3,515	916	2,599	0
TOTAL	6,651	1,499	5,152	0

**Not shown: Disputed NOLs paid by vehicle owner*

The data below represents the disputes that have been heard in a municipal court or Traffic Violations Bureau between February 2024 and December 31, 2025. Some courts are adjudicating the AWZSE NOLs on the information submitted by the Agencies.

TABLE 18, HEARING REQUEST DATA, 2024 - 2025

Agency	Hearing Requests	Found Liable	Found Not Liable	In Process	Other (Cancelled or Rescheduled)	Appealed to Courts
NYSTA	414	21	223	121	49	Unknown
NYSDOT	481	31	189	194	41	Unknown
TOTAL	895	52	412	315	90	Unknown


There have been some challenges including:

- Some courts will not schedule hearings because they cite a lack of jurisdiction
- Some courts will schedule hearings but require an attorney to attend the hearing
- Some courts will schedule hearings but require a trial including witnesses
- Some Registered Owners failed to appear, default judgments denied, hearings conducted, and dismissal later issued

The Agencies will continue to try to make progress with the courts for the adjudication of the AWZSE notices of liability that range from \$50-\$100, with no points on a driver license or impact on insurance.

Appendix A: Deployments List

FIGURE 8, 2024-2025 DEPLOYMENT MAP



Each deployment is represented by a different circle. The size of the circle represents the number of violations detected at a given deployment site.

Deployments are coded by location, using a combination of the Region, Route, reference or mile marker, and direction. The reference marker in the Location ID and shown on the NOL indicates the exact location on the route that the deployment was stationed. The Figures on the next page show how the locations are coded for each agency.

FIGURE 9, NYSDOT LOCATION CODE





FIGURE 10, NYSTA LOCATION CODE



The full deployment list for the 2024 - 2025 AWZSE program is attached as a PDF file. Please note that the PDF lists all deployments, including those that may have been rejected.

A list of reference routes has also been included.

Reference Route	Name on First Segment of Roadway
900A	MAIN ST
900B	GLEN COVE RD
900C	ORIENT PARK RD
900D	Old Sunrise Hwy
900F	Union Turnpike
900G	RFK - Triborough Br W
900J	MTA-CROSS BAY BRIDGE
900P	Jamaica Ave
900W	Montauk Hwy
901A	SIMEON WOODS RD
901B	MTA-Marine Pkwy Bridge
901C	Seagirt Blvd
906A	LIE S SERVICE RD
906B	LIE N SERVICE RD
906C	RT 27 S SERVICE RD
906D	RT 27 N SERVICE RD
907A	CROSS ISLAND PKWY
907B	LAURELTON PKWY
907C	SHORE PK/LF ERIC DR
907D	SOUTHERN PKWY
907E	Bethpage State Pkwy
907F	BRONX PELHAM PKWY
907H	BRONX RIVER PKWY
907J	CROSS BAY PKWY
907K	Cross County Parkway
907L	FDR DRIVE
907M	GRAND CNTRL PKWY
907P	HARLEM RIVER DR
907V	HENRY HUDSON PKWY
907W	Hutchinson Riv Pkwy
908A	Hutchinson River Pkwy
908B	Jackie Robinson Pkwy
908C	Loop Pkwy
908E	Meadowbrook St Pkwy
908F	MOSHOLU PKWY
908G	Northern State Pkwy
908H	OCEAN PKWY
908J	Robert Moses Causeway
908K	Sagtikos State Pkwy
908L	SHORE FRONT PKY
908M	Heckscher State Pkwy
908T	Wantagh State Pkwy
909C	RICHMOND PKWY
909D	OCEAN PKWY
909E	Bay Pkwy
909G	ROCKAWAY BLVD

Reference Route	Name on First Segment of Roadway
910A	Feura Bush
910B	Wolf Road
910C	Broadway
910D	Washington Ave Ext
910F	Fuller Rd Alternate
910G	Potter Hollow Rd
910J	Thacher Park Rd
910K	Blue Ridge Rd
910M	JOHN BROWN RD
910P	US9W/NY23 CONN
910U	MANSION ST EXT
911E	Lower Warren St
911F	FREEMAN BRIDGE ROAD
911G	Union St
911H	Altamont Ave
911P	Crescent-Vischer Rd
911T	Ushers Rd
911V	CR23/I87 EXIT 21 CONN
912C	MAIN ST
912F	Miller Rd
912G	Grand St
912M	Berkshire Spur
912Q	Lake George Connect
912S	I-787 Exit 1 Conn
912T	US9W/NY373 CONN
912W	Rice Rd-E of Campbell
913B	FORDS CORNERS CONN
913C	NY 85/157 CONN
913D	NY 157/157A CONN
913E	NY 156/157 CONN
913G	Curry Rd
913H	US9W/NY32 JCT
913J	NY23/US9W JCT
913M	NY30/159 CONN
913Q	Bobsled Run Rd
913T	I-787 Exit 6 conn
913V	DOT-South Mall Exprwy
914A	MAIN ST
914B	Rice Rd-W of Campbell
914D	Broadway
914E	Veeder St
914F	US20/NY66 CONN
914T	Balltown Rd
914V	Glenridge Rd
915B	Green Island Bridge
915C	Stillwater Bridge

Reference Route	Name on First Segment of Roadway
915D	Broadway
915E	Third Ave
915F	I87 EXIT 27 CONN
915G	Bennington Bypass
915H	NYS Thruway
915J	Curry Rd
915K	I-87 Exit 33 Connector
915M	CHRISLER AVE EXT
915P	I-87 Exit 24 Connector
915Q	I-88 Exit 24 Conn
917A	PROSPECT MTN PKWY
920A	S EAST AVE
920C	Briggs St
920D	Harrison Ave
920H	Bridge St
920J	Saratoga Blvd
920P	Riverside Drive
920T	Moyer St
920V	Prospect Ave
921B	Burrstone Rd
921C	Genesee St
921D	Mappa Ave
921E	Genesee St
921G	MECHANIC ST
921P	John St
921T	Campion Rd
921W	Champlin Ave
922A	CAVANAUGH RD
922B	Washington St
922C	College Hill Rd
922E	RIVER ST
926A	HORATIO ST (NB)
930B	West St Arterial
930C	E Adams St
930F	East Shore Dr
930J	Bear Rd
930P	Bridge St
930Q	NY281/I 81 CONN
930W	West Genesee St
931B	State Fair Blvd
931E	Half Acre Rd
931F	Forward Rd
931G	Oswego St
931H	Circle Dr
931J	Pardee Rd
931K	Soule Rd

Reference Route	Name on First Segment of Roadway
931L	S STATE ST
931M	ARTERIAL RD
931P	SORREL HILL RD
936A	I-81 NB Svce Rd
936B	I-81 SB Svce Rd
936C	I-690 EB SERVICE RD
936D	I-690 WB SERVICE RD
936E	I-81 NB SERVICE RD
936F	I-81 SB SERVICE RD
940D	NY145A/CR 63 CONN
940H	RIVER RD
940J	MONROE ST
940K	Mount Read Blvd
940L	Howard Rd
940M	Lake Ave
940T	INNER LOOP
940U	W COMMERCIAL ST
941A	Latta Rd
941B	Empire Blvd
941K	COURT ST
941M	NY 98/18 CONN
941V	Blossom Rd
942D	MARY JAMISON
942G	Plymouth Ave
942T	S MAIN ST
943C	Calkins Rd
943E	ERIE STATION RD
943F	PATTONWOOD DRIVE
946A	NY104 EB SERVICE RD
946B	NY104 WB SERVICE RD
946C	NY104 EB SERVICE RD
946D	NY104 WB SERVICE RD
946E	NY 531 EB SERVICE RD
946F	NY 531 WB SERVICE RD
947A	Lake Ontario St Pkwy
948A	Lk Ontario Pkwy Spur
950A	Brown Run Rd
950C	Grand Island Blvd
950D	Shortmann Rd
950E	South Division St
950J	Camp Rd
950K	Niagara Falls Blvd
950M	Potters Rd
950U	Highland Ave
951A	LA SALLE EXP
951B	Walnut St

Reference Route	Name on First Segment of Roadway
951E	Big Tree Rd
951H	CUSTOMS TO I-190 CONN
951J	ACC I-190 SB
951K	NY5/I-190 CONN
951L	I-190 EXIT 8/NY266 CONN
951M	Parkway Dr
951T	OLD RT 17
951V	OLEAN RD
952A	Genesee St
952B	John B. Daly Blvd
952G	Church St
952H	Central Ave
952J	ARMOR DUELLS RD
952M	MAIN ST
952P	Forest Ave
952Q	Walden Ave
952T	Sweet Home Rd
952V	Williams Rd
952W	W Fivemile Rd
953A	Schoolhouse Rd
953B	Strunk Rd
953C	NY16/400 CONN
954D	Elm St
954E	Buffalo St
954F	I-990/N CAMPUS BLVD CONN
954G	Two Rod Rd
954J	I86/NY430 NB CONN
954K	W THIRD ST
954L	Broadway
954P	NF BRIDGE COMM-Upper Mountain Rd
954T	I86/NY417 CONN
954V	1ST ST/RAINBOW BLVD
955A	RAINBOW BRIDGE
955B	BUFFALO FORT ERIE PUBLIC BA-PEACE BRIDGE
955C	NIAGARA FALL BRIDGE COMM-WHIRLPOOL BRIDGE
957A	Niagara Scenic Pkwy
957B	South Parkway
957C	West River Parkway
958A	Niagara Scenic Pkwy Spur
960A	I-86 EXIT 58 CONN - REEDS CROSSINGS RD
960B	North Main St
960H	Mill St
960J	NY 434/NY17C CONN
960M	MEADS CREEK RD
960U	Babcock Hollow Rd
961A	Wyncoop Ck Rd

Reference Route	Name on First Segment of Roadway
961B	Wilawana Rd
961F	West Ave
961G	NY 244/21 CONN
961H	Spur Rd
961J	Michigan Hollow Rd
961L	Hammondsport-Wayne Rd
961M	CLEMENS CENTER PKWY
961Q	I-86 Exit 47 connector
961T	I-86 Exit 48 connector
962A	Karr Valley Rd
962B	Brasted District Rd
962C	NY 14-14A connector
962D	Loon Lake Rd
962E	I-86/NY14 INTERCHANGE CONN
962F	Conn I86 & NY14 interchange
962G	NY 434/NY17 WB CONN
962J	NY 434/NY17C CONN
970B	MAIN ST
970C	Andrew St
970E	State St
970F	NY374/3 CONN
970G	NY3/374 CONN
970H	NY 374/3 JCT
970J	McAlpine St
970K	CADY RD
970L	JAMES ST
970T	WATER ST
971A	Ford St
971B	NY9 NB SERVICE ROAD
971J	NY131 SPUR TO CR 43
971K	Church St
971L	Ellenburg Bridge
971P	Kellogg Hill Rd
971Q	Fort Drum Mem Dr
971T	Park St
971U	Maple St
971V	CR50/NY3 CONN
972A	W SERVICE RD
972B	I-87 EXIT 37/NY3 CONN
972D	US9/I-87 EXIT 43 CONN
972E	Seaway Int Br Rd Conn
980B	MAIN ST
980C	US20/NY22 CONN
980D	Albany St
980E	NY 71/22 CONN
980F	OLD NY 22

Reference Route	Name on First Segment of Roadway
980G	NY22/343 CONN
980J	Old Rt 52 - Fishkill Ave
980P	South St
980T	LEROY PL
980U	MAIN ST
980W	West Point Hwy
981B	I-684 / NY22 Conn
981F	Westside Ave
981G	Seven Lakes Rd
981H	Highland Ave
981J	NY340/US9W CONN
981K	Washington Ave
981L	Reservoir Rd
981M	NY983F/US9W CONN
981U	MEMORIAL HWY
981V	MEMORIAL HWY
982B	Midland Ave
982C	Putnam Ave
982E	Crystal Lk Cross Rd
982H	BURNETT BLVD
982J	PALMER AVE
982K	CEDAR ST
982L	Garden St Pkwy Conn
982M	RHINECLIFF RD
982P	MAIN ST
982Q	SPRING ST
983B	Nepperhan Ave
983C	Yonkers Ave
983D	SPRING ST
983F	Albany Ave
983G	East St James St
983T	HOOKER AVE
983W	MAIN ST
984A	SALT POINT TPK
984C	NY32/THRUWAY CONN
984D	Wurts St
984E	Yonkers Ave
984H	Riverdale Ave
984J	I-684 - Hutchinson River Pkwy conn
984K	North St
984L	Tuckahoe Rd
984M	FARRAGUT AVE
984P	Franklin Ave
987A	Lake Welch Pkwy
987C	Palisades Int Pkwy
987D	Saw Mill River Pkwy

Reference Route	Name on First Segment of Roadway
987E	Seven Lakes Pkwy
987F	Sprain Brook Pkwy
987G	Taconic State Pkwy
987H	Bear Mountain Pkwy
987J	FARRAGUT PKWY
990D	Riverside Dr
990E	Floral Ave
990F	CRESCENT DR
990G	US 11/I-86 EXIT 75 CONN
990H	Chenango St
990J	COVE STATE PARK RD
990L	East Main St
990T	NY 17 Exit 84/NY 10 CONN
990V	NY 30 to CR 3/CR 18 CONN
991A	Bowman Lake Dr
991C	NY 201 - Harry L Dr connector
991D	NY205 / CR48A Conn
991F	I-88 Exit 16/NY 7 CONN
991H	I-88 Exit 10/NY 7 CONN
991J	CR 48/NY 7 CONN
991L	I-88 (Exit 7)/NY 41 CONN
991T	GERSONI RD
992D	MAIN ST
992E	N SHORE DRIVE
992G	DK LIFGREN DR
992H	I-88 Exit 18/NY 7 CONN
992J	Hollenbeck Rd
992K	I-88 Exit 20/NY 7 CONN
992L	Hite Rd
992P	Martin Hill Rd
992Q	EXIT RD
992R	NY-PA INTERSTATE COMMISSION-S PENNSYLVANIA AVE
992S	NY-PA INTERSTATE COMMISSION-LORDVILLE RD
992T	NY-PA INTERSTATE COMMISSION-KELLAMS BRIDGE RD
992U	NY-PA INTERSTATE COMMISSION-BRIDGE ST
992V	NY-PA INTERSTATE COMMISSION-NEWBURGH TPK
992W	NY-PA INTERSTATE COMMISSION-SKINNERS FALLS RD W
992X	NY-PA INTERSTATE COMMISSION-HIGH RD

Region/Division	Deployment ID	Location Code
DOT-01	N0187117101141N_20240320_111553	N0187117101141N
DOT-01	N0187117101141N_20240321_074113	N0187117101141N
DOT-01	N0187117101141N_20240325_093102	N0187117101141N
DOT-01	N0187117101141N_20240326_074940	N0187117101141N
DOT-01	N0187117101141N_20240327_072914	N0187117101141N
DOT-01	N0187117101141N_20240328_072650	N0187117101141N
DOT-01	N0187117101141N_20240329_071641	N0187117101141N
DOT-01	N0187117101141N_20240401_082517	N0187117101141N
DOT-01	N0187117101141N_20240402_072455	N0187117101141N
DOT-01	N0187117101141N_20240410_080027	N0187117101141N
DOT-01	N0187117101141N_20240411_071128	N0187117101141N
DOT-01	N0187117101141N_20240412_080932	N0187117101141N
DOT-01	N0187117101141N_20240415_071656	N0187117101141N
DOT-01	N0187112111009N_20240415_102548	N0187112111009N
DOT-01	N0187117101141N_20240415_115355	N0187117101141N
DOT-01	N0187117101141N_20240416_063943	N0187117101141N
DOT-01	N0187112111009N_20240416_093404	N0187112111009N
DOT-01	N0187117101141N_20240417_071332	N0187117101141N
DOT-01	N0187112111009N_20240417_093646	N0187112111009N
DOT-01	N0187117101141N_20240418_072443	N0187117101141N
DOT-01	N0187117101141N_20240419_075059	N0187117101141N
DOT-01	N0187117101141N_20240422_081548	N0187117101141N
DOT-01	N0188116081131W_20240422_095841	N0188116081131W
DOT-01	N0188116081108E_20240422_101355	N0188116081108E
DOT-01	N0187117101141N_20240423_070936	N0187117101141N
DOT-01	N0188116081108E_20240423_070958	N0188116081108E
DOT-01	N0187117101141N_20240423_090713	N0187117101141N
DOT-01	N0187117101141N_20240424_065740	N0187117101141N
DOT-01	N0188116081108E_20240424_081108	N0188116081108E
DOT-01	N0187112111170S_20240424_082015	N0187112111170S
DOT-01	N0188116081108E_20240424_101910	N0188116081108E
DOT-01	N0187117101141N_20240425_072020	N0187117101141N
DOT-01	N0188116081108E_20240425_080917	N0188116081108E
DOT-01	N0187112111170S_20240425_083346	N0187112111170S
DOT-01	N0187117101141N_20240426_072630	N0187117101141N
DOT-01	N0188116081108E_20240426_074414	N0188116081108E
DOT-01	N0187112111170S_20240426_080053	N0187112111170S
DOT-01	N0187112111170N_20240426_105549	N0187112111170N
DOT-01	N0187117101141N_20240429_073051	N0187117101141N
DOT-01	N0188116081108E_20240429_074414	N0188116081108E
DOT-01	N0187112111170S_20240429_075754	N0187112111170S
DOT-01	N0188116081122W_20240429_080528	N0188116081122W
DOT-01	N0187112111170S_20240430_072449	N0187112111170S

Region/Division	Deployment ID	Location Code
DOT-01	N0187117101141N_20240430_073043	N0187117101141N
DOT-01	N0188116081108E_20240430_081454	N0188116081108E
DOT-01	N0187117101141N_20240501_072604	N0187117101141N
DOT-01	N0188116081108E_20240501_073351	N0188116081108E
DOT-01	N0187112111170S_20240501_074328	N0187112111170S
DOT-01	N0187117101141N_20240502_070228	N0187117101141N
DOT-01	N0187112111170S_20240502_072554	N0187112111170S
DOT-01	N0188116081122W_20240502_081846	N0188116081122W
DOT-01	N0188116081108E_20240502_092000	N0188116081108E
DOT-01	N0187117101141N_20240502_140613	N0187117101141N
DOT-01	N0187117101141N_20240503_072652	N0187117101141N
DOT-01	N0187112111170S_20240503_073112	N0187112111170S
DOT-01	N0188116081122W_20240503_082907	N0188116081122W
DOT-01	N0188116081108E_20240503_084341	N0188116081108E
DOT-01	N0187112111170S_20240506_072342	N0187112111170S
DOT-01	N0188116081106W_20240506_090215	N0188116081106W
DOT-01	N0187112111170S_20240507_083503	N0187112111170S
DOT-01	N0188116081106W_20240507_085157	N0188116081106W
DOT-01	N0187112111170S_20240508_071433	N0187112111170S
DOT-01	N0188116081106W_20240508_094713	N0188116081106W
DOT-01	N0187112111170S_20240509_072409	N0187112111170S
DOT-01	N0188116081106W_20240509_082956	N0188116081106W
DOT-01	N0187112111170S_20240510_074006	N0187112111170S
DOT-01	N0188116081106W_20240510_082945	N0188116081106W
DOT-01	N0187117101141N_20240513_070336	N0187117101141N
DOT-01	N0187117101141S_20240513_072642	N0187117101141S
DOT-01	N0188116081108W_20240513_083301	N0188116081108W
DOT-01	N0187117101141N_20240514_071716	N0187117101141N
DOT-01	N0187117101141S_20240514_072601	N0187117101141S
DOT-01	N0188116081108W_20240514_083421	N0188116081108W
DOT-01	N0187117101141N_20240515_065140	N0187117101141N
DOT-01	N0188116081108E_20240515_073555	N0188116081108E
DOT-01	N0187117101141N_20240516_070644	N0187117101141N
DOT-01	N0188116081108W_20240516_073711	N0188116081108W
DOT-01	N0187117101141N_20240517_071354	N0187117101141N
DOT-01	N0187112111170S_20240517_072242	N0187112111170S
DOT-01	N0188116081108E_20240517_073622	N0188116081108E
DOT-01	N0187117101141N_20240520_071727	N0187117101141N
DOT-01	N0187117101352N_20240520_072120	N0187117101352N
DOT-01	N0187112111170S_20240520_081314	N0187112111170S
DOT-01	N0188116081108W_20240520_134615	N0188116081108W
DOT-01	N0187112111170S_20240521_070848	N0187112111170S
DOT-01	N0187117101141N_20240521_074546	N0187117101141N

Region/Division	Deployment ID	Location Code
DOT-01	N0187117101352N_20240521_075017	N0187117101352N
DOT-01	N0188116081108W_20240521_083420	N0188116081108W
DOT-01	N0188116081108W_20240522_073420	N0188116081108W
DOT-01	N0187117101141N_20240522_074625	N0187117101141N
DOT-01	N0187117101352S_20240522_075823	N0187117101352S
DOT-01	N0188116081108W_20240522_080254	N0188116081108W
DOT-01	N0187112111170S_20240522_125401	N0187112111170S
DOT-01	N0187117101352S_20240523_075348	N0187117101352S
DOT-01	N0187112111170S_20240523_075456	N0187112111170S
DOT-01	N0187117101141N_20240523_080410	N0187117101141N
DOT-01	N0188116081108W_20240523_083303	N0188116081108W
DOT-01	N0187117101141N_20240524_074639	N0187117101141N
DOT-01	N0187112111170S_20240524_081031	N0187112111170S
DOT-01	N0187117101352N_20240524_082031	N0187117101352N
DOT-01	N0187117101141N_20240528_071517	N0187117101141N
DOT-01	N0187112111170S_20240528_074038	N0187112111170S
DOT-01	N0188116081108W_20240528_074410	N0188116081108W
DOT-01	N0188116081108W_20240529_073634	N0188116081108W
DOT-01	N0187112111170S_20240529_074555	N0187112111170S
DOT-01	N0188116081108E_20240529_130139	N0188116081108E
DOT-01	N0187117101141N_20240530_074803	N0187117101141N
DOT-01	N0187112111170S_20240530_080846	N0187112111170S
DOT-01	N0188116081108W_20240530_084746	N0188116081108W
DOT-01	N0187112111170S_20240531_065821	N0187112111170S
DOT-01	N0188116081108W_20240531_080224	N0188116081108W
DOT-01	N0187117101141N_20240531_092106	N0187117101141N
DOT-01	N0187112111170S_20240603_065549	N0187112111170S
DOT-01	N0187117101141S_20240603_071322	N0187117101141S
DOT-01	N0187117101140N_20240603_073350	N0187117101140N
DOT-01	N0188116081108E_20240603_074911	N0188116081108E
DOT-01	N0187112111170S_20240604_071058	N0187112111170S
DOT-01	N0187117101141N_20240604_082133	N0187117101141N
DOT-01	N0188116081108E_20240604_082252	N0188116081108E
DOT-01	N0187117101141N_20240605_065521	N0187117101141N
DOT-01	N0188116081108E_20240605_073355	N0188116081108E
DOT-01	N0187112111170S_20240605_075153	N0187112111170S
DOT-01	N0187117101141N_20240606_070620	N0187117101141N
DOT-01	N0187112111170S_20240606_071329	N0187112111170S
DOT-01	N0188116081108E_20240606_082625	N0188116081108E
DOT-01	N0188116081108W_20240606_111017	N0188116081108W
DOT-01	N0187117101141N_20240607_070629	N0187117101141N
DOT-01	N0187112111170S_20240607_070720	N0187112111170S
DOT-01	N0188116081108W_20240607_073252	N0188116081108W

Region/Division	Deployment ID	Location Code
DOT-01	N0188I16081108W_20240607_080632	N0188I16081108W
DOT-01	N0187I12111170S_20240610_073937	N0187I12111170S
DOT-01	N0188I16081108W_20240610_073952	N0188I16081108W
DOT-01	N0187I17101141N_20240610_081849	N0187I17101141N
DOT-01	N0187I17101141N_20240611_071620	N0187I17101141N
DOT-01	N0188I16081108W_20240611_072826	N0188I16081108W
DOT-01	N0187I12111170S_20240611_074226	N0187I12111170S
DOT-01	N0187I12111170S_20240612_075113	N0187I12111170S
DOT-01	N0188I16081108W_20240612_081050	N0188I16081108W
DOT-01	N0187I17101141N_20240612_082006	N0187I17101141N
DOT-01	N0187I17101141N_20240613_061739	N0187I17101141N
DOT-01	N0187I12111170S_20240613_065802	N0187I12111170S
DOT-01	N0188I16081108W_20240613_073918	N0188I16081108W
DOT-01	N0187I12111170S_20240614_070206	N0187I12111170S
DOT-01	N0188I16081108W_20240614_072538	N0188I16081108W
DOT-01	N0187I17101141N_20240614_083510	N0187I17101141N
DOT-01	N0187I17101141N_20240618_070052	N0187I17101141N
DOT-01	N0187I12111170S_20240618_072840	N0187I12111170S
DOT-01	N0188I16081108W_20240618_073400	N0188I16081108W
DOT-01	N0188I16081108E_20240618_075432	N0188I16081108E
DOT-01	N0187I12111170S_20240619_074028	N0187I12111170S
DOT-01	N0188I16081108E_20240619_074923	N0188I16081108E
DOT-01	N0187I17101140N_20240619_080250	N0187I17101140N
DOT-01	N0187I12111170S_20240620_065832	N0187I12111170S
DOT-01	N0187I17101141N_20240620_072642	N0187I17101141N
DOT-01	N0188I16081108W_20240620_074715	N0188I16081108W
DOT-01	N0187I12111170S_20240621_072923	N0187I12111170S
DOT-01	N0188I16081108E_20240621_082441	N0188I16081108E
DOT-01	N0187I17101141N_20240621_085049	N0187I17101141N
DOT-01	N0187I17101141N_20240624_074403	N0187I17101141N
DOT-01	N0187I12111170S_20240624_075458	N0187I12111170S
DOT-01	N0188I16081108W_20240624_080533	N0188I16081108W
DOT-01	N0187I17101141N_20240625_065917	N0187I17101141N
DOT-01	N0187I12111170S_20240625_075250	N0187I12111170S
DOT-01	N0188I16081108W_20240625_081159	N0188I16081108W
DOT-01	N0188I16081108W_20240626_070711	N0188I16081108W
DOT-01	N0187I17101141N_20240626_074504	N0187I17101141N
DOT-01	N0187I12111170S_20240626_080314	N0187I12111170S
DOT-01	N0187I12111170S_20240627_065649	N0187I12111170S
DOT-01	N0188I16081108W_20240627_071605	N0188I16081108W
DOT-01	N0187I17101141N_20240627_074638	N0187I17101141N
DOT-01	N0187I12111170S_20240628_065414	N0187I12111170S
DOT-01	N0187I17101141N_20240628_073832	N0187I17101141N

Region/Division	Deployment ID	Location Code
DOT-01	N0188I16081108W_20240628_083040	N0188I16081108W
DOT-01	N0188I16081108W_20240701_065554	N0188I16081108W
DOT-01	N0187I12111170S_20240701_065929	N0187I12111170S
DOT-01	N0187I17101141N_20240701_085050	N0187I17101141N
DOT-01	N0187I12111170S_20240702_072251	N0187I12111170S
DOT-01	N0188I16081108W_20240702_072917	N0188I16081108W
DOT-01	N0187I17101141N_20240702_082818	N0187I17101141N
DOT-01	N0187I12111170S_20240703_065052	N0187I12111170S
DOT-01	N0188I16081108W_20240703_070430	N0188I16081108W
DOT-01	N0187I17101141N_20240703_081644	N0187I17101141N
DOT-01	N0188I16081108E_20240708_074353	N0188I16081108E
DOT-01	N0187I12111170S_20240708_081120	N0187I12111170S
DOT-01	N0187I12111456S_20240708_090104	N0187I12111456S
DOT-01	N0187I12111456S_20240709_070932	N0187I12111456S
DOT-01	N0187I12111170S_20240709_072615	N0187I12111170S
DOT-01	N0188I16081108E_20240709_074522	N0188I16081108E
DOT-01	N0188I16081108E_20240710_071432	N0188I16081108E
DOT-01	N0187I12111170S_20240710_075107	N0187I12111170S
DOT-01	N0187I17101141N_20240710_090400	N0187I17101141N
DOT-01	N0187I12111170S_20240711_080201	N0187I12111170S
DOT-01	N0188I16081108E_20240711_085626	N0188I16081108E
DOT-01	N0187I12111557S_20240711_092155	N0187I12111557S
DOT-01	N0187I17101141N_20240711_104948	N0187I17101141N
DOT-01	N0187I12111170S_20240712_072424	N0187I12111170S
DOT-01	N0188I16081108E_20240712_074121	N0188I16081108E
DOT-01	N0187I12111557S_20240712_081459	N0187I12111557S
DOT-01	N0187I12111170S_20240715_072041	N0187I12111170S
DOT-01	N0187I17101141S_20240715_073703	N0187I17101141S
DOT-01	N0188I16081108E_20240715_074201	N0188I16081108E
DOT-01	N0187I17101141S_20240716_070308	N0187I17101141S
DOT-01	N0187I12111170S_20240716_072010	N0187I12111170S
DOT-01	N0188I16081108E_20240716_082434	N0188I16081108E
DOT-01	N0188I16081108E_20240716_101223	N0188I16081108E
DOT-01	N0188I16081108E_20240717_062706	N0188I16081108E
DOT-01	N0187I17101141S_20240717_065828	N0187I17101141S
DOT-01	N0187I12111170S_20240717_080305	N0187I12111170S
DOT-01	N0188I16081108E_20240718_071108	N0188I16081108E
DOT-01	N0187I12111170S_20240718_071323	N0187I12111170S
DOT-01	N0187I17101141S_20240718_073616	N0187I17101141S
DOT-01	N0187I12111170S_20240719_065534	N0187I12111170S
DOT-01	N0188I16081108E_20240719_072258	N0188I16081108E
DOT-01	N0187I17101141S_20240719_081111	N0187I17101141S
DOT-01	N0187I17101141S_20240719_084020	N0187I17101141S

Region/Division	Deployment ID	Location Code
DOT-01	N0187117101141S_20240722_075049	N0187117101141S
DOT-01	N0187112111170S_20240722_082014	N0187112111170S
DOT-01	N0188116081108E_20240722_104708	N0188116081108E
DOT-01	N0188116081108E_20240722_113850	N0188116081108E
DOT-01	N0187112111170S_20240723_072207	N0187112111170S
DOT-01	N0187117101141S_20240723_074447	N0187117101141S
DOT-01	N0188116081108E_20240723_080630	N0188116081108E
DOT-01	N0188116081108E_20240723_114230	N0188116081108E
DOT-01	N0187117101141S_20240724_073204	N0187117101141S
DOT-01	N0188116081122W_20240724_074808	N0188116081122W
DOT-01	N0187112111170S_20240724_084156	N0187112111170S
DOT-01	N0188116081108E_20240725_063507	N0188116081108E
DOT-01	N0187117101141S_20240725_072531	N0187117101141S
DOT-01	N0187112111170S_20240725_073012	N0187112111170S
DOT-01	N0188116081108E_20240726_065449	N0188116081108E
DOT-01	N0187112111170S_20240726_070004	N0187112111170S
DOT-01	N0187117101141S_20240726_070811	N0187117101141S
DOT-01	N0187117101141S_20240729_070230	N0187117101141S
DOT-01	N0188116081108E_20240729_071300	N0188116081108E
DOT-01	N0187112111170S_20240729_073126	N0187112111170S
DOT-01	N0188116081108E_20240730_064255	N0188116081108E
DOT-01	N0187117101141S_20240730_071716	N0187117101141S
DOT-01	N0187112111170S_20240730_074555	N0187112111170S
DOT-01	N0188116081108E_20240731_070829	N0188116081108E
DOT-01	N0187117101141S_20240731_072115	N0187117101141S
DOT-01	N0187112111170S_20240731_074139	N0187112111170S
DOT-01	N0188116081108E_20240731_123554	N0188116081108E
DOT-01	N0187112111170S_20240801_071425	N0187112111170S
DOT-01	N0188116081108E_20240801_072231	N0188116081108E
DOT-01	N0187117101141S_20240801_103743	N0187117101141S
DOT-01	N0187117101141S_20240801_105824	N0187117101141S
DOT-01	N0187117101141S_20240802_070230	N0187117101141S
DOT-01	N0187112111170S_20240802_071555	N0187112111170S
DOT-01	N0188116081108E_20240802_081252	N0188116081108E
DOT-01	N0187112111170S_20240805_065348	N0187112111170S
DOT-01	N0187117101141S_20240805_074032	N0187117101141S
DOT-01	N0187112111170S_20240806_071051	N0187112111170S
DOT-01	N0187117101141S_20240806_072250	N0187117101141S
DOT-01	N0188116081108E_20240806_090943	N0188116081108E
DOT-01	N0187117101141S_20240807_070443	N0187117101141S
DOT-01	N0187112111170S_20240807_073457	N0187112111170S
DOT-01	N0188116081108E_20240807_080032	N0188116081108E
DOT-01	N0187112111170S_20240808_071555	N0187112111170S

Region/Division	Deployment ID	Location Code
DOT-01	N018816081108E_20240808_072902	N018816081108E
DOT-01	N0187117101141S_20240808_081002	N0187117101141S
DOT-01	N0187112111170S_20240809_070149	N0187112111170S
DOT-01	N0187117101141S_20240809_071912	N0187117101141S
DOT-01	N018816081108E_20240809_073642	N018816081108E
DOT-01	N0187117101141S_20240812_071140	N0187117101141S
DOT-01	N0187112111170S_20240812_074957	N0187112111170S
DOT-01	N018816081108E_20240812_075853	N018816081108E
DOT-01	N018816081108E_20240813_071554	N018816081108E
DOT-01	N0187112111170S_20240813_072522	N0187112111170S
DOT-01	N0187117101141S_20240813_073901	N0187117101141S
DOT-01	N0187117101141S_20240813_074920	N0187117101141S
DOT-01	N0187112111170S_20240814_065513	N0187112111170S
DOT-01	N0187117101141S_20240814_080552	N0187117101141S
DOT-01	N018816081108E_20240814_083626	N018816081108E
DOT-01	N0187117101141S_20240815_065545	N0187117101141S
DOT-01	N0187112111170S_20240815_071644	N0187112111170S
DOT-01	N018816081108E_20240815_083233	N018816081108E
DOT-01	N0187112111170S_20240816_070611	N0187112111170S
DOT-01	N0187117101141S_20240816_074142	N0187117101141S
DOT-01	N0187112111170S_20240819_070208	N0187112111170S
DOT-01	N018816081108E_20240819_070658	N018816081108E
DOT-01	N0187117101141S_20240819_074859	N0187117101141S
DOT-01	N0187117101141S_20240820_070719	N0187117101141S
DOT-01	N0187112111170S_20240820_071944	N0187112111170S
DOT-01	N0187112111170S_20240821_065125	N0187112111170S
DOT-01	N0187117101141S_20240821_071149	N0187117101141S
DOT-01	N0187117101141S_20240822_070059	N0187117101141S
DOT-01	N0187112111170S_20240822_070106	N0187112111170S
DOT-01	N0187112111170S_20240823_065919	N0187112111170S
DOT-01	N0187117101141S_20240823_071713	N0187117101141S
DOT-01	N0187117101141S_20240826_065715	N0187117101141S
DOT-01	N0187112111425S_20240826_070336	N0187112111425S
DOT-01	N0187112111170S_20240826_071610	N0187112111170S
DOT-01	N0187112111170S_20240827_064907	N0187112111170S
DOT-01	N0187117101141S_20240827_065527	N0187117101141S
DOT-01	N0187112111380S_20240827_082724	N0187112111380S
DOT-01	N0187112111380S_20240827_084240	N0187112111380S
DOT-01	N0187117101141S_20240828_065918	N0187117101141S
DOT-01	N0187112111170S_20240828_070408	N0187112111170S
DOT-01	N0187117101141S_20240829_070809	N0187117101141S
DOT-01	N0187112111170S_20240829_073900	N0187112111170S
DOT-01	N0187117101141S_20240830_070251	N0187117101141S

Region/Division	Deployment ID	Location Code
DOT-01	N0187I12111170S_20240830_071252	N0187I12111170S
DOT-01	N0187I12111170S_20240903_072533	N0187I12111170S
DOT-01	N0187I17101141S_20240903_072749	N0187I17101141S
DOT-01	N0188I16081108E_20240903_091427	N0188I16081108E
DOT-01	N0187I12111170S_20240904_065359	N0187I12111170S
DOT-01	N0187I17101141S_20240904_071216	N0187I17101141S
DOT-01	N0188I16081108E_20240904_074301	N0188I16081108E
DOT-01	N0188I16081108E_20240904_074602	N0188I16081108E
DOT-01	N0187I17101141S_20240904_083335	N0187I17101141S
DOT-01	N0187I17101141S_20240905_063651	N0187I17101141S
DOT-01	N0188I16081122W_20240905_075203	N0188I16081122W
DOT-01	N0187I12111170S_20240905_080323	N0187I12111170S
DOT-01	N0187I17101141S_20240906_065253	N0187I17101141S
DOT-01	N0187I12111170S_20240906_065702	N0187I12111170S
DOT-01	N0188I16081108E_20240906_072013	N0188I16081108E
DOT-01	N0187I17101141S_20240909_065612	N0187I17101141S
DOT-01	N0187I12111170S_20240909_071527	N0187I12111170S
DOT-01	N0188I16081108W_20240909_075304	N0188I16081108W
DOT-01	N0187I17101141S_20240910_075355	N0187I17101141S
DOT-01	N0188I16081108W_20240910_075638	N0188I16081108W
DOT-01	N0187I12111170S_20240910_094407	N0187I12111170S
DOT-01	N0188I16081108W_20240911_070139	N0188I16081108W
DOT-01	N0187I17101141S_20240911_073039	N0187I17101141S
DOT-01	N0188I16081108W_20240912_064951	N0188I16081108W
DOT-01	N0187I17101141S_20240912_065859	N0187I17101141S
DOT-01	N0187I12111170S_20240913_065941	N0187I12111170S
DOT-01	N0188I16081108W_20240913_071916	N0188I16081108W
DOT-01	N0187I17101141S_20240913_085214	N0187I17101141S
DOT-01	N0187I12111170S_20240916_065135	N0187I12111170S
DOT-01	N0188I16081108W_20240916_065840	N0188I16081108W
DOT-01	N0187I17101141S_20240916_072536	N0187I17101141S
DOT-01	N0187I17101141S_20240917_070453	N0187I17101141S
DOT-01	N0187I12111170S_20240917_070741	N0187I12111170S
DOT-01	N0188I16081108W_20240917_071444	N0188I16081108W
DOT-01	N0187I12111170S_20240918_065541	N0187I12111170S
DOT-01	N0187I17101141S_20240918_070858	N0187I17101141S
DOT-01	N0188I16081108W_20240918_071916	N0188I16081108W
DOT-01	N0187I17101141S_20240919_064025	N0187I17101141S
DOT-01	N0187I12111170S_20240919_070157	N0187I12111170S
DOT-01	N0188I16081108W_20240919_071027	N0188I16081108W
DOT-01	N0187I12111170S_20240920_070202	N0187I12111170S
DOT-01	N0188I16081108W_20240920_071000	N0188I16081108W
DOT-01	N0187I17101141S_20240920_071653	N0187I17101141S

Region/Division	Deployment ID	Location Code
DOT-01	N018712111170S_20240923_065346	N018712111170S
DOT-01	N018717101141S_20240923_071401	N018717101141S
DOT-01	N018816081108E_20240923_083345	N018816081108E
DOT-01	N018712111170N_20240923_115639	N018712111170N
DOT-01	N018717101141S_20240924_070402	N018717101141S
DOT-01	N018816081108W_20240924_072555	N018816081108W
DOT-01	N018717101141S_20240925_070957	N018717101141S
DOT-01	N018717101141S_20240926_064931	N018717101141S
DOT-01	N018712111170S_20240926_070842	N018712111170S
DOT-01	N018816081122W_20240926_080659	N018816081122W
DOT-01	N018816081122W_20240926_130655	N018816081122W
DOT-01	N018712111170N_20240927_065520	N018712111170N
DOT-01	N018717101141S_20240927_071156	N018717101141S
DOT-01	N018816081108W_20240927_072905	N018816081108W
DOT-01	N018712111170S_20240927_084306	N018712111170S
DOT-01	N018712111170N_20240930_070254	N018712111170N
DOT-01	N018717101141N_20240930_071940	N018717101141N
DOT-01	N018816081108W_20240930_074317	N018816081108W
DOT-01	N018717101141N_20240930_075524	N018717101141N
DOT-01	N018717101141N_20241001_070914	N018717101141N
DOT-01	N018712111170N_20241001_071910	N018712111170N
DOT-01	N018816081108W_20241001_072442	N018816081108W
DOT-01	N018717101141N_20241001_073333	N018717101141N
DOT-01	N018712111170N_20241002_080626	N018712111170N
DOT-01	N018816081108W_20241002_091838	N018816081108W
DOT-01	N018712111170S_20241002_104555	N018712111170S
DOT-01	N018712111170N_20241003_070150	N018712111170N
DOT-01	N018816081108W_20241003_081822	N018816081108W
DOT-01	N018717101141S_20241003_093443	N018717101141S
DOT-01	N018712111170N_20241004_070804	N018712111170N
DOT-01	N018717101141N_20241004_073015	N018717101141N
DOT-01	N018816081108E_20241004_101554	N018816081108E
DOT-01	N018712111170N_20241007_072459	N018712111170N
DOT-01	N018816081108E_20241007_073823	N018816081108E
DOT-01	N018717101141N_20241007_081029	N018717101141N
DOT-01	N018717101141N_20241007_134549	N018717101141N
DOT-01	N018712111170N_20241008_071107	N018712111170N
DOT-01	N018712111170S_20241008_072918	N018712111170S
DOT-01	N018816081108W_20241008_101947	N018816081108W
DOT-01	N018712111170N_20241009_071941	N018712111170N
DOT-01	N018712111170S_20241009_074002	N018712111170S
DOT-01	N018717101141N_20241009_094107	N018717101141N
DOT-01	N018712111170S_20241010_071209	N018712111170S

Region/Division	Deployment ID	Location Code
DOT-01	N018816081108E_20241010_073617	N018816081108E
DOT-01	N0187117101141N_20241010_104335	N0187117101141N
DOT-01	N018816081108W_20241010_130127	N018816081108W
DOT-01	N0187112111170N_20241011_065710	N0187112111170N
DOT-01	N0187112111170S_20241011_071805	N0187112111170S
DOT-01	N018816081108E_20241011_073813	N018816081108E
DOT-01	N0187117101141N_20241011_081852	N0187117101141N
DOT-01	N018816081122W_20241011_095543	N018816081122W
DOT-01	N0187112111170N_20241014_071533	N0187112111170N
DOT-01	N0187117101141S_20241014_074047	N0187117101141S
DOT-01	N0187117101141S_20241015_070357	N0187117101141S
DOT-01	N018816081108W_20241015_072002	N018816081108W
DOT-01	N0187117101141N_20241015_091318	N0187117101141N
DOT-01	N018816081108W_20241016_063137	N018816081108W
DOT-01	N0187112111170N_20241016_070607	N0187112111170N
DOT-01	N0187112111170S_20241016_071812	N0187112111170S
DOT-01	N0187112111170S_20241016_073411	N0187112111170S
DOT-01	N0187117101141N_20241016_083733	N0187117101141N
DOT-01	N0187112111170S_20241017_070512	N0187112111170S
DOT-01	N0187117101141S_20241017_072054	N0187117101141S
DOT-01	N018816081108W_20241017_073119	N018816081108W
DOT-01	N0187112111170S_20241018_071750	N0187112111170S
DOT-01	N0187117101141S_20241018_072221	N0187117101141S
DOT-01	N018816081108W_20241018_073619	N018816081108W
DOT-01	N0187112111170S_20241021_071653	N0187112111170S
DOT-01	N0187112111170N_20241021_072349	N0187112111170N
DOT-01	N018816081108W_20241021_073731	N018816081108W
DOT-01	N0187112111170S_20241022_070816	N0187112111170S
DOT-01	N0187112111170N_20241022_072831	N0187112111170N
DOT-01	N018816081108W_20241022_074038	N018816081108W
DOT-01	N0187112111170N_20241023_070552	N0187112111170N
DOT-01	N0187112111170S_20241023_074617	N0187112111170S
DOT-01	N018816081108W_20241023_084631	N018816081108W
DOT-01	N0187112111170S_20241024_071110	N0187112111170S
DOT-01	N0187112111170N_20241024_072446	N0187112111170N
DOT-01	N018816081108W_20241024_080900	N018816081108W
DOT-01	N0187112111170S_20241025_071756	N0187112111170S
DOT-01	N0187112111170N_20241025_074410	N0187112111170N
DOT-01	N0187112111170N_20241028_070815	N0187112111170N
DOT-01	N0187112111170S_20241028_071837	N0187112111170S
DOT-01	N0187117101141S_20241028_075241	N0187117101141S
DOT-01	N0187112111170S_20241029_070544	N0187112111170S
DOT-01	N0187112111170N_20241029_072425	N0187112111170N

Region/Division	Deployment ID	Location Code
DOT-01	N0187117101141S_20241029_075532	N0187117101141S
DOT-01	N0187112111170S_20241030_071951	N0187112111170S
DOT-01	N0187112111170N_20241030_073823	N0187112111170N
DOT-01	N0187117101141S_20241030_081042	N0187117101141S
DOT-01	N0187112111170N_20241031_070226	N0187112111170N
DOT-01	N0187112111170S_20241031_075328	N0187112111170S
DOT-01	N0187117101141S_20241031_083126	N0187117101141S
DOT-01	N0187112111170S_20241101_070740	N0187112111170S
DOT-01	N0187112111170N_20241101_075626	N0187112111170N
DOT-01	N0187117101141S_20241101_085049	N0187117101141S
DOT-01	N0187112111170N_20241104_070022	N0187112111170N
DOT-01	N0187117101141S_20241104_071437	N0187117101141S
DOT-01	N01787111011025N_20241104_101536	N01787111011025N
DOT-01	N0187117101141N_20241104_122546	N0187117101141N
DOT-01	N01787111011025N_20241104_132345	N01787111011025N
DOT-01	N0187112111170N_20241105_070009	N0187112111170N
DOT-01	N0187117101140N_20241105_083228	N0187117101140N
DOT-01	N0187112111170N_20241106_070005	N0187112111170N
DOT-01	N0187117101141N_20241106_080038	N0187117101141N
DOT-01	N0187112111170N_20241107_070019	N0187112111170N
DOT-01	N0187112111170N_20241108_065511	N0187112111170N
DOT-01	N0187117101141N_20241108_070616	N0187117101141N
DOT-01	N0187117101141N_20241108_072526	N0187117101141N
DOT-01	N0187112111170N_20241111_065841	N0187112111170N
DOT-01	N0187112111170N_20241111_071059	N0187112111170N
DOT-01	N0187112111170N_20241112_065730	N0187112111170N
DOT-01	N0187112111170N_20241113_070027	N0187112111170N
DOT-01	N0187112111170N_20241114_070026	N0187112111170N
DOT-01	N0187112111170N_20241115_072143	N0187112111170N
DOT-01	N0190114022101E_20250407_082626	N0190114022101E
DOT-01	N0190114022101E_20250408_074814	N0190114022101E
DOT-01	N0190114022101E_20250409_073253	N0190114022101E
DOT-01	N0190114022101E_20250410_070231	N0190114022101E
DOT-01	N0190114022101E_20250411_072903	N0190114022101E
DOT-01	N0190114022101W_20250414_072449	N0190114022101W
DOT-01	N0190114022101E_20250415_080157	N0190114022101E
DOT-01	N0190114022101W_20250416_080640	N0190114022101W
DOT-01	N0190114022101W_20250417_072059	N0190114022101W
DOT-01	N0190114022101W_20250418_072443	N0190114022101W
DOT-01	N0190114022101E_20250421_074655	N0190114022101E
DOT-01	N0187112111170N_20250421_081509	N0187112111170N
DOT-01	N0187112111170N_20250422_072314	N0187112111170N
DOT-01	N0190114022101E_20250422_072544	N0190114022101E

Region/Division	Deployment ID	Location Code
DOT-01	N0190I14022101E_20250422_073242	N0190I14022101E
DOT-01	N0190I14022101E_20250423_074722	N0190I14022101E
DOT-01	N0187I12111170N_20250423_084944	N0187I12111170N
DOT-01	N0187I12111170N_20250424_070823	N0187I12111170N
DOT-01	N0187I12111170S_20250424_084049	N0187I12111170S
DOT-01	N0190I14022101E_20250424_093427	N0190I14022101E
DOT-01	N0190I14022101E_20250425_072305	N0190I14022101E
DOT-01	N0190I14022101E_20250428_071959	N0190I14022101E
DOT-01	N0187I12111170N_20250428_092455	N0187I12111170N
DOT-01	N0187I12111170N_20250429_070156	N0187I12111170N
DOT-01	N0190I14022101E_20250429_072700	N0190I14022101E
DOT-01	N0187I12111170N_20250430_070317	N0187I12111170N
DOT-01	N0190I14022101E_20250430_073954	N0190I14022101E
DOT-01	N0187I12111170N_20250501_070006	N0187I12111170N
DOT-01	N0190I14022101E_20250501_072946	N0190I14022101E
DOT-01	N0190I14022101E_20250502_073220	N0190I14022101E
DOT-01	N0190I14022101E_20250505_072358	N0190I14022101E
DOT-01	N0190I14022101E_20250506_072854	N0190I14022101E
DOT-01	N0187I12111170N_20250506_073612	N0187I12111170N
DOT-01	N0190I14022101E_20250507_070938	N0190I14022101E
DOT-01	N0187I12111170N_20250507_082830	N0187I12111170N
DOT-01	N0187I12111170N_20250507_091724	N0187I12111170N
DOT-01	N0190I14022101W_20250507_095916	N0190I14022101W
DOT-01	N0187I12111170N_20250508_070005	N0187I12111170N
DOT-01	N0190I14022101E_20250508_071314	N0190I14022101E
DOT-01	N0190I14022101E_20250512_070749	N0190I14022101E
DOT-01	N0187I12111170N_20250512_071848	N0187I12111170N
DOT-01	N0190I14022101E_20250513_072211	N0190I14022101E
DOT-01	N0187I12111170N_20250513_073905	N0187I12111170N
DOT-01	N0190I14022101E_20250514_070415	N0190I14022101E
DOT-01	N0187I12111170N_20250514_073043	N0187I12111170N
DOT-01	N0187I12111170N_20250515_070252	N0187I12111170N
DOT-01	N0190I14022101E_20250515_070634	N0190I14022101E
DOT-01	N0190I14022101E_20250516_071920	N0190I14022101E
DOT-01	N0190I14022101E_20250519_071022	N0190I14022101E
DOT-01	N0187I12111170N_20250519_072531	N0187I12111170N
DOT-01	N0190I14022101E_20250520_070901	N0190I14022101E
DOT-01	N0187I12111170N_20250520_075044	N0187I12111170N
DOT-01	N0187I12111170N_20250520_080439	N0187I12111170N
DOT-01	N0187I12111170N_20250521_070007	N0187I12111170N
DOT-01	N0190I14022101E_20250521_071839	N0190I14022101E
DOT-01	N0187I12111170N_20250522_065815	N0187I12111170N
DOT-01	N0190I14022101E_20250522_073127	N0190I14022101E

Region/Division	Deployment ID	Location Code
DOT-01	N0190I14022101E_20250527_071417	N0190I14022101E
DOT-01	N0187I12111170N_20250527_071602	N0187I12111170N
DOT-01	N0190I14022101W_20250527_083832	N0190I14022101W
DOT-01	N0190I14022101E_20250528_064310	N0190I14022101E
DOT-01	N0190I14022101W_20250528_065546	N0190I14022101W
DOT-01	N0187I12111170N_20250528_070755	N0187I12111170N
DOT-01	N0187I12111170N_20250529_065329	N0187I12111170N
DOT-01	N0190I14022101E_20250529_071719	N0190I14022101E
DOT-01	N0190I14022101W_20250529_073432	N0190I14022101W
DOT-01	N0190I14022101W_20250530_065246	N0190I14022101W
DOT-01	N0190I14022101E_20250530_073208	N0190I14022101E
DOT-01	N0190I14022101E_20250602_071201	N0190I14022101E
DOT-01	N0187I12111170N_20250602_071850	N0187I12111170N
DOT-01	N0190I14022101E_20250603_071647	N0190I14022101E
DOT-01	N0187I12111170N_20250603_073201	N0187I12111170N
DOT-01	N0187I12111170N_20250604_065407	N0187I12111170N
DOT-01	N0190I14022101E_20250604_071232	N0190I14022101E
DOT-01	N0187I12111170N_20250605_070005	N0187I12111170N
DOT-01	N0190I14022101E_20250605_071403	N0190I14022101E
DOT-01	N0190I14022101E_20250606_071427	N0190I14022101E
DOT-01	N0190I14022101W_20250606_111613	N0190I14022101W
DOT-01	N0187I12111170N_20250609_072324	N0187I12111170N
DOT-01	N0190I14022101W_20250609_090056	N0190I14022101W
DOT-01	N0187I12111170S_20250610_072330	N0187I12111170S
DOT-01	N0190I14022101W_20250610_073408	N0190I14022101W
DOT-01	N0190I14022101W_20250611_070814	N0190I14022101W
DOT-01	N0187I12111170S_20250611_071740	N0187I12111170S
DOT-01	N0190I14022101E_20250611_090907	N0190I14022101E
DOT-01	N0190I14022101E_20250612_070151	N0190I14022101E
DOT-01	N0190I14022101W_20250612_071929	N0190I14022101W
DOT-01	N0187I12111170S_20250612_072159	N0187I12111170S
DOT-01	N0190I14022101E_20250613_065640	N0190I14022101E
DOT-01	N0190I14022101W_20250616_071127	N0190I14022101W
DOT-01	N0187I12111170S_20250616_071548	N0187I12111170S
DOT-01	N0190I14022101W_20250617_072119	N0190I14022101W
DOT-01	N0187I12111170S_20250617_080016	N0187I12111170S
DOT-01	N0187I12111170S_20250618_072824	N0187I12111170S
DOT-01	N0190I14022101W_20250618_073616	N0190I14022101W
DOT-01	N0187I12111170S_20250619_070536	N0187I12111170S
DOT-01	N0190I14022101W_20250619_072747	N0190I14022101W
DOT-01	N0190I14022101W_20250620_073753	N0190I14022101W
DOT-01	N0187I12111170S_20250623_070347	N0187I12111170S
DOT-01	N0187I12111170S_20250623_071112	N0187I12111170S

Region/Division	Deployment ID	Location Code
DOT-01	N0187I12111170S_20250623_071154	N0187I12111170S
DOT-01	N0190I14022101W_20250623_071802	N0190I14022101W
DOT-01	N0187I12111170S_20250624_071659	N0187I12111170S
DOT-01	N0190I14022101W_20250624_072201	N0190I14022101W
DOT-01	N0187I12111170S_20250625_072106	N0187I12111170S
DOT-01	N0190I14022101W_20250625_073728	N0190I14022101W
DOT-01	N0187I12111170N_20250626_075027	N0187I12111170N
DOT-01	N0190I14022101E_20250626_090443	N0190I14022101E
DOT-01	N0190I14022101W_20250627_071026	N0190I14022101W
DOT-01	N0187I12111170N_20250630_071922	N0187I12111170N
DOT-01	N0187I12111170S_20250630_110854	N0187I12111170S
DOT-01	N0187I12111170N_20250701_072218	N0187I12111170N
DOT-01	N0190I14022101E_20250701_074350	N0190I14022101E
DOT-01	N0190I14022101E_20250702_071319	N0190I14022101E
DOT-01	N0187I12111170N_20250703_070206	N0187I12111170N
DOT-01	N0190I14022101E_20250703_073510	N0190I14022101E
DOT-01	N0190I14022101E_20250703_081138	N0190I14022101E
DOT-01	N0187I12111170S_20250707_070928	N0187I12111170S
DOT-01	N0190I14022101W_20250707_113617	N0190I14022101W
DOT-01	N0190I14022101E_20250708_071338	N0190I14022101E
DOT-01	N0187I12111170S_20250708_071605	N0187I12111170S
DOT-01	N0190I14022101E_20250709_070600	N0190I14022101E
DOT-01	N0187I12111170N_20250709_111000	N0187I12111170N
DOT-01	N0187I12111170N_20250709_111557	N0187I12111170N
DOT-01	N0190I14022101E_20250710_071018	N0190I14022101E
DOT-01	N0187I12111170N_20250710_091209	N0187I12111170N
DOT-01	N0190I14022101E_20250711_071829	N0190I14022101E
DOT-01	N0190I14022101E_20250714_071522	N0190I14022101E
DOT-01	N0190I14022101E_20250715_071214	N0190I14022101E
DOT-01	N0190I14022101E_20250716_070747	N0190I14022101E
DOT-01	N0190I14022101E_20250717_064503	N0190I14022101E
DOT-01	N0190I14022101W_20250718_063606	N0190I14022101W
DOT-01	N0190I14022101E_20250718_071427	N0190I14022101E
DOT-01	N0190I14022101W_20250721_072222	N0190I14022101W
DOT-01	N0190I14022101E_20250721_074154	N0190I14022101E
DOT-01	N0190I14022101E_20250722_070958	N0190I14022101E
DOT-01	N0190I14022101W_20250722_073920	N0190I14022101W
DOT-01	N0190I14022101E_20250723_064818	N0190I14022101E
DOT-01	N0190I14022101W_20250723_075739	N0190I14022101W
DOT-01	N0190I14022101E_20250724_070144	N0190I14022101E
DOT-01	N0190I14022101W_20250724_070907	N0190I14022101W
DOT-01	N0190I14022101W_20250725_064120	N0190I14022101W
DOT-01	N0190I14022101E_20250725_064426	N0190I14022101E

Region/Division	Deployment ID	Location Code
DOT-01	N0190I14022101E_20250728_070818	N0190I14022101E
DOT-01	N0187I15091292N_20250728_085331	N0187I15091292N
DOT-01	N0190I14022101E_20250729_071047	N0190I14022101E
DOT-01	N0187I15091292N_20250729_073147	N0187I15091292N
DOT-01	N0187I15091292S_20250729_130510	N0187I15091292S
DOT-01	N0190I14022101E_20250730_071312	N0190I14022101E
DOT-01	N0187I15091292S_20250730_073539	N0187I15091292S
DOT-01	N0190I14022101E_20250731_074603	N0190I14022101E
DOT-01	N0187I15091292S_20250731_085108	N0187I15091292S
DOT-01	N0187I15091292S_20250801_071202	N0187I15091292S
DOT-01	N0190I14022101W_20250801_071317	N0190I14022101W
DOT-01	N0190I14022101W_20250804_064846	N0190I14022101W
DOT-01	N0190I14022101E_20250804_065448	N0190I14022101E
DOT-01	N0190I14022101W_20250804_075502	N0190I14022101W
DOT-01	N0187I15091292S_20250804_081234	N0187I15091292S
DOT-01	N0190I14022101W_20250805_063730	N0190I14022101W
DOT-01	N0190I14022101E_20250805_072208	N0190I14022101E
DOT-01	N0187I15091313N_20250805_081251	N0187I15091313N
DOT-01	N0190I14022101W_20250806_071254	N0190I14022101W
DOT-01	N0187I15091330S_20250806_080054	N0187I15091330S
DOT-01	N0190I14022101E_20250806_110251	N0190I14022101E
DOT-01	N0190I14022101W_20250807_062843	N0190I14022101W
DOT-01	N0190I14022101E_20250807_071356	N0190I14022101E
DOT-01	N0187I15091313N_20250807_085011	N0187I15091313N
DOT-01	N0190I14022101W_20250808_064511	N0190I14022101W
DOT-01	N0190I14022101E_20250808_072346	N0190I14022101E
DOT-01	N0187I15091330S_20250808_074044	N0187I15091330S
DOT-01	N0187I15091330S_20250808_075211	N0187I15091330S
DOT-01	N0190I14022101E_20250811_063236	N0190I14022101E
DOT-01	N0190I14022101W_20250811_064717	N0190I14022101W
DOT-01	N0190I14022101E_20250812_063942	N0190I14022101E
DOT-01	N0190I14022101W_20250812_070023	N0190I14022101W
DOT-01	N0190I14022101W_20250813_070028	N0190I14022101W
DOT-01	N0190I14022101E_20250813_072719	N0190I14022101E
DOT-01	N0190I14022101E_20250814_071045	N0190I14022101E
DOT-01	N0190I14022101W_20250814_071832	N0190I14022101W
DOT-01	N0190I14022101W_20250815_065454	N0190I14022101W
DOT-01	N0190I14022101E_20250815_071053	N0190I14022101E
DOT-01	N0190I14022101W_20250815_081911	N0190I14022101W
DOT-01	N0190I14022101E_20250818_070422	N0190I14022101E
DOT-01	N0190I14022101W_20250818_095454	N0190I14022101W
DOT-01	N0190I14022101E_20250819_065501	N0190I14022101E
DOT-01	N0190I14022101W_20250819_071339	N0190I14022101W

Region/Division	Deployment ID	Location Code
DOT-01	N0190I14022101E_20250820_071457	N0190I14022101E
DOT-01	N0190I14022101W_20250820_073340	N0190I14022101W
DOT-01	N0190I14022101W_20250821_063942	N0190I14022101W
DOT-01	N0190I14022101E_20250822_064406	N0190I14022101E
DOT-01	N0190I14022101E_20250825_063416	N0190I14022101E
DOT-01	N0190I14022101W_20250825_090937	N0190I14022101W
DOT-01	N0190I14022101E_20250826_072311	N0190I14022101E
DOT-01	N0190I14022101W_20250826_083606	N0190I14022101W
DOT-01	N0190I14022101W_20250827_063233	N0190I14022101W
DOT-01	N0190I14022101E_20250827_071015	N0190I14022101E
DOT-01	N0190I14022101E_20250828_064026	N0190I14022101E
DOT-01	N0190I14022101W_20250828_070000	N0190I14022101W
DOT-01	N0190I14022101W_20250828_070609	N0190I14022101W
DOT-01	N0190I14022101W_20250902_064925	N0190I14022101W
DOT-01	N0190I14022101E_20250902_071127	N0190I14022101E
DOT-01	N0190I14022101E_20250903_063510	N0190I14022101E
DOT-01	N0190I14022101W_20250903_071122	N0190I14022101W
DOT-01	N0190I14022101E_20250904_064554	N0190I14022101E
DOT-01	N0190I14022101W_20250904_071644	N0190I14022101W
DOT-01	N0190I14022101E_20250905_064724	N0190I14022101E
DOT-01	N0190I14022101W_20250905_072216	N0190I14022101W
DOT-01	N0190I14022101E_20250908_063442	N0190I14022101E
DOT-01	N0190I14022101W_20250908_063653	N0190I14022101W
DOT-01	N0190I14022101W_20250909_063230	N0190I14022101W
DOT-01	N0190I14022101E_20250909_064950	N0190I14022101E
DOT-01	N0190I14022101E_20250910_070227	N0190I14022101E
DOT-01	N0190I14022101W_20250910_072133	N0190I14022101W
DOT-01	N0190I14022101W_20250911_070037	N0190I14022101W
DOT-01	N0190I14022101E_20250911_071744	N0190I14022101E
DOT-01	N0190I14022101E_20250912_062029	N0190I14022101E
DOT-01	N0190I14022101W_20250912_074239	N0190I14022101W
DOT-01	N0190I14022101E_20250915_063423	N0190I14022101E
DOT-01	N0190I14022101W_20250915_065811	N0190I14022101W
DOT-01	N0190I14022101W_20250916_070654	N0190I14022101W
DOT-01	N0190I14022101E_20250916_071722	N0190I14022101E
DOT-01	N0190I14022101W_20250917_072354	N0190I14022101W
DOT-01	N0190I14022101E_20250917_075009	N0190I14022101E
DOT-01	N0190I14022101W_20250918_064848	N0190I14022101W
DOT-01	N0190I14022101E_20250918_070845	N0190I14022101E
DOT-01	N0190I14022101W_20250919_065654	N0190I14022101W
DOT-01	N0190I14022101E_20250919_073104	N0190I14022101E
DOT-01	N0190I14022101W_20250922_071725	N0190I14022101W
DOT-01	N0190I14022101E_20250922_072944	N0190I14022101E

Region/Division	Deployment ID	Location Code
DOT-01	N0190I14022101E_20250923_064930	N0190I14022101E
DOT-01	N0190I14022101W_20250923_073654	N0190I14022101W
DOT-01	N0190I14022101E_20250924_065654	N0190I14022101E
DOT-01	N0190I14022101W_20250924_071824	N0190I14022101W
DOT-01	N0190I14022101W_20250925_071852	N0190I14022101W
DOT-01	N0190I14022101E_20250925_072716	N0190I14022101E
DOT-01	N0190I14022101E_20250926_064655	N0190I14022101E
DOT-01	N0190I14022101W_20250926_065306	N0190I14022101W
DOT-01	N0190I14022101E_20250929_070149	N0190I14022101E
DOT-01	N0190I14022101W_20250929_071150	N0190I14022101W
DOT-01	N0190I14022101E_20250930_070427	N0190I14022101E
DOT-01	N0190I14022101W_20250930_073939	N0190I14022101W
DOT-01	N0190I14022101W_20251001_072319	N0190I14022101W
DOT-01	N0190I14022101W_20251002_072520	N0190I14022101W
DOT-01	N0190I14022101W_20251003_080944	N0190I14022101W
DOT-01	N0190I14022101W_20251006_072202	N0190I14022101W
DOT-01	N0190I14022101W_20251007_072637	N0190I14022101W
DOT-01	N0190I14022101W_20251008_080902	N0190I14022101W
DOT-01	N0190I14022101W_20251009_070224	N0190I14022101W
DOT-01	N01890I16012005W_20251010_070938	N0190I14022101W
DOT-01	N0190I14022101W_20251013_082941	N0190I14022101W
DOT-01	N0190I14022101W_20251014_091531	N0190I14022101W
DOT-01	N0190I14022101W_20251015_073358	N0190I14022101W
DOT-01	N0187I12111380S_20251107_101802	N0187I12111380S
DOT-01	N01890I16012005W_20251117_203149	N01890I16012005W
DOT-01	N01890I16012005W_20251118_194851	N01890I16012005W
DOT-01	N01890I16012005W_20251119_195314	N01890I16012005W
DOT-01	N0187I15091191S_20251120_095939	N0187I15091191S
DOT-01	N0187I15091191S_20251120_110852	N0187I15091191S
DOT-01	N0187I15091191S_20251120_111433	N0187I15091191S
DOT-01	N01890I16012005W_20251120_194345	N01890I16012005W
DOT-01	N01787I11012020S_20251121_095855	N01787I11012020S
DOT-01	N01890I16012005W_20251121_200728	N01890I16012005W
DOT-01	N0190I11013017E_20251201_211411	N0190I11013017E
DOT-01	N0190I11013017E_20251204_220051	N0190I11013017E
DOT-01	N0190I11013017E_20251205_205936	N0190I11013017E
DOT-01	N0190I11013017E_20251215_205256	N0190I11013017E
DOT-01	N0190I11013017E_20251216_204916	N0190I11013017E
DOT-02	N02526104004E_20240611_101516	N02526104004E
DOT-02	N02526104004W_20240612_112425	N02526104004W
DOT-02	N02526104004W_20240613_104615	N02526104004W
DOT-02	N02790I26011017E_20250512_074542	N02790I26011017E
DOT-02	N02790I26011017W_20250513_120244	N02790I26011017W

Region/Division	Deployment ID	Location Code
DOT-02	N02826073240S_20250702_072712	N02826073240S
DOT-02	N021226043006S_20250708_064309	N021226043006S
DOT-02	N021226043006S_20250708_121735	N021226043006S
DOT-02	N021226043006N_20250710_065648	N021226043006N
DOT-02	N025S23021078W_20250728_080347	N025S23021078W
DOT-02	N025S23021078W_20250729_074549	N025S23021078W
DOT-02	N025S23021078W_20250730_073304	N025S23021078W
DOT-02	N025S23021078W_20250730_112819	N025S23021078W
DOT-02	N025S23021078W_20250801_081435	N025S23021078W
DOT-02	N025S23021078W_20250801_121950	N025S23021078W
DOT-02	N024926023583W_20250819_113044	N024926023583W
DOT-02	N024926023583E_20250826_100349	N024926023583E
DOT-02	N024926023583E_20250827_083232	N024926023583E
DOT-02	N025S23021078W_20250915_094126	N025S23021078W
DOT-02	N025S23021078W_20250916_065532	N025S23021078W
DOT-02	N025S23021078W_20250916_070132	N025S23021078W
DOT-02	N025S23021078W_20250917_065615	N025S23021078W
DOT-02	N025S23021078W_20250918_070935	N025S23021078W
DOT-02	N025S23021078W_20250919_073016	N025S23021078W
DOT-02	N025S23021078W_20250922_063647	N025S23021078W
DOT-02	N025S23021078W_20250923_063845	N025S23021078W
DOT-02	N025S23021078W_20250924_065558	N025S23021078W
DOT-02	N025S23021078W_20250925_065935	N025S23021078W
DOT-03	N03481I33012140N_20240122_084210	N03481I33012140N
DOT-03	N03481I33012140N_20240122_093519	N03481I33012140N
DOT-03	N03481I33012140N_20240122_105406	N03481I33012140N
DOT-03	N03481I33012140N_20240122_130624	N03481I33012140N
DOT-03	N03481I33012140N_20240122_142513	N03481I33012140N
DOT-03	N03481I33012140N_20240123_081601	N03481I33012140N
DOT-03	N03481I33012140N_20240124_082717	N03481I33012140N
DOT-03	N03481I33012140N_20240125_092055	N03481I33012140N
DOT-03	N03481I33012140N_20240126_095858	N03481I33012140N
DOT-03	N03481I33012140N_20240129_070302	N03481I33012140N
DOT-03	N03481I33012140N_20240129_084848	N03481I33012140N
DOT-03	N03481I33012140N_20240130_074541	N03481I33012140N
DOT-03	N03481I33012140N_20240131_063755	N03481I33012140N
DOT-03	N03481I33012140N_20240131_140654	N03481I33012140N
DOT-03	N03481I33012140N_20240201_064540	N03481I33012140N
DOT-03	N03481I33012140N_20240201_080701	N03481I33012140N
DOT-03	N03481I33012140N_20240202_072648	N03481I33012140N
DOT-03	N03481I33012140N_20240202_075343	N03481I33012140N
DOT-03	N03481I33012140N_20240202_145511	N03481I33012140N
DOT-03	N03481I33012140N_20240205_071033	N03481I33012140N

Region/Division	Deployment ID	Location Code
DOT-03	N03481I33012140N_20240206_081836	N03481I33012140N
DOT-03	N03481I33012140N_20240207_071741	N03481I33012140N
DOT-03	N03481I33012140N_20240207_081302	N03481I33012140N
DOT-03	N03481I33012140N_20240207_134929	N03481I33012140N
DOT-03	N03481I33012140N_20240207_144428	N03481I33012140N
DOT-03	N03481I33012140N_20240208_075119	N03481I33012140N
DOT-03	N03481I33012140N_20240209_070549	N03481I33012140N
DOT-03	N03481I33012140N_20240312_102148	N03481I33012140N
DOT-03	N03481I33012080S_20240312_102630	N03481I33012080S
DOT-03	N03481I33012140N_20240313_092201	N03481I33012140N
DOT-03	N03481I33012140N_20240313_150630	N03481I33012140N
DOT-03	N03481I33012140N_20240314_103441	N03481I33012140N
DOT-03	N03481I33012140N_20240315_103609	N03481I33012140N
DOT-03	N03481I33012140N_20240315_144738	N03481I33012140N
DOT-03	N03481I33012143N_20240318_091337	N03481I33012143N
DOT-03	N0381I33032010N_20240318_095021	N0381I33032010N
DOT-03	N03481I33012143N_20240318_095513	N03481I33012143N
DOT-03	N03481I33012143N_20240319_090608	N03481I33012143N
DOT-03	N03481I33012143N_20240320_084622	N03481I33012143N
DOT-03	N03481I33012143N_20240321_085015	N03481I33012143N
DOT-03	N03481I33012143N_20240322_090625	N03481I33012143N
DOT-03	N03481I33012143N_20240325_085228	N03481I33012143N
DOT-03	N03481I33012143N_20240325_092707	N03481I33012143N
DOT-03	N0381I33032012S_20240325_114031	N0381I33032012S
DOT-03	N03481I33012143N_20240326_082044	N03481I33012143N
DOT-03	N0381I33032012S_20240326_091908	N0381I33032012S
DOT-03	N03481I33012143N_20240327_083924	N03481I33012143N
DOT-03	N0381I33032012S_20240327_091012	N0381I33032012S
DOT-03	N03481I33012143N_20240328_092739	N03481I33012143N
DOT-03	N0381I33032012S_20240328_093851	N0381I33032012S
DOT-03	N03481I33012143N_20240329_084026	N03481I33012143N
DOT-03	N0381I33032012S_20240329_091911	N0381I33032012S
DOT-03	N03481I33012143N_20240329_102119	N03481I33012143N
DOT-03	N03481I33012143N_20240401_082634	N03481I33012143N
DOT-03	N03481I33012143N_20240401_091942	N03481I33012143N
DOT-03	N0381I33032012S_20240401_095558	N0381I33032012S
DOT-03	N0381I33032012S_20240402_083344	N0381I33032012S
DOT-03	N03481I33012143N_20240403_082220	N03481I33012143N
DOT-03	N0381I33032012S_20240403_094223	N0381I33032012S
DOT-03	N03481I33012143N_20240404_092420	N03481I33012143N
DOT-03	N03481I33012143N_20240405_090016	N03481I33012143N
DOT-03	N0381I33032010N_20240405_094058	N0381I33032010N
DOT-03	N03481I33012143N_20240405_110938	N03481I33012143N

Region/Division	Deployment ID	Location Code
DOT-03	N03481I33012143N_20240410_085521	N03481I33012143N
DOT-03	N0381I33032012S_20240410_091503	N0381I33032012S
DOT-03	N03481I33012143N_20240411_095256	N03481I33012143N
DOT-03	N03481I33012143N_20240412_083453	N03481I33012143N
DOT-03	N0381I33032012S_20240412_090332	N0381I33032012S
DOT-03	N0381I33032012S_20240412_121002	N0381I33032012S
DOT-03	N03481I33012027N_20240415_084145	N03481I33012027N
DOT-03	N0381I33032010N_20240415_110944	N0381I33032010N
DOT-03	N0381I33032010N_20240415_120219	N0381I33032010N
DOT-03	N03481I33012027N_20240416_083209	N03481I33012027N
DOT-03	N03481I33012143N_20240416_092741	N03481I33012143N
DOT-03	N0381I33032012S_20240416_101917	N0381I33032012S
DOT-03	N03481I33012027N_20240417_084418	N03481I33012027N
DOT-03	N03481I33012143N_20240417_085144	N03481I33012143N
DOT-03	N0381I33032012S_20240417_112759	N0381I33032012S
DOT-03	N03481I33012027N_20240418_090222	N03481I33012027N
DOT-03	N0381I33032012S_20240418_095105	N0381I33032012S
DOT-03	N03481I33012143N_20240418_095241	N03481I33012143N
DOT-03	N03481I33012143N_20240419_082644	N03481I33012143N
DOT-03	N03481I33012027N_20240419_085617	N03481I33012027N
DOT-03	N0381I33032012S_20240419_085657	N0381I33032012S
DOT-03	N03481I33012143N_20240419_105104	N03481I33012143N
DOT-03	N0381I33032012S_20240422_091453	N0381I33032012S
DOT-03	N03481I33012027N_20240422_093256	N03481I33012027N
DOT-03	N03481I33012011N_20240423_085934	N03481I33012011N
DOT-03	N03481I33012011N_20240424_091236	N03481I33012011N
DOT-03	N03481I33012011N_20240425_090526	N03481I33012011N
DOT-03	N03481I33012011N_20240426_090531	N03481I33012011N
DOT-03	N03481I33012011N_20240429_084833	N03481I33012011N
DOT-03	N03481I33012011N_20240430_092608	N03481I33012011N
DOT-03	N03481I33012011N_20240501_085728	N03481I33012011N
DOT-03	N03481I33012011N_20240502_085459	N03481I33012011N
DOT-03	N03481I33012011N_20240503_085940	N03481I33012011N
DOT-03	N03481I33012135N_20240506_092229	N03481I33012135N
DOT-03	N03481I33012011N_20240506_092657	N03481I33012011N
DOT-03	N0381I33033065N_20240506_100424	N0381I33033065N
DOT-03	N0381I33033065N_20240507_083943	N0381I33033065N
DOT-03	N03481I33012011N_20240507_091550	N03481I33012011N
DOT-03	N03481I33012135N_20240507_094029	N03481I33012135N
DOT-03	N03481I33012135N_20240507_112212	N03481I33012135N
DOT-03	N03481I33012135N_20240507_132202	N03481I33012135N
DOT-03	N03481I33012135N_20240508_091040	N03481I33012135N
DOT-03	N0381I33033065N_20240508_091157	N0381I33033065N

Region/Division	Deployment ID	Location Code
DOT-03	N03481I33012011N_20240508_092615	N03481I33012011N
DOT-03	N0381I33033065N_20240509_082918	N0381I33033065N
DOT-03	N03481I33012011N_20240509_090252	N03481I33012011N
DOT-03	N03481I33012135N_20240509_093841	N03481I33012135N
DOT-03	N0381I33033065N_20240510_082838	N0381I33033065N
DOT-03	N03481I33012011N_20240510_090456	N03481I33012011N
DOT-03	N03481I33012135N_20240510_093340	N03481I33012135N
DOT-03	N03481I33012135N_20240513_095709	N03481I33012135N
DOT-03	N0381I33033065N_20240513_103433	N0381I33033065N
DOT-03	N03481I33012135N_20240514_085315	N03481I33012135N
DOT-03	N0381I33033065N_20240514_095934	N0381I33033065N
DOT-03	N0381I33033065N_20240515_082138	N0381I33033065N
DOT-03	N03481I33012135N_20240515_094434	N03481I33012135N
DOT-03	N0381I33033065N_20240516_083852	N0381I33033065N
DOT-03	N03481I33012135N_20240516_120126	N03481I33012135N
DOT-03	N03481I33012135N_20240517_090220	N03481I33012135N
DOT-03	N0381I33033065N_20240517_095826	N0381I33033065N
DOT-03	N0381I33033065N_20240520_094205	N0381I33033065N
DOT-03	N03481I33012135N_20240520_094837	N03481I33012135N
DOT-03	N0381I33033065N_20240521_090906	N0381I33033065N
DOT-03	N03481I33012135N_20240521_104151	N03481I33012135N
DOT-03	N03481I33012135N_20240521_150418	N03481I33012135N
DOT-03	N0381I33033065N_20240522_085645	N0381I33033065N
DOT-03	N03481I33012135N_20240522_122102	N03481I33012135N
DOT-03	N0381I33033065N_20240523_090116	N0381I33033065N
DOT-03	N03481I33012135N_20240523_091726	N03481I33012135N
DOT-03	N03481I33012135N_20240524_084933	N03481I33012135N
DOT-03	N0381I33033065N_20240524_091444	N0381I33033065N
DOT-03	N03481I33012135N_20240528_083654	N03481I33012135N
DOT-03	N0381I33033065N_20240528_085500	N0381I33033065N
DOT-03	N03481I33012060S_20240528_093017	N03481I33012060S
DOT-03	N0381I33032026S_20240528_105937	N0381I33032026S
DOT-03	N0381I33033065N_20240529_084210	N0381I33033065N
DOT-03	N03481I33012060S_20240529_084502	N03481I33012060S
DOT-03	N03481I33012135N_20240529_094034	N03481I33012135N
DOT-03	N0381I33033065N_20240530_083401	N0381I33033065N
DOT-03	N03481I33012135N_20240530_090254	N03481I33012135N
DOT-03	N03481I33012060S_20240530_092342	N03481I33012060S
DOT-03	N0381I33032026S_20240531_070544	N0381I33032026S
DOT-03	N03481I33012135N_20240531_083824	N03481I33012135N
DOT-03	N0381I33033065N_20240531_084443	N0381I33033065N
DOT-03	N03481I33012060S_20240531_092125	N03481I33012060S
DOT-03	N03481I33012135N_20240603_082636	N03481I33012135N

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33033065N_20240603_085711	N0381I33033065N
DOT-03	N03481I33012060S_20240603_091743	N03481I33012060S
DOT-03	N03481I33012135N_20240604_080541	N03481I33012135N
DOT-03	N03481I33012060S_20240604_083416	N03481I33012060S
DOT-03	N0381I33033065N_20240604_085845	N0381I33033065N
DOT-03	N0381I33033065N_20240605_084131	N0381I33033065N
DOT-03	N03481I33012060S_20240605_085324	N03481I33012060S
DOT-03	N03481I33012135N_20240605_093416	N03481I33012135N
DOT-03	N03481I33012135N_20240605_144453	N03481I33012135N
DOT-03	N0381I33033065N_20240606_085144	N0381I33033065N
DOT-03	N03481I33012060S_20240606_085646	N03481I33012060S
DOT-03	N03481I33012135N_20240606_094339	N03481I33012135N
DOT-03	N03481I33012060S_20240607_090055	N03481I33012060S
DOT-03	N0381I33033065N_20240607_091108	N0381I33033065N
DOT-03	N03481I33012135N_20240607_091421	N03481I33012135N
DOT-03	N03481I33012060S_20240610_084109	N03481I33012060S
DOT-03	N0381I33033065N_20240610_084421	N0381I33033065N
DOT-03	N03481I33012135N_20240610_093420	N03481I33012135N
DOT-03	N0381I34041232S_20240610_101517	N0381I34041232S
DOT-03	N0381I33033065N_20240611_082401	N0381I33033065N
DOT-03	N03481I33012060S_20240611_083552	N03481I33012060S
DOT-03	N03481I33012135N_20240611_085139	N03481I33012135N
DOT-03	N0381I34041232S_20240611_085345	N0381I34041232S
DOT-03	N03481I33012135N_20240612_083438	N03481I33012135N
DOT-03	N0381I33033065N_20240612_085110	N0381I33033065N
DOT-03	N03481I33012060S_20240612_085336	N03481I33012060S
DOT-03	N0381I34041232S_20240612_091146	N0381I34041232S
DOT-03	N03481I33012135N_20240613_083246	N03481I33012135N
DOT-03	N0381I33033065N_20240613_083652	N0381I33033065N
DOT-03	N03481I33012060S_20240613_085150	N03481I33012060S
DOT-03	N0381I34041232S_20240613_085404	N0381I34041232S
DOT-03	N0381I34041232S_20240613_100033	N0381I34041232S
DOT-03	N03481I33012135N_20240614_082731	N03481I33012135N
DOT-03	N0381I34041232S_20240614_084005	N0381I34041232S
DOT-03	N0381I33033065N_20240614_085259	N0381I33033065N
DOT-03	N03481I33012060S_20240614_085857	N03481I33012060S
DOT-03	N0381I33033065N_20240614_104605	N0381I33033065N
DOT-03	N03481I33012060S_20240618_083550	N03481I33012060S
DOT-03	N03481I33012060N_20240618_083815	N03481I33012060N
DOT-03	N0381I33033065N_20240618_084735	N0381I33033065N
DOT-03	N03481I33012135N_20240618_090323	N03481I33012135N
DOT-03	N03481I33012135N_20240618_103244	N03481I33012135N
DOT-03	N03481I33012135N_20240618_134741	N03481I33012135N

Region/Division	Deployment ID	Location Code
DOT-03	N03481I33012060S_20240620_083614	N03481I33012060S
DOT-03	N03481I33012060N_20240620_084538	N03481I33012060N
DOT-03	N0381I33033065N_20240620_085844	N0381I33033065N
DOT-03	N03481I33012140S_20240620_101756	N03481I33012140S
DOT-03	N03481I33012060S_20240621_083243	N03481I33012060S
DOT-03	N03481I33012060N_20240621_084439	N03481I33012060N
DOT-03	N0381I33033065N_20240621_084958	N0381I33033065N
DOT-03	N03481I33012140S_20240621_103231	N03481I33012140S
DOT-03	N0381I33033065N_20240624_090036	N0381I33033065N
DOT-03	N03481I33012060S_20240624_094203	N03481I33012060S
DOT-03	N03481I33012060N_20240624_103111	N03481I33012060N
DOT-03	N03481I33012140S_20240624_131411	N03481I33012140S
DOT-03	N03481I33012060N_20240625_085616	N03481I33012060N
DOT-03	N0381I33033065N_20240625_091831	N0381I33033065N
DOT-03	N03481I33012060S_20240625_105640	N03481I33012060S
DOT-03	N03481I33012140S_20240625_110421	N03481I33012140S
DOT-03	N03481I33012140S_20240626_091643	N03481I33012140S
DOT-03	N03481I33012060S_20240626_092701	N03481I33012060S
DOT-03	N03481I33012060N_20240626_093911	N03481I33012060N
DOT-03	N03481I33012060S_20240627_090322	N03481I33012060S
DOT-03	N03481I33012060N_20240627_092336	N03481I33012060N
DOT-03	N0381I33033065N_20240627_093711	N0381I33033065N
DOT-03	N03481I33012140S_20240627_093753	N03481I33012140S
DOT-03	N03481I33012060N_20240628_085135	N03481I33012060N
DOT-03	N03481I33012140S_20240628_091611	N03481I33012140S
DOT-03	N0381I33033065N_20240628_092558	N0381I33033065N
DOT-03	N03481I33012060S_20240628_101435	N03481I33012060S
DOT-03	N03481I33012060N_20240701_090051	N03481I33012060N
DOT-03	N03481I33012135S_20240701_091905	N03481I33012135S
DOT-03	N03481I33012060N_20240702_085801	N03481I33012060N
DOT-03	N03481I33012135S_20240702_094018	N03481I33012135S
DOT-03	N03481I33012135S_20240703_090339	N03481I33012135S
DOT-03	N03481I33012060N_20240703_091544	N03481I33012060N
DOT-03	N03481I33012135S_20240703_125322	N03481I33012135S
DOT-03	N03481I33012135S_20240708_094200	N03481I33012135S
DOT-03	N03481I33012135S_20240709_093320	N03481I33012135S
DOT-03	N03481I33012135S_20240710_091605	N03481I33012135S
DOT-03	N03481I33012135S_20240711_084822	N03481I33012135S
DOT-03	N03481I33012135S_20240711_090524	N03481I33012135S
DOT-03	N03481I33012135S_20240712_092746	N03481I33012135S
DOT-03	N03481I33012135S_20240722_101641	N03481I33012135S
DOT-03	N03481I33012135S_20240723_090436	N03481I33012135S
DOT-03	N03481I33012135S_20240724_091429	N03481I33012135S

Region/Division	Deployment ID	Location Code
DOT-03	N03481I33012135S_20240725_085634	N03481I33012135S
DOT-03	N03481I33012135S_20240725_094643	N03481I33012135S
DOT-03	N03481I33012135S_20240726_091525	N03481I33012135S
DOT-03	N03481I33012011N_20240729_085816	N03481I33012011N
DOT-03	N03481I33012011N_20240730_090000	N03481I33012011N
DOT-03	N03481I33012011N_20240731_091335	N03481I33012011N
DOT-03	N03481I33012011N_20240801_085913	N03481I33012011N
DOT-03	N03481I33012011N_20240802_083625	N03481I33012011N
DOT-03	N03481I33012135S_20240805_100137	N03481I33012135S
DOT-03	N03481I33012135S_20240806_093046	N03481I33012135S
DOT-03	N0381I33033065N_20240807_090156	N0381I33033065N
DOT-03	N0381I33033065N_20240808_090835	N0381I33033065N
DOT-03	N0381I33033065N_20240809_084911	N0381I33033065N
DOT-03	N0381I33033065N_20240812_081016	N0381I33033065N
DOT-03	N03481I33012027N_20240812_085940	N03481I33012027N
DOT-03	N03481I33012027N_20240813_085939	N03481I33012027N
DOT-03	N0381I33033065N_20240813_092932	N0381I33033065N
DOT-03	N0381I33033065N_20240813_102950	N0381I33033065N
DOT-03	N0381I33033065N_20240814_082630	N0381I33033065N
DOT-03	N03481I33012027N_20240814_093413	N03481I33012027N
DOT-03	N0381I33033065N_20240815_083056	N0381I33033065N
DOT-03	N03481I33012027N_20240815_085903	N03481I33012027N
DOT-03	N0381I33033065N_20240816_085345	N0381I33033065N
DOT-03	N03481I33012027N_20240816_094616	N03481I33012027N
DOT-03	N03481I33012140S_20240819_084412	N03481I33012140S
DOT-03	N0381I33033065N_20240819_084449	N0381I33033065N
DOT-03	N03481I33012140S_20240819_091141	N03481I33012140S
DOT-03	N0381I33033065N_20240820_084756	N0381I33033065N
DOT-03	N03481I33012140S_20240820_090728	N03481I33012140S
DOT-03	N03481I33012140S_20240821_083556	N03481I33012140S
DOT-03	N0381I33033065N_20240821_085250	N0381I33033065N
DOT-03	N0381I33033065N_20240822_084624	N0381I33033065N
DOT-03	N03481I33012140S_20240822_084756	N03481I33012140S
DOT-03	N0381I33032026N_20240822_085907	N0381I33032026N
DOT-03	N03481I33012140S_20240823_084728	N03481I33012140S
DOT-03	N0381I33033065N_20240823_084823	N0381I33033065N
DOT-03	N0381I33032026N_20240823_085845	N0381I33032026N
DOT-03	N0381I33033065N_20240823_131604	N0381I33033065N
DOT-03	N0381I33033065N_20240826_083939	N0381I33033065N
DOT-03	N03481I33012140S_20240826_084843	N03481I33012140S
DOT-03	N03481I33012140S_20240827_083846	N03481I33012140S
DOT-03	N0381I33033065N_20240827_084640	N0381I33033065N
DOT-03	N03481I33012140S_20240828_084133	N03481I33012140S

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33033065N_20240828_084332	N0381I33033065N
DOT-03	N0381I33033065N_20240829_083142	N0381I33033065N
DOT-03	N03481I33012140S_20240829_083905	N03481I33012140S
DOT-03	N0381I33033065N_20240830_084029	N0381I33033065N
DOT-03	N03481I33012140S_20240830_085736	N03481I33012140S
DOT-03	N0381I33033065N_20240830_090301	N0381I33033065N
DOT-03	N0381I33032026N_20240903_084004	N0381I33032026N
DOT-03	N03481I33012011N_20240903_084555	N03481I33012011N
DOT-03	N0381I33033065N_20240903_085308	N0381I33033065N
DOT-03	N03481I33012140S_20240903_090338	N03481I33012140S
DOT-03	N03481I33012011N_20240904_083818	N03481I33012011N
DOT-03	N0381I33033065N_20240904_084346	N0381I33033065N
DOT-03	N0381I33032026N_20240904_085606	N0381I33032026N
DOT-03	N03481I33012140S_20240904_090021	N03481I33012140S
DOT-03	N03481I33012140S_20240904_094836	N03481I33012140S
DOT-03	N0381I33033065N_20240905_065723	N0381I33033065N
DOT-03	N03481I33012140S_20240905_073425	N03481I33012140S
DOT-03	N03481I33012011N_20240905_084530	N03481I33012011N
DOT-03	N0381I33032026N_20240905_114108	N0381I33032026N
DOT-03	N03481I33012140S_20240906_071920	N03481I33012140S
DOT-03	N0381I33033065N_20240906_085925	N0381I33033065N
DOT-03	N03481I33012011N_20240906_090004	N03481I33012011N
DOT-03	N0381I33032026N_20240906_090754	N0381I33032026N
DOT-03	N03481I33012140S_20240906_091353	N03481I33012140S
DOT-03	N0381I33033033S_20240909_083839	N0381I33033033S
DOT-03	N0381I33033065N_20240909_084422	N0381I33033065N
DOT-03	N03481I33012011N_20240909_084902	N03481I33012011N
DOT-03	N0381I33033033S_20240909_104222	N0381I33033033S
DOT-03	N0381I33033033S_20240909_104319	N0381I33033033S
DOT-03	N03481I33012140S_20240909_111425	N03481I33012140S
DOT-03	N03481I33012140S_20240909_163003	N03481I33012140S
DOT-03	N0381I33033065N_20240910_085218	N0381I33033065N
DOT-03	N03481I33012011N_20240910_085717	N03481I33012011N
DOT-03	N0381I33032026N_20240910_085952	N0381I33032026N
DOT-03	N03481I33012140S_20240910_090002	N03481I33012140S
DOT-03	N0381I33033033S_20240910_093013	N0381I33033033S
DOT-03	N03481I33012140S_20240910_093905	N03481I33012140S
DOT-03	N0381I33033065N_20240911_083354	N0381I33033065N
DOT-03	N03481I33012011N_20240911_084316	N03481I33012011N
DOT-03	N03481I33012140S_20240911_084644	N03481I33012140S
DOT-03	N0381I33032026N_20240911_085552	N0381I33032026N
DOT-03	N03481I33012140S_20240911_093655	N03481I33012140S
DOT-03	N0381I33033033S_20240911_114337	N0381I33033033S

Region/Division	Deployment ID	Location Code
DOT-03	N03481I33012011N_20240911_141005	N03481I33012011N
DOT-03	N0381I33033065N_20240912_084102	N0381I33033065N
DOT-03	N03481I33012011N_20240912_084505	N03481I33012011N
DOT-03	N0381I33032026N_20240912_084957	N0381I33032026N
DOT-03	N03481I33012140S_20240912_085413	N03481I33012140S
DOT-03	N03481I33012140S_20240912_091259	N03481I33012140S
DOT-03	N0381I33033033S_20240912_095943	N0381I33033033S
DOT-03	N03481I33012140S_20240913_083101	N03481I33012140S
DOT-03	N0381I33033065N_20240913_084105	N0381I33033065N
DOT-03	N03481I33012011N_20240913_085523	N03481I33012011N
DOT-03	N03481I33012140S_20240913_090947	N03481I33012140S
DOT-03	N03481I33012140S_20240913_091050	N03481I33012140S
DOT-03	N0381I33033033S_20240913_105545	N0381I33033033S
DOT-03	N03481I33012011N_20240913_123850	N03481I33012011N
DOT-03	N03481I33012140S_20240916_084849	N03481I33012140S
DOT-03	N0381I33033055N_20240916_085753	N0381I33033055N
DOT-03	N0381I33032026N_20240916_085950	N0381I33032026N
DOT-03	N03481I33012140S_20240916_092302	N03481I33012140S
DOT-03	N03481I33012140S_20240917_082102	N03481I33012140S
DOT-03	N0381I33032026N_20240917_083630	N0381I33032026N
DOT-03	N0381I33033055N_20240917_085842	N0381I33033055N
DOT-03	N0381I33033055N_20240917_090547	N0381I33033055N
DOT-03	N03481I33012140S_20240917_093648	N03481I33012140S
DOT-03	N0381I33032026N_20240918_082602	N0381I33032026N
DOT-03	N03481I33012140S_20240918_084951	N03481I33012140S
DOT-03	N0381I33033055N_20240918_085812	N0381I33033055N
DOT-03	N03481I33012140S_20240918_090745	N03481I33012140S
DOT-03	N0381I33033055N_20240919_084126	N0381I33033055N
DOT-03	N0381I33032026N_20240919_084542	N0381I33032026N
DOT-03	N03481I33012140S_20240919_085546	N03481I33012140S
DOT-03	N0381I33033055N_20240919_124105	N0381I33033055N
DOT-03	N0381I33032026N_20240920_083322	N0381I33032026N
DOT-03	N0381I33033055N_20240920_084848	N0381I33033055N
DOT-03	N03481I33012140S_20240920_091907	N03481I33012140S
DOT-03	N0381I33033055N_20240923_083025	N0381I33033055N
DOT-03	N0381I33032026N_20240923_083358	N0381I33032026N
DOT-03	N03481I33012140S_20240923_084520	N03481I33012140S
DOT-03	N0381I33033035S_20240923_093823	N0381I33033035S
DOT-03	N0381I33032026N_20240924_083557	N0381I33032026N
DOT-03	N03481I33012140S_20240924_084251	N03481I33012140S
DOT-03	N0381I33033055N_20240924_084941	N0381I33033055N
DOT-03	N0381I33033035S_20240924_092839	N0381I33033035S
DOT-03	N0381I33032026N_20240924_100859	N0381I33032026N

Region/Division	Deployment ID	Location Code
DOT-03	N03481I33012140S_20240924_115217	N03481I33012140S
DOT-03	N0381I33033055N_20240924_133637	N0381I33033055N
DOT-03	N0381I33033035S_20240925_080518	N0381I33033035S
DOT-03	N0381I33032026N_20240925_084322	N0381I33032026N
DOT-03	N0381I33033055N_20240925_085534	N0381I33033055N
DOT-03	N03481I33012140S_20240925_085914	N03481I33012140S
DOT-03	N0381I33032026N_20240926_084145	N0381I33032026N
DOT-03	N0381I33033055N_20240926_084714	N0381I33033055N
DOT-03	N03481I33012140S_20240926_085829	N03481I33012140S
DOT-03	N0381I33033035S_20240926_092245	N0381I33033035S
DOT-03	N0381I33033055N_20240927_083534	N0381I33033055N
DOT-03	N0381I33033035S_20240927_085313	N0381I33033035S
DOT-03	N03481I33012140S_20240927_085448	N03481I33012140S
DOT-03	N0381I33032026N_20240927_085635	N0381I33032026N
DOT-03	N03481I33012140S_20240927_091642	N03481I33012140S
DOT-03	N03481I33012140S_20240927_093248	N03481I33012140S
DOT-03	N0381I33032026N_20240930_085806	N0381I33032026N
DOT-03	N0381I33032026N_20241001_083458	N0381I33032026N
DOT-03	N0381I33032026N_20241002_103608	N0381I33032026N
DOT-03	N0381I33032026N_20241003_084414	N0381I33032026N
DOT-03	N0381I33032026N_20241004_085118	N0381I33032026N
DOT-03	N0381I33032026N_20241007_082835	N0381I33032026N
DOT-03	N0381I33033065S_20241007_085812	N0381I33033065S
DOT-03	N03481I33012140S_20241007_090350	N03481I33012140S
DOT-03	N03481I33012140S_20241007_091436	N03481I33012140S
DOT-03	N0381I33033065S_20241007_092116	N0381I33033065S
DOT-03	N03481I33012060N_20241007_092404	N03481I33012060N
DOT-03	N0381I33033035S_20241007_093212	N0381I33033035S
DOT-03	N0381I33032026N_20241007_124723	N0381I33032026N
DOT-03	N0381I33033065S_20241008_084918	N0381I33033065S
DOT-03	N0381I33032026N_20241008_085026	N0381I33032026N
DOT-03	N03481I33012060N_20241008_090014	N03481I33012060N
DOT-03	N0381I33033035S_20241008_090146	N0381I33033035S
DOT-03	N03481I33012140S_20241008_091905	N03481I33012140S
DOT-03	N0381I33033065S_20241008_115344	N0381I33033065S
DOT-03	N03481I33012140S_20241009_081515	N03481I33012140S
DOT-03	N0381I33032026N_20241009_084940	N0381I33032026N
DOT-03	N03481I33012060N_20241009_091050	N03481I33012060N
DOT-03	N0381I33033035S_20241009_100429	N0381I33033035S
DOT-03	N03481I33012140S_20241009_101819	N03481I33012140S
DOT-03	N0381I33033035S_20241010_084538	N0381I33033035S
DOT-03	N0381I33032026N_20241010_084853	N0381I33032026N
DOT-03	N03481I33012140S_20241010_084916	N03481I33012140S

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33033065S_20241010_091150	N0381I33033065S
DOT-03	N03481I33012060N_20241010_091236	N03481I33012060N
DOT-03	N03481I33012140S_20241010_091946	N03481I33012140S
DOT-03	N03481I33012140S_20241010_101654	N03481I33012140S
DOT-03	N0381I33033035S_20241011_084929	N0381I33033035S
DOT-03	N03481I33012140S_20241011_085021	N03481I33012140S
DOT-03	N0381I33032026N_20241011_085310	N0381I33032026N
DOT-03	N03481I33012140S_20241011_085346	N03481I33012140S
DOT-03	N03481I33012140S_20241011_091651	N03481I33012140S
DOT-03	N0381I33032026N_20241014_084851	N0381I33032026N
DOT-03	N0381I33033065S_20241014_090833	N0381I33033065S
DOT-03	N03481I33012140S_20241014_092705	N03481I33012140S
DOT-03	N03481I33012060N_20241014_093748	N03481I33012060N
DOT-03	N03481I33012140S_20241015_082606	N03481I33012140S
DOT-03	N03481I33012060N_20241015_084724	N03481I33012060N
DOT-03	N0381I33033065S_20241015_085849	N0381I33033065S
DOT-03	N03481I33012140S_20241015_090604	N03481I33012140S
DOT-03	N0381I33032026N_20241016_084332	N0381I33032026N
DOT-03	N0381I33033035S_20241016_092914	N0381I33033035S
DOT-03	N03481I33012060N_20241017_083703	N03481I33012060N
DOT-03	N0381I33033065S_20241017_095919	N0381I33033065S
DOT-03	N0381I33033065S_20241018_082447	N0381I33033065S
DOT-03	N0381I33032026N_20241018_082705	N0381I33032026N
DOT-03	N0381I33033065S_20241018_084222	N0381I33033065S
DOT-03	N03481I33012140S_20241018_085233	N03481I33012140S
DOT-03	N03481I33012060N_20241018_090741	N03481I33012060N
DOT-03	N03481I33012140S_20241018_091641	N03481I33012140S
DOT-03	N03481I33012060N_20241018_091827	N03481I33012060N
DOT-03	N0381I33032026N_20241021_084245	N0381I33032026N
DOT-03	N0381I33033065S_20241021_084746	N0381I33033065S
DOT-03	N03481I33012140S_20241021_090041	N03481I33012140S
DOT-03	N03481I33012140S_20241021_091612	N03481I33012140S
DOT-03	N03481I33012140S_20241022_083712	N03481I33012140S
DOT-03	N0381I33033065S_20241022_084031	N0381I33033065S
DOT-03	N0381I33032026N_20241022_084321	N0381I33032026N
DOT-03	N03481I33012140S_20241022_091007	N03481I33012140S
DOT-03	N0381I33032026S_20241022_195257	N0381I33032026S
DOT-03	N0381I33032026N_20241023_083708	N0381I33032026N
DOT-03	N0381I33033065S_20241023_084408	N0381I33033065S
DOT-03	N03481I33012140S_20241023_084910	N03481I33012140S
DOT-03	N03481I33012140S_20241023_091558	N03481I33012140S
DOT-03	N0381I33032026S_20241023_194606	N0381I33032026S
DOT-03	N0381I33032026N_20241024_083827	N0381I33032026N

Region/Division	Deployment ID	Location Code
DOT-03	N03481I33012140S_20241024_084513	N03481I33012140S
DOT-03	N0381I33033065S_20241024_090311	N0381I33033065S
DOT-03	N03481I33012140S_20241024_091148	N03481I33012140S
DOT-03	N0381I33032026S_20241024_195433	N0381I33032026S
DOT-03	N0381I33032026N_20241025_083711	N0381I33032026N
DOT-03	N03481I33012140S_20241025_095356	N03481I33012140S
DOT-03	N0381I33032026N_20241028_082313	N0381I33032026N
DOT-03	N03481I33012140S_20241028_085555	N03481I33012140S
DOT-03	N03481I33012140S_20241028_092305	N03481I33012140S
DOT-03	N0381I33033065S_20241028_105552	N0381I33033065S
DOT-03	N0381I33032026S_20241028_195054	N0381I33032026S
DOT-03	N03481I33012140S_20241029_084831	N03481I33012140S
DOT-03	N0381I33032026N_20241029_085716	N0381I33032026N
DOT-03	N03481I33012140S_20241029_090432	N03481I33012140S
DOT-03	N0381I33033065N_20241029_104824	N0381I33033065N
DOT-03	N0381I33032026N_20241029_124945	N0381I33032026N
DOT-03	N0381I33032056N_20241029_202123	N0381I33032056N
DOT-03	N0381I33032026N_20241030_082647	N0381I33032026N
DOT-03	N03481I33012140S_20241030_084744	N03481I33012140S
DOT-03	N03481I33012140S_20241030_090935	N03481I33012140S
DOT-03	N0381I33033065N_20241030_104207	N0381I33033065N
DOT-03	N0381I33032056N_20241030_194455	N0381I33032056N
DOT-03	N0381I33032026N_20241031_082642	N0381I33032026N
DOT-03	N03481I33012140S_20241031_085021	N03481I33012140S
DOT-03	N03481I33012140S_20241031_090019	N03481I33012140S
DOT-03	N0381I33033065N_20241031_092601	N0381I33033065N
DOT-03	N0381I33032056N_20241031_203154	N0381I33032056N
DOT-03	N0381I33032026N_20241101_081500	N0381I33032026N
DOT-03	N03481I33012140S_20241101_083654	N03481I33012140S
DOT-03	N03481I33012140S_20241101_091430	N03481I33012140S
DOT-03	N0381I33033065N_20241101_093013	N0381I33033065N
DOT-03	N03481I33012140S_20241104_083354	N03481I33012140S
DOT-03	N03481I33012140S_20241104_091125	N03481I33012140S
DOT-03	N0381I33033035S_20241104_093606	N0381I33033035S
DOT-03	N0381I33032026N_20241104_100252	N0381I33032026N
DOT-03	N0381I33033035N_20241104_100544	N0381I33033035N
DOT-03	N0381I33032056N_20241104_194143	N0381I33032056N
DOT-03	N03481I33012140S_20241105_083557	N03481I33012140S
DOT-03	N0381I33033035S_20241105_085541	N0381I33033035S
DOT-03	N0381I33033035N_20241105_091248	N0381I33033035N
DOT-03	N03481I33012140S_20241105_091519	N03481I33012140S
DOT-03	N0381I33032026N_20241105_092555	N0381I33032026N
DOT-03	N0381I33032056N_20241105_194901	N0381I33032056N

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33033035S_20241106_083718	N0381I33033035S
DOT-03	N0381I33032026N_20241106_085011	N0381I33032026N
DOT-03	N03481I33012140S_20241106_085541	N03481I33012140S
DOT-03	N0381I33033035N_20241106_090525	N0381I33033035N
DOT-03	N03481I33012140S_20241106_090710	N03481I33012140S
DOT-03	N0381I33032026N_20241106_092744	N0381I33032026N
DOT-03	N0381I33033035N_20241107_083019	N0381I33033035N
DOT-03	N03481I33012140S_20241107_084541	N03481I33012140S
DOT-03	N0381I33033035S_20241107_085847	N0381I33033035S
DOT-03	N03481I33012140S_20241107_091300	N03481I33012140S
DOT-03	N0381I33032026N_20241107_091803	N0381I33032026N
DOT-03	N0381I33033035N_20241108_083454	N0381I33033035N
DOT-03	N03481I33012140S_20241108_084255	N03481I33012140S
DOT-03	N0381I33032026N_20241108_090401	N0381I33032026N
DOT-03	N0381I33033035S_20241108_090433	N0381I33033035S
DOT-03	N03481I33012140S_20241108_091306	N03481I33012140S
DOT-03	N0381I33033035N_20241111_084348	N0381I33033035N
DOT-03	N0381I33033035S_20241111_085521	N0381I33033035S
DOT-03	N03481I33012140S_20241111_085715	N03481I33012140S
DOT-03	N03481I33012140S_20241111_091136	N03481I33012140S
DOT-03	N0381I33032010N_20241111_092643	N0381I33032010N
DOT-03	N0381I33033035S_20241111_105835	N0381I33033035S
DOT-03	N0381I33033035N_20241112_083809	N0381I33033035N
DOT-03	N0381I33033035S_20241112_084611	N0381I33033035S
DOT-03	N03481I33012140S_20241112_085301	N03481I33012140S
DOT-03	N0381I33032010N_20241112_085800	N0381I33032010N
DOT-03	N03481I33012140S_20241112_091821	N03481I33012140S
DOT-03	N03481I33012140S_20241113_083721	N03481I33012140S
DOT-03	N0381I33033035S_20241113_084234	N0381I33033035S
DOT-03	N0381I33032010N_20241113_090850	N0381I33032010N
DOT-03	N0381I33033035N_20241113_092230	N0381I33033035N
DOT-03	N03481I33012140S_20241113_093020	N03481I33012140S
DOT-03	N0381I33033035S_20241114_083606	N0381I33033035S
DOT-03	N0381I33032010N_20241114_084211	N0381I33032010N
DOT-03	N0381I33033035N_20241114_084450	N0381I33033035N
DOT-03	N03481I33012140S_20241114_084912	N03481I33012140S
DOT-03	N03481I33012140S_20241114_123358	N03481I33012140S
DOT-03	N03481I33012140S_20241115_083154	N03481I33012140S
DOT-03	N0381I33033035N_20241115_084241	N0381I33033035N
DOT-03	N0381I33033035S_20241115_084242	N0381I33033035S
DOT-03	N0381I33032010N_20241115_084731	N0381I33032010N
DOT-03	N03481I33012140S_20241115_092228	N03481I33012140S
DOT-03	N03481I33012140N_20241118_084902	N03481I33012140N

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33032010N_20241118_085142	N0381I33032010N
DOT-03	N0381I33032026S_20241118_201654	N0381I33032026S
DOT-03	N03481I33012140N_20241119_090353	N03481I33012140N
DOT-03	N0381I33032010N_20241119_090411	N0381I33032010N
DOT-03	N03481I33012140N_20241119_140948	N03481I33012140N
DOT-03	N0381I33032026S_20241119_201709	N0381I33032026S
DOT-03	N03481I33012140N_20241120_085918	N03481I33012140N
DOT-03	N0381I33032026N_20241120_195024	N0381I33032026N
DOT-03	N03481I33012140N_20241121_084241	N03481I33012140N
DOT-03	N0381I33032056N_20241121_202950	N0381I33032056N
DOT-03	N03481I33012140N_20241122_085750	N03481I33012140N
DOT-03	N03481I33012140N_20241125_082954	N03481I33012140N
DOT-03	N0381I33032012S_20241125_084454	N0381I33032012S
DOT-03	N0381I33032012S_20241126_082723	N0381I33032012S
DOT-03	N03481I33012140N_20241126_084330	N03481I33012140N
DOT-03	N0381I33032012S_20241126_111829	N0381I33032012S
DOT-03	N0381I33032012S_20241127_084126	N0381I33032012S
DOT-03	N03481I33012140N_20241127_084813	N03481I33012140N
DOT-03	N0381I33032012S_20241202_084608	N0381I33032012S
DOT-03	N0381I33032012S_20241203_083702	N0381I33032012S
DOT-03	N0381I33032012S_20241204_093140	N0381I33032012S
DOT-03	N0381I33032012S_20241206_085835	N0381I33032012S
DOT-03	N0381I33032012S_20241209_083823	N0381I33032012S
DOT-03	N0381I33032056N_20241209_114116	N0381I33032056N
DOT-03	N0381I33032012S_20241210_082833	N0381I33032012S
DOT-03	N0381I33032056S_20241210_113230	N0381I33032056S
DOT-03	N0381I33032012S_20241211_084242	N0381I33032012S
DOT-03	N0381I33032056S_20241211_103424	N0381I33032056S
DOT-03	N0381I33032012S_20241212_113038	N0381I33032012S
DOT-03	N0381I33032056S_20241213_120508	N0381I33032056S
DOT-03	N0381I33033035N_20241216_085834	N0381I33033035N
DOT-03	N0381I33032012S_20241217_084518	N0381I33032012S
DOT-03	N0381I33033035N_20241217_092522	N0381I33033035N
DOT-03	N0381I33032012S_20241218_083026	N0381I33032012S
DOT-03	N0381I33033035N_20241218_085725	N0381I33033035N
DOT-03	N0381I33032012S_20241219_081952	N0381I33032012S
DOT-03	N0381I33033035N_20241219_085932	N0381I33033035N
DOT-03	N0381I33032012S_20241220_084628	N0381I33032012S
DOT-03	N0381I33032012S_20241230_084530	N0381I33032012S
DOT-03	N0381I33032012S_20241231_085128	N0381I33032012S
DOT-03	N0381I33032012S_20250102_083934	N0381I33032012S
DOT-03	N0381I33032012S_20250103_084040	N0381I33032012S
DOT-03	N0381I33032012S_20250103_104807	N0381I33032012S

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33032012S_20250103_104947	N0381I33032012S
DOT-03	N0381I33032012S_20250106_093145	N0381I33032012S
DOT-03	N0381I33032012S_20250107_084953	N0381I33032012S
DOT-03	N0381I33032012S_20250113_083703	N0381I33032012S
DOT-03	N0381I33032012S_20250114_083332	N0381I33032012S
DOT-03	N0381I33032012S_20250115_083705	N0381I33032012S
DOT-03	N0381I33032012S_20250115_091121	N0381I33032012S
DOT-03	N0381I33032012S_20250116_084512	N0381I33032012S
DOT-03	N0381I33032012S_20250117_083133	N0381I33032012S
DOT-03	N0381I33032012S_20250123_084159	N0381I33032012S
DOT-03	N0381I33032012S_20250124_082732	N0381I33032012S
DOT-03	N03481I33012080S_20250317_104734	N03481I33012080S
DOT-03	N03481I33012080S_20250318_103831	N03481I33012080S
DOT-03	N03481I33012070N_20250318_105743	N03481I33012070N
DOT-03	N03481I33012070N_20250320_103618	N03481I33012070N
DOT-03	N03481I33012080S_20250321_105030	N03481I33012080S
DOT-03	N03481I33012011N_20250321_105624	N03481I33012011N
DOT-03	N0381I33032056S_20250324_111939	N0381I33032056S
DOT-03	N03481I33012080S_20250324_114308	N03481I33012080S
DOT-03	N03481I33012080S_20250325_095306	N03481I33012080S
DOT-03	N0381I33032056N_20250325_113015	N0381I33032056N
DOT-03	N03481I33012060N_20250325_114007	N03481I33012060N
DOT-03	N03481I33012060N_20250326_091206	N03481I33012060N
DOT-03	N03481I33012080S_20250326_095235	N03481I33012080S
DOT-03	N0381I33032056N_20250326_102228	N0381I33032056N
DOT-03	N03481I33012080S_20250326_105102	N03481I33012080S
DOT-03	N03481I33012060N_20250327_092340	N03481I33012060N
DOT-03	N03481I33012080S_20250327_094613	N03481I33012080S
DOT-03	N0381I33032056N_20250327_104717	N0381I33032056N
DOT-03	N03481I33012060N_20250328_091951	N03481I33012060N
DOT-03	N03481I33012080S_20250328_104413	N03481I33012080S
DOT-03	N03481I33012060N_20250331_093509	N03481I33012060N
DOT-03	N0381I33033035S_20250331_094631	N0381I33033035S
DOT-03	N03481I33012080S_20250331_100937	N03481I33012080S
DOT-03	N0381I33033035S_20250401_091610	N0381I33033035S
DOT-03	N03481I33012080S_20250401_110405	N03481I33012080S
DOT-03	N0381I33033035S_20250402_100237	N0381I33033035S
DOT-03	N03481I33012080S_20250402_101102	N03481I33012080S
DOT-03	N0381I33033035S_20250402_114937	N0381I33033035S
DOT-03	N0381I33033035S_20250403_091327	N0381I33033035S
DOT-03	N03481I33012080S_20250403_094950	N03481I33012080S
DOT-03	N0381I33033035S_20250404_094423	N0381I33033035S
DOT-03	N0381I33033035S_20250407_065246	N0381I33033035S

Region/Division	Deployment ID	Location Code
DOT-03	N03481I33012080S_20250407_101538	N03481I33012080S
DOT-03	N03481I33012070N_20250407_110651	N03481I33012070N
DOT-03	N0381I33033035S_20250408_070931	N0381I33033035S
DOT-03	N0381I33033035S_20250409_072355	N0381I33033035S
DOT-03	N0381I33033035S_20250410_065854	N0381I33033035S
DOT-03	N0381I33033035S_20250411_065822	N0381I33033035S
DOT-03	N0381I33033035S_20250414_075454	N0381I33033035S
DOT-03	N03481I33012060N_20250414_101357	N03481I33012060N
DOT-03	N0381I33033096N_20250414_104157	N0381I33033096N
DOT-03	N0381I33033035S_20250415_080933	N0381I33033035S
DOT-03	N03481I33012060N_20250415_090511	N03481I33012060N
DOT-03	N0381I33033083S_20250415_102112	N0381I33033083S
DOT-03	N03481I33012060N_20250415_134432	N03481I33012060N
DOT-03	N0381I33033035S_20250416_073749	N0381I33033035S
DOT-03	N03481I33012060N_20250416_082147	N03481I33012060N
DOT-03	N0381I33033035N_20250416_103235	N0381I33033035N
DOT-03	N0381I33033035S_20250417_075301	N0381I33033035S
DOT-03	N03481I33012060N_20250417_090343	N03481I33012060N
DOT-03	N03481I33012060N_20250417_092340	N03481I33012060N
DOT-03	N03481I33012060N_20250417_133705	N03481I33012060N
DOT-03	N03481I33012060N_20250418_085557	N03481I33012060N
DOT-03	N0381I33032010N_20250421_064957	N0381I33032010N
DOT-03	N0381I33033035N_20250421_065711	N0381I33033035N
DOT-03	N0381I33033051S_20250421_091235	N0381I33033051S
DOT-03	N0381I33032010N_20250422_065151	N0381I33032010N
DOT-03	N0381I33033065S_20250422_085816	N0381I33033065S
DOT-03	N03481I33012080S_20250422_100334	N03481I33012080S
DOT-03	N0381I33032010N_20250423_065154	N0381I33032010N
DOT-03	N0381I33033035S_20250423_072712	N0381I33033035S
DOT-03	N0381I33033035S_20250424_071245	N0381I33033035S
DOT-03	N0381I33032010N_20250424_074931	N0381I33032010N
DOT-03	N0381I33032010N_20250424_113223	N0381I33032010N
DOT-03	N0381I33032010N_20250425_064745	N0381I33032010N
DOT-03	N0381I33033065S_20250425_073113	N0381I33033065S
DOT-03	N0381I33033035N_20250425_074920	N0381I33033035N
DOT-03	N0381I33033065S_20250425_092408	N0381I33033065S
DOT-03	N0381I33032010N_20250428_070030	N0381I33032010N
DOT-03	N03481I33012060N_20250428_071527	N03481I33012060N
DOT-03	N0381I33033065S_20250428_073647	N0381I33033065S
DOT-03	N0381I33033065N_20250428_084210	N0381I33033065N
DOT-03	N0381I33033065S_20250428_093613	N0381I33033065S
DOT-03	N0381I33033065N_20250428_134554	N0381I33033065N
DOT-03	N0381I33033065S_20250429_063236	N0381I33033065S

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33032010N_20250429_064216	N0381I33032010N
DOT-03	N03481I33012060N_20250429_065537	N03481I33012060N
DOT-03	N0381I33033065N_20250429_071401	N0381I33033065N
DOT-03	N03481I33012060N_20250429_083443	N03481I33012060N
DOT-03	N0381I33033065S_20250429_091247	N0381I33033065S
DOT-03	N0381I33033065S_20250430_065801	N0381I33033065S
DOT-03	N0381I33032010N_20250430_070308	N0381I33032010N
DOT-03	N03481I33012060N_20250430_072448	N03481I33012060N
DOT-03	N0381I33033065N_20250430_072744	N0381I33033065N
DOT-03	N0381I33033065S_20250430_091607	N0381I33033065S
DOT-03	N0381I33032010N_20250501_065041	N0381I33032010N
DOT-03	N03481I33012060N_20250501_065423	N03481I33012060N
DOT-03	N0381I33033065N_20250501_070129	N0381I33033065N
DOT-03	N0381I33033065S_20250501_070557	N0381I33033065S
DOT-03	N0381I33033065S_20250501_090523	N0381I33033065S
DOT-03	N0381I33033065N_20250502_062559	N0381I33033065N
DOT-03	N0381I33032010N_20250502_065121	N0381I33032010N
DOT-03	N0381I33033065S_20250502_073008	N0381I33033065S
DOT-03	N0381I33033065S_20250502_102256	N0381I33033065S
DOT-03	N0381I33032010N_20250505_063543	N0381I33032010N
DOT-03	N03481I33012060S_20250505_071331	N03481I33012060S
DOT-03	N0381I33033065S_20250505_073041	N0381I33033065S
DOT-03	N0381I33033035N_20250505_083048	N0381I33033035N
DOT-03	N0381I33033065S_20250505_090526	N0381I33033065S
DOT-03	N0381I33033035N_20250506_065729	N0381I33033035N
DOT-03	N0381I33032010N_20250506_070259	N0381I33032010N
DOT-03	N0381I33033065S_20250506_071127	N0381I33033065S
DOT-03	N0381I33033065S_20250506_091701	N0381I33033065S
DOT-03	N0381I33033065S_20250506_093035	N0381I33033065S
DOT-03	N03481I33012060S_20250506_095120	N03481I33012060S
DOT-03	N0381I33033065S_20250506_135657	N0381I33033065S
DOT-03	N0381I33032010N_20250507_064711	N0381I33032010N
DOT-03	N0381I33033035N_20250507_071414	N0381I33033035N
DOT-03	N0381I33033065S_20250507_072806	N0381I33033065S
DOT-03	N0381I33033065S_20250507_091948	N0381I33033065S
DOT-03	N03481I33012060S_20250507_112457	N03481I33012060S
DOT-03	N0381I33032010N_20250508_063452	N0381I33032010N
DOT-03	N0381I33033035N_20250508_065947	N0381I33033035N
DOT-03	N03481I33012060S_20250508_075223	N03481I33012060S
DOT-03	N0381I33033065S_20250509_063909	N0381I33033065S
DOT-03	N03481I33012060S_20250509_065259	N03481I33012060S
DOT-03	N0381I33033035N_20250509_065358	N0381I33033035N
DOT-03	N0381I33032010N_20250509_070425	N0381I33032010N

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33033065S_20250509_090939	N0381I33033065S
DOT-03	N0381I33032010N_20250512_083626	N0381I33032010N
DOT-03	N03481I33012060N_20250512_083647	N03481I33012060N
DOT-03	N0381I33031001N_20250512_094828	N0381I33031001N
DOT-03	N0381I33033035N_20250512_102917	N0381I33033035N
DOT-03	N0381I33032010N_20250513_070145	N0381I33032010N
DOT-03	N0381I33033065S_20250513_073011	N0381I33033065S
DOT-03	N0381I33033035N_20250513_080022	N0381I33033035N
DOT-03	N0381I33033035N_20250513_080301	N0381I33033035N
DOT-03	N0381I33031001N_20250513_082321	N0381I33031001N
DOT-03	N0381I33033065S_20250513_093335	N0381I33033065S
DOT-03	N0381I33033065S_20250513_132245	N0381I33033065S
DOT-03	N0381I33032010N_20250514_070658	N0381I33032010N
DOT-03	N0381I33033065S_20250514_073335	N0381I33033065S
DOT-03	N0381I33033035N_20250514_082947	N0381I33033035N
DOT-03	N0381I33033065S_20250514_094257	N0381I33033065S
DOT-03	N0381I33032010N_20250515_065712	N0381I33032010N
DOT-03	N0381I33033065S_20250515_072043	N0381I33033065S
DOT-03	N03481I33012060S_20250515_073603	N03481I33012060S
DOT-03	N0381I33033035N_20250515_081323	N0381I33033035N
DOT-03	N0381I33033065S_20250515_094834	N0381I33033065S
DOT-03	N0381I33033065S_20250515_111104	N0381I33033065S
DOT-03	N0381I33033065S_20250515_132456	N0381I33033065S
DOT-03	N0381I33032010N_20250516_063427	N0381I33032010N
DOT-03	N03481I33012060N_20250516_071114	N03481I33012060N
DOT-03	N0381I33033065S_20250516_071643	N0381I33033065S
DOT-03	N0381I33033035N_20250516_075808	N0381I33033035N
DOT-03	N0381I33033065S_20250516_092931	N0381I33033065S
DOT-03	N0381I33033065S_20250519_063810	N0381I33033065S
DOT-03	N0381I33032010N_20250519_070230	N0381I33032010N
DOT-03	N03481I33012060N_20250519_081520	N03481I33012060N
DOT-03	N0381I33033065N_20250519_083651	N0381I33033065N
DOT-03	N0381I33033065S_20250519_090242	N0381I33033065S
DOT-03	N0381I33033065S_20250519_120345	N0381I33033065S
DOT-03	N0381I33032010N_20250520_063542	N0381I33032010N
DOT-03	N03481I33012060N_20250520_064033	N03481I33012060N
DOT-03	N0381I33033065S_20250520_065249	N0381I33033065S
DOT-03	N0381I33033065N_20250520_074123	N0381I33033065N
DOT-03	N0381I33033065S_20250520_085713	N0381I33033065S
DOT-03	N0381I33032010N_20250521_063254	N0381I33032010N
DOT-03	N0381I33033065S_20250521_064903	N0381I33033065S
DOT-03	N0381I33033065N_20250521_070501	N0381I33033065N
DOT-03	N0381I33032010N_20250521_085648	N0381I33032010N

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33033065S_20250521_090048	N0381I33033065S
DOT-03	N0381I33032010N_20250521_140127	N0381I33032010N
DOT-03	N0381I33032010N_20250522_063026	N0381I33032010N
DOT-03	N0381I33032010N_20250522_065553	N0381I33032010N
DOT-03	N0381I33033065S_20250522_072043	N0381I33033065S
DOT-03	N0381I33033065N_20250522_073739	N0381I33033065N
DOT-03	N0381I33033065N_20250522_073837	N0381I33033065N
DOT-03	N0381I33033065S_20250522_085940	N0381I33033065S
DOT-03	N0381I33033065S_20250523_064059	N0381I33033065S
DOT-03	N0381I33032010N_20250523_064202	N0381I33032010N
DOT-03	N0381I33033065N_20250523_071353	N0381I33033065N
DOT-03	N0381I33032015N_20250527_072036	N0381I33032015N
DOT-03	N0381I33033063S_20250527_075239	N0381I33033063S
DOT-03	N0381I33033065N_20250527_080600	N0381I33033065N
DOT-03	N03481I33012080S_20250527_104412	N03481I33012080S
DOT-03	N0381I33033063S_20250527_112037	N0381I33033063S
DOT-03	N0381I33033063S_20250528_072721	N0381I33033063S
DOT-03	N0381I33033035N_20250528_073815	N0381I33033035N
DOT-03	N0381I33032015N_20250528_081207	N0381I33032015N
DOT-03	N0381I33033063S_20250528_091919	N0381I33033063S
DOT-03	N0381I33032010N_20250529_063036	N0381I33032010N
DOT-03	N0381I33033063N_20250529_071333	N0381I33033063N
DOT-03	N0381I33033063S_20250529_071640	N0381I33033063S
DOT-03	N0381I33033063S_20250529_071744	N0381I33033063S
DOT-03	N0381I33033063N_20250529_073729	N0381I33033063N
DOT-03	N0381I33033063S_20250529_091821	N0381I33033063S
DOT-03	N0381I33032010N_20250530_070045	N0381I33032010N
DOT-03	N0381I33033063S_20250530_074517	N0381I33033063S
DOT-03	N0381I33033063S_20250530_091148	N0381I33033063S
DOT-03	N0381I33033063N_20250530_104430	N0381I33033063N
DOT-03	N0381I33033063S_20250530_105240	N0381I33033063S
DOT-03	N0381I33033063S_20250530_143327	N0381I33033063S
DOT-03	N0381I33032010N_20250602_064424	N0381I33032010N
DOT-03	N0381I33033035N_20250602_071017	N0381I33033035N
DOT-03	N0381I33033065S_20250602_073016	N0381I33033065S
DOT-03	N0381I33033065S_20250602_090918	N0381I33033065S
DOT-03	N0381I33033065S_20250603_065413	N0381I33033065S
DOT-03	N0381I33033035N_20250603_070531	N0381I33033035N
DOT-03	N0381I33032010N_20250603_073131	N0381I33032010N
DOT-03	N0381I33033065S_20250603_092530	N0381I33033065S
DOT-03	N0381I33033065S_20250603_142706	N0381I33033065S
DOT-03	N0381I33033035N_20250604_065846	N0381I33033035N
DOT-03	N0381I33032010N_20250604_071500	N0381I33032010N

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33033065S_20250604_071612	N0381I33033065S
DOT-03	N0381I33033065S_20250604_090101	N0381I33033065S
DOT-03	N0381I33032010N_20250605_064938	N0381I33032010N
DOT-03	N0381I33033035N_20250605_065147	N0381I33033035N
DOT-03	N0381I33033065S_20250605_065212	N0381I33033065S
DOT-03	N0381I33033065S_20250605_092711	N0381I33033065S
DOT-03	N0381I33033035N_20250606_060608	N0381I33033035N
DOT-03	N0381I33033035N_20250606_060915	N0381I33033035N
DOT-03	N0381I33032010N_20250606_070708	N0381I33032010N
DOT-03	N0381I33033065S_20250606_072106	N0381I33033065S
DOT-03	N0381I33033065S_20250606_090359	N0381I33033065S
DOT-03	N0381I33032015N_20250609_070405	N0381I33032015N
DOT-03	N0381I33033063S_20250609_073552	N0381I33033063S
DOT-03	N0381I33033063S_20250609_091543	N0381I33033063S
DOT-03	N0381I33032015N_20250610_065008	N0381I33032015N
DOT-03	N0381I33033063S_20250610_071546	N0381I33033063S
DOT-03	N0381I33033063S_20250610_090908	N0381I33033063S
DOT-03	N0381I33032015N_20250611_063016	N0381I33032015N
DOT-03	N0381I33032015N_20250611_070405	N0381I33032015N
DOT-03	N0381I33033063S_20250611_070934	N0381I33033063S
DOT-03	N0381I33033063S_20250611_090104	N0381I33033063S
DOT-03	N0381I33033063S_20250612_070844	N0381I33033063S
DOT-03	N0381I33032015N_20250612_071013	N0381I33032015N
DOT-03	N0381I33033063S_20250612_092411	N0381I33033063S
DOT-03	N0381I33032015N_20250613_064611	N0381I33032015N
DOT-03	N0381I33033063N_20250613_075311	N0381I33033063N
DOT-03	N0381I33032015N_20250613_094743	N0381I33032015N
DOT-03	N0381I33032015N_20250613_112945	N0381I33032015N
DOT-03	N0381I33032015N_20250616_070247	N0381I33032015N
DOT-03	N0381I33033065S_20250616_073716	N0381I33033065S
DOT-03	N0381I33033065S_20250616_092317	N0381I33033065S
DOT-03	N0381I33032015N_20250617_065212	N0381I33032015N
DOT-03	N0381I33032015N_20250617_070258	N0381I33032015N
DOT-03	N0381I33032015N_20250618_063726	N0381I33032015N
DOT-03	N0381I33032015N_20250619_063713	N0381I33032015N
DOT-03	N0381I33032015N_20250620_064640	N0381I33032015N
DOT-03	N0381I33032015N_20250620_070511	N0381I33032015N
DOT-03	N0381I33032015N_20250623_064246	N0381I33032015N
DOT-03	N0381I33032015N_20250624_063946	N0381I33032015N
DOT-03	N0381I33032015N_20250625_063635	N0381I33032015N
DOT-03	N0381I33033063S_20250625_064223	N0381I33033063S
DOT-03	N0381I33033063S_20250625_090031	N0381I33033063S
DOT-03	N0381I33032015N_20250626_060356	N0381I33032015N

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33032015N_20250626_061443	N0381I33032015N
DOT-03	N0381I33033063S_20250626_063708	N0381I33033063S
DOT-03	N0381I33033063S_20250626_085504	N0381I33033063S
DOT-03	N0381I33033063S_20250627_062008	N0381I33033063S
DOT-03	N0381I33032015N_20250627_064236	N0381I33032015N
DOT-03	N0381I33033063S_20250630_070312	N0381I33033063S
DOT-03	N0381I33032015N_20250630_072626	N0381I33032015N
DOT-03	N0381I33033063S_20250630_081054	N0381I33033063S
DOT-03	N0381I33033063S_20250630_090229	N0381I33033063S
DOT-03	N0381I33033063S_20250701_064548	N0381I33033063S
DOT-03	N0381I33032015N_20250701_070631	N0381I33032015N
DOT-03	N0381I33033063S_20250701_091049	N0381I33033063S
DOT-03	N0381I33032015N_20250701_092721	N0381I33032015N
DOT-03	N0381I33033063S_20250702_065730	N0381I33033063S
DOT-03	N0381I33032015N_20250702_070824	N0381I33032015N
DOT-03	N0381I33033063S_20250702_091547	N0381I33033063S
DOT-03	N0381I33032015N_20250703_063919	N0381I33032015N
DOT-03	N0381I33032015N_20250707_063503	N0381I33032015N
DOT-03	N0381I33033063S_20250707_064134	N0381I33033063S
DOT-03	N0381I33033063S_20250707_093025	N0381I33033063S
DOT-03	N0381I33032015N_20250709_064729	N0381I33032015N
DOT-03	N0381I33032015N_20250710_064249	N0381I33032015N
DOT-03	N0381I33032015N_20250711_062526	N0381I33032015N
DOT-03	N0381I33033063S_20250711_063440	N0381I33033063S
DOT-03	N0381I33032015N_20250711_102517	N0381I33032015N
DOT-03	N0381I33033063S_20250714_063431	N0381I33033063S
DOT-03	N0381I33032015N_20250714_064756	N0381I33032015N
DOT-03	N0381I33033063S_20250714_092251	N0381I33033063S
DOT-03	N0381I33032015N_20250714_100833	N0381I33032015N
DOT-03	N0381I33032015N_20250715_063053	N0381I33032015N
DOT-03	N0381I33033063S_20250715_063712	N0381I33033063S
DOT-03	N0381I33033063S_20250715_090528	N0381I33033063S
DOT-03	N0381I33033063S_20250716_061538	N0381I33033063S
DOT-03	N0381I33033063S_20250716_062232	N0381I33033063S
DOT-03	N0381I33032015N_20250716_062558	N0381I33032015N
DOT-03	N0381I33033063S_20250716_091053	N0381I33033063S
DOT-03	N0381I33032015N_20250717_061609	N0381I33032015N
DOT-03	N0381I33033063S_20250717_061629	N0381I33033063S
DOT-03	N0381I33033063S_20250717_090835	N0381I33033063S
DOT-03	N0381I33033063S_20250718_061123	N0381I33033063S
DOT-03	N0381I33032015N_20250718_071212	N0381I33032015N
DOT-03	N0381I33033063S_20250718_092237	N0381I33033063S
DOT-03	N0381I33032015N_20250718_114159	N0381I33032015N

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33033063S_20250721_062456	N0381I33033063S
DOT-03	N0381I33032015N_20250721_070457	N0381I33032015N
DOT-03	N0381I33033063S_20250721_090502	N0381I33033063S
DOT-03	N0381I33033063S_20250722_061030	N0381I33033063S
DOT-03	N0381I33032015N_20250722_070409	N0381I33032015N
DOT-03	N0381I33033063S_20250722_090323	N0381I33033063S
DOT-03	N0381I33033063S_20250723_061033	N0381I33033063S
DOT-03	N0381I33032015N_20250723_065812	N0381I33032015N
DOT-03	N0381I33033033N_20250723_070602	N0381I33033033N
DOT-03	N0381I33033033N_20250723_071619	N0381I33033033N
DOT-03	N0381I33032015N_20250723_073937	N0381I33032015N
DOT-03	N0381I33032015N_20250723_074017	N0381I33032015N
DOT-03	N0381I33033063S_20250723_090937	N0381I33033063S
DOT-03	N0381I33032015N_20250724_063421	N0381I33032015N
DOT-03	N0381I33033033N_20250724_064953	N0381I33033033N
DOT-03	N0381I33033033N_20250724_070542	N0381I33033033N
DOT-03	N0381I33033033N_20250724_143038	N0381I33033033N
DOT-03	N0381I33033033N_20250725_064123	N0381I33033033N
DOT-03	N0381I33032015N_20250725_065509	N0381I33032015N
DOT-03	N0381I33033063S_20250728_063734	N0381I33033063S
DOT-03	N0381I33033063S_20250728_063846	N0381I33033063S
DOT-03	N0381I33032015N_20250728_065557	N0381I33032015N
DOT-03	N0381I33033033N_20250728_075646	N0381I33033033N
DOT-03	N0381I33033063S_20250728_085951	N0381I33033063S
DOT-03	N0381I33033063S_20250729_065640	N0381I33033063S
DOT-03	N0381I33033033N_20250729_065948	N0381I33033033N
DOT-03	N0381I33032015N_20250729_071548	N0381I33032015N
DOT-03	N0381I33033063S_20250729_090328	N0381I33033063S
DOT-03	N0381I33033063S_20250730_062717	N0381I33033063S
DOT-03	N0381I33032015N_20250730_063140	N0381I33032015N
DOT-03	N0381I33033033N_20250730_070916	N0381I33033033N
DOT-03	N0381I33033063S_20250730_085923	N0381I33033063S
DOT-03	N0381I33033033N_20250731_062931	N0381I33033033N
DOT-03	N0381I33033063S_20250731_065352	N0381I33033063S
DOT-03	N0381I33032015N_20250731_072147	N0381I33032015N
DOT-03	N0381I33033063S_20250731_090659	N0381I33033063S
DOT-03	N0381I33033063S_20250801_065329	N0381I33033063S
DOT-03	N0381I33032015N_20250801_070002	N0381I33032015N
DOT-03	N0381I33033033N_20250801_080303	N0381I33033033N
DOT-03	N0381I33033063S_20250801_090321	N0381I33033063S
DOT-03	N0381I33032015N_20250804_073036	N0381I33032015N
DOT-03	N0381I33032015N_20250804_073811	N0381I33032015N
DOT-03	N0381I33033033N_20250804_082436	N0381I33033033N

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33033063S_20250804_125543	N0381I33033063S
DOT-03	N0381I33032015N_20250805_064044	N0381I33032015N
DOT-03	N0381I33033033N_20250805_064710	N0381I33033033N
DOT-03	N0381I33033063S_20250805_140030	N0381I33033063S
DOT-03	N0381I33033033N_20250806_064020	N0381I33033033N
DOT-03	N0381I33032015N_20250806_071531	N0381I33032015N
DOT-03	N0381I33033063S_20250806_075204	N0381I33033063S
DOT-03	N0381I33033063S_20250806_090306	N0381I33033063S
DOT-03	N0381I33033033N_20250807_063534	N0381I33033033N
DOT-03	N0381I33032015N_20250807_073800	N0381I33032015N
DOT-03	N0381I33033033N_20250807_075650	N0381I33033033N
DOT-03	N0381I33032015N_20250808_062457	N0381I33032015N
DOT-03	N0381I33032015N_20250808_063612	N0381I33032015N
DOT-03	N0381I33033033N_20250808_064627	N0381I33033033N
DOT-03	N0381I33033063S_20250808_071517	N0381I33033063S
DOT-03	N0381I33033063S_20250808_094918	N0381I33033063S
DOT-03	N0381I33033063S_20250808_100351	N0381I33033063S
DOT-03	N0381I33032015N_20250811_061523	N0381I33032015N
DOT-03	N0381I33032015N_20250811_062801	N0381I33032015N
DOT-03	N0381I33033063S_20250811_072859	N0381I33033063S
DOT-03	N0381I33033033N_20250811_080126	N0381I33033033N
DOT-03	N0381I33033063S_20250811_090708	N0381I33033063S
DOT-03	N0381I33033063S_20250812_061221	N0381I33033063S
DOT-03	N0381I33032015N_20250812_062518	N0381I33032015N
DOT-03	N0381I33033063S_20250812_091338	N0381I33033063S
DOT-03	N0381I33033063S_20250813_061334	N0381I33033063S
DOT-03	N0381I33032015N_20250813_065421	N0381I33032015N
DOT-03	N0381I33033063S_20250813_091245	N0381I33033063S
DOT-03	N0381I33032015N_20250814_062356	N0381I33032015N
DOT-03	N0381I33032015N_20250815_074130	N0381I33032015N
DOT-03	N0381I33033033N_20250815_100655	N0381I33033033N
DOT-03	N0381I33033033N_20250815_100731	N0381I33033033N
DOT-03	N0381I33032015N_20250818_071458	N0381I33032015N
DOT-03	N0381I33033033N_20250818_092651	N0381I33033033N
DOT-03	N0381I33033063S_20250819_061933	N0381I33033063S
DOT-03	N0381I33032015N_20250819_062609	N0381I33032015N
DOT-03	N0381I33033033N_20250819_065256	N0381I33033033N
DOT-03	N0381I33032015N_20250819_100452	N0381I33032015N
DOT-03	N0381I33033063S_20250820_065338	N0381I33033063S
DOT-03	N0381I33033033N_20250820_070030	N0381I33033033N
DOT-03	N0381I33032015N_20250821_062315	N0381I33032015N
DOT-03	N0381I33033063S_20250821_064738	N0381I33033063S
DOT-03	N0381I33032015N_20250822_073417	N0381I33032015N

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33033063S_20250825_062747	N0381I33033063S
DOT-03	N0381I33032026N_20250825_072549	N0381I33032026N
DOT-03	N0381I33032026N_20250825_130700	N0381I33032026N
DOT-03	N0381I33033063S_20250826_063704	N0381I33033063S
DOT-03	N0381I33032026N_20250826_065609	N0381I33032026N
DOT-03	N0381I33032026N_20250827_064550	N0381I33032026N
DOT-03	N0381I33033063S_20250827_072234	N0381I33033063S
DOT-03	N0381I33032026N_20250827_072729	N0381I33032026N
DOT-03	N0381I33032026N_20250828_070609	N0381I33032026N
DOT-03	N0381I33033063N_20250828_071241	N0381I33033063N
DOT-03	N0381I33033063N_20250828_072417	N0381I33033063N
DOT-03	N0381I33032026N_20250829_064424	N0381I33032026N
DOT-03	N0381I33033063N_20250829_091546	N0381I33033063N
DOT-03	N0381I33033063N_20250902_070655	N0381I33033063N
DOT-03	N0381I33033063N_20250903_085226	N0381I33033063N
DOT-03	N0381I33033063N_20250904_064722	N0381I33033063N
DOT-03	N0381I33032026N_20250904_071047	N0381I33032026N
DOT-03	N0381I33032026N_20250904_100306	N0381I33032026N
DOT-03	N0381I33032026N_20250904_135137	N0381I33032026N
DOT-03	N0381I33033063N_20250905_070558	N0381I33033063N
DOT-03	N0381I33032026N_20250905_070954	N0381I33032026N
DOT-03	N0381I33033063N_20250905_071921	N0381I33033063N
DOT-03	N0381I33032026N_20250905_075549	N0381I33032026N
DOT-03	N0381I33032026N_20250905_091438	N0381I33032026N
DOT-03	N0381I33032026N_20250905_120817	N0381I33032026N
DOT-03	N0381I33033063N_20250908_070350	N0381I33033063N
DOT-03	N0381I33032026N_20250908_075013	N0381I33032026N
DOT-03	N0381I33032026N_20250908_093110	N0381I33032026N
DOT-03	N0381I33032026N_20250908_100255	N0381I33032026N
DOT-03	N0381I33032026N_20250909_070425	N0381I33032026N
DOT-03	N0381I33033063N_20250909_073828	N0381I33033063N
DOT-03	N0381I33032026N_20250909_091201	N0381I33032026N
DOT-03	N0381I33032026N_20250909_143527	N0381I33032026N
DOT-03	N0381I33033063N_20250910_071440	N0381I33033063N
DOT-03	N0381I33032026N_20250910_072127	N0381I33032026N
DOT-03	N0381I33032026N_20250910_094522	N0381I33032026N
DOT-03	N0381I33033063N_20250911_065020	N0381I33033063N
DOT-03	N0381I33032026N_20250911_071704	N0381I33032026N
DOT-03	N0381I33032026N_20250911_091621	N0381I33032026N
DOT-03	N0381I33033063N_20250912_072746	N0381I33033063N
DOT-03	N0381I33033063N_20250915_064000	N0381I33033063N
DOT-03	N0381I33032026N_20250915_091003	N0381I33032026N
DOT-03	N0381I33032026N_20250915_095759	N0381I33032026N

Region/Division	Deployment ID	Location Code
DOT-03	N0381I33032026N_20250915_151935	N0381I33032026N
DOT-03	N0381I33033063N_20250916_065920	N0381I33033063N
DOT-03	N0381I33032026N_20250916_093911	N0381I33032026N
DOT-03	N0381I33032026N_20250916_145819	N0381I33032026N
DOT-03	N0381I33033063N_20250917_070912	N0381I33033063N
DOT-03	N0381I33033063N_20250918_075159	N0381I33033063N
DOT-03	N0381I33033063N_20250919_065941	N0381I33033063N
DOT-03	N0381I33033063N_20250922_074836	N0381I33033063N
DOT-03	N0381I33033063N_20250923_071808	N0381I33033063N
DOT-03	N0381I33033063N_20250924_073807	N0381I33033063N
DOT-03	N0381I33033063N_20250925_073930	N0381I33033063N
DOT-03	N0381I33033063N_20250926_071538	N0381I33033063N
DOT-03	N0381I33033063N_20250929_075312	N0381I33033063N
DOT-03	N0381I33032026N_20250929_091004	N0381I33032026N
DOT-03	N0381I33032026N_20250929_093305	N0381I33032026N
DOT-03	N0381I33032026N_20250929_151314	N0381I33032026N
DOT-03	N0381I33033063N_20250930_071946	N0381I33033063N
DOT-03	N0381I33032026N_20250930_080257	N0381I33032026N
DOT-03	N0381I33032026N_20250930_092540	N0381I33032026N
DOT-03	N0381I33032026N_20250930_150239	N0381I33032026N
DOT-03	N0381I33033063N_20251001_071257	N0381I33033063N
DOT-03	N0381I33032026N_20251001_081838	N0381I33032026N
DOT-03	N0381I33032026N_20251001_093946	N0381I33032026N
DOT-03	N0381I33032026N_20251001_151028	N0381I33032026N
DOT-03	N0381I33033063N_20251002_070529	N0381I33033063N
DOT-03	N0381I33032026N_20251002_083459	N0381I33032026N
DOT-03	N0381I33032026N_20251002_091055	N0381I33032026N
DOT-03	N0381I33032026N_20251002_150458	N0381I33032026N
DOT-03	N0381I33033063N_20251003_072106	N0381I33033063N
DOT-03	N0381I33032026N_20251003_080140	N0381I33032026N
DOT-03	N0381I33032026N_20251003_092006	N0381I33032026N
DOT-03	N0381I33032026N_20251003_122500	N0381I33032026N
DOT-03	N03690I33012035E_20251006_064645	N03690I33012035E
DOT-03	N0381I33033063N_20251006_073944	N0381I33033063N
DOT-03	N0381I33032026N_20251006_081532	N0381I33032026N
DOT-03	N0381I33033063N_20251007_062953	N0381I33033063N
DOT-03	N03690I33012035E_20251007_070120	N03690I33012035E
DOT-03	N03690I33012035E_20251008_063217	N03690I33012035E
DOT-03	N0381I33033063N_20251008_071414	N0381I33033063N
DOT-03	N0381I33033063N_20251009_065151	N0381I33033063N
DOT-03	N03690I33012035E_20251009_070440	N03690I33012035E
DOT-03	N03690I33012035E_20251010_070902	N03690I33012035E
DOT-03	N0381I33033063N_20251010_080006	N0381I33033063N

Region/Division	Deployment ID	Location Code
DOT-03	N03690I33012035E_20251013_071012	N03690I33012035E
DOT-03	N0381I33033063N_20251013_075320	N0381I33033063N
DOT-03	N03690I33012035E_20251014_065040	N03690I33012035E
DOT-03	N0381I33033063N_20251014_072018	N0381I33033063N
DOT-03	N03690I33012035E_20251014_111603	N03690I33012035E
DOT-03	N03690I33012035E_20251015_070641	N03690I33012035E
DOT-03	N0381I33033063N_20251015_072542	N0381I33033063N
DOT-03	N03690I33012035E_20251016_070812	N03690I33012035E
DOT-03	N0381I33033063N_20251016_072728	N0381I33033063N
DOT-03	N0381I33033063N_20251017_065257	N0381I33033063N
DOT-03	N03690I33012035E_20251017_065611	N03690I33012035E
DOT-03	N0381I33033063N_20251020_062442	N0381I33033063N
DOT-03	N03690I33012035E_20251020_070427	N03690I33012035E
DOT-03	N0381I33032026N_20251020_081031	N0381I33032026N
DOT-03	N03690I33012035E_20251021_070359	N03690I33012035E
DOT-03	N0381I33032026N_20251021_080541	N0381I33032026N
DOT-03	N03690I33012035E_20251022_065408	N03690I33012035E
DOT-03	N0381I33032026N_20251022_075253	N0381I33032026N
DOT-03	N03690I33012035E_20251023_065853	N03690I33012035E
DOT-03	N0381I33032026N_20251023_082408	N0381I33032026N
DOT-03	N03690I33012035E_20251024_065947	N03690I33012035E
DOT-03	N0381I33032026N_20251024_080421	N0381I33032026N
DOT-03	N03690I33012035E_20251027_070711	N03690I33012035E
DOT-03	N0381I33032026N_20251027_085751	N0381I33032026N
DOT-03	N03690I33012035E_20251028_070650	N03690I33012035E
DOT-03	N0381I33032026N_20251028_093610	N0381I33032026N
DOT-03	N0381I33032026N_20251028_102804	N0381I33032026N
DOT-03	N0381I33032026N_20251028_162412	N0381I33032026N
DOT-03	N0381I33032026N_20251029_082631	N0381I33032026N
DOT-03	N03690I33012035E_20251110_081151	N03690I33012035E
DOT-03	N03690I33012035E_20251113_072428	N03690I33012035E
DOT-03	N03690I33012035E_20251114_070432	N03690I33012035E
DOT-03	N0381I33032026N_20251117_104626	N0381I33032026N
DOT-03	N0381I33032026N_20251118_080821	N0381I33032026N
DOT-03	N0381I33032026N_20251119_080355	N0381I33032026N
DOT-03	N0381I33032026N_20251125_074737	N0381I33032026N
DOT-03	N0381I33032026N_20251201_075019	N0381I33032026N
DOT-03	N0381I33032026N_20251215_080909	N0381I33032026N
DOT-03	N0381I33032026N_20251216_075309	N0381I33032026N
DOT-03	N0381I33032026N_20251217_081511	N0381I33032026N
DOT-03	N0381I33032026N_20251217_092828	N0381I33032026N
DOT-03	N0381I33032026N_20251217_145308	N0381I33032026N
DOT-03	N0381I33032026N_20251218_075653	N0381I33032026N

Region/Division	Deployment ID	Location Code
DOT-03	N0381133032026N_20251219_080209	N0381133032026N
DOT-04	N0410443033000E_20240108_081343	N0410443033000E
DOT-04	N0410443033000E_20240108_081857	N0410443033000E
DOT-04	N0410443033000E_20240109_073456	N0410443033000E
DOT-04	N0410443033000E_20240110_075120	N0410443033000E
DOT-04	N0410443033000E_20240111_080113	N0410443033000E
DOT-04	N0410443033000E_20240112_075532	N0410443033000E
DOT-04	N0410443033000E_20240112_083856	N0410443033000E
DOT-04	N0410443033000E_20240115_080134	N0410443033000E
DOT-04	N0410443033000E_20240116_075825	N0410443033000E
DOT-04	N0410443033000E_20240116_084935	N0410443033000E
DOT-04	N0410443033000E_20240117_075907	N0410443033000E
DOT-04	N0410443033000E_20240117_115239	N0410443033000E
DOT-04	N0410443033000E_20240118_080259	N0410443033000E
DOT-04	N0410443033000E_20240119_075141	N0410443033000E
DOT-04	N0410443033000E_20240119_082111	N0410443033000E
DOT-04	N0410443033000E_20240122_072942	N0410443033000E
DOT-04	N0410443033000E_20240123_073133	N0410443033000E
DOT-04	N0410443033000E_20240123_091553	N0410443033000E
DOT-04	N0410443033000E_20240124_073003	N0410443033000E
DOT-04	N0410443033000E_20240125_072032	N0410443033000E
DOT-04	N0410443033000E_20240126_075406	N0410443033000E
DOT-04	N0410443033000E_20240129_074441	N0410443033000E
DOT-04	N0410443033000E_20240130_072559	N0410443033000E
DOT-04	N0410443033000E_20240130_084107	N0410443033000E
DOT-04	N0410443033000E_20240131_080818	N0410443033000E
DOT-04	N0410443033000E_20240131_081946	N0410443033000E
DOT-04	N0410443033000E_20240131_084423	N0410443033000E
DOT-04	N0410443033000E_20240131_102554	N0410443033000E
DOT-04	N0410443033000E_20240201_080012	N0410443033000E
DOT-04	N0410443033000E_20240202_073535	N0410443033000E
DOT-04	N0410443033000E_20240207_075845	N0410443033000E
DOT-04	N0410443033000E_20240212_082303	N0410443033000E
DOT-04	N0410443033000E_20240213_075622	N0410443033000E
DOT-04	N0410443033000E_20240214_075930	N0410443033000E
DOT-04	N0410443033000E_20240214_093445	N0410443033000E
DOT-04	N0410443033000E_20240215_074507	N0410443033000E
DOT-04	N0410443033000E_20240216_074320	N0410443033000E
DOT-04	N0410443033000E_20240219_074118	N0410443033000E
DOT-04	N0410443033000E_20240220_074215	N0410443033000E
DOT-04	N0410443033000E_20240221_095201	N0410443033000E
DOT-04	N0410443033000E_20240222_095622	N0410443033000E
DOT-04	N0410443033000E_20240223_071947	N0410443033000E

Region/Division	Deployment ID	Location Code
DOT-04	N04490I43021013W_20240304_102925	N04490I43021013W
DOT-04	N04490I43021013W_20240305_105250	N04490I43021013W
DOT-04	N04490I43021013E_20240307_112357	N04490I43021013E
DOT-04	N04490I43021013E_20240308_104323	N04490I43021013E
DOT-04	N0410443033000E_20240311_074929	N0410443033000E
DOT-04	N0410443033000E_20240312_075646	N0410443033000E
DOT-04	N0410443033000E_20240313_073905	N0410443033000E
DOT-04	N0410443033000E_20240314_090021	N0410443033000E
DOT-04	N0410443033000E_20240315_073552	N0410443033000E
DOT-04	N0410443033000E_20240318_071023	N0410443033000E
DOT-04	N0410443033000E_20240318_080917	N0410443033000E
DOT-04	N04390I42021025N_20240318_105413	N04390I42021025N
DOT-04	N04390I42021025N_20240318_130711	N04390I42021025N
DOT-04	N0410443033000E_20240319_082354	N0410443033000E
DOT-04	N0410443033000E_20240320_074031	N0410443033000E
DOT-04	N0410443033000E_20240320_121337	N0410443033000E
DOT-04	N0410443033000E_20240321_072737	N0410443033000E
DOT-04	N0410443033000E_20240322_083819	N0410443033000E
DOT-04	N04390I42021325S_20240325_091708	N04390I42021325S
DOT-04	N0410443033000E_20240326_095132	N0410443033000E
DOT-04	N0410443033000E_20240327_080153	N0410443033000E
DOT-04	N0410443033000E_20240328_075157	N0410443033000E
DOT-04	N0410443033000E_20240329_071444	N0410443033000E
DOT-04	N0410443033000W_20240401_072756	N0410443033000W
DOT-04	N0410443033000W_20240401_085157	N0410443033000W
DOT-04	N04390I42021325S_20240401_111603	N04390I42021325S
DOT-04	N0410443033000W_20240402_073432	N0410443033000W
DOT-04	N0410443033000E_20240403_085915	N0410443033000E
DOT-04	N0410443033000E_20240404_071150	N0410443033000E
DOT-04	N0410443033000E_20240405_083135	N0410443033000E
DOT-04	N0410443033000E_20240410_071747	N0410443033000E
DOT-04	N04390I43031124N_20240415_083922	N04390I43031124N
DOT-04	N04390I43031124N_20240416_072323	N04390I43031124N
DOT-04	N04390I43031124N_20240417_072334	N04390I43031124N
DOT-04	N04390I43031124N_20240418_070450	N04390I43031124N
DOT-04	N04390I43031124N_20240419_072444	N04390I43031124N
DOT-04	N04390I42021325S_20240422_082812	N04390I42021325S
DOT-04	N04390I42021325S_20240423_083733	N04390I42021325S
DOT-04	N04390I42021325S_20240424_073114	N04390I42021325S
DOT-04	N04390I42021325S_20240425_075838	N04390I42021325S
DOT-04	N04390I42021325S_20240426_074646	N04390I42021325S
DOT-04	N04390I42021280S_20240426_124609	N04390I42021280S
DOT-04	N04390I43031124N_20240429_082131	N04390I43031124N

Region/Division	Deployment ID	Location Code
DOT-04	N04390I43031124N_20240430_073132	N04390I43031124N
DOT-04	N04390I43031124S_20240430_100020	N04390I43031124S
DOT-04	N04390I43031124S_20240430_133714	N04390I43031124S
DOT-04	N04390I43031124N_20240501_071853	N04390I43031124N
DOT-04	N04390I43031124N_20240502_082427	N04390I43031124N
DOT-04	N04390I43031124N_20240503_070812	N04390I43031124N
DOT-04	N04390I43031124N_20240503_081815	N04390I43031124N
DOT-04	N04390I43031124S_20240503_142555	N04390I43031124S
DOT-04	N04390I42021325S_20240506_082116	N04390I42021325S
DOT-04	N04390I42021280S_20240506_150152	N04390I42021280S
DOT-04	N04390I42021280S_20240507_075128	N04390I42021280S
DOT-04	N04390I42021280S_20240508_072754	N04390I42021280S
DOT-04	N04390I42021280S_20240509_080254	N04390I42021280S
DOT-04	N04390I42021280S_20240510_075412	N04390I42021280S
DOT-04	N04390I42021280S_20240510_130745	N04390I42021280S
DOT-04	N04390I43031124N_20240513_072645	N04390I43031124N
DOT-04	N04390I43031124N_20240514_070443	N04390I43031124N
DOT-04	N04390I43031124N_20240514_083359	N04390I43031124N
DOT-04	N04390I43031124N_20240514_083742	N04390I43031124N
DOT-04	N04390I43031124N_20240515_071415	N04390I43031124N
DOT-04	N04390I43031124N_20240516_072751	N04390I43031124N
DOT-04	N04390I43031124N_20240517_072748	N04390I43031124N
DOT-04	N04390I42021298S_20240520_105450	N04390I42021298S
DOT-04	N04390I42021298S_20240521_072103	N04390I42021298S
DOT-04	N04490I43021164E_20240521_121550	N04490I43021164E
DOT-04	N04390I42021298S_20240522_071333	N04390I42021298S
DOT-04	N04390I42021298S_20240523_080228	N04390I42021298S
DOT-04	N04390I42021298S_20240524_073621	N04390I42021298S
DOT-04	N04390I43031124S_20240528_081300	N04390I43031124S
DOT-04	N04390I43031124S_20240529_072610	N04390I43031124S
DOT-04	N04390I43031124N_20240529_085318	N04390I43031124N
DOT-04	N04390I43031124N_20240530_074933	N04390I43031124N
DOT-04	N04390I43031124S_20240530_082227	N04390I43031124S
DOT-04	N04390I43031124N_20240531_070836	N04390I43031124N
DOT-04	N04390I43031124N_20240531_072041	N04390I43031124N
DOT-04	N04390I43031124S_20240531_080955	N04390I43031124S
DOT-04	N04390I42021338S_20240603_091138	N04390I42021338S
DOT-04	N04390I42021325S_20240604_085206	N04390I42021325S
DOT-04	N04390I42021338S_20240605_074802	N04390I42021338S
DOT-04	N04390I42021338S_20240606_082305	N04390I42021338S
DOT-04	N04390I42021338S_20240607_120856	N04390I42021338S
DOT-04	N04390I43031124N_20240610_073048	N04390I43031124N
DOT-04	N04390I43031124S_20240610_081039	N04390I43031124S

Region/Division	Deployment ID	Location Code
DOT-04	N04390I43031124N_20240611_075040	N04390I43031124N
DOT-04	N04390I43031124S_20240611_082340	N04390I43031124S
DOT-04	N04390I43031124S_20240612_072420	N04390I43031124S
DOT-04	N04390I43031124N_20240612_072632	N04390I43031124N
DOT-04	N04390I43031124S_20240613_070344	N04390I43031124S
DOT-04	N04390I43031124N_20240613_071035	N04390I43031124N
DOT-04	N04390I43031124N_20240614_071957	N04390I43031124N
DOT-04	N04390I43031124S_20240614_073715	N04390I43031124S
DOT-04	N04390I42021338S_20240614_075631	N04390I42021338S
DOT-04	N04490I43022037W_20240617_225720	N04490I43022037W
DOT-04	N04390I42021338S_20240618_075809	N04390I42021338S
DOT-04	N04490I43022037W_20240618_212126	N04490I43022037W
DOT-04	N04390I42021279S_20240619_083154	N04390I42021279S
DOT-04	N04390I43031124N_20240619_114757	N04390I43031124N
DOT-04	N04490I43022037W_20240619_215000	N04490I43022037W
DOT-04	N04390I42021279S_20240620_085150	N04390I42021279S
DOT-04	N04390I43031124N_20240620_105927	N04390I43031124N
DOT-04	N04390I43031124S_20240620_124052	N04390I43031124S
DOT-04	N04490I43022037W_20240620_214713	N04490I43022037W
DOT-04	N04390I42021279S_20240621_085011	N04390I42021279S
DOT-04	N04490I43022037W_20240621_211518	N04490I43022037W
DOT-04	N04390I43031124N_20240624_064839	N04390I43031124N
DOT-04	N04390I42021279S_20240624_074121	N04390I42021279S
DOT-04	N04390I43031124S_20240624_075811	N04390I43031124S
DOT-04	N04390I43031124S_20240625_065027	N04390I43031124S
DOT-04	N04390I42021279S_20240625_074534	N04390I42021279S
DOT-04	N04390I43031124N_20240625_075143	N04390I43031124N
DOT-04	N04390I43031124S_20240626_072003	N04390I43031124S
DOT-04	N04390I43031124N_20240626_072421	N04390I43031124N
DOT-04	N04390I42021279S_20240626_074315	N04390I42021279S
DOT-04	N04390I43031124S_20240627_064411	N04390I43031124S
DOT-04	N04390I43031124N_20240627_072304	N04390I43031124N
DOT-04	N04390I42021279S_20240627_072855	N04390I42021279S
DOT-04	N04390I42021338S_20240627_090124	N04390I42021338S
DOT-04	N04390I42021338S_20240627_090624	N04390I42021338S
DOT-04	N04390I43031124S_20240628_064234	N04390I43031124S
DOT-04	N04390I43031124N_20240628_071501	N04390I43031124N
DOT-04	N04390I42021338S_20240628_080605	N04390I42021338S
DOT-04	N04390I42021338S_20240701_072157	N04390I42021338S
DOT-04	N0410443033000W_20240701_202259	N0410443033000W
DOT-04	N04390I42021338S_20240702_073952	N04390I42021338S
DOT-04	N0410443032038W_20240702_231842	N0410443032038W
DOT-04	N04390I42021338S_20240703_075934	N04390I42021338S

Region/Division	Deployment ID	Location Code
DOT-04	N04390I43031124S_20240708_115926	N04390I43031124S
DOT-04	N04390I43031124S_20240708_121340	N04390I43031124S
DOT-04	N04390I43031124N_20240708_124439	N04390I43031124N
DOT-04	N0410443032038W_20240708_221129	N0410443032038W
DOT-04	N04490I43022037W_20240708_223723	N04490I43022037W
DOT-04	N04490I43022037W_20240708_233612	N04490I43022037W
DOT-04	N04390I43031124N_20240709_104602	N04390I43031124N
DOT-04	N0410443032038W_20240709_214304	N0410443032038W
DOT-04	N04490I43022037W_20240709_220708	N04490I43022037W
DOT-04	N04390I43031124S_20240710_065349	N04390I43031124S
DOT-04	N04390I43031124N_20240710_074828	N04390I43031124N
DOT-04	N04390I43031124S_20240711_072732	N04390I43031124S
DOT-04	N04390I43031124N_20240711_125311	N04390I43031124N
DOT-04	N0410443032038W_20240711_211144	N0410443032038W
DOT-04	N04490I43022037W_20240711_212736	N04490I43022037W
DOT-04	N04390I43031124S_20240712_105549	N04390I43031124S
DOT-04	N04490I43022037W_20240712_204008	N04490I43022037W
DOT-04	N04390I43031124S_20240715_063631	N04390I43031124S
DOT-04	N04390I43031138N_20240715_081717	N04390I43031138N
DOT-04	N04490I43022037W_20240715_213438	N04490I43022037W
DOT-04	N04390I43031124S_20240716_064553	N04390I43031124S
DOT-04	N04390I43031138N_20240716_071314	N04390I43031138N
DOT-04	N04490I43022037W_20240716_212638	N04490I43022037W
DOT-04	N04390I43031124S_20240717_070057	N04390I43031124S
DOT-04	N04390I43031138N_20240717_072148	N04390I43031138N
DOT-04	N04490I43022037W_20240717_211915	N04490I43022037W
DOT-04	N04390I43031124S_20240718_071550	N04390I43031124S
DOT-04	N04390I43031138N_20240718_074950	N04390I43031138N
DOT-04	N04390I43031138N_20240718_081645	N04390I43031138N
DOT-04	N04490I43022037W_20240718_215119	N04490I43022037W
DOT-04	N04390I43031124S_20240719_071710	N04390I43031124S
DOT-04	N04390I43031138N_20240719_072952	N04390I43031138N
DOT-04	N04490I43022037W_20240719_211548	N04490I43022037W
DOT-04	N04390I43031124S_20240722_071549	N04390I43031124S
DOT-04	N04390I43031124N_20240722_073457	N04390I43031124N
DOT-04	N04390I43031124N_20240722_092943	N04390I43031124N
DOT-04	N04390I43031124N_20240722_094121	N04390I43031124N
DOT-04	N04490I43022037W_20240722_214401	N04490I43022037W
DOT-04	N04390I43031124N_20240723_064819	N04390I43031124N
DOT-04	N04390I43031124S_20240723_070205	N04390I43031124S
DOT-04	N04490I43022037W_20240723_214548	N04490I43022037W
DOT-04	N04390I43031124S_20240724_064615	N04390I43031124S
DOT-04	N04390I43031124N_20240724_072946	N04390I43031124N

Region/Division	Deployment ID	Location Code
DOT-04	N04390I43031124N_20240724_080831	N04390I43031124N
DOT-04	N04490I43022037W_20240724_212832	N04490I43022037W
DOT-04	N04390I43031124S_20240725_073155	N04390I43031124S
DOT-04	N04390I43031124N_20240725_073710	N04390I43031124N
DOT-04	N04390I43031124N_20240725_073820	N04390I43031124N
DOT-04	N04490I43022037W_20240725_210416	N04490I43022037W
DOT-04	N04390I43031124S_20240726_071258	N04390I43031124S
DOT-04	N04390I43031124N_20240726_080502	N04390I43031124N
DOT-04	N04490I43022037W_20240726_205407	N04490I43022037W
DOT-04	N04390I43031124S_20240730_121233	N04390I43031124S
DOT-04	N04390I43031124S_20240731_075934	N04390I43031124S
DOT-04	N04390I43031124N_20240731_110523	N04390I43031124N
DOT-04	N04390I43031124S_20240801_070019	N04390I43031124S
DOT-04	N04390I43031124S_20240802_072556	N04390I43031124S
DOT-04	N04390I43031124S_20240806_102927	N04390I43031124S
DOT-04	N04390I43031124S_20240807_071132	N04390I43031124S
DOT-04	N04390I43031124N_20240807_080134	N04390I43031124N
DOT-04	N04390I43031124N_20240808_071639	N04390I43031124N
DOT-04	N04390I43031124S_20240808_072930	N04390I43031124S
DOT-04	N04390I43031124S_20240809_072320	N04390I43031124S
DOT-04	N04390I43031124N_20240809_075050	N04390I43031124N
DOT-04	N04390I43031124N_20240812_064722	N04390I43031124N
DOT-04	N04390I43031124S_20240812_071030	N04390I43031124S
DOT-04	N04490I43022037E_20240812_221807	N04490I43022037E
DOT-04	N04390I43031124N_20240813_065225	N04390I43031124N
DOT-04	N04390I43031124S_20240813_070006	N04390I43031124S
DOT-04	N04490I43022037E_20240813_220124	N04490I43022037E
DOT-04	N04490I43022037E_20240814_212253	N04490I43022037E
DOT-04	N04390I43031124N_20240815_065330	N04390I43031124N
DOT-04	N04390I43031124S_20240815_070040	N04390I43031124S
DOT-04	N04390I43031124S_20240816_065138	N04390I43031124S
DOT-04	N04390I43031124N_20240816_065235	N04390I43031124N
DOT-04	N04390I43031124S_20240819_065429	N04390I43031124S
DOT-04	N04390I43031124S_20240820_072710	N04390I43031124S
DOT-04	N0410443033005W_20240820_095928	N0410443033005W
DOT-04	N04390I43031124N_20240821_064329	N04390I43031124N
DOT-04	N0410443033005W_20240821_104637	N0410443033005W
DOT-04	N04390I43031124S_20240822_065728	N04390I43031124S
DOT-04	N04390I43031124N_20240822_070124	N04390I43031124N
DOT-04	N0410443033005W_20240822_105312	N0410443033005W
DOT-04	N04390I43031124N_20240823_064602	N04390I43031124N
DOT-04	N04390I43031124S_20240823_081334	N04390I43031124S
DOT-04	N04390I43031124S_20240826_072110	N04390I43031124S

Region/Division	Deployment ID	Location Code
DOT-04	N04390I42021298S_20240826_082033	N04390I42021298S
DOT-04	N04390I43031124S_20240827_065859	N04390I43031124S
DOT-04	N04390I42021298S_20240827_070025	N04390I42021298S
DOT-04	N04390I42021126N_20240827_100202	N04390I42021126N
DOT-04	N04390I43031124S_20240828_065300	N04390I43031124S
DOT-04	N04390I42021298S_20240828_075038	N04390I42021298S
DOT-04	N04390I42021126N_20240828_093815	N04390I42021126N
DOT-04	N04390I42021298S_20240829_074850	N04390I42021298S
DOT-04	N04390I42021165N_20240829_095326	N04390I42021165N
DOT-04	N04390I42021298S_20240830_074818	N04390I42021298S
DOT-04	N04390I42021298N_20240903_092758	N04390I42021298N
DOT-04	N04390I42021298N_20240904_073713	N04390I42021298N
DOT-04	N04390I42021298N_20240904_074038	N04390I42021298N
DOT-04	N04390I42021298N_20240905_083602	N04390I42021298N
DOT-04	N04390I42021279S_20240906_093839	N04390I42021279S
DOT-04	N04390I42021165N_20240917_103250	N04390I42021165N
DOT-04	N04490I43022037E_20240917_104026	N04490I43022037E
DOT-04	N04390I42021165S_20240918_082135	N04390I42021165S
DOT-04	N04390I42021165N_20240919_081436	N04390I42021165N
DOT-04	N04390I42021165N_20240920_100713	N04390I42021165N
DOT-04	N04490I43022037E_20240923_084132	N04490I43022037E
DOT-04	N04490I43022037E_20240924_072256	N04490I43022037E
DOT-04	N04490I43022037E_20240924_101215	N04490I43022037E
DOT-04	N04490I43022037E_20240925_081907	N04490I43022037E
DOT-04	N04490I43022037E_20240926_072746	N04490I43022037E
DOT-04	N04490I43022037E_20240927_072304	N04490I43022037E
DOT-04	N04390I42021165S_20240927_115841	N04390I42021165S
DOT-04	N04490I43022037E_20240930_100158	N04490I43022037E
DOT-04	N04490I43022037E_20241001_080548	N04490I43022037E
DOT-04	N04490I43022037E_20241001_120655	N04490I43022037E
DOT-04	N04490I43022037E_20241002_081436	N04490I43022037E
DOT-04	N04490I43022037E_20241002_100123	N04490I43022037E
DOT-04	N04490I43022037E_20241002_125735	N04490I43022037E
DOT-04	N04490I43022037E_20241004_084230	N04490I43022037E
DOT-04	N04490I43022037E_20241007_082109	N04490I43022037E
DOT-04	N04490I43022037E_20241008_073700	N04490I43022037E
DOT-04	N04490I43022037E_20241008_122132	N04490I43022037E
DOT-04	N04490I43022037E_20241009_082553	N04490I43022037E
DOT-04	N04490I43022037E_20241010_080858	N04490I43022037E
DOT-04	N04490I43022037E_20241011_082236	N04490I43022037E
DOT-04	N04490I43022037E_20241014_081818	N04490I43022037E
DOT-04	N04490I43022037E_20241015_075506	N04490I43022037E
DOT-04	N04490I43022037E_20241015_113918	N04490I43022037E

Region/Division	Deployment ID	Location Code
DOT-04	N04490I43022037E_20241016_075830	N04490I43022037E
DOT-04	N04490I43022037E_20241016_144500	N04490I43022037E
DOT-04	N04490I43022037E_20241017_081408	N04490I43022037E
DOT-04	N04490I43022037E_20241018_082116	N04490I43022037E
DOT-04	N04490I43022040E_20241028_090054	N04490I43022040E
DOT-04	N04490I43022040E_20241028_093117	N04490I43022040E
DOT-04	N04490I43022040E_20241028_094227	N04490I43022040E
DOT-04	N04490I43022040E_20241028_123531	N04490I43022040E
DOT-04	N04490I43022040E_20241029_083058	N04490I43022040E
DOT-04	N04490I43022040E_20241030_074834	N04490I43022040E
DOT-04	N04490I43022040E_20241031_083335	N04490I43022040E
DOT-04	N04490I43022040E_20241101_074730	N04490I43022040E
DOT-04	N04390I43035001S_20241105_115908	N04390I43035001S
DOT-04	N04390I43035001S_20241106_110926	N04390I43035001S
DOT-04	N04390I43031120S_20241111_102159	N04390I43031120S
DOT-04	N04390I43031065S_20241112_103104	N04390I43031065S
DOT-04	N0410443033000W_20241210_212400	N0410443033000W
DOT-04	N0410443032039W_20241211_201551	N0410443032039W
DOT-04	N0410443032039E_20241211_233308	N0410443032039E
DOT-04	N0410443032039E_20250325_095615	N0410443032039E
DOT-04	N0410443032039E_20250326_112544	N0410443032039E
DOT-04	N0410443032039E_20250327_101052	N0410443032039E
DOT-04	N0410443032039E_20250327_101547	N0410443032039E
DOT-04	N0410443032039E_20250328_101239	N0410443032039E
DOT-04	N0410443032039W_20250331_120603	N0410443032039W
DOT-04	N0410443032039W_20250401_105537	N0410443032039W
DOT-04	N0410443032039W_20250402_102719	N0410443032039W
DOT-04	N0410443032039W_20250403_103315	N0410443032039W
DOT-04	N0410443032039W_20250404_114432	N0410443032039W
DOT-04	N0410443033000W_20250414_110130	N0410443033000W
DOT-04	N0410443033000W_20250415_095722	N0410443033000W
DOT-04	N0410443033000W_20250416_094334	N0410443033000W
DOT-04	N0410443033000W_20250417_092743	N0410443033000W
DOT-04	N0410443033000W_20250418_093437	N0410443033000W
DOT-04	N0410443033000W_20250421_085432	N0410443033000W
DOT-04	N0410443033000W_20250422_092954	N0410443033000W
DOT-04	N0410443033000W_20250423_093747	N0410443033000W
DOT-04	N0410443033000W_20250423_095816	N0410443033000W
DOT-04	N0410443033000W_20250424_100017	N0410443033000W
DOT-04	N04390I42021298N_20250428_105546	N04390I42021298N
DOT-04	N04390I42021298N_20250429_094018	N04390I42021298N
DOT-04	N04390I42021338N_20250519_101517	N04390I42021338N
DOT-04	N04390I42021338N_20250520_095507	N04390I42021338N

Region/Division	Deployment ID	Location Code
DOT-04	N04390I42021338N_20250521_101333	N04390I42021338N
DOT-04	N04390I42021338N_20250522_101114	N04390I42021338N
DOT-04	N0410443032039E_20250602_195303	N0410443032039E
DOT-04	N0410443033000E_20250603_195110	N0410443033000E
DOT-04	N0410443033000E_20250604_201327	N0410443033000E
DOT-04	N04390I42021338S_20250616_082345	N04390I42021338S
DOT-04	N0410443033000W_20250616_210129	N0410443033000W
DOT-04	N04390I42021338S_20250617_083344	N04390I42021338S
DOT-04	N0410443032039W_20250617_211058	N0410443032039W
DOT-04	N04390I42021338S_20250618_083050	N04390I42021338S
DOT-04	N04490I43022037E_20250618_210746	N04490I43022037E
DOT-04	N0410443032039W_20250618_211703	N0410443032039W
DOT-04	N04390I42021338S_20250619_080814	N04390I42021338S
DOT-04	N04490I43022037E_20250619_212836	N04490I43022037E
DOT-04	N04390I42021338S_20250620_081555	N04390I42021338S
DOT-04	N04490I43022037E_20250620_213646	N04490I43022037E
DOT-04	N04390I42021338S_20250623_080859	N04390I42021338S
DOT-04	N0410443032039W_20250623_202204	N0410443032039W
DOT-04	N04490I43022037E_20250623_215946	N04490I43022037E
DOT-04	N04390I42021338S_20250624_084057	N04390I42021338S
DOT-04	N0410443032039W_20250624_193305	N0410443032039W
DOT-04	N04490I43022037E_20250624_210012	N04490I43022037E
DOT-04	N04390I42021325S_20250625_075209	N04390I42021325S
DOT-04	N0410443032039E_20250625_202453	N0410443032039E
DOT-04	N04490I43022037E_20250625_220734	N04490I43022037E
DOT-04	N04390I42021338S_20250626_101810	N04390I42021338S
DOT-04	N04490I43022037E_20250626_211716	N04490I43022037E
DOT-04	N04390I42021338N_20250627_094931	N04390I42021338N
DOT-04	N04490I43022037E_20250627_210903	N04490I43022037E
DOT-04	N04490I43022037W_20250714_205920	N04490I43022037W
DOT-04	N04490I43022037W_20250715_204526	N04490I43022037W
DOT-04	N04490I43022037W_20250716_205933	N04490I43022037W
DOT-04	N04490I43022037W_20250717_210520	N04490I43022037W
DOT-04	N04490I43022037W_20250717_211232	N04490I43022037W
DOT-04	N04490I43022037W_20250802_000536	N04490I43022037W
DOT-04	N0439043011030N_20250804_082544	N0439043011030N
DOT-04	N0410443033005W_20250804_200232	N0410443033005W
DOT-04	N0410443032039W_20250805_201713	N0410443032039W
DOT-04	N0410443032039E_20250807_201952	N0410443032039E
DOT-04	N0410443032039E_20250808_193651	N0410443032039E
DOT-04	N04490I43022037W_20250809_005049	N04490I43022037W
DOT-04	N04490I43022037E_20250809_213519	N04490I43022037E
DOT-04	N0439043011030S_20250811_112616	N0439043011030S

Region/Division	Deployment ID	Location Code
DOT-04	N0410443033000E_20250811_194830	N0410443033000E
DOT-04	N0410443033000E_20250811_201429	N0410443033000E
DOT-04	N0439043011030N_20250812_085738	N0439043011030N
DOT-04	N0410443032039W_20250812_212447	N0410443032039W
DOT-04	N0410443032039W_20250813_202238	N0410443032039W
DOT-04	N0410443032039W_20250814_210447	N0410443032039W
DOT-04	N04490I43021164E_20250818_101049	N04490I43021164E
DOT-04	N04490I43021164E_20250819_104446	N04490I43021164E
DOT-04	N04490I43021164E_20250819_120246	N04490I43021164E
DOT-04	N04490I43021164E_20250821_111303	N04490I43021164E
DOT-04	N04490I43021164E_20250822_102538	N04490I43021164E
DOT-04	N04490I43021164E_20250825_104610	N04490I43021164E
DOT-04	N04490I43021164E_20250825_104829	N04490I43021164E
DOT-04	N04490I43021164E_20250825_120427	N04490I43021164E
DOT-04	N04490I43021164W_20250827_123333	N04490I43021164W
DOT-04	N04490I43021164W_20250827_124946	N04490I43021164W
DOT-04	N0453143011015E_20250828_111009	N0453143011015E
DOT-04	N04490I43022037E_20250908_211034	N04490I43022037E
DOT-04	N04490I43022037E_20250908_220551	N04490I43022037E
DOT-04	N04490I43022037E_20250909_204523	N04490I43022037E
DOT-04	N04490I43022037E_20250910_204023	N04490I43022037E
DOT-04	N04490I43022037W_20250911_205402	N04490I43022037W
DOT-04	N04490I43022037W_20250912_203314	N04490I43022037W
DOT-04	N04490I43022037W_20250915_205758	N04490I43022037W
DOT-04	N04490I43022037W_20250916_202840	N04490I43022037W
DOT-04	N04490I43022037W_20250917_204115	N04490I43022037W
DOT-04	N04490I43022037W_20250929_103036	N04490I43022037W
DOT-04	N04490I43021164W_20250929_210021	N04490I43021164W
DOT-04	N04490I43022037W_20250930_095447	N04490I43022037W
DOT-04	N04490I43021164W_20250930_213254	N04490I43021164W
DOT-04	N04490I43022037W_20251001_092805	N04490I43022037W
DOT-04	N04490I43021164W_20251001_210002	N04490I43021164W
DOT-04	N04490I43021164W_20251002_205738	N04490I43021164W
DOT-04	N04490I43022037W_20251003_095142	N04490I43022037W
DOT-04	N04490I43022037E_20251007_002208	N04490I43022037E
DOT-04	N04490I43022037E_20251007_224449	N04490I43022037E
DOT-04	N04490I43022037W_20251009_232244	N04490I43022037W
DOT-04	N04490I43022037W_20251013_205014	N04490I43022037W
DOT-04	N04490I43022037W_20251013_234351	N04490I43022037W
DOT-04	N04490I43022037W_20251014_203334	N04490I43022037W
DOT-04	N04490I43022037E_20251015_001359	N04490I43022037E
DOT-05	N0521953121113S_20240311_112817	N0521953121113S
DOT-05	N0521953121134S_20240312_092402	N0521953121134S

Region/Division	Deployment ID	Location Code
DOT-05	N0521953121134S_20240313_084251	N0521953121134S
DOT-05	N0521953121134S_20240314_070003	N0521953121134S
DOT-05	N0521953121134S_20240315_070223	N0521953121134S
DOT-05	N0521953121113N_20240318_100348	N0521953121113N
DOT-05	N0521953121113N_20240319_114659	N0521953121113N
DOT-05	N051752111194E_20240321_102257	N051752111194E
DOT-05	N0521953121218N_20240321_113453	N0521953121218N
DOT-05	N051752111194E_20240322_073818	N051752111194E
DOT-05	N0521953121218N_20240322_075008	N0521953121218N
DOT-05	N0521953121218N_20240322_095246	N0521953121218N
DOT-05	N0521953121218N_20240322_114623	N0521953121218N
DOT-05	N051752111194E_20240323_083020	N051752111194E
DOT-05	N051752111194E_20240325_082548	N051752111194E
DOT-05	N051752111194E_20240325_082918	N051752111194E
DOT-05	N0521953121134N_20240325_105025	N0521953121134N
DOT-05	N0521953121229S_20240325_123254	N0521953121229S
DOT-05	N0521953121134N_20240326_075537	N0521953121134N
DOT-05	N051752111194E_20240326_081954	N051752111194E
DOT-05	N0521953121229S_20240326_082132	N0521953121229S
DOT-05	N0521953121229S_20240326_111921	N0521953121229S
DOT-05	N0521953121135S_20240327_082017	N0521953121135S
DOT-05	N051752111194E_20240327_094207	N051752111194E
DOT-05	N0521953121135S_20240328_083510	N0521953121135S
DOT-05	N051751121099E_20240328_091516	N051751121099E
DOT-05	N0521953121134N_20240328_131224	N0521953121134N
DOT-05	N051751121099E_20240329_084352	N051751121099E
DOT-05	N0521953121134S_20240401_081015	N0521953121134S
DOT-05	N051752111194E_20240410_081809	N051752111194E
DOT-05	N053353011038E_20240410_090754	N053353011038E
DOT-05	N051752111194E_20240411_091022	N051752111194E
DOT-05	N053353011038E_20240411_094036	N053353011038E
DOT-05	N053353011038E_20240415_090240	N053353011038E
DOT-05	N0521953121218N_20240415_094718	N0521953121218N
DOT-05	N0521953121218N_20240415_103119	N0521953121218N
DOT-05	N051752111194E_20240416_084718	N051752111194E
DOT-05	N053353011038E_20240416_103944	N053353011038E
DOT-05	N051752111194E_20240417_080731	N051752111194E
DOT-05	N053353011038E_20240417_091511	N053353011038E
DOT-05	N051752111194E_20240418_073049	N051752111194E
DOT-05	N053353011038E_20240418_091108	N053353011038E
DOT-05	N0521953121218N_20240418_093100	N0521953121218N
DOT-05	N051752111194E_20240419_081224	N051752111194E
DOT-05	N0521953121218N_20240422_081627	N0521953121218N

Region/Division	Deployment ID	Location Code
DOT-05	N0521953121218N_20240422_093126	N0521953121218N
DOT-05	N053353011038E_20240422_231703	N053353011038E
DOT-05	N0521953121218N_20240423_080120	N0521953121218N
DOT-05	N053353011038W_20240423_223419	N053353011038W
DOT-05	N0521953121218N_20240424_081232	N0521953121218N
DOT-05	N0521953121218N_20240425_075318	N0521953121218N
DOT-05	N053353011038W_20240425_231136	N053353011038W
DOT-05	N0521953121218N_20240426_072604	N0521953121218N
DOT-05	N053353011038W_20240426_220239	N053353011038W
DOT-05	N0521953121205N_20240429_085329	N0521953121205N
DOT-05	N0521953121205N_20240429_085413	N0521953121205N
DOT-05	N0521953121205N_20240429_092129	N0521953121205N
DOT-05	N0521953121205N_20240429_143710	N0521953121205N
DOT-05	N0521953121218N_20240501_111010	N0521953121218N
DOT-05	N0540053011157N_20240501_221248	N0540053011157N
DOT-05	N053353011024W_20240501_223735	N053353011024W
DOT-05	N0521953121205S_20240502_093656	N0521953121205S
DOT-05	N0540053011157N_20240502_213659	N0540053011157N
DOT-05	N053353011049W_20240502_222439	N053353011049W
DOT-05	N0521953121205S_20240503_081923	N0521953121205S
DOT-05	N0540053011157N_20240503_223309	N0540053011157N
DOT-05	N051752111194E_20240506_115800	N051752111194E
DOT-05	N0521953121218N_20240506_134654	N0521953121218N
DOT-05	N051752111194E_20240507_085932	N051752111194E
DOT-05	N0521953121218N_20240507_120339	N0521953121218N
DOT-05	N0521953121218N_20240508_124659	N0521953121218N
DOT-05	N0521953121218N_20240509_121232	N0521953121218N
DOT-05	N051752111194E_20240513_094509	N051752111194E
DOT-05	N0521953121229S_20240513_124524	N0521953121229S
DOT-05	N0540053011157N_20240513_215302	N0540053011157N
DOT-05	N0521953121229S_20240514_093015	N0521953121229S
DOT-05	N053353011024E_20240514_095331	N053353011024E
DOT-05	N05290153011092E_20240514_212947	N05290153011092E
DOT-05	N0521953121229S_20240515_101757	N0521953121229S
DOT-05	N051752111194E_20240515_102251	N051752111194E
DOT-05	N053353011024E_20240515_103532	N053353011024E
DOT-05	N0540053011157N_20240515_214030	N0540053011157N
DOT-05	N053353011024E_20240516_083357	N053353011024E
DOT-05	N0540053011157N_20240516_211452	N0540053011157N
DOT-05	N051752111194E_20240517_083847	N051752111194E
DOT-05	N051752111194E_20240520_075612	N051752111194E
DOT-05	N053353011049W_20240520_213332	N053353011049W
DOT-05	N051752111194E_20240521_083604	N051752111194E

Region/Division	Deployment ID	Location Code
DOT-05	N053353011049W_20240521_233300	N053353011049W
DOT-05	N051752111194E_20240522_084819	N051752111194E
DOT-05	N0521953121218S_20240522_094003	N0521953121218S
DOT-05	N0521953121218S_20240522_094827	N0521953121218S
DOT-05	N053353011049W_20240522_234609	N053353011049W
DOT-05	N051752111194E_20240523_074006	N051752111194E
DOT-05	N0521953121261S_20240523_123350	N0521953121261S
DOT-05	N053353011049W_20240523_221653	N053353011049W
DOT-05	N051752111194E_20240524_080307	N051752111194E
DOT-05	N051752111194E_20240528_081208	N051752111194E
DOT-05	N053353011049E_20240528_093352	N053353011049E
DOT-05	N051752111194E_20240529_073019	N051752111194E
DOT-05	N05290I53011092E_20240529_214529	N05290I53011092E
DOT-05	N0540053011157N_20240529_225018	N0540053011157N
DOT-05	N051752111194E_20240530_081602	N051752111194E
DOT-05	N0540053011157N_20240530_224813	N0540053011157N
DOT-05	N0540053011157N_20240531_030021	N0540053011157N
DOT-05	N051752111194E_20240531_094906	N051752111194E
DOT-05	N0540053011157N_20240531_214041	N0540053011157N
DOT-05	N051752111194E_20240603_083442	N051752111194E
DOT-05	N051752111194E_20240603_202314	N051752111194E
DOT-05	N053353011049E_20240603_222628	N053353011049E
DOT-05	N053353011049E_20240603_232207	N053353011049E
DOT-05	N051752111194E_20240604_073600	N051752111194E
DOT-05	N051752111194E_20240604_212644	N051752111194E
DOT-05	N053353011049E_20240604_225004	N053353011049E
DOT-05	N051752111194E_20240605_083653	N051752111194E
DOT-05	N053353011049E_20240605_205222	N053353011049E
DOT-05	N051752111194E_20240605_211241	N051752111194E
DOT-05	N053353011049E_20240605_221642	N053353011049E
DOT-05	N051752111194E_20240606_080323	N051752111194E
DOT-05	N0540053011070N_20240606_133538	N0540053011070N
DOT-05	N051752111194E_20240606_211000	N051752111194E
DOT-05	N053353011049E_20240606_224701	N053353011049E
DOT-05	N051752111194E_20240607_070703	N051752111194E
DOT-05	N051752111194E_20240607_085630	N051752111194E
DOT-05	N051752111194E_20240607_201949	N051752111194E
DOT-05	N053353011049W_20240607_210203	N053353011049W
DOT-05	N053353011049W_20240607_222030	N053353011049W
DOT-05	N05290I53011048E_20240608_105016	N05290I53011048E
DOT-05	N051752111194E_20240610_092432	N051752111194E
DOT-05	N051752111194E_20240610_203237	N051752111194E
DOT-05	N051752111194E_20240611_085808	N051752111194E

Region/Division	Deployment ID	Location Code
DOT-05	N05190I54011059N_20240611_122141	N05190I54011059N
DOT-05	N051752111194E_20240612_074219	N051752111194E
DOT-05	N051752111194E_20240612_093105	N051752111194E
DOT-05	N05190I54011059N_20240612_103340	N05190I54011059N
DOT-05	N0540053011157S_20240612_122500	N0540053011157S
DOT-05	N051752111194E_20240612_203106	N051752111194E
DOT-05	N051752111194E_20240613_074854	N051752111194E
DOT-05	N05190I54011059N_20240613_093318	N05190I54011059N
DOT-05	N051752111194E_20240613_201444	N051752111194E
DOT-05	N051752111194E_20240614_081511	N051752111194E
DOT-05	N05190I54011059N_20240614_084902	N05190I54011059N
DOT-05	N051752111194E_20240618_072247	N051752111194E
DOT-05	N051751124005E_20240618_095155	N051751124005E
DOT-05	N05190I54011059N_20240618_103625	N05190I54011059N
DOT-05	N051752111194E_20240619_073714	N051752111194E
DOT-05	N05190I54011059N_20240619_091444	N05190I54011059N
DOT-05	N051752111194E_20240620_064436	N051752111194E
DOT-05	N051752111194E_20240621_074332	N051752111194E
DOT-05	N05190I54011059N_20240621_084944	N05190I54011059N
DOT-05	N051752111194E_20240624_072530	N051752111194E
DOT-05	N051752111194E_20240624_080834	N051752111194E
DOT-05	N051751124005E_20240624_092159	N051751124005E
DOT-05	N05190I54011059N_20240624_132126	N05190I54011059N
DOT-05	N053353011049W_20240624_224610	N053353011049W
DOT-05	N051752111194E_20240625_071155	N051752111194E
DOT-05	N051751124005E_20240625_090728	N051751124005E
DOT-05	N053353011049W_20240625_213104	N053353011049W
DOT-05	N051752111194E_20240626_070953	N051752111194E
DOT-05	N051751124005E_20240626_093738	N051751124005E
DOT-05	N0540053011157N_20240626_212933	N0540053011157N
DOT-05	N053353011049W_20240626_223021	N053353011049W
DOT-05	N051752111194E_20240627_072852	N051752111194E
DOT-05	N051751124005E_20240627_085604	N051751124005E
DOT-05	N053353011049E_20240627_212852	N053353011049E
DOT-05	N051752111194E_20240628_074136	N051752111194E
DOT-05	N053353011049E_20240628_205727	N053353011049E
DOT-05	N051752111194E_20240701_072154	N051752111194E
DOT-05	N051751124005E_20240701_085949	N051751124005E
DOT-05	N053353011049E_20240701_220710	N053353011049E
DOT-05	N051752111194E_20240702_074724	N051752111194E
DOT-05	N051751124005E_20240702_082832	N051751124005E
DOT-05	N053353011049W_20240702_201942	N053353011049W
DOT-05	N051752111194E_20240703_073333	N051752111194E

Region/Division	Deployment ID	Location Code
DOT-05	N051751124005E_20240703_090104	N051751124005E
DOT-05	N051752111194E_20240708_074814	N051752111194E
DOT-05	N0519853011028W_20240708_092034	N0519853011028W
DOT-05	N051752111194E_20240709_071434	N051752111194E
DOT-05	N0519853011028W_20240709_092520	N0519853011028W
DOT-05	N051752111194E_20240710_080558	N051752111194E
DOT-05	N051751125054W_20240710_092608	N051751125054W
DOT-05	N051751125054W_20240710_095357	N051751125054W
DOT-05	N0540053011157N_20240710_222522	N0540053011157N
DOT-05	N051752111194E_20240711_081249	N051752111194E
DOT-05	N0519853011028W_20240711_095213	N0519853011028W
DOT-05	N0540053011157N_20240711_203018	N0540053011157N
DOT-05	N051752111194E_20240712_073843	N051752111194E
DOT-05	N0519853011028W_20240712_090747	N0519853011028W
DOT-05	N0540053011157N_20240712_195425	N0540053011157N
DOT-05	N051752111194E_20240715_074104	N051752111194E
DOT-05	N05190I54011059N_20240715_084915	N05190I54011059N
DOT-05	N0519853011028W_20240715_120357	N0519853011028W
DOT-05	N051752111194E_20240716_080628	N051752111194E
DOT-05	N05190I54011059N_20240716_085744	N05190I54011059N
DOT-05	N0519853011028W_20240716_104223	N0519853011028W
DOT-05	N0540053011157N_20240716_104414	N0540053011157N
DOT-05	N051752111194E_20240717_073924	N051752111194E
DOT-05	N0519853011028W_20240717_093841	N0519853011028W
DOT-05	N051752111194E_20240718_074203	N051752111194E
DOT-05	N051752111194E_20240719_071018	N051752111194E
DOT-05	N0519853011028E_20240719_100108	N0519853011028E
DOT-05	N051752111194E_20240722_132622	N051752111194E
DOT-05	N053353011052W_20240722_204738	N053353011052W
DOT-05	N053353011052W_20240722_213327	N053353011052W
DOT-05	N051752111194E_20240723_070627	N051752111194E
DOT-05	N053353011052W_20240723_203212	N053353011052W
DOT-05	N053353011052W_20240723_215845	N053353011052W
DOT-05	N051752111194E_20240724_072850	N051752111194E
DOT-05	N053353011052W_20240724_215134	N053353011052W
DOT-05	N051752111194E_20240725_070032	N051752111194E
DOT-05	N053353011052W_20240725_200115	N053353011052W
DOT-05	N053353011052W_20240725_213348	N053353011052W
DOT-05	N051752111194E_20240726_072056	N051752111194E
DOT-05	N053353011052W_20240726_201601	N053353011052W
DOT-05	N053353011052W_20240726_220343	N053353011052W
DOT-05	N051752111194E_20240729_074425	N051752111194E
DOT-05	N0519853011028E_20240729_102632	N0519853011028E

Region/Division	Deployment ID	Location Code
DOT-05	N051752111194E_20240730_084642	N051752111194E
DOT-05	N051752111194E_20240731_072130	N051752111194E
DOT-05	N051752111194E_20240801_064037	N051752111194E
DOT-05	N051752111194E_20240802_064404	N051752111194E
DOT-05	N0540053011160N_20240804_232355	N0540053011160N
DOT-05	N051752111194E_20240805_073600	N051752111194E
DOT-05	N053353011052E_20240805_095437	N053353011052E
DOT-05	N051752111194E_20240806_064136	N051752111194E
DOT-05	N053353011052E_20240806_102409	N053353011052E
DOT-05	N0540053011157N_20240806_225047	N0540053011157N
DOT-05	N051752111194E_20240807_082655	N051752111194E
DOT-05	N0540053011157N_20240807_223224	N0540053011157N
DOT-05	N051752111194E_20240808_071911	N051752111194E
DOT-05	N051752111194E_20240809_070923	N051752111194E
DOT-05	N051752111194E_20240812_064207	N051752111194E
DOT-05	N051752111194E_20240813_072337	N051752111194E
DOT-05	N051752111194E_20240814_065129	N051752111194E
DOT-05	N051752111194E_20240815_075921	N051752111194E
DOT-05	N051752111194E_20240816_071800	N051752111194E
DOT-05	N053353011052E_20240816_105722	N053353011052E
DOT-05	N051752111194E_20240819_072231	N051752111194E
DOT-05	N053353011052W_20240819_104513	N053353011052W
DOT-05	N051752111194E_20240820_072153	N051752111194E
DOT-05	N051752111194E_20240821_071136	N051752111194E
DOT-05	N051752111194E_20240822_064529	N051752111194E
DOT-05	N051752111194E_20240827_072246	N051752111194E
DOT-05	N051752111194E_20240828_070156	N051752111194E
DOT-05	N051752111194E_20240829_063913	N051752111194E
DOT-05	N051752111194E_20240830_071923	N051752111194E
DOT-05	N051752111194E_20240903_083558	N051752111194E
DOT-05	N051752111194E_20240904_070824	N051752111194E
DOT-05	N051752111194E_20240905_070731	N051752111194E
DOT-05	N051752111194E_20240906_085439	N051752111194E
DOT-05	N051752111194E_20240909_064021	N051752111194E
DOT-05	N051752111194E_20240910_065454	N051752111194E
DOT-05	N051752111194E_20240911_070144	N051752111194E
DOT-05	N0540053011042N_20240911_103625	N0540053011042N
DOT-05	N051752111194E_20240912_070218	N051752111194E
DOT-05	N053353011038E_20240912_090354	N053353011038E
DOT-05	N051752111194E_20240913_070024	N051752111194E
DOT-05	N053353011052W_20240913_101834	N053353011052W
DOT-05	N053353011011E_20240916_092109	N053353011011E
DOT-05	N051752111194E_20240916_113309	N051752111194E

Region/Division	Deployment ID	Location Code
DOT-05	N053353011011W_20240916_121206	N053353011011W
DOT-05	N051752111194E_20240918_080316	N051752111194E
DOT-05	N051752111194E_20240919_071920	N051752111194E
DOT-05	N051752111194E_20240920_070005	N051752111194E
DOT-05	N05290I53011060E_20240922_080949	N05290I53011060E
DOT-05	N053353012017W_20240922_101845	N053353012017W
DOT-05	N051752111194E_20240923_072410	N051752111194E
DOT-05	N051752111194E_20240924_063452	N051752111194E
DOT-05	N051752111194E_20240925_063916	N051752111194E
DOT-05	N051752111194E_20240925_102726	N051752111194E
DOT-05	N051752111194E_20240926_063036	N051752111194E
DOT-05	N051752111194E_20240927_065827	N051752111194E
DOT-05	N051752111194E_20240930_065830	N051752111194E
DOT-05	N0540053011070N_20240930_101836	N0540053011070N
DOT-05	N051751124005E_20240930_110135	N051751124005E
DOT-05	N051752111194E_20241001_063031	N051752111194E
DOT-05	N051751124005E_20241001_081200	N051751124005E
DOT-05	N051751124005E_20241002_074329	N051751124005E
DOT-05	N051752111194E_20241002_080332	N051752111194E
DOT-05	N05190I54011005S_20241002_111358	N05190I54011005S
DOT-05	N051752111194E_20241003_070740	N051752111194E
DOT-05	N051751124005E_20241003_071356	N051751124005E
DOT-05	N0540053011070N_20241003_101404	N0540053011070N
DOT-05	N051752111194E_20241004_072112	N051752111194E
DOT-05	N051751124005E_20241004_082418	N051751124005E
DOT-05	N0540053011070N_20241004_095049	N0540053011070N
DOT-05	N05290I53011060W_20241005_094455	N05290I53011060W
DOT-05	N0521953121261S_20241005_094931	N0521953121261S
DOT-05	N05290I53011060W_20241005_095417	N05290I53011060W
DOT-05	N053353011049E_20241006_104736	N053353011049E
DOT-05	N051751124005E_20241007_080352	N051751124005E
DOT-05	N051751124005E_20241007_092334	N051751124005E
DOT-05	N051751124005E_20241008_072551	N051751124005E
DOT-05	N051751124005E_20241009_082839	N051751124005E
DOT-05	N05553023000E_20241015_123235	N05553023000E
DOT-05	N051751124005E_20241016_082406	N051751124005E
DOT-05	N05553023002W_20241016_095905	N05553023002W
DOT-05	N051751124005E_20241016_121035	N051751124005E
DOT-05	N051751125012E_20241017_113410	N051751125012E
DOT-05	N051751125012E_20241018_102719	N051751125012E
DOT-05	N051751125012E_20241019_101354	N051751125012E
DOT-05	N051751125012E_20241021_064726	N051751125012E
DOT-05	N051752111194E_20241021_065632	N051752111194E

Region/Division	Deployment ID	Location Code
DOT-05	N05553023002W_20241021_102251	N05553023002W
DOT-05	N051751125012E_20241022_065622	N051751125012E
DOT-05	N051752111194E_20241022_074240	N051752111194E
DOT-05	N05553023002E_20241022_110752	N05553023002E
DOT-05	N051752111194E_20241023_063742	N051752111194E
DOT-05	N051751125012E_20241023_071747	N051751125012E
DOT-05	N0540053011042N_20241023_111634	N0540053011042N
DOT-05	N051751125012E_20241024_070306	N051751125012E
DOT-05	N051752111194E_20241024_070703	N051752111194E
DOT-05	N051751125012E_20241024_115129	N051751125012E
DOT-05	N051752111194E_20241025_073114	N051752111194E
DOT-05	N051751125012E_20241025_080026	N051751125012E
DOT-05	N051751125012W_20241104_070230	N051751125012W
DOT-05	N051751125012W_20241105_064929	N051751125012W
DOT-05	N051751125012W_20241106_073338	N051751125012W
DOT-05	N051751125012W_20241107_074126	N051751125012W
DOT-05	N051751125012W_20241108_070416	N051751125012W
DOT-05	N051751125012W_20241112_071601	N051751125012W
DOT-05	N051752111194E_20241112_114626	N051752111194E
DOT-05	N051752111194E_20241112_130559	N051752111194E
DOT-05	N051752111194E_20241112_133902	N051752111194E
DOT-05	N051752111194E_20241112_143654	N051752111194E
DOT-05	N051752111194E_20241113_070003	N051752111194E
DOT-05	N051751125012W_20241113_075022	N051751125012W
DOT-05	N053353012017E_20241113_222712	N053353012017E
DOT-05	N051751125012W_20241114_065739	N051751125012W
DOT-05	N051752111194E_20241114_070433	N051752111194E
DOT-05	N051752111194E_20241115_072621	N051752111194E
DOT-05	N051751125012W_20241115_075002	N051751125012W
DOT-05	N051751125012W_20241118_064350	N051751125012W
DOT-05	N051751125012W_20241119_070244	N051751125012W
DOT-05	N051751125012W_20241120_064337	N051751125012W
DOT-05	N051751125012W_20241121_071013	N051751125012W
DOT-05	N051751125012W_20241122_073509	N051751125012W
DOT-05	N051751125012W_20241125_073257	N051751125012W
DOT-05	N051751125012W_20241126_094422	N051751125012W
DOT-05	N051752111194E_20250324_104304	N051752111194E
DOT-05	N051752111194E_20250325_081212	N051752111194E
DOT-05	N051752111194E_20250326_080016	N051752111194E
DOT-05	N051752111194E_20250327_075916	N051752111194E
DOT-05	N051752111194E_20250328_082600	N051752111194E
DOT-05	N051752111194E_20250331_074545	N051752111194E
DOT-05	N051752111194E_20250401_071750	N051752111194E

Region/Division	Deployment ID	Location Code
DOT-05	N051752111194E_20250402_075111	N051752111194E
DOT-05	N051752111194E_20250403_070148	N051752111194E
DOT-05	N051752111194E_20250404_074400	N051752111194E
DOT-05	N051752111194E_20250407_111708	N051752111194E
DOT-05	N0540053011042N_20250407_115805	N0540053011042N
DOT-05	N053353011041W_20250407_210737	N053353011041W
DOT-05	N0540053011042N_20250408_083542	N0540053011042N
DOT-05	N051752111194E_20250408_105148	N051752111194E
DOT-05	N053353011041W_20250408_205104	N053353011041W
DOT-05	N0540053011042N_20250409_081603	N0540053011042N
DOT-05	N0540053011042N_20250409_090932	N0540053011042N
DOT-05	N051751123130E_20250409_103227	N051751123130E
DOT-05	N051751123130E_20250409_131530	N051751123130E
DOT-05	N053353011041E_20250409_223233	N053353011041E
DOT-05	N051752111194E_20250410_083123	N051752111194E
DOT-05	N0540053011042S_20250410_092223	N0540053011042S
DOT-05	N051751123130E_20250410_102552	N051751123130E
DOT-05	N053353011041E_20250410_213810	N053353011041E
DOT-05	N053353011041E_20250410_223155	N053353011041E
DOT-05	N051752111194E_20250411_074732	N051752111194E
DOT-05	N0540053011042S_20250411_080050	N0540053011042S
DOT-05	N051751123130E_20250411_090526	N051751123130E
DOT-05	N053353011041E_20250411_203800	N053353011041E
DOT-05	N0540053011042S_20250414_102820	N0540053011042S
DOT-05	N051751124005E_20250414_112512	N051751124005E
DOT-05	N051751124005E_20250414_125339	N051751124005E
DOT-05	N0540053011042S_20250414_143849	N0540053011042S
DOT-05	N051751125016E_20250415_081734	N051751125016E
DOT-05	N053353011049E_20250415_090503	N053353011049E
DOT-05	N053353011049E_20250415_092138	N053353011049E
DOT-05	N053353011049W_20250415_121702	N053353011049W
DOT-05	N053353011049E_20250416_080734	N053353011049E
DOT-05	N051752111194W_20250416_082650	N051752111194W
DOT-05	N053353011049E_20250416_104304	N053353011049E
DOT-05	N051752111194E_20250418_072825	N051752111194E
DOT-05	N051752111194E_20250418_080004	N051752111194E
DOT-05	N051752111194E_20250418_090456	N051752111194E
DOT-05	N051751124005E_20250418_110050	N051751124005E
DOT-05	N051752111194E_20250421_110410	N051752111194E
DOT-05	N051752111194E_20250422_073941	N051752111194E
DOT-05	N053353011038W_20250422_215959	N053353011038W
DOT-05	N051752111194E_20250423_070849	N051752111194E
DOT-05	N053353011038W_20250423_214033	N053353011038W

Region/Division	Deployment ID	Location Code
DOT-05	N051752111194E_20250424_063856	N051752111194E
DOT-05	N053353011038W_20250425_021941	N053353011038W
DOT-05	N051752111194E_20250425_070150	N051752111194E
DOT-05	N053353011038W_20250425_211808	N053353011038W
DOT-05	N051752111194E_20250428_070947	N051752111194E
DOT-05	N051752111194E_20250429_070035	N051752111194E
DOT-05	N051752111194E_20250430_065613	N051752111194E
DOT-05	N051752111194E_20250501_065849	N051752111194E
DOT-05	N051752111194E_20250502_065533	N051752111194E
DOT-05	N051752111194E_20250505_065701	N051752111194E
DOT-05	N051752111194E_20250505_101541	N051752111194E
DOT-05	N051752111194E_20250506_065629	N051752111194E
DOT-05	N051752111194E_20250507_064549	N051752111194E
DOT-05	N051752111194E_20250508_065744	N051752111194E
DOT-05	N051752111194E_20250509_064208	N051752111194E
DOT-05	N051752111194E_20250512_075407	N051752111194E
DOT-05	N053353011041E_20250512_123018	N053353011041E
DOT-05	N051752111194E_20250513_065801	N051752111194E
DOT-05	N053353011041E_20250513_093751	N053353011041E
DOT-05	N051752111194E_20250514_065443	N051752111194E
DOT-05	N053353011041E_20250514_095808	N053353011041E
DOT-05	N053353011041E_20250514_110454	N053353011041E
DOT-05	N051752111194E_20250515_064614	N051752111194E
DOT-05	N053353011041E_20250515_093005	N053353011041E
DOT-05	N051752111194E_20250516_070749	N051752111194E
DOT-05	N053353011041E_20250516_105713	N053353011041E
DOT-05	N051752111194E_20250519_065323	N051752111194E
DOT-05	N051752111194E_20250520_065028	N051752111194E
DOT-05	N051752111194E_20250521_074042	N051752111194E
DOT-05	N05990153011030N_20250521_094337	N05990153011030N
DOT-05	N051752111194E_20250522_065825	N051752111194E
DOT-05	N051752111194E_20250522_102931	N051752111194E
DOT-05	N051752111194E_20250523_064328	N051752111194E
DOT-05	N051752111190E_20250527_081423	N051752111190E
DOT-05	N051752111190E_20250528_070506	N051752111190E
DOT-05	N051752111190E_20250529_065754	N051752111190E
DOT-05	N051752111190E_20250530_064933	N051752111190E
DOT-05	N0521953121218S_20250530_102116	N0521953121218S
DOT-05	N053353011011W_20250531_090957	N053353011011W
DOT-05	N053353011011W_20250531_091855	N053353011011W
DOT-05	N053353011011W_20250531_091938	N053353011011W
DOT-05	N051752111190E_20250602_071003	N051752111190E
DOT-05	N051752111190E_20250603_072001	N051752111190E

Region/Division	Deployment ID	Location Code
DOT-05	N051752111190E_20250604_071841	N051752111190E
DOT-05	N051752111190E_20250605_072317	N051752111190E
DOT-05	N051752111190E_20250605_073243	N051752111190E
DOT-05	N05951A54011005E_20250605_080951	N05951A54011005E
DOT-05	N05951A54011005E_20250605_083233	N05951A54011005E
DOT-05	N05951A54011005E_20250605_083447	N05951A54011005E
DOT-05	N0521953121135S_20250605_094253	N0521953121135S
DOT-05	N051752111190E_20250606_064654	N051752111190E
DOT-05	N05951A54011005E_20250606_112206	N05951A54011005E
DOT-05	N051752111190E_20250609_071458	N051752111190E
DOT-05	N05951A54011005E_20250609_075558	N05951A54011005E
DOT-05	N051752111190E_20250610_070216	N051752111190E
DOT-05	N05951A54011005E_20250610_083534	N05951A54011005E
DOT-05	N051752111190E_20250611_072055	N051752111190E
DOT-05	N051752111190E_20250611_081553	N051752111190E
DOT-05	N05951A54011005E_20250611_083615	N05951A54011005E
DOT-05	N051752111190E_20250611_152109	N051752111190E
DOT-05	N051752111190E_20250612_070450	N051752111190E
DOT-05	N05951A54011005E_20250612_080845	N05951A54011005E
DOT-05	N05951A54011005E_20250612_092918	N05951A54011005E
DOT-05	N051752111190E_20250613_065805	N051752111190E
DOT-05	N05951A54011005E_20250613_080212	N05951A54011005E
DOT-05	N051752111190E_20250613_100745	N051752111190E
DOT-05	N051752111190E_20250616_071522	N051752111190E
DOT-05	N05290I53011027W_20250616_103550	N05290I53011027W
DOT-05	N05290I53011027E_20250617_102724	N05290I53011027E
DOT-05	N0521953121135S_20250617_104910	N0521953121135S
DOT-05	N051752111190E_20250618_071000	N051752111190E
DOT-05	N051752111190E_20250619_070743	N051752111190E
DOT-05	N051752111190E_20250620_070416	N051752111190E
DOT-05	N051752111190E_20250623_071113	N051752111190E
DOT-05	N051752111190E_20250624_070958	N051752111190E
DOT-05	N051752111190E_20250625_074102	N051752111190E
DOT-05	N051752111350E_20250625_101638	N051752111350E
DOT-05	N051752111190E_20250626_065323	N051752111190E
DOT-05	N051752111190E_20250627_065824	N051752111190E
DOT-05	N051752111190E_20250630_071647	N051752111190E
DOT-05	N051752111190E_20250701_071635	N051752111190E
DOT-05	N051752111190E_20250701_080322	N051752111190E
DOT-05	N051752111190E_20250702_071118	N051752111190E
DOT-05	N051752111190E_20250702_093319	N051752111190E
DOT-05	N051752111190E_20250703_065349	N051752111190E
DOT-05	N051752111190E_20250703_083136	N051752111190E

Region/Division	Deployment ID	Location Code
DOT-05	N0540053011156S_20250707_102032	N0540053011156S
DOT-05	N051752111190E_20250707_104653	N051752111190E
DOT-05	N051751125054E_20250707_112531	N051751125054E
DOT-05	N0521953121043N_20250707_121542	N0521953121043N
DOT-05	N051752111190E_20250708_071443	N051752111190E
DOT-05	N0521953121043N_20250708_082822	N0521953121043N
DOT-05	N05951A54011005E_20250708_111554	N05951A54011005E
DOT-05	N051752111190E_20250709_071244	N051752111190E
DOT-05	N05951A54011005E_20250709_095037	N05951A54011005E
DOT-05	N0521953121043S_20250709_105317	N0521953121043S
DOT-05	N051752111190E_20250710_065500	N051752111190E
DOT-05	N0540053011156S_20250710_095106	N0540053011156S
DOT-05	N05951A54011005E_20250710_102318	N05951A54011005E
DOT-05	N0521953121043S_20250710_110220	N0521953121043S
DOT-05	N0540053011156S_20250710_140719	N0540053011156S
DOT-05	N051752111190E_20250711_070811	N051752111190E
DOT-05	N05951A54011005E_20250711_073225	N05951A54011005E
DOT-05	N0540053011156S_20250711_085852	N0540053011156S
DOT-05	N0540053011156S_20250711_093105	N0540053011156S
DOT-05	N051752111190E_20250714_065447	N051752111190E
DOT-05	N0540053011156N_20250714_075812	N0540053011156N
DOT-05	N051752111190E_20250715_070029	N051752111190E
DOT-05	N051752111190E_20250715_121831	N051752111190E
DOT-05	N051752111190E_20250716_064810	N051752111190E
DOT-05	N051752111190E_20250717_064604	N051752111190E
DOT-05	N051752111190E_20250718_070841	N051752111190E
DOT-05	N051752111190E_20250721_065513	N051752111190E
DOT-05	N051751125012W_20250721_083041	N051751125012W
DOT-05	N0521953121229S_20250721_110917	N0521953121229S
DOT-05	N051752111190E_20250722_070719	N051752111190E
DOT-05	N051751124005W_20250722_074221	N051751124005W
DOT-05	N0521953121229S_20250722_113828	N0521953121229S
DOT-05	N051752111190E_20250723_065614	N051752111190E
DOT-05	N051751123130W_20250723_090405	N051751123130W
DOT-05	N05553023002W_20250723_110317	N05553023002W
DOT-05	N051752111190E_20250724_070508	N051752111190E
DOT-05	N051752111190E_20250724_073028	N051752111190E
DOT-05	N051752111190E_20250725_070648	N051752111190E
DOT-05	N051751123130W_20250725_083833	N051751123130W
DOT-05	N051751125012W_20250725_142415	N051751125012W
DOT-05	N051752111190E_20250728_065710	N051752111190E
DOT-05	N051751123130W_20250728_074254	N051751123130W
DOT-05	N051752111190E_20250729_070546	N051752111190E

Region/Division	Deployment ID	Location Code
DOT-05	N051752111190E_20250730_071706	N051752111190E
DOT-05	N051752111190E_20250731_073022	N051752111190E
DOT-05	N051752111190E_20250801_070609	N051752111190E
DOT-05	N051752111190E_20250804_064826	N051752111190E
DOT-05	N051752111190E_20250805_064357	N051752111190E
DOT-05	N0540053011156N_20250805_124855	N0540053011156N
DOT-05	N051752111190E_20250806_073051	N051752111190E
DOT-05	N0540053011156N_20250806_105438	N0540053011156N
DOT-05	N051752111190E_20250807_070429	N051752111190E
DOT-05	N0540053011156N_20250807_105504	N0540053011156N
DOT-05	N051752111190E_20250808_070537	N051752111190E
DOT-05	N0540053011156N_20250808_105558	N0540053011156N
DOT-05	N05553023002E_20250809_085332	N05553023002E
DOT-05	N0540053011156N_20250811_103603	N0540053011156N
DOT-05	N051752111190E_20250811_124939	N051752111190E
DOT-05	N051752111190E_20250812_071724	N051752111190E
DOT-05	N0540053011156N_20250812_110647	N0540053011156N
DOT-05	N051752111190E_20250813_082148	N051752111190E
DOT-05	N0540053011156N_20250813_111111	N0540053011156N
DOT-05	N051752111190E_20250814_070803	N051752111190E
DOT-05	N051752111190E_20250815_070133	N051752111190E
DOT-05	N051752111190E_20250818_065831	N051752111190E
DOT-05	N0540053011120N_20250818_192730	N0540053011120N
DOT-05	N0540053011120N_20250818_232355	N0540053011120N
DOT-05	N051752111190E_20250819_065637	N051752111190E
DOT-05	N0540053011156N_20250819_190536	N0540053011156N
DOT-05	N0540053011156N_20250819_191740	N0540053011156N
DOT-05	N0540053011156N_20250820_014804	N0540053011156N
DOT-05	N051752111190E_20250820_070536	N051752111190E
DOT-05	N0540053011156N_20250820_202032	N0540053011156N
DOT-05	N0540053011156N_20250820_231822	N0540053011156N
DOT-05	N051752111190E_20250821_065207	N051752111190E
DOT-05	N0540053011156N_20250821_193051	N0540053011156N
DOT-05	N0540053011156N_20250822_005101	N0540053011156N
DOT-05	N051752111190E_20250822_070037	N051752111190E
DOT-05	N0540053011120N_20250822_202550	N0540053011120N
DOT-05	N053353011057W_20250823_105243	N053353011057W
DOT-05	N051752111190E_20250825_070532	N051752111190E
DOT-05	N0540053011120N_20250825_195711	N0540053011120N
DOT-05	N051752111190E_20250826_065814	N051752111190E
DOT-05	N0540053011120N_20250826_211322	N0540053011120N
DOT-05	N051752111190E_20250827_065421	N051752111190E
DOT-05	N0540053011156N_20250827_204800	N0540053011156N

Region/Division	Deployment ID	Location Code
DOT-05	N0540053011156N_20250828_015622	N0540053011156N
DOT-05	N051752111190E_20250828_091845	N051752111190E
DOT-05	N051752111190E_20250829_065415	N051752111190E
DOT-05	N051752111190E_20250902_073506	N051752111190E
DOT-05	N0540053011156N_20250902_104052	N0540053011156N
DOT-05	N053353011041W_20250902_111751	N053353011041W
DOT-05	N051752111190E_20250903_092125	N051752111190E
DOT-05	N0540053011070S_20250903_102105	N0540053011070S
DOT-05	N053353011041W_20250903_123044	N053353011041W
DOT-05	N051752111190E_20250904_070234	N051752111190E
DOT-05	N0540053011156N_20250904_110024	N0540053011156N
DOT-05	N051752111190E_20250905_071132	N051752111190E
DOT-05	N053353011041E_20250905_092859	N053353011041E
DOT-05	N0540053011070S_20250905_100941	N0540053011070S
DOT-05	N0540053011156N_20250905_114658	N0540053011156N
DOT-05	N051752111190E_20250908_065141	N051752111190E
DOT-05	N051752111190E_20250909_071633	N051752111190E
DOT-05	N0540053011156N_20250909_100141	N0540053011156N
DOT-05	N0521953121218S_20250909_112204	N0521953121218S
DOT-05	N051752111190E_20250910_065659	N051752111190E
DOT-05	N0540053011156N_20250910_100559	N0540053011156N
DOT-05	N0521953121218S_20250910_100942	N0521953121218S
DOT-05	N051752111190E_20250911_065519	N051752111190E
DOT-05	N0521953121218N_20250911_101237	N0521953121218N
DOT-05	N0540053011156N_20250911_102025	N0540053011156N
DOT-05	N051752111190E_20250912_070300	N051752111190E
DOT-05	N0521953121218N_20250912_101644	N0521953121218N
DOT-05	N0540053011156N_20250912_102357	N0540053011156N
DOT-05	N051752111190E_20250915_072145	N051752111190E
DOT-05	N0540053011156N_20250915_101852	N0540053011156N
DOT-05	N051752111190E_20250916_065309	N051752111190E
DOT-05	N0540053011156N_20250916_100420	N0540053011156N
DOT-05	N051752111190E_20250917_063716	N051752111190E
DOT-05	N0540053011156N_20250917_103106	N0540053011156N
DOT-05	N051752111190E_20250918_070841	N051752111190E
DOT-05	N0540053011156N_20250918_100712	N0540053011156N
DOT-05	N051752111190E_20250919_070229	N051752111190E
DOT-05	N0540053011156N_20250919_103131	N0540053011156N
DOT-05	N051752111190E_20250922_074418	N051752111190E
DOT-05	N0540053011156N_20250922_095931	N0540053011156N
DOT-05	N051752111190E_20250923_072341	N051752111190E
DOT-05	N0540053011156N_20250923_100405	N0540053011156N
DOT-05	N051752111190E_20250924_064518	N051752111190E

Region/Division	Deployment ID	Location Code
DOT-05	N0540053011156N_20250924_100810	N0540053011156N
DOT-05	N051752111190E_20250925_071858	N051752111190E
DOT-05	N0540053011156N_20250925_100811	N0540053011156N
DOT-05	N051752111190E_20250926_071932	N051752111190E
DOT-05	N0540053011156N_20250926_100312	N0540053011156N
DOT-05	N051752111190E_20250926_123100	N051752111190E
DOT-05	N051752111190E_20250929_072359	N051752111190E
DOT-05	N051752111190E_20250930_073732	N051752111190E
DOT-05	N0540053011156N_20250930_094624	N0540053011156N
DOT-05	N051752111190E_20251001_071919	N051752111190E
DOT-05	N051752111190E_20251002_073613	N051752111190E
DOT-05	N051752111190E_20251003_075241	N051752111190E
DOT-05	N051752111190E_20251006_071335	N051752111190E
DOT-05	N0540053011156N_20251006_102237	N0540053011156N
DOT-05	N051752111190E_20251007_070629	N051752111190E
DOT-05	N0540053011156N_20251007_102221	N0540053011156N
DOT-05	N0540053011156N_20251007_103621	N0540053011156N
DOT-05	N051752111190E_20251008_074616	N051752111190E
DOT-05	N051752111190E_20251009_072405	N051752111190E
DOT-05	N051752111190E_20251010_065120	N051752111190E
DOT-05	N051752111190E_20251013_072430	N051752111190E
DOT-05	N0540053011156N_20251013_101122	N0540053011156N
DOT-05	N051752111190E_20251014_074127	N051752111190E
DOT-05	N0540053011156N_20251014_101423	N0540053011156N
DOT-05	N051752111190E_20251015_075713	N051752111190E
DOT-05	N0540053011156N_20251015_103513	N0540053011156N
DOT-05	N0521953121218N_20251015_115315	N0521953121218N
DOT-05	N051752111190E_20251016_065458	N051752111190E
DOT-05	N0540053011156N_20251016_100529	N0540053011156N
DOT-05	N0521953121218N_20251016_103340	N0521953121218N
DOT-05	N051752111190E_20251017_074827	N051752111190E
DOT-05	N0521953121261N_20251018_102535	N0521953121261N
DOT-05	N051752111190E_20251020_075802	N051752111190E
DOT-05	N0540053011156N_20251020_104354	N0540053011156N
DOT-05	N051752111190E_20251021_080336	N051752111190E
DOT-05	N0540053011156N_20251021_101923	N0540053011156N
DOT-05	N051752111190E_20251022_081302	N051752111190E
DOT-05	N0540053011156N_20251022_102335	N0540053011156N
DOT-05	N051752111190E_20251023_071448	N051752111190E
DOT-05	N0540053011156N_20251023_101720	N0540053011156N
DOT-05	N0540053011156N_20251023_122919	N0540053011156N
DOT-05	N051752111190E_20251024_081737	N051752111190E
DOT-05	N0540053011156N_20251024_103424	N0540053011156N

Region/Division	Deployment ID	Location Code
DOT-05	N051752111190E_20251027_075730	N051752111190E
DOT-05	N0540053011156N_20251027_121845	N0540053011156N
DOT-05	N051752111190E_20251028_080613	N051752111190E
DOT-05	N051752111190E_20251029_080840	N051752111190E
DOT-05	N05290I53011047E_20251029_110212	N05290I53011047E
DOT-05	N05290I53011047E_20251029_112306	N05290I53011047E
DOT-05	N051752111190E_20251030_080141	N051752111190E
DOT-05	N051752111190E_20251031_082338	N051752111190E
DOT-05	N053353011052E_20251101_101426	N053353011052E
DOT-05	N051752111190E_20251103_074722	N051752111190E
DOT-05	N053353011041W_20251103_202536	N053353011041W
DOT-05	N05290I53011092W_20251104_001448	N05290I53011092W
DOT-05	N05290I53011092W_20251104_030949	N05290I53011092W
DOT-05	N051752111190E_20251104_071743	N051752111190E
DOT-05	N053353011041E_20251104_210856	N053353011041E
DOT-05	N053353011041E_20251105_030458	N053353011041E
DOT-05	N051752111190E_20251105_072400	N051752111190E
DOT-05	N053353011041E_20251105_203833	N053353011041E
DOT-05	N053353011041E_20251105_231026	N053353011041E
DOT-05	N051752111190E_20251106_075120	N051752111190E
DOT-05	N05190I54011032N_20251106_202650	N05190I54011032N
DOT-05	N053353011041W_20251106_203733	N053353011041W
DOT-05	N05190I54011032N_20251106_213515	N05190I54011032N
DOT-05	N053353011041W_20251107_000203	N053353011041W
DOT-05	N051752111190E_20251107_073628	N051752111190E
DOT-05	N051752111190E_20251110_073901	N051752111190E
DOT-05	N051752111190E_20251111_072958	N051752111190E
DOT-05	N051752111190E_20251111_080934	N051752111190E
DOT-05	N051752111190E_20251112_074404	N051752111190E
DOT-05	N051752111190E_20251112_103100	N051752111190E
DOT-05	N051752111190E_20251113_071737	N051752111190E
DOT-05	N051752111190E_20251114_072158	N051752111190E
DOT-05	N051752111190E_20251117_073606	N051752111190E
DOT-05	N051752111190E_20251118_073040	N051752111190E
DOT-05	N051752111190E_20251119_070523	N051752111190E
DOT-05	N051752111190E_20251120_073158	N051752111190E
DOT-05	N051752111190E_20251121_075335	N051752111190E
DOT-05	N051752111190E_20251124_075720	N051752111190E
DOT-05	N053353011057W_20251124_123406	N053353011057W
DOT-05	N051752111190E_20251125_073959	N051752111190E
DOT-05	N051752111190E_20251126_072536	N051752111190E
DOT-05	N051752111190E_20251201_090539	N051752111190E
DOT-05	N0540053011156N_20251208_200210	N0540053011156N

Region/Division	Deployment ID	Location Code
DOT-05	N0540053011156N_20251209_190453	N0540053011156N
DOT-05	N0540053011156N_20251210_191052	N0540053011156N
DOT-05	N0540053011156N_20251211_190629	N0540053011156N
DOT-05	N0540053011156N_20251211_224135	N0540053011156N
DOT-06	N06390I64011016S_20240509_094315	N06390I64011016S
DOT-06	N061764041441E_20240601_102718	N061764041441E
DOT-06	N061764044264W_20240724_105824	N061764044264W
DOT-06	N061764044264W_20240724_113658	N061764044264W
DOT-06	N061764044264E_20240729_110149	N061764044264E
DOT-06	N061764044264W_20240730_094236	N061764044264W
DOT-06	N061764044165E_20240801_095031	N061764044165E
DOT-06	N061764044165W_20240805_092530	N061764044165W
DOT-06	N061764044211E_20240807_131225	N061764044211E
DOT-06	N061762051217W_20240903_094142	N061762051217W
DOT-06	N061762051217W_20240904_105935	N061762051217W
DOT-06	N061762051217W_20240905_101802	N061762051217W
DOT-06	N061764044264E_20240916_083043	N061764044264E
DOT-06	N061764044264E_20240916_093110	N061764044264E
DOT-06	N061764044211W_20240917_084645	N061764044211W
DOT-06	N061764044264W_20240918_084838	N061764044264W
DOT-06	N061764044264W_20240918_131833	N061764044264W
DOT-06	N061764044264E_20240919_075613	N061764044264E
DOT-06	N061764044211W_20240920_080411	N061764044211W
DOT-06	N061764045003W_20240928_100600	N061764045003W
DOT-06	N061764045003W_20240928_112309	N061764045003W
DOT-06	N06390I64011016N_20250826_082218	N06390I64011016N
DOT-06	N061764041441W_20250826_101641	N061764041441W
DOT-06	N06390I64011016S_20250826_111620	N06390I64011016S
DOT-06	N061764041448E_20250827_094945	N061764041448E
DOT-06	N061762051230E_20250915_104854	N061762051230E
DOT-06	N061764044369W_20251124_143545	N061764044369W
DOT-07	N0781I73051100N_20240513_084626	N0781I73051100N
DOT-07	N0781I73051100N_20240514_074943	N0781I73051100N
DOT-07	N0781I73051100N_20240515_074642	N0781I73051100N
DOT-07	N0781I73051100N_20240516_080258	N0781I73051100N
DOT-07	N0781I73051100N_20240517_073151	N0781I73051100N
DOT-07	N0781I73051100N_20240520_083300	N0781I73051100N
DOT-07	N0781I73051100N_20240522_080151	N0781I73051100N
DOT-07	N0781I73051100N_20240529_072701	N0781I73051100N
DOT-07	N0781I73051100N_20240530_070852	N0781I73051100N
DOT-07	N0781I73051100N_20240531_074617	N0781I73051100N
DOT-07	N0781I73051100N_20240603_075159	N0781I73051100N
DOT-07	N0781I73051100N_20240604_080127	N0781I73051100N

Region/Division	Deployment ID	Location Code
DOT-07	N0781I73051100N_20240605_080303	N0781I73051100N
DOT-07	N0781I73051100N_20240606_071355	N0781I73051100N
DOT-07	N0781I73051100N_20240607_070853	N0781I73051100N
DOT-07	N0781I73051102S_20240618_071726	N0781I73051102S
DOT-07	N0781I73051102S_20240619_072408	N0781I73051102S
DOT-07	N0781I73051102S_20240620_075852	N0781I73051102S
DOT-07	N0781I73051102S_20240621_071535	N0781I73051102S
DOT-07	N0781I73051075N_20240709_082126	N0781I73051075N
DOT-07	N0781I73051075N_20240710_081111	N0781I73051075N
DOT-07	N0781I73051075N_20240711_074043	N0781I73051075N
DOT-07	N0781I73051075N_20240712_072514	N0781I73051075N
DOT-07	N0781I73051075N_20240715_070435	N0781I73051075N
DOT-07	N0781I73051075N_20240715_105458	N0781I73051075N
DOT-07	N0781I73051075N_20240716_071747	N0781I73051075N
DOT-07	N0781I73051075N_20240717_072129	N0781I73051075N
DOT-07	N0781I73051075N_20240718_072321	N0781I73051075N
DOT-07	N0781I73051075N_20240719_072342	N0781I73051075N
DOT-07	N0781I73051075N_20240729_072112	N0781I73051075N
DOT-07	N0781I73051075N_20240730_073031	N0781I73051075N
DOT-07	N0781I73051075N_20240731_071548	N0781I73051075N
DOT-07	N0781I73051075N_20240801_071637	N0781I73051075N
DOT-07	N0781I73051075N_20240802_070841	N0781I73051075N
DOT-07	N0781I73051075N_20240805_072456	N0781I73051075N
DOT-07	N0781I73051075N_20240806_065901	N0781I73051075N
DOT-07	N0781I73051075N_20240807_084353	N0781I73051075N
DOT-07	N0781I73051075N_20240808_071652	N0781I73051075N
DOT-07	N0781I73051075N_20240809_073201	N0781I73051075N
DOT-07	N0781I73051075S_20240930_074007	N0781I73051075S
DOT-07	N0781I73051075S_20241001_071805	N0781I73051075S
DOT-07	N0781I73051075S_20241002_074819	N0781I73051075S
DOT-07	N0781I73051075S_20241003_074407	N0781I73051075S
DOT-07	N0781I73051075S_20241004_072351	N0781I73051075S
DOT-07	N0781I73051075S_20250708_074524	N0781I73051075S
DOT-07	N0781I73051075S_20250709_074508	N0781I73051075S
DOT-07	N0781I73051075S_20250710_084031	N0781I73051075S
DOT-07	N0781I73051075S_20250711_074141	N0781I73051075S
DOT-07	N0781I73051075N_20250711_111927	N0781I73051075N
DOT-07	N0781I73051075S_20250715_074523	N0781I73051075S
DOT-07	N0781I73051075S_20250715_104910	N0781I73051075S
DOT-07	N0781I73051075N_20250716_074330	N0781I73051075N
DOT-07	N0781I73051075S_20250717_073951	N0781I73051075S
DOT-08	N0884I82021049E_20240319_130806	N0884I82021049E
DOT-08	N0884I82021049E_20240320_104627	N0884I82021049E

Region/Division	Deployment ID	Location Code
DOT-08	N08684I87011076N_20240321_222625	N08684I87011076N
DOT-08	N08684I87011076N_20240321_224845	N08684I87011076N
DOT-08	N08987G81041268S_20240409_084248	N08987G81041268S
DOT-08	N0884I83011363W_20240416_230914	N0884I83011363W
DOT-08	N0884I83011363W_20240419_021857	N0884I83011363W
DOT-08	N0884I83011363W_20240422_214006	N0884I83011363W
DOT-08	N0884I83011363W_20240429_215354	N0884I83011363W
DOT-08	N0884I83011363W_20240501_220655	N0884I83011363W
DOT-08	N0884I83011363E_20240506_222019	N0884I83011363E
DOT-08	N0884I83011363E_20240514_010716	N0884I83011363E
DOT-08	N0884I83011363W_20240515_225921	N0884I83011363W
DOT-08	N0884I83011363E_20240520_215850	N0884I83011363E
DOT-08	N0884I83011363E_20240521_223345	N0884I83011363E
DOT-08	N08907W87025028S_20240523_120620	N08907W87025028S
DOT-08	N08987G82031026N_20240905_113807	N08987G82031026N
DOT-08	N089W83021047N_20240919_105304	N089W83021047N
DOT-08	N089W83021047S_20240925_112619	N089W83021047S
DOT-08	N089W83021047S_20240927_115916	N089W83021047S
DOT-08	N089W83021047S_20241008_150413	N089W83021047S
DOT-08	N089W83021047S_20241009_121819	N089W83021047S
DOT-08	N0884I83011047W_20241013_211639	N0884I83011047W
DOT-08	N0884I83011047W_20241013_212855	N0884I83011047W
DOT-08	N089W83021047S_20241015_102004	N089W83021047S
DOT-08	N089W83021047N_20241017_141416	N089W83021047N
DOT-08	N089W83021047N_20241018_112411	N089W83021047N
DOT-08	N0884I83011047E_20241020_212855	N0884I83011047E
DOT-08	N089W83021047N_20241021_123359	N089W83021047N
DOT-08	N0884I83011047E_20241021_203439	N0884I83011047E
DOT-08	N089W83021047N_20241022_131655	N089W83021047N
DOT-08	N0884I83011047E_20241022_205536	N0884I83011047E
DOT-08	N089W83021047N_20241023_114004	N089W83021047N
DOT-08	N0884I83011047W_20241023_203850	N0884I83011047W
DOT-08	N089W83021047N_20241024_131337	N089W83021047N
DOT-08	N0884I83011047W_20241024_203720	N0884I83011047W
DOT-08	N089W83021047N_20241025_113045	N089W83021047N
DOT-08	N0884I83011047E_20241027_200353	N0884I83011047E
DOT-08	N089W83021047N_20241028_113558	N089W83021047N
DOT-08	N0884I83011047E_20241028_191852	N0884I83011047E
DOT-08	N089W83021047N_20241029_104517	N089W83021047N
DOT-08	N0884I83011047E_20241029_212231	N0884I83011047E
DOT-08	N089W83021047N_20241030_105203	N089W83021047N
DOT-08	N0884I83011047E_20241030_210305	N0884I83011047E
DOT-08	N089W83021047N_20241031_104215	N089W83021047N

Region/Division	Deployment ID	Location Code
DOT-08	N0884I83011047E_20241031_212726	N0884I83011047E
DOT-08	N089W83021047S_20241101_124721	N089W83021047S
DOT-08	N089W83021047S_20241106_111326	N089W83021047S
DOT-08	N089W83021047S_20241108_130124	N089W83021047S
DOT-08	N089W83021047S_20241112_090715	N089W83021047S
DOT-08	N089W83021047S_20241113_091157	N089W83021047S
DOT-08	N089W83021047S_20241113_113816	N089W83021047S
DOT-08	N089W83021047S_20241114_092859	N089W83021047S
DOT-08	N089W83021047S_20241115_093825	N089W83021047S
DOT-08	N089W83021047S_20241115_103537	N089W83021047S
DOT-08	N089W83021047S_20241115_105225	N089W83021047S
DOT-08	N089W83021047S_20241115_125139	N089W83021047S
DOT-08	N089W83021047S_20241118_084532	N089W83021047S
DOT-08	N089W83021047S_20241119_095313	N089W83021047S
DOT-08	N089W83021047S_20241120_085120	N089W83021047S
DOT-08	N0884I83011363E_20241217_221910	N0884I83011363E
DOT-08	N0884I83011363E_20250114_223011	N0884I83011363E
DOT-08	N089W83021047S_20250318_105745	N089W83021047S
DOT-08	N089W83021047S_20250319_095323	N089W83021047S
DOT-08	N089W83021047S_20250320_111022	N089W83021047S
DOT-08	N089W83021047N_20250326_100101	N089W83021047N
DOT-08	N089W83021047S_20250328_095139	N089W83021047S
DOT-08	N089W83021047S_20250401_090933	N089W83021047S
DOT-08	N0884I83011288E_20250401_205234	N0884I83011288E
DOT-08	N089W83021047S_20250402_100021	N089W83021047S
DOT-08	N089W83021047S_20250402_101503	N089W83021047S
DOT-08	N0884I83011288E_20250402_201129	N0884I83011288E
DOT-08	N0884I83011288E_20250403_215514	N0884I83011288E
DOT-08	N0884I83011288E_20250404_203816	N0884I83011288E
DOT-08	N0884I83011288E_20250404_204457	N0884I83011288E
DOT-08	N0884I83011288E_20250407_202032	N0884I83011288E
DOT-08	N0884I83011288E_20250408_195919	N0884I83011288E
DOT-08	N089W83021047S_20250409_120813	N089W83021047S
DOT-08	N0884I83011288E_20250409_194031	N0884I83011288E
DOT-08	N089W83021047S_20250410_100540	N089W83021047S
DOT-08	N089W83021047N_20250411_101453	N089W83021047N
DOT-08	N089W83021047N_20250411_133415	N089W83021047N
DOT-08	N089W83021047S_20250414_100119	N089W83021047S
DOT-08	N0884I83011288W_20250414_200140	N0884I83011288W
DOT-08	N0884I83011288W_20250414_200658	N0884I83011288W
DOT-08	N08684I87011044S_20250415_005044	N08684I87011044S
DOT-08	N089W83021047S_20250415_090314	N089W83021047S
DOT-08	N0884I83011288W_20250415_195151	N0884I83011288W

Region/Division	Deployment ID	Location Code
DOT-08	N08684I87011044S_20250415_234130	N08684I87011044S
DOT-08	N089W83021047S_20250416_091344	N089W83021047S
DOT-08	N0884I83011288W_20250416_200525	N0884I83011288W
DOT-08	N08684I87011044S_20250416_223025	N08684I87011044S
DOT-08	N089W83021047N_20250417_095654	N089W83021047N
DOT-08	N0884I83011288W_20250417_194334	N0884I83011288W
DOT-08	N089W83021047S_20250418_085312	N089W83021047S
DOT-08	N089W83021047S_20250421_091838	N089W83021047S
DOT-08	N08684I87011044S_20250421_234920	N08684I87011044S
DOT-08	N089W83021047S_20250422_085630	N089W83021047S
DOT-08	N0884I83011288W_20250422_194418	N0884I83011288W
DOT-08	N089W83021047S_20250423_085228	N089W83021047S
DOT-08	N08684I87011076N_20250423_224330	N08684I87011076N
DOT-08	N0884I83011288W_20250424_194404	N0884I83011288W
DOT-08	N089W83021047S_20250425_092534	N089W83021047S
DOT-08	N089W83021047S_20250428_083903	N089W83021047S
DOT-08	N08684I87011044S_20250428_223635	N08684I87011044S
DOT-08	N089W83021047S_20250429_091551	N089W83021047S
DOT-08	N0884I83011288W_20250429_200238	N0884I83011288W
DOT-08	N089W83021047S_20250430_090135	N089W83021047S
DOT-08	N08684I87011076N_20250430_223054	N08684I87011076N
DOT-08	N089W83021047S_20250501_101646	N089W83021047S
DOT-08	N0884I83011288W_20250501_195004	N0884I83011288W
DOT-08	N089W83021047N_20250502_110201	N089W83021047N
DOT-08	N089W83021047S_20250505_092008	N089W83021047S
DOT-08	N089W83021047N_20250505_123649	N089W83021047N
DOT-08	N089W83021047N_20250505_125751	N089W83021047N
DOT-08	N0884I83011288W_20250506_222433	N0884I83011288W
DOT-08	N089W83021047S_20250507_084936	N089W83021047S
DOT-08	N089W83021047S_20250507_091326	N089W83021047S
DOT-08	N0884I83011288W_20250507_195205	N0884I83011288W
DOT-08	N089W83021047S_20250508_091331	N089W83021047S
DOT-08	N089W83021047N_20250509_084902	N089W83021047N
DOT-08	N089W83021047N_20250509_135242	N089W83021047N
DOT-08	N089W83021047S_20250512_090151	N089W83021047S
DOT-08	N0884I83011288W_20250512_195227	N0884I83011288W
DOT-08	N0884I83011288W_20250512_201556	N0884I83011288W
DOT-08	N089W83021047S_20250513_101826	N089W83021047S
DOT-08	N0884I83011288E_20250513_210158	N0884I83011288E
DOT-08	N089W83021047S_20250515_111036	N089W83021047S
DOT-08	N0884I83011288W_20250515_201834	N0884I83011288W
DOT-08	N089W83021047S_20250516_093044	N089W83021047S
DOT-08	N089W83021047S_20250519_085608	N089W83021047S

Region/Division	Deployment ID	Location Code
DOT-08	N0884I83011288W_20250519_200558	N0884I83011288W
DOT-08	N089W83021047S_20250520_110734	N089W83021047S
DOT-08	N0884I83011288E_20250520_194718	N0884I83011288E
DOT-08	N089W83021047N_20250521_102326	N089W83021047N
DOT-08	N089W83021047S_20250527_090417	N089W83021047S
DOT-08	N089W83021047S_20250527_111126	N089W83021047S
DOT-08	N0884I83011288E_20250527_224351	N0884I83011288E
DOT-08	N08684I87011076N_20250527_233838	N08684I87011076N
DOT-08	N089W83021047S_20250528_091438	N089W83021047S
DOT-08	N08684I87011076N_20250528_225651	N08684I87011076N
DOT-08	N08684I87011076N_20250528_230438	N08684I87011076N
DOT-08	N08684I87011076N_20250529_001608	N08684I87011076N
DOT-08	N089W83021047S_20250529_090007	N089W83021047S
DOT-08	N0884I83011288E_20250529_195420	N0884I83011288E
DOT-08	N08684I87011076N_20250529_225115	N08684I87011076N
DOT-08	N089W83021047S_20250530_101909	N089W83021047S
DOT-08	N08684I87011076N_20250530_230807	N08684I87011076N
DOT-08	N089W83021047S_20250602_100341	N089W83021047S
DOT-08	N0884I83011288E_20250602_194823	N0884I83011288E
DOT-08	N089W83021047S_20250603_085805	N089W83021047S
DOT-08	N0884I83011288E_20250603_200325	N0884I83011288E
DOT-08	N089W83021047S_20250604_102643	N089W83021047S
DOT-08	N0884I83011288E_20250605_195654	N0884I83011288E
DOT-08	N089W83021047S_20250606_122743	N089W83021047S
DOT-08	N08684I87011076N_20250608_232136	N08684I87011076N
DOT-08	N08684I87011076N_20250609_002014	N08684I87011076N
DOT-08	N089W83021047S_20250609_081437	N089W83021047S
DOT-08	N0884I83011288E_20250609_202408	N0884I83011288E
DOT-08	N08684I87011076N_20250609_231520	N08684I87011076N
DOT-08	N0884I83011288E_20250610_013915	N0884I83011288E
DOT-08	N089W83021047S_20250610_083014	N089W83021047S
DOT-08	N0884I83011288W_20250610_205800	N0884I83011288W
DOT-08	N08684I87011076N_20250610_230419	N08684I87011076N
DOT-08	N0884I83011288W_20250611_203016	N0884I83011288W
DOT-08	N08684I87011076N_20250611_222111	N08684I87011076N
DOT-08	N0884I83011288W_20250612_211254	N0884I83011288W
DOT-08	N08684I87011076N_20250615_234658	N08684I87011076N
DOT-08	N08684I87011076N_20250616_003145	N08684I87011076N
DOT-08	N08684I87011076N_20250616_222817	N08684I87011076N
DOT-08	N089W83021047N_20250617_090030	N089W83021047N
DOT-08	N089W83021047N_20250618_085039	N089W83021047N
DOT-08	N089W83021047N_20250618_090025	N089W83021047N
DOT-08	N0884I83011047W_20250618_205746	N0884I83011047W

Region/Division	Deployment ID	Location Code
DOT-08	N089W83021047N_20250619_094112	N089W83021047N
DOT-08	N089W83021047S_20250620_102249	N089W83021047S
DOT-08	N0884I83011047W_20250620_204324	N0884I83011047W
DOT-08	N0884I83011047W_20250623_195838	N0884I83011047W
DOT-08	N08684I87011044S_20250623_234912	N08684I87011044S
DOT-08	N0884I83011047W_20250624_202707	N0884I83011047W
DOT-08	N0884I83011047W_20250624_203447	N0884I83011047W
DOT-08	N08684I87011044S_20250624_222927	N08684I87011044S
DOT-08	N0884I83011047W_20250625_200146	N0884I83011047W
DOT-08	N08684I87011044S_20250625_224632	N08684I87011044S
DOT-08	N0884I83011047W_20250626_002152	N0884I83011047W
DOT-08	N0884I82021049E_20250626_203219	N0884I82021049E
DOT-08	N08684I87011044S_20250626_220349	N08684I87011044S
DOT-08	N089W83021047N_20250630_102742	N089W83021047N
DOT-08	N08684I87011044S_20250701_002023	N08684I87011044S
DOT-08	N089W83021047N_20250701_111743	N089W83021047N
DOT-08	N08684I87011044S_20250701_232513	N08684I87011044S
DOT-08	N089W83021047N_20250702_104941	N089W83021047N
DOT-08	N0884I82021049E_20250702_213626	N0884I82021049E
DOT-08	N08684I87011044S_20250702_225025	N08684I87011044S
DOT-08	N089W83021047S_20250703_113955	N089W83021047S
DOT-08	N089W83021047S_20250707_084911	N089W83021047S
DOT-08	N0884I82021049E_20250707_205218	N0884I82021049E
DOT-08	N08684I87011044S_20250707_225755	N08684I87011044S
DOT-08	N08684I87011044S_20250707_232132	N08684I87011044S
DOT-08	N08684I87011044S_20250707_233641	N08684I87011044S
DOT-08	N089W83021047S_20250708_095355	N089W83021047S
DOT-08	N0884I82021049E_20250708_211348	N0884I82021049E
DOT-08	N08684I87011044S_20250708_232608	N08684I87011044S
DOT-08	N08684I87011044S_20250708_234155	N08684I87011044S
DOT-08	N08684I87011044S_20250709_015941	N08684I87011044S
DOT-08	N089W83021047S_20250709_093557	N089W83021047S
DOT-08	N089W83021047S_20250709_100235	N089W83021047S
DOT-08	N08684I87011044S_20250710_015538	N08684I87011044S
DOT-08	N089W83021047S_20250710_083323	N089W83021047S
DOT-08	N0884I82021049E_20250710_211639	N0884I82021049E
DOT-08	N08684I87011044S_20250711_002049	N08684I87011044S
DOT-08	N089W83021047S_20250711_085226	N089W83021047S
DOT-08	N0884I82021049E_20250715_213112	N0884I82021049E
DOT-08	N0884I82021049E_20250716_211424	N0884I82021049E
DOT-08	N0884I82021049E_20250717_213023	N0884I82021049E
DOT-08	N08684I87011076N_20250717_233316	N08684I87011076N
DOT-08	N08684I87011044S_20250718_210300	N08684I87011044S

Region/Division	Deployment ID	Location Code
DOT-08	N08684I87011076N_20250720_225500	N08684I87011076N
DOT-08	N089W83021047S_20250721_111055	N089W83021047S
DOT-08	N089W83021047S_20250721_121052	N089W83021047S
DOT-08	N0884I82021049E_20250721_213615	N0884I82021049E
DOT-08	N089W83021047N_20250722_112559	N089W83021047N
DOT-08	N089W83021047S_20250723_104848	N089W83021047S
DOT-08	N0884I82021132E_20250723_215840	N0884I82021132E
DOT-08	N089W83021047S_20250724_094618	N089W83021047S
DOT-08	N0884I82021132E_20250724_211508	N0884I82021132E
DOT-08	N089W83021047S_20250725_094907	N089W83021047S
DOT-08	N089W83021047S_20250725_115233	N089W83021047S
DOT-08	N08684I87011076N_20250725_221107	N08684I87011076N
DOT-08	N08684I87011076N_20250726_011325	N08684I87011076N
DOT-08	N08684I87011076N_20250727_213330	N08684I87011076N
DOT-08	N089W83021047N_20250728_111924	N089W83021047N
DOT-08	N08684I87011076N_20250729_000306	N08684I87011076N
DOT-08	N089W83021047N_20250729_095942	N089W83021047N
DOT-08	N089W83021047N_20250729_105934	N089W83021047N
DOT-08	N0884I82021049E_20250729_213553	N0884I82021049E
DOT-08	N08684I87011076N_20250729_224217	N08684I87011076N
DOT-08	N0884I82021049E_20250730_014524	N0884I82021049E
DOT-08	N089W83021047N_20250730_095310	N089W83021047N
DOT-08	N0884I84031031E_20250730_220654	N0884I84031031E
DOT-08	N08684I87011076N_20250730_225321	N08684I87011076N
DOT-08	N089W83021047N_20250731_100041	N089W83021047N
DOT-08	N089W83021047N_20250801_090600	N089W83021047N
DOT-08	N089W83021047S_20250804_120139	N089W83021047S
DOT-08	N0884I84031031E_20250804_214053	N0884I84031031E
DOT-08	N08684I87011076N_20250804_221256	N08684I87011076N
DOT-08	N08684I87011076N_20250805_012803	N08684I87011076N
DOT-08	N0884I84031031E_20250805_031046	N0884I84031031E
DOT-08	N089W83021047N_20250805_100953	N089W83021047N
DOT-08	N08684I87011076N_20250805_220019	N08684I87011076N
DOT-08	N0884I84031031E_20250805_220716	N0884I84031031E
DOT-08	N089W83021047N_20250806_112034	N089W83021047N
DOT-08	N0884I84031031E_20250806_214145	N0884I84031031E
DOT-08	N08684I87011076N_20250806_224545	N08684I87011076N
DOT-08	N08684I87011076N_20250807_023653	N08684I87011076N
DOT-08	N089W83021047N_20250807_102109	N089W83021047N
DOT-08	N0884I84031035W_20250807_220227	N0884I84031035W
DOT-08	N08684I87011076N_20250807_234436	N08684I87011076N
DOT-08	N08684I87011076N_20250808_035415	N08684I87011076N
DOT-08	N089W83021047N_20250808_093415	N089W83021047N

Region/Division	Deployment ID	Location Code
DOT-08	N08684I87011076N_20250810_223932	N08684I87011076N
DOT-08	N089W83021047N_20250811_085023	N089W83021047N
DOT-08	N089W83021047N_20250812_083107	N089W83021047N
DOT-08	N0884I84031035W_20250812_220541	N0884I84031035W
DOT-08	N089W83021047N_20250813_091102	N089W83021047N
DOT-08	N089W83021047N_20250814_083920	N089W83021047N
DOT-08	N0884I84031031E_20250814_213810	N0884I84031031E
DOT-08	N0884I84031031E_20250815_011707	N0884I84031031E
DOT-08	N089W83021047N_20250815_085429	N089W83021047N
DOT-08	N08684I87011076N_20250817_223520	N08684I87011076N
DOT-08	N08987G82031143N_20250818_075134	N08987G82031143N
DOT-08	N089W83021047N_20250818_095637	N089W83021047N
DOT-08	N0884I84031035W_20250818_214251	N0884I84031035W
DOT-08	N08684I87011076N_20250818_230649	N08684I87011076N
DOT-08	N08987G82031143N_20250819_074234	N08987G82031143N
DOT-08	N089W83021047N_20250819_091404	N089W83021047N
DOT-08	N0884I84031035W_20250819_220737	N0884I84031035W
DOT-08	N08684I87011076N_20250819_230155	N08684I87011076N
DOT-08	N08987G82031143S_20250820_081327	N08987G82031143S
DOT-08	N089W83021047N_20250820_085949	N089W83021047N
DOT-08	N089W83021047N_20250821_085159	N089W83021047N
DOT-08	N0884I84031035W_20250821_213624	N0884I84031035W
DOT-08	N08684I87011044S_20250822_001709	N08684I87011044S
DOT-08	N0884I84031035W_20250822_010911	N0884I84031035W
DOT-08	N0884I84031035W_20250822_012832	N0884I84031035W
DOT-08	N08987G82031143S_20250822_064602	N08987G82031143S
DOT-08	N089W83021047N_20250822_091116	N089W83021047N
DOT-08	N08684I87011044S_20250822_222047	N08684I87011044S
DOT-08	N089W83021047N_20250825_083313	N089W83021047N
DOT-08	N08987G82031143S_20250825_104248	N08987G82031143S
DOT-08	N08987G82031143S_20250825_104532	N08987G82031143S
DOT-08	N0884I84031035W_20250825_213359	N0884I84031035W
DOT-08	N0884I84031035W_20250825_223528	N0884I84031035W
DOT-08	N08684I87011076N_20250825_231356	N08684I87011076N
DOT-08	N08684I87011076N_20250825_231834	N08684I87011076N
DOT-08	N089W83021047N_20250826_085514	N089W83021047N
DOT-08	N08987G82031143S_20250826_104235	N08987G82031143S
DOT-08	N0884I84031035W_20250826_213140	N0884I84031035W
DOT-08	N08684I87011076N_20250826_231718	N08684I87011076N
DOT-08	N089W83021047N_20250827_090904	N089W83021047N
DOT-08	N0884I84031035W_20250827_215350	N0884I84031035W
DOT-08	N08684I87011076N_20250827_234631	N08684I87011076N
DOT-08	N089W83021047N_20250828_083502	N089W83021047N

Region/Division	Deployment ID	Location Code
DOT-08	N0884I84031035W_20250828_211854	N0884I84031035W
DOT-08	N08684I87011076N_20250828_230023	N08684I87011076N
DOT-08	N089W83021047N_20250902_083642	N089W83021047N
DOT-08	N089W83021047N_20250902_084132	N089W83021047N
DOT-08	N08987G82031143N_20250902_102051	N08987G82031143N
DOT-08	N08987G82031143N_20250902_133701	N08987G82031143N
DOT-08	N0884I84031035W_20250902_203653	N0884I84031035W
DOT-08	N08684I87011076N_20250902_222705	N08684I87011076N
DOT-08	N0884I84031035W_20250903_004909	N0884I84031035W
DOT-08	N089W83021047N_20250903_083936	N089W83021047N
DOT-08	N08987G82031143N_20250903_095702	N08987G82031143N
DOT-08	N0884I84031110W_20250903_202924	N0884I84031110W
DOT-08	N08684I87011076N_20250903_225557	N08684I87011076N
DOT-08	N089W83021047N_20250904_091820	N089W83021047N
DOT-08	N08987G82031143N_20250904_093516	N08987G82031143N
DOT-08	N08684I87011044S_20250904_224321	N08684I87011044S
DOT-08	N089W83021047N_20250905_083012	N089W83021047N
DOT-08	N08987G82031143N_20250905_111422	N08987G82031143N
DOT-08	N08684I87011076N_20250905_223225	N08684I87011076N
DOT-08	N089W83021047N_20250908_083224	N089W83021047N
DOT-08	N08987G82031143N_20250908_104816	N08987G82031143N
DOT-08	N0884I84031081W_20250908_212241	N0884I84031081W
DOT-08	N08684I87011076N_20250908_231237	N08684I87011076N
DOT-08	N089W83021047N_20250909_084933	N089W83021047N
DOT-08	N08987G82031143S_20250909_112806	N08987G82031143S
DOT-08	N0884I84031081W_20250909_210012	N0884I84031081W
DOT-08	N08684I87011044S_20250910_000217	N08684I87011044S
DOT-08	N089W83021047N_20250910_084031	N089W83021047N
DOT-08	N08987G82031143N_20250910_112107	N08987G82031143N
DOT-08	N08987G82031143S_20250910_150214	N08987G82031143S
DOT-08	N0884I84031081W_20250910_204541	N0884I84031081W
DOT-08	N08684I87011076N_20250910_235311	N08684I87011076N
DOT-08	N089W83021047N_20250911_084731	N089W83021047N
DOT-08	N08987G82031143S_20250911_114514	N08987G82031143S
DOT-08	N08684I87011076N_20250911_223027	N08684I87011076N
DOT-08	N0884I84031081W_20250911_235136	N0884I84031081W
DOT-08	N089W83021047N_20250912_083016	N089W83021047N
DOT-08	N08987G82031143S_20250912_105650	N08987G82031143S
DOT-08	N08684I87011076N_20250912_224116	N08684I87011076N
DOT-08	N089W83021047N_20250915_083509	N089W83021047N
DOT-08	N089W83021047N_20250916_095252	N089W83021047N
DOT-08	N089W83021047N_20250917_084130	N089W83021047N
DOT-08	N089W83021047N_20250918_084323	N089W83021047N

Region/Division	Deployment ID	Location Code
DOT-08	N089W83021047N_20250919_091358	N089W83021047N
DOT-08	N089W83021047N_20250922_084055	N089W83021047N
DOT-08	N08684I87011076N_20250922_224242	N08684I87011076N
DOT-08	N089W83021047N_20250923_083112	N089W83021047N
DOT-08	N08684I87011076N_20250923_222158	N08684I87011076N
DOT-08	N089W83021047N_20250924_092349	N089W83021047N
DOT-08	N08684I87011076N_20250924_230941	N08684I87011076N
DOT-08	N089W83021047N_20250925_091746	N089W83021047N
DOT-08	N08684I87011076N_20250925_232159	N08684I87011076N
DOT-08	N089W83021047N_20250926_083305	N089W83021047N
DOT-08	N08684I87011076N_20250926_232257	N08684I87011076N
DOT-08	N089W83021047N_20250929_092552	N089W83021047N
DOT-08	N08684I87011076N_20250929_233625	N08684I87011076N
DOT-08	N089W83021047N_20250930_084226	N089W83021047N
DOT-08	N08684I87011044S_20250930_225843	N08684I87011044S
DOT-08	N089W83021047N_20251001_090432	N089W83021047N
DOT-08	N08684I87011076N_20251001_222304	N08684I87011076N
DOT-08	N089W83021047N_20251002_084446	N089W83021047N
DOT-08	N08684I87011076N_20251002_221747	N08684I87011076N
DOT-08	N08684I87011076N_20251003_011432	N08684I87011076N
DOT-08	N089W83021047N_20251003_083612	N089W83021047N
DOT-08	N08684I87011076N_20251004_002228	N08684I87011076N
DOT-08	N089W83021047N_20251006_085754	N089W83021047N
DOT-08	N089W83021047N_20251007_085227	N089W83021047N
DOT-08	N089W83021047N_20251007_091918	N089W83021047N
DOT-08	N089W83021047N_20251008_084748	N089W83021047N
DOT-08	N089W83021047N_20251009_085859	N089W83021047N
DOT-08	N089W83021047N_20251010_083717	N089W83021047N
DOT-08	N089W83021047N_20251110_084307	N089W83021047N
DOT-08	N089W83021047N_20251111_103606	N089W83021047N
DOT-08	N089W83021047N_20251112_091717	N089W83021047N
DOT-08	N089W83021047N_20251113_092747	N089W83021047N
DOT-08	N089W83021047N_20251114_092416	N089W83021047N
DOT-08	N089W83021047N_20251117_085633	N089W83021047N
DOT-08	N089W83021047N_20251118_095709	N089W83021047N
DOT-08	N089W83021047N_20251118_120600	N089W83021047N
DOT-08	N089W83021047N_20251118_121651	N089W83021047N
DOT-08	N089W83021047S_20251119_083536	N089W83021047S
DOT-08	N089W83021047N_20251120_090447	N089W83021047N
DOT-08	N089W83021047N_20251121_085128	N089W83021047N
DOT-08	N089W83021047N_20251124_082756	N089W83021047N
DOT-08	N089W83021047N_20251125_085010	N089W83021047N
DOT-08	N089W83021047N_20251208_093603	N089W83021047N

Region/Division	Deployment ID	Location Code
DOT-08	N089W83021047N_20251211_084246	N089W83021047N
DOT-08	N089W83021047N_20251212_091710	N089W83021047N
DOT-09	N0988I94063174W_20240513_101659	N0988I94063174W
DOT-09	N0988I94063174W_20240514_081410	N0988I94063174W
DOT-09	N0988I94063174W_20240516_090039	N0988I94063174W
DOT-09	N0988I94063174W_20240516_110645	N0988I94063174W
DOT-09	N0988I94063174W_20240517_081534	N0988I94063174W
DOT-09	N0988I94063163E_20240520_093833	N0988I94063163E
DOT-09	N0988I94063140E_20240521_085513	N0988I94063140E
DOT-09	N0988I94061010E_20240521_095503	N0988I94061010E
DOT-09	N0988I94063140E_20240523_094321	N0988I94063140E
DOT-09	N0988I94063163E_20240524_082514	N0988I94063163E
DOT-09	N0988I94063163E_20240625_111218	N0988I94063163E
DOT-09	N0988I94063140E_20240626_095657	N0988I94063140E
DOT-09	N0988I94063141E_20240627_090641	N0988I94063141E
DOT-09	N0988I95071109W_20240819_074317	N0988I95071109W
DOT-09	N0988I95071109W_20240819_135557	N0988I95071109W
DOT-09	N0988I95071109W_20240820_082303	N0988I95071109W
DOT-09	N0988I95071109W_20240821_072250	N0988I95071109W
DOT-09	N0988I95071193W_20240822_091705	N0988I95071193W
DOT-09	N0988I95071193W_20240822_103033	N0988I95071193W
DOT-09	N0988I95071193W_20240822_131148	N0988I95071193W
DOT-09	N0988I95071193W_20240823_081637	N0988I95071193W
DOT-09	N0988I94063174W_20250416_085544	N0988I94063174W
DOT-09	N0988I94063174W_20250417_075957	N0988I94063174W
DOT-09	N0988I94063148W_20250417_141833	N0988I94063148W
DOT-09	N0988I94063148W_20250421_081512	N0988I94063148W
DOT-09	N0988I94041000W_20250422_071150	N0988I94041000W
DOT-09	N0988I94063148W_20250423_073914	N0988I94063148W
DOT-09	N0988I94041000W_20250423_101853	N0988I94041000W
DOT-09	N0988I94041000W_20250424_064824	N0988I94041000W
DOT-09	N0988I94041000W_20250424_070946	N0988I94041000W
DOT-09	N0988I94041000W_20250424_090143	N0988I94041000W
DOT-09	N0988I94063148W_20250424_102302	N0988I94063148W
DOT-09	N0988I94041000W_20250425_083729	N0988I94041000W
DOT-09	N0988I92021100E_20250520_081356	N0988I92021100E
DOT-09	N0988I92021100E_20250521_073558	N0988I92021100E
DOT-09	N0988I92021100E_20250523_074246	N0988I92021100E
DOT-09	N0988I95071047W_20250527_083436	N0988I95071047W
DOT-09	N0988I95071047W_20250528_064447	N0988I95071047W
DOT-09	N0988I92021100E_20250528_070753	N0988I92021100E
DOT-09	N0988I95071047W_20250529_064055	N0988I95071047W
DOT-09	N0988I95071047W_20250530_060231	N0988I95071047W

Region/Division	Deployment ID	Location Code
DOT-09	N0988I95071047W_20250530_084419	N0988I95071047W
DOT-09	N091793081116E_20250603_085024	N091793081116E
DOT-09	N091793081116E_20250604_065737	N091793081116E
DOT-09	N091793081116E_20250605_071154	N091793081116E
DOT-09	N091793081116E_20250606_071123	N091793081116E
DOT-09	N0988I95071047W_20250609_073959	N0988I95071047W
DOT-09	N091793081116E_20250609_081304	N091793081116E
DOT-09	N0988I95071047W_20250610_074858	N0988I95071047W
DOT-09	N091793081116E_20250610_082130	N091793081116E
DOT-09	N091793081116E_20250611_070051	N091793081116E
DOT-09	N0988I95071047W_20250611_073117	N0988I95071047W
DOT-09	N091765063003W_20250611_112917	N091765063003W
DOT-09	N0988I95071047W_20250612_070606	N0988I95071047W
DOT-09	N091793081116E_20250612_071334	N091793081116E
DOT-09	N0981I91012012N_20250612_083339	N0981I91012012N
DOT-09	N091793081116E_20250613_071547	N091793081116E
DOT-09	N0988I95071047W_20250613_074827	N0988I95071047W
DOT-09	N091765063003W_20250613_095647	N091765063003W
DOT-09	N091793081116E_20250616_063915	N091793081116E
DOT-09	N0988I94063163E_20250616_082338	N0988I94063163E
DOT-09	N091793081116E_20250617_063515	N091793081116E
DOT-09	N0988I94063163E_20250617_073106	N0988I94063163E
DOT-09	N091793081116E_20250618_062023	N091793081116E
DOT-09	N0988I94063163E_20250618_075456	N0988I94063163E
DOT-09	N091793081116E_20250619_055610	N091793081116E
DOT-09	N0988I94063163E_20250619_064446	N0988I94063163E
DOT-09	N091793081116E_20250620_064433	N091793081116E
DOT-09	N0988I95071047E_20250620_075444	N0988I95071047E
DOT-09	N091793081116E_20250623_063200	N091793081116E
DOT-09	N091793081116E_20250624_065030	N091793081116E
DOT-09	N091793081116E_20250625_064506	N091793081116E
DOT-09	N091793081116E_20250626_074543	N091793081116E
DOT-09	N091793081116E_20250627_064723	N091793081116E
DOT-09	N091793081116E_20250630_065511	N091793081116E
DOT-09	N0981I91013030N_20250630_073640	N0981I91013030N
DOT-09	N0988I95071047E_20250630_080748	N0988I95071047E
DOT-09	N0981I91011078S_20250630_081859	N0981I91011078S
DOT-09	N0988I95071047E_20250630_115056	N0988I95071047E
DOT-09	N091793081116E_20250701_072618	N091793081116E
DOT-09	N0981I91013030N_20250701_073643	N0981I91013030N
DOT-09	N0981I91011078S_20250701_075133	N0981I91011078S
DOT-09	N0988I95071047E_20250701_080701	N0988I95071047E
DOT-09	N091793081116E_20250702_065226	N091793081116E

Region/Division	Deployment ID	Location Code
DOT-09	N0981I91011078S_20250702_083235	N0981I91011078S
DOT-09	N0988I95071047E_20250702_083629	N0988I95071047E
DOT-09	N0988I95071047E_20250703_083921	N0988I95071047E
DOT-09	N0981I91011078S_20250707_084526	N0981I91011078S
DOT-09	N091791071033E_20250708_065804	N091791071033E
DOT-09	N0988I95071047E_20250708_074808	N0988I95071047E
DOT-09	N0988I95071047E_20250708_075747	N0988I95071047E
DOT-09	N0988I95071047E_20250709_065448	N0988I95071047E
DOT-09	N0981I91011078S_20250709_081120	N0981I91011078S
DOT-09	N0988I95071047E_20250710_071741	N0988I95071047E
DOT-09	N0988I95071047E_20250710_130831	N0988I95071047E
DOT-09	N0988I95071088E_20250714_070011	N0988I95071088E
DOT-09	N0988I95071088E_20250714_081856	N0988I95071088E
DOT-09	N0988I95071088E_20250715_070621	N0988I95071088E
DOT-09	N0988I95071088E_20250716_072004	N0988I95071088E
DOT-09	N0988I95071088E_20250717_071116	N0988I95071088E
DOT-09	N0988I95071047E_20250721_070509	N0988I95071047E
DOT-09	N091793081116E_20250721_071202	N091793081116E
DOT-09	N0981I91011078N_20250721_104651	N0981I91011078N
DOT-09	N091793081116E_20250722_065721	N091793081116E
DOT-09	N0981I91011078S_20250722_073547	N0981I91011078S
DOT-09	N0988I95071047E_20250722_074429	N0988I95071047E
DOT-09	N0988I95071047E_20250723_071059	N0988I95071047E
DOT-09	N091793081133E_20250723_082320	N091793081133E
DOT-09	N091793081133E_20250724_064110	N091793081133E
DOT-09	N0988I95071047E_20250724_072434	N0988I95071047E
DOT-09	N0981I91011078S_20250724_084719	N0981I91011078S
DOT-09	N091793081133E_20250725_065240	N091793081133E
DOT-09	N0981I91011078S_20250725_081141	N0981I91011078S
DOT-09	N0988I95071047E_20250725_081426	N0988I95071047E
DOT-09	N091793081133E_20250725_104820	N091793081133E
DOT-09	N091793081133E_20250728_063641	N091793081133E
DOT-09	N0988I95071047E_20250728_072234	N0988I95071047E
DOT-09	N0988I95071047E_20250728_105858	N0988I95071047E
DOT-09	N091793081133E_20250729_064348	N091793081133E
DOT-09	N0988I95071047E_20250729_065322	N0988I95071047E
DOT-09	N091793081133E_20250730_063935	N091793081133E
DOT-09	N0988I95071047E_20250730_075620	N0988I95071047E
DOT-09	N0988I94063250E_20250731_083419	N0988I94063250E
DOT-09	N0988I95071047E_20250801_065204	N0988I95071047E
DOT-09	N091793081133E_20250804_065509	N091793081133E
DOT-09	N0981I91013030N_20250805_064422	N0981I91013030N
DOT-09	N0981I91013030N_20250806_072803	N0981I91013030N

Region/Division	Deployment ID	Location Code
DOT-09	N091796091028E_20250806_093954	N091796091028E
DOT-09	N0981191013030N_20250807_082254	N0981191013030N
DOT-09	N091796091135E_20250807_091235	N091796091135E
DOT-09	N0981191013030N_20250811_073911	N0981191013030N
DOT-09	N091796091028E_20250812_100213	N091796091028E
DOT-09	N0981191013030N_20250814_082227	N0981191013030N
DOT-09	N091796091028E_20250814_091221	N091796091028E
DOT-09	N0981191013030N_20250818_080832	N0981191013030N
DOT-09	N0981191013030N_20250819_073842	N0981191013030N
DOT-09	N0988194063163E_20250902_073900	N0988194063163E
DOT-09	N0988194063163E_20250902_134348	N0988194063163E
DOT-09	N0988194063163E_20250903_084811	N0988194063163E
DOT-09	N0988193051072E_20250903_102907	N0988193051072E
DOT-09	N0988194063148W_20250903_130443	N0988194063148W
DOT-09	N0988194063148W_20250904_082434	N0988194063148W
DOT-09	N0988194063148W_20250905_065542	N0988194063148W
DOT-09	N0988194063148W_20250908_085235	N0988194063148W
DOT-09	N091796091028W_20250908_100929	N091796091028W
DOT-09	N0988194063148W_20250909_083905	N0988194063148W
DOT-09	N0988194063140E_20250909_120835	N0988194063140E
DOT-09	N0981191013024S_20250910_083904	N0981191013024S
DOT-09	N0981191013024S_20250911_092730	N0981191013024S
DOT-09	N0981191013024S_20250912_102051	N0981191013024S
DOT-09	N091796091028E_20250915_094950	N091796091028E
DOT-09	N091796091028E_20250916_105818	N091796091028E
DOT-09	N091796091028E_20250917_100108	N091796091028E
DOT-09	N091791071033W_20250923_085944	N091791071033W
DOT-09	N091791071033W_20250924_070605	N091791071033W
DOT-09	N091765063245W_20250924_112413	N091765063245W
DOT-09	N091765063245W_20250926_081740	N091765063245W
DOT-09	N0981191013030N_20250929_095419	N0981191013030N
DOT-09	N091796091028W_20250929_110927	N091796091028W
DOT-09	N0981191013030N_20250930_092745	N0981191013030N
DOT-09	N091796091028W_20250930_095515	N091796091028W
DOT-09	N0981191013030N_20251001_075937	N0981191013030N
DOT-09	N091796091028W_20251001_095119	N091796091028W
DOT-09	N0981191013030N_20251003_081847	N0981191013030N
DOT-09	N0988195071047W_20251006_092043	N0988195071047W
DOT-09	N091793081331E_20251006_103334	N091793081331E
DOT-09	N091793081331E_20251007_071022	N091793081331E
DOT-09	N0988195071047W_20251007_074847	N0988195071047W
DOT-09	N091793081331E_20251008_071533	N091793081331E
DOT-09	N091793081331E_20251009_083636	N091793081331E

Region/Division	Deployment ID	Location Code
DOT-09	N091793081116E_20251027_081721	N091793081116E
DOT-09	N0988I94062007E_20251027_100831	N0988I94062007E
DOT-09	N091791071033E_20251027_111738	N091791071033E
DOT-09	N0988I94062007E_20251028_075504	N0988I94062007E
DOT-09	N0988I94062007E_20251028_080001	N0988I94062007E
DOT-09	N091793081116E_20251028_085218	N091793081116E
DOT-09	N0981I91013024S_20251028_092604	N0981I91013024S
DOT-09	N091791071033E_20251028_102254	N091791071033E
DOT-09	N0988I94062007E_20251029_092647	N0988I94062007E
DOT-09	N091791071033E_20251029_093920	N091791071033E
DOT-09	N0981I91013024S_20251029_094625	N0981I91013024S
DOT-09	N0981I91013024S_20251103_083526	N0981I91013024S
DOT-09	N0981I91013024S_20251104_082030	N0981I91013024S
DOT-09	N0988I91011077W_20251105_075554	N0988I91011077W
DOT-09	N0981I91013024S_20251106_084127	N0981I91013024S
DOT-09	N0981I91013024S_20251107_075806	N0981I91013024S
DOT-10	N10908C03011021E_20240102_073803	N10908C03011021E
DOT-10	N10908C03011021E_20240103_075633	N10908C03011021E
DOT-10	N10908C03011021E_20240104_072127	N10908C03011021E
DOT-10	N10908C03011021E_20240105_075521	N10908C03011021E
DOT-10	N10908E03011005N_20240108_090633	N10908E03011005N
DOT-10	N1049503021117W_20240108_123844	N1049503021117W
DOT-10	N1049503021117W_20240109_113414	N1049503021117W
DOT-10	N10908M03011023W_20240110_121255	N10908M03011023W
DOT-10	N1049507031221W_20240110_234717	N1049507031221W
DOT-10	N10908E03011005N_20240111_072743	N10908E03011005N
DOT-10	N10908C03011021E_20240111_083056	N10908C03011021E
DOT-10	N102707051185W_20240111_112330	N102707051185W
DOT-10	N10908G03011058W_20240111_121024	N10908G03011058W
DOT-10	N1049507031238E_20240111_234601	N1049507031238E
DOT-10	N10908E03011005N_20240112_072018	N10908E03011005N
DOT-10	N102707051191E_20240112_114314	N102707051191E
DOT-10	N10908E03011005N_20240115_080439	N10908E03011005N
DOT-10	N10908E03011005N_20240117_085822	N10908E03011005N
DOT-10	N10908E03011005N_20240118_080835	N10908E03011005N
DOT-10	N10908C03011021E_20240119_110546	N10908C03011021E
DOT-10	N10908E03011005N_20240122_072737	N10908E03011005N
DOT-10	N102707051175E_20240122_233916	N102707051175E
DOT-10	N1049507031181E_20240123_014447	N1049507031181E
DOT-10	N10908C03011021E_20240123_073856	N10908C03011021E
DOT-10	N102707051175E_20240124_003707	N102707051175E
DOT-10	N1049507031181E_20240124_011344	N1049507031181E
DOT-10	N102707051175E_20240124_235739	N102707051175E

Region/Division	Deployment ID	Location Code
DOT-10	N1049507031226W_20240127_010508	N1049507031226W
DOT-10	N10908C03011021E_20240129_084125	N10908C03011021E
DOT-10	N10908C03011021E_20240129_142242	N10908C03011021E
DOT-10	N102707051175E_20240129_230355	N102707051175E
DOT-10	N10908K07011041S_20240130_000859	N10908K07011041S
DOT-10	N10908C03011021E_20240130_075527	N10908C03011021E
DOT-10	N10908E03011005N_20240130_081100	N10908E03011005N
DOT-10	N10908K07011041S_20240131_005421	N10908K07011041S
DOT-10	N10908E03011005N_20240131_073447	N10908E03011005N
DOT-10	N10908C03011021E_20240131_075809	N10908C03011021E
DOT-10	N10908K07011041S_20240131_223425	N10908K07011041S
DOT-10	N10908E03011005S_20240201_073009	N10908E03011005S
DOT-10	N10908C03011021E_20240201_075746	N10908C03011021E
DOT-10	N10908E03011005N_20240201_081343	N10908E03011005N
DOT-10	N10908K07011041S_20240201_235708	N10908K07011041S
DOT-10	N10908C03011021E_20240202_085927	N10908C03011021E
DOT-10	N10908K07011041S_20240202_225256	N10908K07011041S
DOT-10	N102707051175E_20240203_010828	N102707051175E
DOT-10	N102707051175E_20240203_051937	N102707051175E
DOT-10	N102707051175E_20240203_131932	N102707051175E
DOT-10	N102707051175E_20240203_212748	N102707051175E
DOT-10	N10908C03011021E_20240205_073630	N10908C03011021E
DOT-10	N10908E03011005S_20240205_075343	N10908E03011005S
DOT-10	N10908K07011041S_20240205_230536	N10908K07011041S
DOT-10	N10908E03011005S_20240206_080455	N10908E03011005S
DOT-10	N1049507031046E_20240206_131832	N1049507031046E
DOT-10	N10908K07011041S_20240206_222934	N10908K07011041S
DOT-10	N10908E03011005S_20240207_074323	N10908E03011005S
DOT-10	N10908C03011021E_20240207_080918	N10908C03011021E
DOT-10	N10908K07011041S_20240207_225248	N10908K07011041S
DOT-10	N10908E03011005S_20240208_073937	N10908E03011005S
DOT-10	N10908C03011021E_20240208_080714	N10908C03011021E
DOT-10	N1049507031217E_20240208_235356	N1049507031217E
DOT-10	N10908E03011005S_20240209_074827	N10908E03011005S
DOT-10	N10908C03011021E_20240209_075614	N10908C03011021E
DOT-10	N10908K07011041S_20240209_223121	N10908K07011041S
DOT-10	N10908C03011021E_20240212_073919	N10908C03011021E
DOT-10	N10908E03011005N_20240212_093607	N10908E03011005N
DOT-10	N10908K07011041S_20240215_015119	N10908K07011041S
DOT-10	N10908E03011005N_20240215_070408	N10908E03011005N
DOT-10	N10908C03011021E_20240215_072528	N10908C03011021E
DOT-10	N10908K07011041S_20240215_220829	N10908K07011041S
DOT-10	N1049503021095E_20240216_005213	N1049503021095E

Region/Division	Deployment ID	Location Code
DOT-10	N10908C03011021E_20240216_071452	N10908C03011021E
DOT-10	N10908E03011005N_20240219_085008	N10908E03011005N
DOT-10	N10908K07011040S_20240219_220628	N10908K07011040S
DOT-10	N10908E03011005N_20240220_072003	N10908E03011005N
DOT-10	N10908C03011021E_20240220_072928	N10908C03011021E
DOT-10	N10908E03011005S_20240221_083529	N10908E03011005S
DOT-10	N10908E03011005N_20240221_101156	N10908E03011005N
DOT-10	N10908E03011005N_20240222_071919	N10908E03011005N
DOT-10	N10908E03011005S_20240222_074305	N10908E03011005S
DOT-10	N10908K07011040N_20240223_005718	N10908K07011040N
DOT-10	N1049507031238W_20240224_000608	N1049507031238W
DOT-10	N10908E03011005N_20240226_072017	N10908E03011005N
DOT-10	N10908E03011005S_20240226_110038	N10908E03011005S
DOT-10	N10908E03011005N_20240226_115137	N10908E03011005N
DOT-10	N10908E03011005N_20240227_071518	N10908E03011005N
DOT-10	N10908E03011005S_20240227_072142	N10908E03011005S
DOT-10	N10908E03011005N_20240229_072410	N10908E03011005N
DOT-10	N10908E03011005S_20240301_071133	N10908E03011005S
DOT-10	N10908E03011005N_20240301_071444	N10908E03011005N
DOT-10	N1049507031217W_20240302_011821	N1049507031217W
DOT-10	N10908E03011005S_20240304_072351	N10908E03011005S
DOT-10	N10908E03011005N_20240304_072648	N10908E03011005N
DOT-10	N1049507031238W_20240306_000108	N1049507031238W
DOT-10	N10908T03011078N_20240306_115754	N10908T03011078N
DOT-10	N10908E03011005N_20240307_110213	N10908E03011005N
DOT-10	N10908T03011078N_20240307_115257	N10908T03011078N
DOT-10	N10908E03011005S_20240308_070026	N10908E03011005S
DOT-10	N10908C03011021E_20240308_080250	N10908C03011021E
DOT-10	N10908G03011077W_20240312_001633	N10908G03011077W
DOT-10	N10908C03011021E_20240312_072738	N10908C03011021E
DOT-10	N10908E03011005S_20240312_091354	N10908E03011005S
DOT-10	N102707051496E_20240312_112740	N102707051496E
DOT-10	N10908M03011049E_20240312_232854	N10908M03011049E
DOT-10	N1049503021027E_20240313_022735	N1049503021027E
DOT-10	N10908E03011005S_20240313_080128	N10908E03011005S
DOT-10	N102707051496W_20240313_112252	N102707051496W
DOT-10	N10908C03011021E_20240313_115454	N10908C03011021E
DOT-10	N1049503021156E_20240314_001029	N1049503021156E
DOT-10	N10908C03011021E_20240314_073651	N10908C03011021E
DOT-10	N10908E03011005S_20240314_074734	N10908E03011005S
DOT-10	N10908M03011093E_20240314_235535	N10908M03011093E
DOT-10	N1049507031047W_20240315_004809	N1049507031047W
DOT-10	N10908C03011021E_20240315_071917	N10908C03011021E

Region/Division	Deployment ID	Location Code
DOT-10	N10908E03011005S_20240315_074812	N10908E03011005S
DOT-10	N10908M03011093E_20240315_231937	N10908M03011093E
DOT-10	N10908E03011005S_20240318_072317	N10908E03011005S
DOT-10	N10908C03011021E_20240318_074332	N10908C03011021E
DOT-10	N102707051051E_20240318_111254	N102707051051E
DOT-10	N1049507031029E_20240319_005627	N1049507031029E
DOT-10	N10908E03011005S_20240319_072306	N10908E03011005S
DOT-10	N10908C03011021E_20240319_073336	N10908C03011021E
DOT-10	N10908J07011039N_20240319_110727	N10908J07011039N
DOT-10	N1049503021117W_20240319_232532	N1049503021117W
DOT-10	N10908M03011144E_20240319_235841	N10908M03011144E
DOT-10	N10908E03011005S_20240320_071254	N10908E03011005S
DOT-10	N10908C03011021E_20240320_072917	N10908C03011021E
DOT-10	N10908M03011144E_20240320_233723	N10908M03011144E
DOT-10	N1049503021095E_20240321_010959	N1049503021095E
DOT-10	N10908C03011021E_20240321_070240	N10908C03011021E
DOT-10	N10908E03011005S_20240321_072224	N10908E03011005S
DOT-10	N10908J07011039N_20240321_111626	N10908J07011039N
DOT-10	N10908M03011144W_20240322_000002	N10908M03011144W
DOT-10	N10908M03011144W_20240322_002954	N10908M03011144W
DOT-10	N1049503021095E_20240322_013852	N1049503021095E
DOT-10	N10908E03011005S_20240322_071832	N10908E03011005S
DOT-10	N10908C03011021E_20240322_073611	N10908C03011021E
DOT-10	N10908J07011039N_20240322_110207	N10908J07011039N
DOT-10	N10908M03011118W_20240323_000035	N10908M03011118W
DOT-10	N1049503021095E_20240323_011255	N1049503021095E
DOT-10	N10908C03011021E_20240325_071421	N10908C03011021E
DOT-10	N10908E03011005S_20240325_080946	N10908E03011005S
DOT-10	N1049503021131W_20240326_003449	N1049503021131W
DOT-10	N10908G03011142W_20240326_012325	N10908G03011142W
DOT-10	N10908E03011005S_20240326_072842	N10908E03011005S
DOT-10	N10908C03011021E_20240326_081950	N10908C03011021E
DOT-10	N1049503021131W_20240327_003931	N1049503021131W
DOT-10	N10908G03011135E_20240327_012959	N10908G03011135E
DOT-10	N10908C03011021E_20240327_075125	N10908C03011021E
DOT-10	N1049503021131W_20240327_235342	N1049503021131W
DOT-10	N10908C03011021E_20240329_072444	N10908C03011021E
DOT-10	N1049503021131W_20240330_002438	N1049503021131W
DOT-10	N1049503021117W_20240402_021124	N1049503021117W
DOT-10	N10908C03011021E_20240405_074339	N10908C03011021E
DOT-10	N10908C03011021E_20240408_071322	N10908C03011021E
DOT-10	N10908E03011005S_20240408_085704	N10908E03011005S
DOT-10	N1049503021056E_20240408_121403	N1049503021056E

Region/Division	Deployment ID	Location Code
DOT-10	N10908C03011021E_20240409_080457	N10908C03011021E
DOT-10	N1049503021056E_20240409_111002	N1049503021056E
DOT-10	N10908E03011005N_20240410_073911	N10908E03011005N
DOT-10	N10908C03011021E_20240410_081959	N10908C03011021E
DOT-10	N10908C03011021E_20240411_065231	N10908C03011021E
DOT-10	N10908E03011005N_20240411_072705	N10908E03011005N
DOT-10	N10908E03011005S_20240411_074401	N10908E03011005S
DOT-10	N10908E03011005N_20240412_065235	N10908E03011005N
DOT-10	N10908C03011021E_20240415_071750	N10908C03011021E
DOT-10	N10908E03011005S_20240415_100646	N10908E03011005S
DOT-10	N1049503021077W_20240415_121643	N1049503021077W
DOT-10	N10908C03011021E_20240416_065805	N10908C03011021E
DOT-10	N1049503021077E_20240416_115827	N1049503021077E
DOT-10	N10908C03011021E_20240417_074929	N10908C03011021E
DOT-10	N1049503021077E_20240417_114513	N1049503021077E
DOT-10	N10908C03011021E_20240418_064915	N10908C03011021E
DOT-10	N10908C03011021E_20240419_065111	N10908C03011021E
DOT-10	N10908C03011021E_20240422_071323	N10908C03011021E
DOT-10	N10908C03011021E_20240423_072953	N10908C03011021E
DOT-10	N10908C03011021E_20240424_071428	N10908C03011021E
DOT-10	N10908C03011021E_20240425_072701	N10908C03011021E
DOT-10	N10908C03011021E_20240426_070613	N10908C03011021E
DOT-10	N10908C03011021E_20240429_070447	N10908C03011021E
DOT-10	N102707051329W_20240429_102145	N102707051329W
DOT-10	N10908C03011021E_20240430_072132	N10908C03011021E
DOT-10	N10908C03011021E_20240501_080945	N10908C03011021E
DOT-10	N10908C03011021E_20240502_072701	N10908C03011021E
DOT-10	N10908K07011070N_20240502_105753	N10908K07011070N
DOT-10	N102707051329W_20240502_132854	N102707051329W
DOT-10	N10908C03011021E_20240503_065319	N10908C03011021E
DOT-10	N102707051329W_20240503_094039	N102707051329W
DOT-10	N102707051329W_20240506_101421	N102707051329W
DOT-10	N102707051329W_20240507_092748	N102707051329W
DOT-10	N102707051329W_20240508_092640	N102707051329W
DOT-10	N10908T03011065S_20240508_120751	N10908T03011065S
DOT-10	N102707051329W_20240509_085139	N102707051329W
DOT-10	N10908T03011065N_20240509_113151	N10908T03011065N
DOT-10	N102707051329W_20240510_090755	N102707051329W
DOT-10	N102707051329W_20240510_132913	N102707051329W
DOT-10	N10908C03011021E_20240513_081701	N10908C03011021E
DOT-10	N102707051329W_20240513_084941	N102707051329W
DOT-10	N10908C03011020W_20240514_075502	N10908C03011020W
DOT-10	N10908C03011021E_20240514_081837	N10908C03011021E

Region/Division	Deployment ID	Location Code
DOT-10	N1049507031217E_20240514_112349	N1049507031217E
DOT-10	N10908C03011020W_20240516_085208	N10908C03011020W
DOT-10	N10908C03011021E_20240516_090348	N10908C03011021E
DOT-10	N10908C03011020W_20240516_113051	N10908C03011020W
DOT-10	N10908C03011021E_20240517_081142	N10908C03011021E
DOT-10	N1049507031056E_20240517_112445	N1049507031056E
DOT-10	N10908C03011021E_20240520_091232	N10908C03011021E
DOT-10	N102707051329W_20240520_101552	N102707051329W
DOT-10	N10908C03011021E_20240521_074857	N10908C03011021E
DOT-10	N102707051329W_20240521_093024	N102707051329W
DOT-10	N1049507031131W_20240521_113511	N1049507031131W
DOT-10	N10908C03011020W_20240522_074425	N10908C03011020W
DOT-10	N102707051329W_20240522_085856	N102707051329W
DOT-10	N10908C03011020W_20240523_090737	N10908C03011020W
DOT-10	N102707051329W_20240523_094806	N102707051329W
DOT-10	N1049507031047W_20240523_123229	N1049507031047W
DOT-10	N10908M03011152W_20240523_231616	N10908M03011152W
DOT-10	N10908C03011021E_20240528_110403	N10908C03011021E
DOT-10	N102707051329W_20240528_111250	N102707051329W
DOT-10	N10908C03011020W_20240529_095804	N10908C03011020W
DOT-10	N102707051329W_20240529_101734	N102707051329W
DOT-10	N102707051329W_20240530_094301	N102707051329W
DOT-10	N102707051329W_20240531_091252	N102707051329W
DOT-10	N1049507031217W_20240531_112702	N1049507031217W
DOT-10	N102707051329W_20240603_085540	N102707051329W
DOT-10	N1049507031251W_20240603_233036	N1049507031251W
DOT-10	N102707051329W_20240604_091724	N102707051329W
DOT-10	N102707051329W_20240604_115116	N102707051329W
DOT-10	N1049507031251W_20240605_002419	N1049507031251W
DOT-10	N102707051329W_20240605_093601	N102707051329W
DOT-10	N1049507031221W_20240606_005540	N1049507031221W
DOT-10	N102707051329W_20240606_084039	N102707051329W
DOT-10	N1049507031217W_20240607_001214	N1049507031217W
DOT-10	N102707051329W_20240607_083432	N102707051329W
DOT-10	N102707051330W_20240607_115152	N102707051330W
DOT-10	N1049507031181W_20240608_002010	N1049507031181W
DOT-10	N102707051329W_20240610_094140	N102707051329W
DOT-10	N1049507031257E_20240610_114510	N1049507031257E
DOT-10	N10908M03011144W_20240610_231734	N10908M03011144W
DOT-10	N1049507031181W_20240611_010725	N1049507031181W
DOT-10	N102707051329W_20240611_105046	N102707051329W
DOT-10	N1013503011055N_20240611_111008	N1013503011055N
DOT-10	N1049507031257E_20240611_113511	N1049507031257E

Region/Division	Deployment ID	Location Code
DOT-10	N10908M03011118W_20240611_231143	N10908M03011118W
DOT-10	N102707051329W_20240612_090703	N102707051329W
DOT-10	N1049503021131E_20240612_111514	N1049503021131E
DOT-10	N102707051329W_20240613_092314	N102707051329W
DOT-10	N1013503011048S_20240613_104240	N1013503011048S
DOT-10	N102707051329W_20240614_085604	N102707051329W
DOT-10	N102707051329W_20240618_091346	N102707051329W
DOT-10	N102707051329W_20240619_084741	N102707051329W
DOT-10	N102707051329W_20240619_115913	N102707051329W
DOT-10	N102707051329W_20240620_092445	N102707051329W
DOT-10	N102707051329W_20240621_095731	N102707051329W
DOT-10	N102707051329W_20240624_094413	N102707051329W
DOT-10	N102707051329W_20240625_091312	N102707051329W
DOT-10	N102707051329W_20240626_100542	N102707051329W
DOT-10	N102707051329W_20240626_100740	N102707051329W
DOT-10	N102707051329W_20240626_103504	N102707051329W
DOT-10	N102707051329W_20240626_113509	N102707051329W
DOT-10	N102707051329W_20240627_084050	N102707051329W
DOT-10	N102707051329W_20240628_094736	N102707051329W
DOT-10	N102707051329W_20240701_095121	N102707051329W
DOT-10	N102707051329W_20240702_095934	N102707051329W
DOT-10	N102707051329W_20240703_100727	N102707051329W
DOT-10	N102707051329W_20240708_091508	N102707051329W
DOT-10	N102707051329W_20240709_083536	N102707051329W
DOT-10	N1023107011016S_20240709_112543	N1023107011016S
DOT-10	N1049507031376W_20240709_223317	N1049507031376W
DOT-10	N102707051329W_20240710_083621	N102707051329W
DOT-10	N102707051329W_20240711_093303	N102707051329W
DOT-10	N1049507031376W_20240711_214643	N1049507031376W
DOT-10	N102707051329W_20240712_084237	N102707051329W
DOT-10	N102707051329W_20240715_094156	N102707051329W
DOT-10	N1049507031376W_20240715_213027	N1049507031376W
DOT-10	N102707051329W_20240716_095152	N102707051329W
DOT-10	N1049507031376W_20240716_211526	N1049507031376W
DOT-10	N102707051329W_20240717_090229	N102707051329W
DOT-10	N102707051329W_20240718_090800	N102707051329W
DOT-10	N1049507031376W_20240718_221004	N1049507031376W
DOT-10	N102707051329W_20240719_091301	N102707051329W
DOT-10	N1049507031376W_20240719_222030	N1049507031376W
DOT-10	N102707051329W_20240722_102906	N102707051329W
DOT-10	N102707051329W_20240723_093304	N102707051329W
DOT-10	N102707051248E_20240723_232403	N102707051248E
DOT-10	N102707051329W_20240724_101554	N102707051329W

Region/Division	Deployment ID	Location Code
DOT-10	N1049503021042E_20240725_013106	N1049503021042E
DOT-10	N102707051329W_20240725_090637	N102707051329W
DOT-10	N1049507031376W_20240725_220834	N1049507031376W
DOT-10	N1049503021042E_20240726_011943	N1049503021042E
DOT-10	N102707051329W_20240726_092319	N102707051329W
DOT-10	N1049507031376W_20240726_220450	N1049507031376W
DOT-10	N102707051329W_20240729_091056	N102707051329W
DOT-10	N1049507031376W_20240729_215500	N1049507031376W
DOT-10	N1049507031162E_20240730_002329	N1049507031162E
DOT-10	N1049503021056E_20240730_014002	N1049503021056E
DOT-10	N102707051329W_20240730_085823	N102707051329W
DOT-10	N102707051329W_20240731_090102	N102707051329W
DOT-10	N1049507031376W_20240801_005238	N1049507031376W
DOT-10	N102707051329W_20240801_092251	N102707051329W
DOT-10	N1049503021056E_20240802_010718	N1049503021056E
DOT-10	N102707051329W_20240802_092737	N102707051329W
DOT-10	N102707051329W_20240805_084936	N102707051329W
DOT-10	N1049507031376W_20240805_214739	N1049507031376W
DOT-10	N10908G03011071E_20240806_011449	N10908G03011071E
DOT-10	N1049503021077E_20240806_011642	N1049503021077E
DOT-10	N102707051329W_20240806_093604	N102707051329W
DOT-10	N102707051329W_20240807_092201	N102707051329W
DOT-10	N1049507031376W_20240807_215003	N1049507031376W
DOT-10	N102707051329W_20240808_085329	N102707051329W
DOT-10	N1049507031376W_20240808_215316	N1049507031376W
DOT-10	N102707051329W_20240809_090414	N102707051329W
DOT-10	N102707051329W_20240812_092708	N102707051329W
DOT-10	N1049507031376W_20240812_222121	N1049507031376W
DOT-10	N1049503021131E_20240813_002447	N1049503021131E
DOT-10	N102707051329W_20240813_090417	N102707051329W
DOT-10	N1049507031376W_20240813_213237	N1049507031376W
DOT-10	N1049503021077E_20240814_011914	N1049503021077E
DOT-10	N1049503021077E_20240814_030902	N1049503021077E
DOT-10	N102707051329W_20240814_090244	N102707051329W
DOT-10	N1049507031376W_20240814_214213	N1049507031376W
DOT-10	N102707051329W_20240815_084602	N102707051329W
DOT-10	N1049507031376W_20240815_212600	N1049507031376W
DOT-10	N1049503021027W_20240815_231716	N1049503021027W
DOT-10	N1049503021089E_20240816_011114	N1049503021089E
DOT-10	N1049503021089E_20240816_021238	N1049503021089E
DOT-10	N102707051329W_20240816_084954	N102707051329W
DOT-10	N102707051329W_20240819_090330	N102707051329W
DOT-10	N1049507031376W_20240819_211618	N1049507031376W

Region/Division	Deployment ID	Location Code
DOT-10	N1049503021132E_20240820_004204	N1049503021132E
DOT-10	N1049503021099E_20240820_030255	N1049503021099E
DOT-10	N102707051329W_20240820_094744	N102707051329W
DOT-10	N1049507031376W_20240820_212345	N1049507031376W
DOT-10	N1049503021132E_20240821_011129	N1049503021132E
DOT-10	N102707051329W_20240821_092616	N102707051329W
DOT-10	N1049507031376W_20240821_223029	N1049507031376W
DOT-10	N1049503021132E_20240822_004909	N1049503021132E
DOT-10	N1049507031376W_20240822_030221	N1049507031376W
DOT-10	N102707051329W_20240822_093507	N102707051329W
DOT-10	N1049507031376W_20240822_213755	N1049507031376W
DOT-10	N1049503021132E_20240823_004035	N1049503021132E
DOT-10	N102707051329W_20240823_091147	N102707051329W
DOT-10	N102707051329W_20240826_090932	N102707051329W
DOT-10	N1049507031376W_20240826_212850	N1049507031376W
DOT-10	N1049503021042E_20240827_011059	N1049503021042E
DOT-10	N102707051329W_20240827_085629	N102707051329W
DOT-10	N1049507031376W_20240827_213351	N1049507031376W
DOT-10	N10908T03011078S_20240827_233101	N10908T03011078S
DOT-10	N1049503021077E_20240828_015956	N1049503021077E
DOT-10	N102707051329W_20240828_091133	N102707051329W
DOT-10	N1049507031376W_20240828_213858	N1049507031376W
DOT-10	N102707051329W_20240829_090733	N102707051329W
DOT-10	N102707051329W_20240903_094450	N102707051329W
DOT-10	N1049507031376W_20240903_214638	N1049507031376W
DOT-10	N1049503021132E_20240904_023055	N1049503021132E
DOT-10	N1049503021132E_20240904_023233	N1049503021132E
DOT-10	N1049503021132E_20240904_024742	N1049503021132E
DOT-10	N102707051329W_20240904_085550	N102707051329W
DOT-10	N1049507031376W_20240904_211717	N1049507031376W
DOT-10	N102707051329W_20240905_091831	N102707051329W
DOT-10	N1049503021132E_20240905_235511	N1049503021132E
DOT-10	N102707051329W_20240906_090014	N102707051329W
DOT-10	N1049507031376W_20240906_222926	N1049507031376W
DOT-10	N1049503021132E_20240907_001050	N1049503021132E
DOT-10	N102707051329W_20240909_090009	N102707051329W
DOT-10	N1049507031376W_20240909_212045	N1049507031376W
DOT-10	N1049503021132E_20240910_001142	N1049503021132E
DOT-10	N10908G03011012W_20240910_002753	N10908G03011012W
DOT-10	N102707051329W_20240910_083213	N102707051329W
DOT-10	N1049507031376W_20240910_213342	N1049507031376W
DOT-10	N102707051329W_20240911_084451	N102707051329W
DOT-10	N1049507031376W_20240911_211546	N1049507031376W

Region/Division	Deployment ID	Location Code
DOT-10	N1049503021132W_20240912_004251	N1049503021132W
DOT-10	N102707051329W_20240912_110332	N102707051329W
DOT-10	N1049507031376W_20240912_223006	N1049507031376W
DOT-10	N1049503021117W_20240913_003527	N1049503021117W
DOT-10	N102707051329W_20240913_091432	N102707051329W
DOT-10	N1049507031376W_20240913_221828	N1049507031376W
DOT-10	N1049503021077W_20240916_001800	N1049503021077W
DOT-10	N102707051329W_20240916_084917	N102707051329W
DOT-10	N1049507031376W_20240916_223203	N1049507031376W
DOT-10	N1049503021051W_20240917_001852	N1049503021051W
DOT-10	N102707051329W_20240917_084340	N102707051329W
DOT-10	N1049507031376W_20240917_214635	N1049507031376W
DOT-10	N102707051329W_20240918_095618	N102707051329W
DOT-10	N1049507031297W_20240918_234540	N1049507031297W
DOT-10	N1049503021027E_20240920_003657	N1049503021027E
DOT-10	N1049503021132W_20240920_004644	N1049503021132W
DOT-10	N1049507031376W_20240920_012433	N1049507031376W
DOT-10	N102707051329W_20240920_094135	N102707051329W
DOT-10	N1049507031376W_20240920_223257	N1049507031376W
DOT-10	N1049503021132W_20240921_002800	N1049503021132W
DOT-10	N1049503021132W_20240923_001954	N1049503021132W
DOT-10	N102707051329W_20240923_085107	N102707051329W
DOT-10	N10908J07011024N_20240923_105630	N10908J07011024N
DOT-10	N102707051329W_20240923_111442	N102707051329W
DOT-10	N1049507031376W_20240923_211122	N1049507031376W
DOT-10	N10908G03011023W_20240923_232232	N10908G03011023W
DOT-10	N102707051329W_20240924_085206	N102707051329W
DOT-10	N1049507031376W_20240924_210328	N1049507031376W
DOT-10	N1049503021132W_20240925_013456	N1049503021132W
DOT-10	N102707051329W_20240925_085753	N102707051329W
DOT-10	N102707051329W_20240926_090815	N102707051329W
DOT-10	N102707051329W_20240926_101641	N102707051329W
DOT-10	N10908G03011023W_20240927_001415	N10908G03011023W
DOT-10	N102707051329W_20240927_085355	N102707051329W
DOT-10	N1049507031376W_20240927_204424	N1049507031376W
DOT-10	N102707051329W_20240930_091110	N102707051329W
DOT-10	N1049507031376W_20240930_222229	N1049507031376W
DOT-10	N10908G03011023W_20241001_000107	N10908G03011023W
DOT-10	N102707051329W_20241001_085428	N102707051329W
DOT-10	N1049507031376W_20241001_205924	N1049507031376W
DOT-10	N102707051329W_20241002_090519	N102707051329W
DOT-10	N1049507031376W_20241002_212608	N1049507031376W
DOT-10	N102707051329W_20241003_144254	N102707051329W

Region/Division	Deployment ID	Location Code
DOT-10	N1049507031376W_20241003_212327	N1049507031376W
DOT-10	N10908G03011023W_20241003_234642	N10908G03011023W
DOT-10	N1049507031376W_20241004_212007	N1049507031376W
DOT-10	N102707051329W_20241007_083707	N102707051329W
DOT-10	N1049507031376W_20241007_230817	N1049507031376W
DOT-10	N1049503021042E_20241008_013143	N1049503021042E
DOT-10	N102707051329W_20241008_101311	N102707051329W
DOT-10	N102707051329W_20241009_114121	N102707051329W
DOT-10	N1049507031376W_20241009_211626	N1049507031376W
DOT-10	N1049507031376W_20241010_214717	N1049507031376W
DOT-10	N102707051329W_20241011_103003	N102707051329W
DOT-10	N1049507031376W_20241011_210127	N1049507031376W
DOT-10	N1049507031376W_20241012_030537	N1049507031376W
DOT-10	N1049507031376W_20241014_211451	N1049507031376W
DOT-10	N1049507031376W_20241015_211352	N1049507031376W
DOT-10	N1049507031376W_20241016_211535	N1049507031376W
DOT-10	N1049507031376W_20241017_211124	N1049507031376W
DOT-10	N1049507031376W_20241018_211014	N1049507031376W
DOT-10	N1049503021035E_20241019_000309	N1049503021035E
DOT-10	N1049503021132E_20241020_235237	N1049503021132E
DOT-10	N102707051329W_20241021_104001	N102707051329W
DOT-10	N102707051329W_20241021_112418	N102707051329W
DOT-10	N1049507031297E_20241021_221445	N1049507031297E
DOT-10	N1049503021002E_20241021_233817	N1049503021002E
DOT-10	N1049503021002E_20241022_230853	N1049503021002E
DOT-10	N1049503021042E_20241023_011334	N1049503021042E
DOT-10	N1049503021077E_20241024_004551	N1049503021077E
DOT-10	N1049507031376W_20241024_211318	N1049507031376W
DOT-10	N1049503021077E_20241025_011831	N1049503021077E
DOT-10	N1049503021077E_20241025_014410	N1049503021077E
DOT-10	N1049503021077E_20241025_014828	N1049503021077E
DOT-10	N1049507031324E_20241025_204805	N1049507031324E
DOT-10	N10908J07011039S_20241028_114027	N10908J07011039S
DOT-10	N1049507031376E_20241028_231622	N1049507031376E
DOT-10	N10908G03011023W_20241029_002243	N10908G03011023W
DOT-10	N10908J07011039S_20241029_104911	N10908J07011039S
DOT-10	N1049503021132W_20241030_000424	N1049503021132W
DOT-10	N10908J07011039S_20241030_102524	N10908J07011039S
DOT-10	N1049507031376E_20241030_204000	N1049507031376E
DOT-10	N1049503021155W_20241031_000411	N1049503021155W
DOT-10	N1049507031376W_20241031_212026	N1049507031376W
DOT-10	N1049503021002W_20241101_003356	N1049503021002W
DOT-10	N1049507031376W_20241101_213711	N1049507031376W

Region/Division	Deployment ID	Location Code
DOT-10	N1049507031376W_20241104_210529	N1049507031376W
DOT-10	N10908G03011009W_20241105_002505	N10908G03011009W
DOT-10	N1049503021132E_20241105_004245	N1049503021132E
DOT-10	N1049503021132E_20241105_011037	N1049503021132E
DOT-10	N10908J07011034S_20241105_101744	N10908J07011034S
DOT-10	N1049507031376W_20241105_225223	N1049507031376W
DOT-10	N1049503021132E_20241106_004856	N1049503021132E
DOT-10	N10908J07011034S_20241106_102939	N10908J07011034S
DOT-10	N1049507031376W_20241106_211906	N1049507031376W
DOT-10	N1049503021132E_20241106_235333	N1049503021132E
DOT-10	N10908J07011034S_20241107_103516	N10908J07011034S
DOT-10	N1049507031376W_20241107_222233	N1049507031376W
DOT-10	N1049503021132E_20241108_002937	N1049503021132E
DOT-10	N10908J07011034S_20241108_102322	N10908J07011034S
DOT-10	N1049507031376E_20241108_213228	N1049507031376E
DOT-10	N1049507031376E_20241111_214619	N1049507031376E
DOT-10	N1049507031376E_20241112_212545	N1049507031376E
DOT-10	N1049503021132E_20241112_235438	N1049503021132E
DOT-10	N102707051514W_20241113_000454	N102707051514W
DOT-10	N1049507031376E_20241113_213450	N1049507031376E
DOT-10	N1049503021132E_20241114_022519	N1049503021132E
DOT-10	N10908M03011049E_20241114_115140	N10908M03011049E
DOT-10	N1049507031376E_20241114_212118	N1049507031376E
DOT-10	N10908G03011045E_20241115_001154	N10908G03011045E
DOT-10	N10908M03011149E_20241115_002307	N10908M03011149E
DOT-10	N1049503021132W_20241115_011455	N1049503021132W
DOT-10	N1049503021132W_20241115_235923	N1049503021132W
DOT-10	N1049503021117W_20241117_232736	N1049503021117W
DOT-10	N1049507031376W_20241118_214729	N1049507031376W
DOT-10	N1049503021117W_20241118_234809	N1049503021117W
DOT-10	N10908G03011063W_20241119_012954	N10908G03011063W
DOT-10	N1049507031376E_20241119_220253	N1049507031376E
DOT-10	N102707051514W_20241119_232021	N102707051514W
DOT-10	N1049503021131E_20241120_002424	N1049503021131E
DOT-10	N1049507031376E_20241120_223816	N1049507031376E
DOT-10	N1049507031376E_20241125_205316	N1049507031376E
DOT-10	N10908G03011058E_20241125_234606	N10908G03011058E
DOT-10	N1049507031376E_20241126_230213	N1049507031376E
DOT-10	N1049503021094W_20241126_231520	N1049503021094W
DOT-10	N102707051081E_20241203_123135	N102707051081E
DOT-10	N102707051081E_20241204_121958	N102707051081E
DOT-10	N102707051081E_20241205_125615	N102707051081E
DOT-10	N102707051081E_20241205_131408	N102707051081E

Region/Division	Deployment ID	Location Code
DOT-10	N102707051081E_20241206_112317	N102707051081E
DOT-10	N1049503021039W_20241209_232317	N1049503021039W
DOT-10	N10908J07011034S_20241210_103705	N10908J07011034S
DOT-10	N1049507031376E_20241217_221820	N1049507031376E
DOT-10	N1049503021077W_20241218_003600	N1049503021077W
DOT-10	N1049507031376E_20241219_225625	N1049507031376E
DOT-10	N1049507031001E_20241227_002644	N1049507031001E
DOT-10	N10908J07011039N_20250121_102238	N10908J07011039N
DOT-10	N10908J07011039N_20250121_130639	N10908J07011039N
DOT-10	N10908J07011039N_20250122_141401	N10908J07011039N
DOT-10	N10908J07011039N_20250123_103906	N10908J07011039N
DOT-10	N10908J07011039N_20250124_102030	N10908J07011039N
DOT-10	N10908J07011034N_20250203_112934	N10908J07011034N
DOT-10	N1049503021002W_20250203_234338	N1049503021002W
DOT-10	N10908J07011034N_20250204_095927	N10908J07011034N
DOT-10	N10908J07011034N_20250205_101511	N10908J07011034N
DOT-10	N10908J07011034N_20250207_102707	N10908J07011034N
DOT-10	N102707051088W_20250224_110206	N102707051088W
DOT-10	N102707051088E_20250225_102352	N102707051088E
DOT-10	N102707051088E_20250226_110926	N102707051088E
DOT-10	N102707051088E_20250227_102208	N102707051088E
DOT-10	N102707051088E_20250228_104615	N102707051088E
DOT-10	N1049503021027E_20250303_235217	N1049503021027E
DOT-10	N1049507031376E_20250310_231041	N1049507031376E
DOT-10	N1049507031376E_20250311_215514	N1049507031376E
DOT-10	N1049507031376E_20250312_221252	N1049507031376E
DOT-10	N1049507031376E_20250313_214048	N1049507031376E
DOT-10	N1049507031376E_20250314_211638	N1049507031376E
DOT-10	N1049507031376E_20250317_212422	N1049507031376E
DOT-10	N1049503021095E_20250318_020356	N1049503021095E
DOT-10	N102707051088W_20250318_111123	N102707051088W
DOT-10	N1049507031376E_20250318_214947	N1049507031376E
DOT-10	N102707051165E_20250319_113842	N102707051165E
DOT-10	N1049507031376E_20250319_210319	N1049507031376E
DOT-10	N102707051088W_20250320_104939	N102707051088W
DOT-10	N102707051088W_20250321_104735	N102707051088W
DOT-10	N1049507031376E_20250321_205056	N1049507031376E
DOT-10	N10908G03011038E_20250324_235208	N10908G03011038E
DOT-10	N102707051088W_20250325_104904	N102707051088W
DOT-10	N102707051088W_20250325_110417	N102707051088W
DOT-10	N102707051088W_20250325_111233	N102707051088W
DOT-10	N1049507031376E_20250325_215549	N1049507031376E
DOT-10	N102707051088W_20250326_110350	N102707051088W

Region/Division	Deployment ID	Location Code
DOT-10	N1049507031376E_20250326_211022	N1049507031376E
DOT-10	N102707051088E_20250327_111136	N102707051088E
DOT-10	N1049507031376E_20250327_211848	N1049507031376E
DOT-10	N102707051165E_20250328_123218	N102707051165E
DOT-10	N102707051088E_20250331_114145	N102707051088E
DOT-10	N102707051088E_20250401_114710	N102707051088E
DOT-10	N1049507031376E_20250401_215306	N1049507031376E
DOT-10	N102707051081E_20250402_120314	N102707051081E
DOT-10	N1049507031376E_20250402_213508	N1049507031376E
DOT-10	N102707051088W_20250403_112452	N102707051088W
DOT-10	N102707051088W_20250404_114157	N102707051088W
DOT-10	N1049507031376E_20250404_221015	N1049507031376E
DOT-10	N102707051088E_20250408_102817	N102707051088E
DOT-10	N102707051200W_20250408_111658	N102707051200W
DOT-10	N1049507031376E_20250408_212230	N1049507031376E
DOT-10	N102707051088W_20250409_105957	N102707051088W
DOT-10	N10908M07021016W_20250409_113114	N10908M07021016W
DOT-10	N1049507031376E_20250409_213713	N1049507031376E
DOT-10	N10908M07021016W_20250410_100222	N10908M07021016W
DOT-10	N102707051088W_20250410_104954	N102707051088W
DOT-10	N102707051165W_20250411_112425	N102707051165W
DOT-10	N1049507031106W_20250413_235313	N1049507031106W
DOT-10	N1049503021150W_20250414_113547	N1049503021150W
DOT-10	N102707051088W_20250414_114624	N102707051088W
DOT-10	N1049503021150W_20250414_142303	N1049503021150W
DOT-10	N1049507031106W_20250414_232646	N1049507031106W
DOT-10	N1049503021132E_20250414_235613	N1049503021132E
DOT-10	N102707051088W_20250415_103730	N102707051088W
DOT-10	N1049503021150W_20250415_113943	N1049503021150W
DOT-10	N1049503021150W_20250415_114525	N1049503021150W
DOT-10	N1049507031376E_20250415_205659	N1049507031376E
DOT-10	N1049507031106W_20250415_233340	N1049507031106W
DOT-10	N1049507031106W_20250415_234649	N1049507031106W
DOT-10	N1049503021106W_20250416_000026	N1049503021106W
DOT-10	N102707051088W_20250416_103152	N102707051088W
DOT-10	N1049503021150W_20250416_110727	N1049503021150W
DOT-10	N1049507031376E_20250416_212819	N1049507031376E
DOT-10	N1049507031106W_20250416_232419	N1049507031106W
DOT-10	N1049503021106W_20250416_233616	N1049503021106W
DOT-10	N102707051165W_20250417_103404	N102707051165W
DOT-10	N1013503011055N_20250417_112528	N1013503011055N
DOT-10	N1049507031106W_20250417_231547	N1049507031106W
DOT-10	N1049503021106W_20250417_231637	N1049503021106W

Region/Division	Deployment ID	Location Code
DOT-10	N102707051088E_20250418_110713	N102707051088E
DOT-10	N1049507031376E_20250418_212847	N1049507031376E
DOT-10	N102707051088E_20250421_111700	N102707051088E
DOT-10	N10908E03011005S_20250421_112603	N10908E03011005S
DOT-10	N1013503011048S_20250421_112711	N1013503011048S
DOT-10	N1049503021106W_20250421_232754	N1049503021106W
DOT-10	N10908E03011005S_20250422_104908	N10908E03011005S
DOT-10	N102707051088E_20250422_105425	N102707051088E
DOT-10	N102707051088E_20250422_110219	N102707051088E
DOT-10	N1013503011048S_20250422_120011	N1013503011048S
DOT-10	N1049507031376E_20250422_212908	N1049507031376E
DOT-10	N10908K07011021S_20250422_225851	N10908K07011021S
DOT-10	N1049507031106W_20250422_233314	N1049507031106W
DOT-10	N10908K07011021S_20250422_235809	N10908K07011021S
DOT-10	N10908E03011005S_20250423_104144	N10908E03011005S
DOT-10	N10908G03011070E_20250423_113251	N10908G03011070E
DOT-10	N1049507031376E_20250423_213332	N1049507031376E
DOT-10	N1049503021051W_20250423_233546	N1049503021051W
DOT-10	N10908E03011005S_20250424_103014	N10908E03011005S
DOT-10	N102707051165E_20250424_120721	N102707051165E
DOT-10	N1049507031376E_20250424_234817	N1049507031376E
DOT-10	N1049507031376E_20250425_022826	N1049507031376E
DOT-10	N10908E03011005S_20250425_095829	N10908E03011005S
DOT-10	N102707051081E_20250425_115253	N102707051081E
DOT-10	N102707051081E_20250425_120028	N102707051081E
DOT-10	N1049507031376E_20250425_224952	N1049507031376E
DOT-10	N1049507031106W_20250427_230726	N1049507031106W
DOT-10	N102707051081E_20250428_113822	N102707051081E
DOT-10	N1049507031106W_20250428_231232	N1049507031106W
DOT-10	N102707051081E_20250429_110026	N102707051081E
DOT-10	N1049507031376E_20250429_210814	N1049507031376E
DOT-10	N1049507031106W_20250429_232128	N1049507031106W
DOT-10	N102707051081E_20250430_105001	N102707051081E
DOT-10	N1049507031106W_20250501_002537	N1049507031106W
DOT-10	N1049507031376E_20250502_001844	N1049507031376E
DOT-10	N1049507031106W_20250504_231213	N1049507031106W
DOT-10	N1049507031106W_20250507_004754	N1049507031106W
DOT-10	N102707051081E_20250507_120141	N102707051081E
DOT-10	N1049507031376E_20250507_212451	N1049507031376E
DOT-10	N1049507031106W_20250507_231414	N1049507031106W
DOT-10	N102707051081E_20250508_112130	N102707051081E
DOT-10	N1049507031376E_20250508_205142	N1049507031376E
DOT-10	N1049507031106W_20250508_230538	N1049507031106W

Region/Division	Deployment ID	Location Code
DOT-10	N1049507031106W_20250511_225945	N1049507031106W
DOT-10	N102707051081E_20250512_111404	N102707051081E
DOT-10	N1049507031376E_20250512_212916	N1049507031376E
DOT-10	N1049507031106W_20250512_230900	N1049507031106W
DOT-10	N10908T03011048S_20250513_112819	N10908T03011048S
DOT-10	N102707051088W_20250513_113310	N102707051088W
DOT-10	N10908T03011048S_20250513_222116	N10908T03011048S
DOT-10	N1049507031106W_20250513_235634	N1049507031106W
DOT-10	N102707051088W_20250514_112637	N102707051088W
DOT-10	N1049507031106W_20250514_230227	N1049507031106W
DOT-10	N10908G03011156W_20250514_231112	N10908G03011156W
DOT-10	N102707051088E_20250515_111414	N102707051088E
DOT-10	N1049507031376E_20250515_213855	N1049507031376E
DOT-10	N1049507031106W_20250515_225658	N1049507031106W
DOT-10	N10908G03011156W_20250516_001740	N10908G03011156W
DOT-10	N102707051088E_20250516_105127	N102707051088E
DOT-10	N1049507031106W_20250518_225627	N1049507031106W
DOT-10	N102707051088E_20250519_103554	N102707051088E
DOT-10	N1049507031376E_20250519_222500	N1049507031376E
DOT-10	N1049507031106W_20250519_231215	N1049507031106W
DOT-10	N102707051081E_20250520_104746	N102707051081E
DOT-10	N10908J07011034N_20250520_131909	N10908J07011034N
DOT-10	N1049507031376E_20250520_213342	N1049507031376E
DOT-10	N1049507031106W_20250520_224624	N1049507031106W
DOT-10	N10908G03011156W_20250520_231101	N10908G03011156W
DOT-10	N102707051088E_20250521_104316	N102707051088E
DOT-10	N1049507031324E_20250527_221041	N1049507031324E
DOT-10	N1049507031324E_20250529_210911	N1049507031324E
DOT-10	N1049507031376E_20250601_214944	N1049507031376E
DOT-10	N102707051081E_20250602_110227	N102707051081E
DOT-10	N1049507031376E_20250602_213946	N1049507031376E
DOT-10	N1049507031376E_20250602_214234	N1049507031376E
DOT-10	N102707051088E_20250603_110126	N102707051088E
DOT-10	N1049507031376E_20250603_213346	N1049507031376E
DOT-10	N102707051088E_20250604_103630	N102707051088E
DOT-10	N1049507031376E_20250604_205925	N1049507031376E
DOT-10	N102707051088E_20250605_110757	N102707051088E
DOT-10	N1049507031376E_20250605_212939	N1049507031376E
DOT-10	N102707051088E_20250606_102743	N102707051088E
DOT-10	N1049507031376E_20250608_211715	N1049507031376E
DOT-10	N102707051081E_20250609_110713	N102707051081E
DOT-10	N1049507031376E_20250609_212116	N1049507031376E
DOT-10	N102707051088E_20250610_104133	N102707051088E

Region/Division	Deployment ID	Location Code
DOT-10	N102707051088E_20250610_105803	N102707051088E
DOT-10	N1049507031376E_20250610_211037	N1049507031376E
DOT-10	N102707051088W_20250611_104857	N102707051088W
DOT-10	N1049507031376E_20250611_210625	N1049507031376E
DOT-10	N102707051088W_20250612_135141	N102707051088W
DOT-10	N1049507031376E_20250612_215129	N1049507031376E
DOT-10	N102707051088E_20250613_104242	N102707051088E
DOT-10	N1049507031376E_20250616_211706	N1049507031376E
DOT-10	N1049507031376E_20250617_205939	N1049507031376E
DOT-10	N1049507031376E_20250618_204834	N1049507031376E
DOT-10	N10908E03011045S_20250618_232455	N10908E03011045S
DOT-10	N10908E03011045N_20250619_224010	N10908E03011045N
DOT-10	N10908E03011045N_20250619_225814	N10908E03011045N
DOT-10	N10908E03011045N_20250619_233627	N10908E03011045N
DOT-10	N10908E03011045N_20250620_233943	N10908E03011045N
DOT-10	N1049507031376E_20250622_204131	N1049507031376E
DOT-10	N1049507031376E_20250623_215742	N1049507031376E
DOT-10	N10908E03011045N_20250623_225347	N10908E03011045N
DOT-10	N1049507031376E_20250624_205906	N1049507031376E
DOT-10	N10908E03011045N_20250624_231320	N10908E03011045N
DOT-10	N1049503021089E_20250625_001157	N1049503021089E
DOT-10	N1049507031376E_20250625_211454	N1049507031376E
DOT-10	N10908E03011045N_20250625_233757	N10908E03011045N
DOT-10	N1049507031376E_20250626_212239	N1049507031376E
DOT-10	N10908E03011045N_20250626_230520	N10908E03011045N
DOT-10	N1049507031376E_20250630_214721	N1049507031376E
DOT-10	N10908E03011107S_20250630_231755	N10908E03011107S
DOT-10	N1049507031376W_20250702_211445	N1049507031376W
DOT-10	N1049507031376W_20250702_212403	N1049507031376W
DOT-10	N10908E03011045S_20250703_001334	N10908E03011045S
DOT-10	N10908E03011045N_20250707_230717	N10908E03011045N
DOT-10	N10908E03011045S_20250709_000724	N10908E03011045S
DOT-10	N1049507031376E_20250715_225514	N1049507031376E
DOT-10	N1049507031376E_20250717_213454	N1049507031376E
DOT-10	N1049507031376E_20250717_222800	N1049507031376E
DOT-10	N1049507031376E_20250720_211214	N1049507031376E
DOT-10	N1049507031376E_20250721_210704	N1049507031376E
DOT-10	N10908G03011051E_20250721_225145	N10908G03011051E
DOT-10	N10908G03011051E_20250721_225731	N10908G03011051E
DOT-10	N1049507031376E_20250722_211715	N1049507031376E
DOT-10	N1049507031376E_20250723_210655	N1049507031376E
DOT-10	N1049507031376E_20250724_211758	N1049507031376E
DOT-10	N1049507031376E_20250727_211229	N1049507031376E

Region/Division	Deployment ID	Location Code
DOT-10	N1049507031376E_20250728_212322	N1049507031376E
DOT-10	N1049507031376E_20250729_210721	N1049507031376E
DOT-10	N1049507031376E_20250730_214449	N1049507031376E
DOT-10	N1049507031376E_20250731_215622	N1049507031376E
DOT-10	N1049507031376E_20250804_214754	N1049507031376E
DOT-10	N1049503021027E_20250804_233628	N1049503021027E
DOT-10	N1049503021027E_20250805_232848	N1049503021027E
DOT-10	N1049503021027E_20250805_234459	N1049503021027E
DOT-10	N1049507031324E_20250818_103728	N1049507031324E
DOT-10	N10908G03011135W_20250819_221019	N10908G03011135W
DOT-10	N10908G03011135E_20250821_234738	N10908G03011135E
DOT-10	N10908G03011135E_20250822_225926	N10908G03011135E
DOT-10	N10908G03011063W_20250825_225204	N10908G03011063W
DOT-10	N10908E03011084S_20250826_231537	N10908E03011084S
DOT-10	N10908G03011009W_20250902_234546	N10908G03011009W
DOT-10	N1049507031161W_20250904_234009	N1049507031161W
DOT-10	N10908J07011011N_20251017_092634	N10908J07011011N
DOT-10	N10908J07011034N_20251020_112802	N10908J07011034N
DOT-10	N10908J07011034N_20251021_093600	N10908J07011034N
DOT-10	N10908J07011034N_20251022_100619	N10908J07011034N
DOT-10	N10908J07011034N_20251023_101443	N10908J07011034N
DOT-10	N10908J07011034N_20251024_100454	N10908J07011034N
DOT-10	N10908J07011034N_20251027_102054	N10908J07011034N
DOT-10	N102707051248E_20251027_124750	N102707051248E
DOT-10	N10908G03011009E_20251027_233354	N10908G03011009E
DOT-10	N10908G03011009W_20251028_001154	N10908G03011009W
DOT-10	N10908J07011034N_20251028_094256	N10908J07011034N
DOT-10	N102707051248E_20251028_100828	N102707051248E
DOT-10	N102707051248E_20251028_101615	N102707051248E
DOT-10	N10908J07011034N_20251029_100818	N10908J07011034N
DOT-10	N102707051248E_20251029_104638	N102707051248E
DOT-10	N102707051248E_20251030_095942	N102707051248E
DOT-10	N10908J07011034N_20251031_103321	N10908J07011034N
DOT-10	N102707051248W_20251103_115357	N102707051248W
DOT-10	N102707051185E_20251106_110707	N102707051185E
DOT-10	N102707051191E_20251107_104037	N102707051191E
DOT-10	N102707051191E_20251110_105143	N102707051191E
DOT-10	N102707051191E_20251112_104312	N102707051191E
DOT-10	N102707051248E_20251113_113146	N102707051248E
DOT-10	N102707051248E_20251114_103551	N102707051248E
DOT-10	N10908J07011034N_20251115_100107	N10908J07011034N
DOT-10	N102707051248E_20251117_105222	N102707051248E
DOT-10	N10908T03011021N_20251117_114259	N10908T03011021N

Region/Division	Deployment ID	Location Code
DOT-10	N10908J07011034N_20251118_101039	N10908J07011034N
DOT-10	N10908J07011034N_20251118_103126	N10908J07011034N
DOT-10	N102707051248E_20251118_104908	N102707051248E
DOT-10	N10908T03011021N_20251118_105957	N10908T03011021N
DOT-10	N102707051191E_20251119_102454	N102707051191E
DOT-10	N10908T03011021N_20251119_110318	N10908T03011021N
DOT-10	N10908T03011021N_20251120_102234	N10908T03011021N
DOT-10	N10908T03011021N_20251121_090643	N10908T03011021N
DOT-10	N10908J07011034N_20251124_101525	N10908J07011034N
DOT-10	N10908T03011021N_20251124_104427	N10908T03011021N
DOT-10	N10908T03011021N_20251124_135305	N10908T03011021N
DOT-10	N10908T03011021N_20251125_084526	N10908T03011021N
DOT-10	N10908T03011021N_20251125_085217	N10908T03011021N
DOT-10	N10908J07011034N_20251125_093947	N10908J07011034N
DOT-10	N10908T03011021N_20251125_103306	N10908T03011021N
DOT-10	N10908T03011021N_20251125_114525	N10908T03011021N
DOT-10	N10908T03011021N_20251126_092120	N10908T03011021N
DOT-10	N10908T03011021N_20251201_101313	N10908T03011021N
DOT-10	N10908T03011021N_20251202_085347	N10908T03011021N
DOT-10	N10908T03011021N_20251203_101030	N10908T03011021N
DOT-10	N10908T03011021N_20251203_135627	N10908T03011021N
DOT-10	N10908T03011021N_20251204_103027	N10908T03011021N
DOT-10	N10908T03011021N_20251205_095222	N10908T03011021N
DOT-10	N10908T03011021N_20251208_100254	N10908T03011021N
DOT-10	N10908T03011021N_20251209_093618	N10908T03011021N
DOT-10	N102707051248E_20251209_095742	N102707051248E
DOT-10	N10908T03011021N_20251209_135924	N10908T03011021N
DOT-10	N10908T03011021N_20251210_100411	N10908T03011021N
DOT-10	N102707051248E_20251212_103047	N102707051248E
DOT-10	N10908T03011021N_20251212_103549	N10908T03011021N
DOT-10	N10908T03011021N_20251215_114131	N10908T03011021N
DOT-10	N10908T03011021N_20251216_103625	N10908T03011021N
DOT-10	N10908T03011021N_20251217_100337	N10908T03011021N
DOT-10	N10908T03011021N_20251218_104813	N10908T03011021N
DOT-10	N10908T03011021N_20251222_112913	N10908T03011021N
DOT-10	N10908T03011021N_20251222_114938	N10908T03011021N
DOT-10	N10908T03011021N_20251222_142103	N10908T03011021N
DOT-10	N10908T03011021N_20251223_100448	N10908T03011021N
DOT-10	N10908T03011021N_20251223_141354	N10908T03011021N
DOT-10	N10908T03011021N_20251230_095727	N10908T03011021N
DOT-11	N1187IX1M12012S_20240103_002218	N1187IX1M12012S
DOT-11	N1195IX1M21060N_20240104_122714	N1195IX1M21060N
DOT-11	N1187IX1M12012S_20240105_001037	N1187IX1M12012S

Region/Division	Deployment ID	Location Code
DOT-11	N1187IX1M12012S_20240106_002404	N1187IX1M12012S
DOT-11	N11907HX1M11011N_20240109_012208	N11907HX1M11011N
DOT-11	N11907HX1M11011N_20240111_004900	N11907HX1M11011N
DOT-11	N11907HX1M11011N_20240112_012741	N11907HX1M11011N
DOT-11	N11278IX6M13020E_20240122_122132	N11278IX6M13020E
DOT-11	N11678IX5M12029S_20240213_015026	N11678IX5M12029S
DOT-11	N11678IX5M12029S_20240214_011102	N11678IX5M12029S
DOT-11	N11678IX5M11031N_20240216_011228	N11678IX5M11031N
DOT-11	N11678IX5M11031N_20240217_005837	N11678IX5M11031N
DOT-11	N11678IX5M12029S_20240217_013927	N11678IX5M12029S
DOT-11	N1195IX1M21060S_20240220_010902	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20240221_235145	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20240222_014856	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20240224_000656	N1195IX1M21060S
DOT-11	N1187IX1M11011N_20240227_003243	N1187IX1M11011N
DOT-11	N1187IX1M11011N_20240228_001142	N1187IX1M11011N
DOT-11	N1187IX1M11011N_20240229_003400	N1187IX1M11011N
DOT-11	N1187IX1M11011N_20240301_000752	N1187IX1M11011N
DOT-11	N11495IX5M14118W_20240302_001923	N11495IX5M14118W
DOT-11	N11495IX5M14118W_20240302_005448	N11495IX5M14118W
DOT-11	N1187IX1M11011N_20240302_011857	N1187IX1M11011N
DOT-11	N11495IX5M14118W_20240305_011415	N11495IX5M14118W
DOT-11	N11495IX5M14118W_20240306_005653	N11495IX5M14118W
DOT-11	N11495IX5M14118W_20240308_012152	N11495IX5M14118W
DOT-11	N11440X6M11075S_20240309_000036	N11440X6M11075S
DOT-11	N11678IX5M11010N_20240311_124752	N11678IX5M11010N
DOT-11	N11678IX5M11010N_20240311_131945	N11678IX5M11010N
DOT-11	N11440X6M11075S_20240312_000451	N11440X6M11075S
DOT-11	N11678IX5M11010N_20240312_124301	N11678IX5M11010N
DOT-11	N11278IX1M53008E_20240313_001447	N11278IX1M53008E
DOT-11	N11440X6M11075S_20240313_003730	N11440X6M11075S
DOT-11	N11278IX1M53008E_20240314_004048	N11278IX1M53008E
DOT-11	N11278IX1M53008E_20240317_000129	N11278IX1M53008E
DOT-11	N11440X6M11044S_20240320_002220	N11440X6M11044S
DOT-11	N1195IX1M21060N_20240320_021846	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240320_233022	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240321_233024	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240323_014849	N1195IX1M21060N
DOT-11	N11440X6M11075N_20240405_000312	N11440X6M11075N
DOT-11	N11495IX5M14118W_20240408_114101	N11495IX5M14118W
DOT-11	N11495IX5M14118W_20240409_123615	N11495IX5M14118W
DOT-11	N11495IX5M14118W_20240410_124940	N11495IX5M14118W
DOT-11	N11440X6M11044N_20240411_002543	N11440X6M11044N

Region/Division	Deployment ID	Location Code
DOT-11	N11495IX5M14118W_20240411_113308	N11495IX5M14118W
DOT-11	N11495IX5M14118W_20240412_110822	N11495IX5M14118W
DOT-11	N11440X6M11044N_20240413_003904	N11440X6M11044N
DOT-11	N11495IX5M13109E_20240415_122750	N11495IX5M13109E
DOT-11	N11440X6M11075S_20240416_005406	N11440X6M11075S
DOT-11	N11495IX5M14118W_20240416_114248	N11495IX5M14118W
DOT-11	N11495IX5M13109E_20240417_120733	N11495IX5M13109E
DOT-11	N11495IX5M13109E_20240418_121316	N11495IX5M13109E
DOT-11	N11495IX5M13109E_20240419_110149	N11495IX5M13109E
DOT-11	N1187IX1M12061S_20240422_124146	N1187IX1M12061S
DOT-11	N1187IX1M11044N_20240423_110434	N1187IX1M11044N
DOT-11	N1187IX1M11044N_20240424_111917	N1187IX1M11044N
DOT-11	N1187IX1M11044N_20240426_104858	N1187IX1M11044N
DOT-11	N1187IX1M11011S_20240429_233907	N1187IX1M11011S
DOT-11	N1187IX1M12012S_20240501_233315	N1187IX1M12012S
DOT-11	N1187IX1M11011S_20240502_225033	N1187IX1M11011S
DOT-11	N1187IX1M12012S_20240504_021608	N1187IX1M12012S
DOT-11	N1195IX1M21060N_20240625_014320	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240626_012833	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240628_003243	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240629_025144	N1195IX1M21060N
DOT-11	N1195IX1M21060S_20240702_000444	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20240702_234511	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20240704_001123	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20240709_004319	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20240709_234508	N1195IX1M21060S
DOT-11	N1195IX1M21060N_20240711_000149	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240712_004233	N1195IX1M21060N
DOT-11	N1195IX1M21060S_20240712_012342	N1195IX1M21060S
DOT-11	N1195IX1M21060N_20240716_002651	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240717_014342	N1195IX1M21060N
DOT-11	N1195IX1M21060S_20240718_231015	N1195IX1M21060S
DOT-11	N1195IX1M21060N_20240719_001421	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240719_233635	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240721_020533	N1195IX1M21060N
DOT-11	N11678IX5M11031N_20240723_001751	N11678IX5M11031N
DOT-11	N1195IX1M21060S_20240723_011159	N1195IX1M21060S
DOT-11	N1195IX1M21060N_20240723_021531	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240724_004527	N1195IX1M21060N
DOT-11	N1195IX1M21060S_20240724_020433	N1195IX1M21060S
DOT-11	N11678IX5M11031N_20240724_025622	N11678IX5M11031N
DOT-11	N11678IX5M11031N_20240725_002919	N11678IX5M11031N
DOT-11	N1195IX1M21060N_20240725_005656	N1195IX1M21060N

Region/Division	Deployment ID	Location Code
DOT-11	N1195IX1M21060S_20240725_015901	N1195IX1M21060S
DOT-11	N11678IX5M11031N_20240725_235728	N11678IX5M11031N
DOT-11	N1195IX1M21060N_20240726_004544	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240727_001106	N1195IX1M21060N
DOT-11	N1195IX1M21060S_20240727_002042	N1195IX1M21060S
DOT-11	N11678IX5M11031N_20240727_011432	N11678IX5M11031N
DOT-11	N1195IX1M21060S_20240729_234252	N1195IX1M21060S
DOT-11	N11678IX5M11031N_20240730_002823	N11678IX5M11031N
DOT-11	N1195IX1M21060N_20240730_023910	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240731_001302	N1195IX1M21060N
DOT-11	N11678IX5M11031N_20240731_004131	N11678IX5M11031N
DOT-11	N1195IX1M21060S_20240801_005415	N1195IX1M21060S
DOT-11	N11678IX5M11031N_20240801_012138	N11678IX5M11031N
DOT-11	N11695IX1M11009N_20240801_021550	N11695IX1M11009N
DOT-11	N11695IX1M11009N_20240801_023620	N11695IX1M11009N
DOT-11	N1195IX1M21060S_20240802_002128	N1195IX1M21060S
DOT-11	N11678IX5M11031N_20240802_010500	N11678IX5M11031N
DOT-11	N1195IX1M21060N_20240802_011955	N1195IX1M21060N
DOT-11	N1195IX1M21060S_20240802_232853	N1195IX1M21060S
DOT-11	N1195IX1M21060N_20240802_235649	N1195IX1M21060N
DOT-11	N11678IX5M11031N_20240803_003221	N11678IX5M11031N
DOT-11	N1195IX1M21060N_20240805_235423	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240806_000740	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240806_002109	N1195IX1M21060N
DOT-11	N11678IX5M11031N_20240806_003048	N11678IX5M11031N
DOT-11	N11678IX5M11031N_20240806_120806	N11678IX5M11031N
DOT-11	N11678IX5M11041S_20240809_005423	N11678IX5M11041S
DOT-11	N11678IX5M11041S_20240810_010851	N11678IX5M11041S
DOT-11	N1195IX1M21060N_20240810_024157	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240810_024532	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240810_030439	N1195IX1M21060N
DOT-11	N11678IX5M12029S_20240812_231603	N11678IX5M12029S
DOT-11	N1195IX1M21060S_20240812_232654	N1195IX1M21060S
DOT-11	N11695IX1M11009N_20240813_003915	N11695IX1M11009N
DOT-11	N1195IX1M21060S_20240813_231038	N1195IX1M21060S
DOT-11	N11678IX5M12029S_20240814_020249	N11678IX5M12029S
DOT-11	N11695IX1M11009N_20240814_235135	N11695IX1M11009N
DOT-11	N1195IX1M21060S_20240815_005127	N1195IX1M21060S
DOT-11	N11678IX5M12029S_20240815_011112	N11678IX5M12029S
DOT-11	N1195IX1M21060S_20240815_015154	N1195IX1M21060S
DOT-11	N11678IX5M12029S_20240815_021004	N11678IX5M12029S
DOT-11	N1195IX1M21060S_20240815_023738	N1195IX1M21060S
DOT-11	N11678IX5M12029S_20240815_030154	N11678IX5M12029S

Region/Division	Deployment ID	Location Code
DOT-11	N1195IX1M21060S_20240815_121014	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20240815_234928	N1195IX1M21060S
DOT-11	N1195IX1M21060N_20240816_002111	N1195IX1M21060N
DOT-11	N11678IX5M11031N_20240816_020250	N11678IX5M11031N
DOT-11	N11678IX5M11031N_20240817_013033	N11678IX5M11031N
DOT-11	N1195IX1M21060N_20240817_014554	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240817_020109	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240817_024141	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240817_030649	N1195IX1M21060N
DOT-11	N11678IX5M11031N_20240820_005457	N11678IX5M11031N
DOT-11	N1195IX1M21060N_20240820_011004	N1195IX1M21060N
DOT-11	N11678IX5M11031N_20240820_030640	N11678IX5M11031N
DOT-11	N11695IX1M11009N_20240821_001928	N11695IX1M11009N
DOT-11	N1195IX1M21060N_20240821_004402	N1195IX1M21060N
DOT-11	N11678IX5M11031N_20240821_010731	N11678IX5M11031N
DOT-11	N1195IX1M21060N_20240821_030948	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240822_003729	N1195IX1M21060N
DOT-11	N11678IX5M11031N_20240822_004958	N11678IX5M11031N
DOT-11	N11907HX1M11011S_20240822_111502	N11907HX1M11011S
DOT-11	N11678IX5M11031N_20240823_001751	N11678IX5M11031N
DOT-11	N11695IX1M11009N_20240823_002715	N11695IX1M11009N
DOT-11	N1195IX1M21060N_20240824_000716	N1195IX1M21060N
DOT-11	N11678IX5M11031N_20240824_012646	N11678IX5M11031N
DOT-11	N1195IX1M21060N_20240826_230654	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240827_000843	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240828_004016	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240828_223950	N1195IX1M21060N
DOT-11	N1195IX1M21060N_20240829_033233	N1195IX1M21060N
DOT-11	N11295IX5M11022N_20240829_132836	N11295IX5M11022N
DOT-11	N1187IX1M12061S_20240904_001452	N1187IX1M12061S
DOT-11	N1195IX1M21060S_20240904_001509	N1195IX1M21060S
DOT-11	N11695IX1M11009N_20240904_003039	N11695IX1M11009N
DOT-11	N1187IX1M12061S_20240904_031638	N1187IX1M12061S
DOT-11	N1187IX1M12061S_20240905_003236	N1187IX1M12061S
DOT-11	N1195IX1M21060S_20240905_012041	N1195IX1M21060S
DOT-11	N11440X6M11044N_20240905_111110	N11440X6M11044N
DOT-11	N11278IX6M13020W_20240906_002819	N11278IX6M13020W
DOT-11	N1187IX1M12028N_20240906_005704	N1187IX1M12028N
DOT-11	N1195IX1M21060S_20240906_015647	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20240906_023737	N1195IX1M21060S
DOT-11	N11278IX6M13020W_20240906_031834	N11278IX6M13020W
DOT-11	N11278IX6M13020W_20240906_234036	N11278IX6M13020W
DOT-11	N1187IX1M12028N_20240907_004602	N1187IX1M12028N

Region/Division	Deployment ID	Location Code
DOT-11	N11695IXIM11009N_20240907_020641	N11695IXIM11009N
DOT-11	N1195IX1M21060S_20240910_000851	N1195IX1M21060S
DOT-11	N1187IX1M12028N_20240910_005339	N1187IX1M12028N
DOT-11	N11678IX5M11031N_20240910_010459	N11678IX5M11031N
DOT-11	N1195IX1M21060S_20240911_001242	N1195IX1M21060S
DOT-11	N1187IX1M11061N_20240911_004040	N1187IX1M11061N
DOT-11	N1187IX1M12061S_20240911_012136	N1187IX1M12061S
DOT-11	N1195IX1M21060N_20240911_013303	N1195IX1M21060N
DOT-11	N11278IX6M13020W_20240911_015931	N11278IX6M13020W
DOT-11	N1195IX1M21060S_20240911_031856	N1195IX1M21060S
DOT-11	N1187IX1M12061S_20240911_233907	N1187IX1M12061S
DOT-11	N1195IX1M21060N_20240911_235323	N1195IX1M21060N
DOT-11	N11278IX6M13020W_20240912_000547	N11278IX6M13020W
DOT-11	N1187IX1M11061N_20240912_001255	N1187IX1M11061N
DOT-11	N11678IX5M11031N_20240912_010542	N11678IX5M11031N
DOT-11	N1127X2M13011E_20240912_111435	N1127X2M13011E
DOT-11	N11278IX6M13020W_20240912_235822	N11278IX6M13020W
DOT-11	N1187IX1M12061S_20240912_235854	N1187IX1M12061S
DOT-11	N1187IX1M11061N_20240913_002257	N1187IX1M11061N
DOT-11	N1195IX1M21060S_20240913_011235	N1195IX1M21060S
DOT-11	N1187IX1M11061N_20240913_031907	N1187IX1M11061N
DOT-11	N1187IX1M11061N_20240914_000523	N1187IX1M11061N
DOT-11	N1187IX1M12028S_20240914_005252	N1187IX1M12028S
DOT-11	N11278IX6M13020W_20240914_011022	N11278IX6M13020W
DOT-11	N11678IX5M11031N_20240914_013307	N11678IX5M11031N
DOT-11	N1195IX1M21060N_20240916_000223	N1195IX1M21060N
DOT-11	N1195IX1M21060S_20240916_235705	N1195IX1M21060S
DOT-11	N1195IX1M21060N_20240917_002659	N1195IX1M21060N
DOT-11	N1187IX1M11061N_20240917_004137	N1187IX1M11061N
DOT-11	N1187IX1M12061S_20240917_004837	N1187IX1M12061S
DOT-11	N11495IX5M13115E_20240918_002457	N11495IX5M13115E
DOT-11	N1187IX1M11061N_20240918_003201	N1187IX1M11061N
DOT-11	N11678IX5M11031N_20240918_004343	N11678IX5M11031N
DOT-11	N1187IX1M12061S_20240918_010812	N1187IX1M12061S
DOT-11	N1195IX1M21060S_20240918_011336	N1195IX1M21060S
DOT-11	N11278IX6M13020W_20240918_015211	N11278IX6M13020W
DOT-11	N1187IX1M12061S_20240918_030424	N1187IX1M12061S
DOT-11	N1187IX1M11061N_20240918_233949	N1187IX1M11061N
DOT-11	N11278IX6M13020W_20240918_235144	N11278IX6M13020W
DOT-11	N1187IX1M11061N_20240919_001158	N1187IX1M11061N
DOT-11	N1187IX1M12028S_20240919_010811	N1187IX1M12028S
DOT-11	N11678IX5M11031N_20240919_012012	N11678IX5M11031N
DOT-11	N1195IX1M21060S_20240919_013138	N1195IX1M21060S

Region/Division	Deployment ID	Location Code
DOT-11	N11278IX6M13020W_20240919_033826	N11278IX6M13020W
DOT-11	N1187IX1M12028S_20240919_112952	N1187IX1M12028S
DOT-11	N11278IX6M13020W_20240919_234619	N11278IX6M13020W
DOT-11	N1187IX1M12061S_20240920_002058	N1187IX1M12061S
DOT-11	N1187IX1M11061N_20240920_002746	N1187IX1M11061N
DOT-11	N1195IX1M21060S_20240920_013654	N1195IX1M21060S
DOT-11	N1187IX1M12061S_20240920_225144	N1187IX1M12061S
DOT-11	N1187IX1M11061N_20240920_235358	N1187IX1M11061N
DOT-11	N11278IX6M13020W_20240921_000145	N11278IX6M13020W
DOT-11	N11678IX5M11031N_20240921_005439	N11678IX5M11031N
DOT-11	N11278IX6M13020W_20240921_005728	N11278IX6M13020W
DOT-11	N11278IX6M13020W_20240921_040352	N11278IX6M13020W
DOT-11	N1187IX1M12061S_20240923_231726	N1187IX1M12061S
DOT-11	N1187IX1M11061N_20240924_000814	N1187IX1M11061N
DOT-11	N1187IX1M12061S_20240925_000326	N1187IX1M12061S
DOT-11	N1187IX1M11061N_20240925_001428	N1187IX1M11061N
DOT-11	N11495IX5M14091W_20240925_015151	N11495IX5M14091W
DOT-11	N1187IX1M12061S_20240925_030507	N1187IX1M12061S
DOT-11	N1187IX1M12061S_20240925_231821	N1187IX1M12061S
DOT-11	N1187IX1M11061N_20240925_233534	N1187IX1M11061N
DOT-11	N1195IX1M21060S_20240926_001803	N1195IX1M21060S
DOT-11	N11495IX5M14104W_20240926_004516	N11495IX5M14104W
DOT-11	N1187IX1M12061S_20240926_223557	N1187IX1M12061S
DOT-11	N1195IX1M21060S_20240926_235134	N1195IX1M21060S
DOT-11	N1187IX1M11061N_20240927_003317	N1187IX1M11061N
DOT-11	N11678IX5M12025S_20240927_013640	N11678IX5M12025S
DOT-11	N1195IX1M21060S_20240927_233928	N1195IX1M21060S
DOT-11	N1187IX1M12061S_20240928_001939	N1187IX1M12061S
DOT-11	N1187IX1M11061N_20240928_003818	N1187IX1M11061N
DOT-11	N1195IX1M21060S_20241001_001207	N1195IX1M21060S
DOT-11	N1195IX1M21060N_20241001_002108	N1195IX1M21060N
DOT-11	N1187IX1M12061S_20241001_005630	N1187IX1M12061S
DOT-11	N1195IX1M21060S_20241002_000514	N1195IX1M21060S
DOT-11	N1187IX1M12028N_20241002_002508	N1187IX1M12028N
DOT-11	N1187IX1M12061S_20241002_003511	N1187IX1M12061S
DOT-11	N1195IX1M21060S_20241002_013358	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20241002_021928	N1195IX1M21060S
DOT-11	N11495IX5M13103W_20241002_023149	N11495IX5M13103W
DOT-11	N1187IX1M12061S_20241002_235018	N1187IX1M12061S
DOT-11	N1187IX1M12028N_20241003_005130	N1187IX1M12028N
DOT-11	N11278IX6M13020W_20241003_013957	N11278IX6M13020W
DOT-11	N1187IX1M12061S_20241003_022654	N1187IX1M12061S
DOT-11	N11278IX6M13020W_20241004_001244	N11278IX6M13020W

Region/Division	Deployment ID	Location Code
DOT-11	N1195IX1M21060S_20241004_001649	N1195IX1M21060S
DOT-11	N1187IX1M12028N_20241004_002201	N1187IX1M12028N
DOT-11	N1187IX1M12061S_20241004_005457	N1187IX1M12061S
DOT-11	N1187IX1M12028N_20241004_030506	N1187IX1M12028N
DOT-11	N11295IX5M11022N_20241004_112818	N11295IX5M11022N
DOT-11	N11278IX6M13020W_20241004_231837	N11278IX6M13020W
DOT-11	N1187IX1M12028S_20241004_235437	N1187IX1M12028S
DOT-11	N1187IX1M12028N_20241005_001730	N1187IX1M12028N
DOT-11	N1195IX1M21060S_20241005_020145	N1195IX1M21060S
DOT-11	N11278IX6M13020E_20241008_000511	N11278IX6M13020E
DOT-11	N1195IX1M21060S_20241008_005758	N1195IX1M21060S
DOT-11	N11278IX6M13020E_20241008_030322	N11278IX6M13020E
DOT-11	N11278IX6M13020E_20241008_232144	N11278IX6M13020E
DOT-11	N11278IX6M13020E_20241008_234738	N11278IX6M13020E
DOT-11	N1187IX1M12028N_20241009_003924	N1187IX1M12028N
DOT-11	N1195IX1M21060S_20241009_011127	N1195IX1M21060S
DOT-11	N11695IX1M12012S_20241009_012016	N11695IX1M12012S
DOT-11	N1187IX1M12028S_20241009_012457	N1187IX1M12028S
DOT-11	N1187IX1M11044S_20241009_234223	N1187IX1M11044S
DOT-11	N1195IX1M21060S_20241010_001744	N1195IX1M21060S
DOT-11	N11907HX1M11011S_20241010_113215	N11907HX1M11011S
DOT-11	N1187IX1M11044S_20241011_002234	N1187IX1M11044S
DOT-11	N11278IX6M13020W_20241011_011827	N11278IX6M13020W
DOT-11	N1195IX1M21060S_20241011_012729	N1195IX1M21060S
DOT-11	N1187IX1M11044S_20241011_030948	N1187IX1M11044S
DOT-11	N1187IX1M12028S_20241011_233345	N1187IX1M12028S
DOT-11	N1187IX1M12028N_20241012_003743	N1187IX1M12028N
DOT-11	N1187IX1M12028S_20241015_011109	N1187IX1M12028S
DOT-11	N1195IX1M21060S_20241015_011320	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20241016_002518	N1195IX1M21060S
DOT-11	N1187IX1M12028S_20241016_011909	N1187IX1M12028S
DOT-11	N1187IX1M12028S_20241016_030734	N1187IX1M12028S
DOT-11	N1187IX1M12028S_20241016_234321	N1187IX1M12028S
DOT-11	N1195IX1M21060S_20241016_234848	N1195IX1M21060S
DOT-11	N1187IX1M12028N_20241017_003341	N1187IX1M12028N
DOT-11	N1127X2M13011W_20241017_112800	N1127X2M13011W
DOT-11	N1187IX1M12028S_20241018_001445	N1187IX1M12028S
DOT-11	N1187IX1M12028N_20241018_002515	N1187IX1M12028N
DOT-11	N1195IX1M21060S_20241018_004612	N1195IX1M21060S
DOT-11	N1187IX1M12028N_20241019_004222	N1187IX1M12028N
DOT-11	N1195IX1M21060S_20241021_232017	N1195IX1M21060S
DOT-11	N1187IX1M12028S_20241022_000126	N1187IX1M12028S
DOT-11	N1187IX1M12028S_20241022_235115	N1187IX1M12028S

Region/Division	Deployment ID	Location Code
DOT-11	N1187IX1M12028S_20241023_224520	N1187IX1M12028S
DOT-11	N1195IX1M21060S_20241024_000819	N1195IX1M21060S
DOT-11	N1187IX1M12028S_20241024_031256	N1187IX1M12028S
DOT-11	N1187IX1M12028S_20241025_011312	N1187IX1M12028S
DOT-11	N1195IX1M21060S_20241025_012132	N1195IX1M21060S
DOT-11	N11295IX1M21022N_20241025_113050	N11295IX1M21022N
DOT-11	N1187IX1M12028S_20241025_225849	N1187IX1M12028S
DOT-11	N1195IX1M21060S_20241025_235311	N1195IX1M21060S
DOT-11	N1187IX1M12028S_20241026_030212	N1187IX1M12028S
DOT-11	N1187IX1M12028S_20241027_235803	N1187IX1M12028S
DOT-11	N1195IX1M21060S_20241029_001554	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20241030_012427	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20241030_032228	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20241031_005516	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20241101_002300	N1195IX1M21060S
DOT-11	N1187IX1M12028N_20241101_014421	N1187IX1M12028N
DOT-11	N1195IX1M21060S_20241102_003759	N1195IX1M21060S
DOT-11	N1187IX1M12028N_20241102_004938	N1187IX1M12028N
DOT-11	N1187IX1M12028N_20241105_235218	N1187IX1M12028N
DOT-11	N1187IX1M12028S_20241108_231952	N1187IX1M12028S
DOT-11	N1195IX1M21060S_20241109_004103	N1195IX1M21060S
DOT-11	N1195IX1M21060S_20241109_035431	N1195IX1M21060S
DOT-11	N1187IX1M12028S_20241111_231259	N1187IX1M12028S
DOT-11	N1187IX1M12028S_20241112_030849	N1187IX1M12028S
DOT-11	N1187IX1M12028N_20241113_011117	N1187IX1M12028N
DOT-11	N11907MX5M14135E_20241115_105548	N11907MX5M14135E
DOT-11	N11678IX5M12025N_20241119_002820	N11678IX5M12025N
DOT-11	N11678IX5M12025N_20241120_012239	N11678IX5M12025N
DOT-11	N11678IX5M12025N_20241121_004202	N11678IX5M12025N
DOT-11	N11678IX5M12025N_20241122_004148	N11678IX5M12025N
DOT-11	N11678IX5M12025N_20241123_001848	N11678IX5M12025N
DOT-11	N11678IX5M12025N_20241126_002520	N11678IX5M12025N
DOT-11	N11678IX5M12025N_20241127_004421	N11678IX5M12025N
DOT-11	N11678IX5M12025N_20241203_004425	N11678IX5M12025N
DOT-11	N11495IX5M13103W_20241203_020842	N11495IX5M13103W
DOT-11	N11678IX5M12025N_20241204_003709	N11678IX5M12025N
DOT-11	N11495IX5M13103W_20241204_012954	N11495IX5M13103W
DOT-11	N11495IX5M13103W_20241205_012626	N11495IX5M13103W
DOT-11	N11295IX1M21022N_20241205_113903	N11295IX1M21022N
DOT-11	N11678IX5M12025N_20241206_005008	N11678IX5M12025N
DOT-11	N11495IX5M13103W_20241206_023715	N11495IX5M13103W
DOT-11	N11678IX5M12025N_20241207_002458	N11678IX5M12025N
DOT-11	N11495IX5M13103W_20241207_014143	N11495IX5M13103W

Region/Division	Deployment ID	Location Code
DOT-11	N11678IX5M12025N_20241210_001444	N11678IX5M12025N
DOT-11	N11278IX1M53008W_20241210_234915	N11278IX1M53008W
DOT-11	N11678IX5M12025S_20241211_022842	N11678IX5M12025S
DOT-11	N11678IX5M12025N_20241212_013911	N11678IX5M12025N
DOT-11	N11678IX5M12025N_20241213_003433	N11678IX5M12025N
DOT-11	N11278IX1M53008W_20241213_014847	N11278IX1M53008W
DOT-11	N1127X2M13011W_20241213_110107	N1127X2M13011W
DOT-11	N11278IX1M53008W_20241213_233520	N11278IX1M53008W
DOT-11	N11678IX5M12025N_20241214_003447	N11678IX5M12025N
DOT-11	N11678IX5M12025N_20241218_002126	N11678IX5M12025N
DOT-11	N11678IX5M12072N_20241228_004927	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250115_011822	N11678IX5M12072N
DOT-11	N11678IX5M12072S_20250116_023648	N11678IX5M12072S
DOT-11	N11678IX5M12072S_20250122_005032	N11678IX5M12072S
DOT-11	N11678IX5M12072S_20250123_004846	N11678IX5M12072S
DOT-11	N11678IX5M12072S_20250124_005959	N11678IX5M12072S
DOT-11	N11678IX5M12072S_20250124_233821	N11678IX5M12072S
DOT-11	N11678IX5M12072S_20250128_002902	N11678IX5M12072S
DOT-11	N11678IX5M12072S_20250129_003122	N11678IX5M12072S
DOT-11	N11678IX5M12072S_20250130_003100	N11678IX5M12072S
DOT-11	N11678IX5M12072S_20250201_003119	N11678IX5M12072S
DOT-11	N11678IX5M12072S_20250204_002745	N11678IX5M12072S
DOT-11	N11678IX5M12072S_20250205_003155	N11678IX5M12072S
DOT-11	N11678IX5M12072S_20250206_001614	N11678IX5M12072S
DOT-11	N11678IX5M12072S_20250207_002549	N11678IX5M12072S
DOT-11	N11678IX5M12072S_20250208_001431	N11678IX5M12072S
DOT-11	N11678IX5M12072S_20250210_234853	N11678IX5M12072S
DOT-11	N11678IX5M12072N_20250212_000813	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250214_005226	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250215_000131	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250218_235922	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250221_003034	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250222_002607	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250225_003716	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250226_001256	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250227_005106	N11678IX5M12072N
DOT-11	N11678IX5M12072S_20250228_001941	N11678IX5M12072S
DOT-11	N11678IX5M12072N_20250304_003439	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250305_001238	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250307_001519	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250308_000411	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250311_012259	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250312_005003	N11678IX5M12072N

Region/Division	Deployment ID	Location Code
DOT-11	N11678IX5M12072N_20250313_002154	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250314_002027	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250315_005730	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250318_003809	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250319_003246	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250320_003327	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250320_004254	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250322_001315	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250325_003739	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250326_003816	N11678IX5M12072N
DOT-11	N11907LX4M11010N_20250326_031701	N11907LX4M11010N
DOT-11	N11678IX5M12072N_20250327_003431	N11678IX5M12072N
DOT-11	N11907LX4M11010N_20250327_015407	N11907LX4M11010N
DOT-11	N11907HX1M11011N_20250327_103445	N11907HX1M11011N
DOT-11	N11907LX4M11010N_20250327_232519	N11907LX4M11010N
DOT-11	N11678IX5M12072N_20250328_003720	N11678IX5M12072N
DOT-11	N11678IX5M12072N_20250329_005613	N11678IX5M12072N
DOT-11	N11907LX4M11010N_20250401_234722	N11907LX4M11010N
DOT-11	N11678IX5M11072N_20250402_001203	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20250403_000757	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250403_014856	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250404_002928	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20250405_001313	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20250405_001547	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250405_005027	N11278IX2M24110E
DOT-11	N11907LX4M11010N_20250405_020017	N11907LX4M11010N
DOT-11	N11678IX5M11072N_20250408_001832	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20250409_004220	N11678IX5M11072N
DOT-11	N1187IX1M11011N_20250409_031425	N1187IX1M11011N
DOT-11	N11678IX5M11072N_20250410_001348	N11678IX5M11072N
DOT-11	N1187IX1M11011N_20250410_023107	N1187IX1M11011N
DOT-11	N11678IX5M11072N_20250411_022449	N11678IX5M11072N
DOT-11	N11278IX2M23022E_20250411_022710	N11278IX2M23022E
DOT-11	N11678IX5M12072S_20250412_001106	N11678IX5M12072S
DOT-11	N11678IX5M11072N_20250415_004804	N11678IX5M11072N
DOT-11	N11907LX4M11010N_20250416_023121	N11907LX4M11010N
DOT-11	N11678IX5M11072N_20250417_000417	N11678IX5M11072N
DOT-11	N11907LX4M11010N_20250417_015619	N11907LX4M11010N
DOT-11	N11907MX5M14135E_20250417_121853	N11907MX5M14135E
DOT-11	N11678IX5M11072N_20250418_001437	N11678IX5M11072N
DOT-11	N1187IX1M11011N_20250418_013408	N1187IX1M11011N
DOT-11	N11678IX5M11072N_20250418_234829	N11678IX5M11072N
DOT-11	N1187IX1M11011N_20250418_235326	N1187IX1M11011N

Region/Division	Deployment ID	Location Code
DOT-11	N11495IX5M13103W_20250421_233613	N11495IX5M13103W
DOT-11	N11678IX5M11072N_20250422_003912	N11678IX5M11072N
DOT-11	N11495IX5M13103W_20250422_004209	N11495IX5M13103W
DOT-11	N11495IX5M13103W_20250422_004829	N11495IX5M13103W
DOT-11	N11495IX5M13103W_20250423_003908	N11495IX5M13103W
DOT-11	N11278IX2M24110E_20250423_034741	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250424_001110	N11678IX5M11072N
DOT-11	N11495IX5M13103W_20250424_011011	N11495IX5M13103W
DOT-11	N11278IX2M24110E_20250424_020656	N11278IX2M24110E
DOT-11	N1187IX1M11011S_20250425_021959	N1187IX1M11011S
DOT-11	N11495IX5M13103W_20250425_022220	N11495IX5M13103W
DOT-11	N11678IX5M11072N_20250425_022514	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250425_023040	N11278IX2M24110E
DOT-11	N1127X2M13011E_20250425_114023	N1127X2M13011E
DOT-11	N11278IX2M24110E_20250426_013651	N11278IX2M24110E
DOT-11	N11495IX5M13103W_20250426_020940	N11495IX5M13103W
DOT-11	N11678IX5M11072N_20250426_022739	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250427_013333	N11278IX2M24110E
DOT-11	N11907HX1M11011N_20250428_112128	N11907HX1M11011N
DOT-11	N11678IX5M11072N_20250428_234655	N11678IX5M11072N
DOT-11	N1187IX1M11011S_20250429_021308	N1187IX1M11011S
DOT-11	N11278IX5M34045E_20250429_025212	N11278IX5M34045E
DOT-11	N11278IX2M24110E_20250430_010337	N11278IX2M24110E
DOT-11	N1187IX1M11011S_20250430_022313	N1187IX1M11011S
DOT-11	N11907HX1M11011N_20250430_105612	N11907HX1M11011N
DOT-11	N11278IX5M34045W_20250501_000709	N11278IX5M34045W
DOT-11	N11278IX5M34045W_20250501_003649	N11278IX5M34045W
DOT-11	N11278IX2M24110E_20250501_010221	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250501_012831	N11678IX5M11072N
DOT-11	N1195IX1M22004S_20250501_104758	N1195IX1M22004S
DOT-11	N11907HX1M11011N_20250501_114200	N11907HX1M11011N
DOT-11	N11678IX5M11072S_20250501_235832	N11678IX5M11072S
DOT-11	N11278IX2M24110E_20250502_015534	N11278IX2M24110E
DOT-11	N11907HX1M11011N_20250502_104956	N11907HX1M11011N
DOT-11	N11278IX2M24110E_20250503_013103	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250503_020147	N11678IX5M11072N
DOT-11	N11907HX1M11011N_20250505_112256	N11907HX1M11011N
DOT-11	N11907HX1M11011N_20250505_114250	N11907HX1M11011N
DOT-11	N11907HX1M11011N_20250506_115034	N11907HX1M11011N
DOT-11	N11278IX2M24110E_20250506_234924	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250507_002429	N11678IX5M11072N
DOT-11	N11907HX1M11011N_20250507_115242	N11907HX1M11011N
DOT-11	N11278IX2M24110E_20250508_001350	N11278IX2M24110E

Region/Division	Deployment ID	Location Code
DOT-11	N11678IX5M12072S_20250508_005006	N11678IX5M12072S
DOT-11	N11907HX1M11011N_20250508_112950	N11907HX1M11011N
DOT-11	N11278IX2M24110E_20250508_234650	N11278IX2M24110E
DOT-11	N11678IX5M11072S_20250509_014520	N11678IX5M11072S
DOT-11	N11907HX1M11011N_20250512_114950	N11907HX1M11011N
DOT-11	N11678IX5M11072N_20250513_002800	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20250513_004104	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250513_011621	N11278IX2M24110E
DOT-11	N11907HX1M11011N_20250513_114850	N11907HX1M11011N
DOT-11	N11907HX1M11011N_20250514_121029	N11907HX1M11011N
DOT-11	N11278IX2M24110E_20250514_235450	N11278IX2M24110E
DOT-11	N11678IX5M11072S_20250515_001449	N11678IX5M11072S
DOT-11	N11907HX1M11011N_20250515_111001	N11907HX1M11011N
DOT-11	N11907HX1M11011N_20250515_112316	N11907HX1M11011N
DOT-11	N11278IX2M24110E_20250515_232456	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250516_001527	N11678IX5M11072N
DOT-11	N11907HX1M11011N_20250516_111653	N11907HX1M11011N
DOT-11	N11907MX5M14135W_20250516_111908	N11907MX5M14135W
DOT-11	N11278IX2M24110E_20250517_005028	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250517_010523	N11678IX5M11072N
DOT-11	N11907HX1M11011N_20250519_112216	N11907HX1M11011N
DOT-11	N11278IX2M24110E_20250519_232229	N11278IX2M24110E
DOT-11	N11678IX5M11072S_20250520_004532	N11678IX5M11072S
DOT-11	N11278IX2M24110E_20250520_012656	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20250521_005156	N11278IX2M24110E
DOT-11	N11907HX1M11011N_20250521_114053	N11907HX1M11011N
DOT-11	N11278IX2M24110W_20250523_001349	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250523_004318	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250523_004611	N11278IX2M24110W
DOT-11	N11907HX1M11011N_20250527_105900	N11907HX1M11011N
DOT-11	N11907VX4M11101N_20250527_121628	N11907VX4M11101N
DOT-11	N11678IX5M11072N_20250528_001434	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250528_003620	N11278IX2M24110E
DOT-11	N11907HX1M11011N_20250528_112954	N11907HX1M11011N
DOT-11	N11907VX4M11101N_20250528_115220	N11907VX4M11101N
DOT-11	N11907HX1M11011N_20250529_105935	N11907HX1M11011N
DOT-11	N11678IX5M11072N_20250530_004646	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250530_010850	N11278IX2M24110E
DOT-11	N11907HX1M11011N_20250530_110549	N11907HX1M11011N
DOT-11	N11907VX4M11101N_20250530_112416	N11907VX4M11101N
DOT-11	N11907HX1M11011N_20250602_114733	N11907HX1M11011N
DOT-11	N11278IX2M24110W_20250603_000938	N11278IX2M24110W
DOT-11	N11907HX1M11011N_20250603_122544	N11907HX1M11011N

Region/Division	Deployment ID	Location Code
DOT-11	N11278IX2M24110W_20250604_001304	N11278IX2M24110W
DOT-11	N11907HX1M11011N_20250604_110715	N11907HX1M11011N
DOT-11	N11907HX1M11011N_20250604_112430	N11907HX1M11011N
DOT-11	N11678IX5M11072N_20250605_002013	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250605_010504	N11278IX2M24110W
DOT-11	N11278IX2M24110W_20250605_041729	N11278IX2M24110W
DOT-11	N1127X2M13011W_20250605_103728	N1127X2M13011W
DOT-11	N11278IX2M24110W_20250605_234830	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250606_021948	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250607_002231	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250607_011104	N11678IX5M11072N
DOT-11	N11907HX1M11011N_20250609_112752	N11907HX1M11011N
DOT-11	N11278IX2M24110W_20250609_233758	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250610_004121	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250611_001227	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250611_002528	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20250612_004019	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250612_020003	N11278IX2M24110W
DOT-11	N11907HX1M11011N_20250612_111225	N11907HX1M11011N
DOT-11	N11678IX5M11072N_20250613_000420	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250613_002902	N11278IX2M24110W
DOT-11	N11907HX1M11011N_20250613_111116	N11907HX1M11011N
DOT-11	N11678IX5M11072N_20250614_001650	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20250617_003249	N11678IX5M11072N
DOT-11	N11907HX1M11011N_20250617_115718	N11907HX1M11011N
DOT-11	N11278IX2M24110E_20250618_002644	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250618_002931	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250618_004343	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250619_010518	N11678IX5M11072N
DOT-11	N11907HX1M11011N_20250619_112920	N11907HX1M11011N
DOT-11	N11278IX2M24110W_20250620_001648	N11278IX2M24110W
DOT-11	N11678IX5M11072S_20250620_012630	N11678IX5M11072S
DOT-11	N11278IX2M24110W_20250620_235441	N11278IX2M24110W
DOT-11	N11278IX2M24110W_20250621_000856	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250621_004827	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250623_230831	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250624_004145	N11678IX5M11072N
DOT-11	N1195IX1M21060N_20250624_100445	N1195IX1M21060N
DOT-11	N11278IX2M24110W_20250624_233706	N11278IX2M24110W
DOT-11	N11278IX2M24110W_20250625_234144	N11278IX2M24110W
DOT-11	N11278IX2M24110E_20250626_235657	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250627_004335	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250628_001237	N11278IX2M24110W

Region/Division	Deployment ID	Location Code
DOT-11	N11678IX5M11072N_20250628_010017	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250701_003050	N11278IX2M24110W
DOT-11	N11278IX2M24110W_20250701_233300	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250708_003049	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20250708_013506	N11678IX5M11072N
DOT-11	N11907HX1M11011N_20250708_120425	N11907HX1M11011N
DOT-11	N11678IX5M11072N_20250709_003137	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20250710_000118	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250711_004131	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250711_005859	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20250712_001137	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250712_024316	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20250712_030246	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20250715_231612	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20250715_232736	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250716_000723	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250716_233909	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20250716_234550	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250717_015003	N11678IX5M11072N
DOT-11	N11878X5M13006E_20250717_115114	N11878X5M13006E
DOT-11	N11278IX2M24110E_20250717_222729	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20250717_225531	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250718_003912	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250718_235820	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250719_004144	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250721_235526	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20250722_000033	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250722_003414	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250722_230547	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250723_003350	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250724_001956	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250724_005005	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250724_233228	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250725_003002	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250725_231131	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250726_003627	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250728_230943	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250729_002111	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250730_020048	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250730_031804	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20250730_235259	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250731_015055	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20250802_013727	N11278IX2M24110E

Region/Division	Deployment ID	Location Code
DOT-11	N11678IX5M11072S_20250802_014004	N11678IX5M11072S
DOT-11	N11907MX5M14135E_20250804_123632	N11907MX5M14135E
DOT-11	N11278IX6M13020W_20250804_231819	N11278IX6M13020W
DOT-11	N11278IX6M13020W_20250805_002324	N11278IX6M13020W
DOT-11	N11278IX2M24110E_20250805_005338	N11278IX2M24110E
DOT-11	N11678IX5M11072S_20250805_010043	N11678IX5M11072S
DOT-11	N11907MX5M14135E_20250805_111920	N11907MX5M14135E
DOT-11	N11278IX6M13020W_20250805_230512	N11278IX6M13020W
DOT-11	N11278IX6M13020W_20250805_235659	N11278IX6M13020W
DOT-11	N11678IX5M11072S_20250806_011638	N11678IX5M11072S
DOT-11	N11278IX2M24110W_20250806_011851	N11278IX2M24110W
DOT-11	N11907MX5M14135E_20250806_110112	N11907MX5M14135E
DOT-11	N1195IX1M22004S_20250806_110701	N1195IX1M22004S
DOT-11	N11278IX6M13020W_20250807_001902	N11278IX6M13020W
DOT-11	N11278IX2M24110W_20250807_003454	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250807_013209	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250807_025706	N11278IX2M24110W
DOT-11	N11907MX5M14135E_20250807_112036	N11907MX5M14135E
DOT-11	N11678IX5M11072N_20250808_003347	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250808_011343	N11278IX2M24110W
DOT-11	N11278IX2M24110E_20250808_233518	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250809_011057	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250812_000121	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250812_002642	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250812_012844	N11278IX2M24110W
DOT-11	N11907MX5M14135E_20250812_020546	N11907MX5M14135E
DOT-11	N11278IX2M24110W_20250812_233024	N11278IX2M24110W
DOT-11	N11678IX5M11072S_20250813_010359	N11678IX5M11072S
DOT-11	N11678IX5M11072S_20250813_010644	N11678IX5M11072S
DOT-11	N11907MX5M14135E_20250813_023039	N11907MX5M14135E
DOT-11	N11678IX5M11072N_20250814_004506	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250814_004513	N11278IX2M24110W
DOT-11	N11278IX2M24110W_20250814_234004	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250815_005444	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250816_002008	N11278IX2M24110E
DOT-11	N11678IX5M11072S_20250816_023124	N11678IX5M11072S
DOT-11	N11278IX2M24110W_20250818_233322	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250819_002630	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250819_230711	N11278IX2M24110W
DOT-11	N11278IX2M24110W_20250819_233331	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250820_002314	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250821_233935	N11278IX2M24110W
DOT-11	N11278IX2M24110W_20250822_000143	N11278IX2M24110W

Region/Division	Deployment ID	Location Code
DOT-11	N11678IX5M12029S_20250822_011040	N11678IX5M12029S
DOT-11	N11278IX2M24110W_20250823_000659	N11278IX2M24110W
DOT-11	N11278IX2M24110W_20250826_002134	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250826_012435	N11678IX5M11072N
DOT-11	N11908BX5M23039W_20250826_122917	N11908BX5M23039W
DOT-11	N11278IX2M24110W_20250827_000051	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250827_020239	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250827_231807	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250828_013443	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250828_233049	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250829_011529	N11678IX5M11072N
DOT-11	N11678IX5M11072S_20250830_015857	N11678IX5M11072S
DOT-11	N11278IX2M24110W_20250903_002206	N11278IX2M24110W
DOT-11	N11678IX5M11072S_20250903_020651	N11678IX5M11072S
DOT-11	N11278IX2M24110W_20250903_233800	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250904_014607	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250906_001021	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250906_020221	N11678IX5M11072N
DOT-11	N11278IX2M24110W_20250909_003233	N11278IX2M24110W
DOT-11	N11678IX5M11072N_20250909_004455	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20250910_012113	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20250910_235931	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20250911_003231	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20250912_003450	N11678IX5M11072N
DOT-11	N11678IX5M11072S_20250913_011612	N11678IX5M11072S
DOT-11	N11495IX5M13090E_20250916_010355	N11495IX5M13090E
DOT-11	N11495IX5M13090E_20250916_011315	N11495IX5M13090E
DOT-11	N11678IX5M11072N_20250916_012220	N11678IX5M11072N
DOT-11	N11495IX5M13090E_20250916_232336	N11495IX5M13090E
DOT-11	N11678IX5M11072N_20250917_002834	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20250918_004815	N11678IX5M11072N
DOT-11	N11495IX5M13074E_20250918_010909	N11495IX5M13074E
DOT-11	N11678IX5M11072S_20250919_004954	N11678IX5M11072S
DOT-11	N11495IX5M13074E_20250919_012040	N11495IX5M13074E
DOT-11	N11495IX5M13074E_20250919_234827	N11495IX5M13074E
DOT-11	N11678IX5M11072N_20250920_004525	N11678IX5M11072N
DOT-11	N11907HX1M11011N_20250922_113938	N11907HX1M11011N
DOT-11	N11907HX1M11011N_20250922_114856	N11907HX1M11011N
DOT-11	N11495IX5M13090E_20250922_233054	N11495IX5M13090E
DOT-11	N11678IX5M11072N_20250923_004931	N11678IX5M11072N
DOT-11	N11907HX1M11011N_20250923_110504	N11907HX1M11011N
DOT-11	N11495IX5M13090E_20250923_234632	N11495IX5M13090E
DOT-11	N11678IX5M11072N_20250924_000439	N11678IX5M11072N

Region/Division	Deployment ID	Location Code
DOT-11	N11907HX1M11011N_20250924_111228	N11907HX1M11011N
DOT-11	N11495IX5M13090E_20250924_233453	N11495IX5M13090E
DOT-11	N11908BX5M23039E_20250925_003106	N11908BX5M23039E
DOT-11	N11678IX5M11072N_20250925_003739	N11678IX5M11072N
DOT-11	N11908BX5M23039W_20250926_000935	N11908BX5M23039W
DOT-11	N11678IX5M11072N_20250926_001643	N11678IX5M11072N
DOT-11	N11907HX1M11011N_20250926_113844	N11907HX1M11011N
DOT-11	N11495IX5M13090E_20250926_232219	N11495IX5M13090E
DOT-11	N11908BX5M23039W_20250927_000622	N11908BX5M23039W
DOT-11	N11678IX5M11072N_20250927_002753	N11678IX5M11072N
DOT-11	N11908BX5M23039W_20250927_012821	N11908BX5M23039W
DOT-11	N11495IX5M13074E_20250927_234703	N11495IX5M13074E
DOT-11	N11907HX1M11011N_20250929_115828	N11907HX1M11011N
DOT-11	N11495IX5M13090E_20250929_233719	N11495IX5M13090E
DOT-11	N11678IX5M11072N_20250930_003009	N11678IX5M11072N
DOT-11	N11908BX5M23039W_20250930_014937	N11908BX5M23039W
DOT-11	N11907HX1M11011N_20250930_114314	N11907HX1M11011N
DOT-11	N11495IX5M13090E_20250930_231116	N11495IX5M13090E
DOT-11	N11678IX5M11072N_20251001_002515	N11678IX5M11072N
DOT-11	N11907HX1M11011N_20251001_113937	N11907HX1M11011N
DOT-11	N11495IX5M13090W_20251001_234359	N11495IX5M13090W
DOT-11	N11678IX5M11072N_20251002_005003	N11678IX5M11072N
DOT-11	N11495IX5M13090E_20251002_233954	N11495IX5M13090E
DOT-11	N11678IX5M11072N_20251003_002915	N11678IX5M11072N
DOT-11	N11908BX5M23039W_20251003_003044	N11908BX5M23039W
DOT-11	N11907HX1M11011N_20251003_115547	N11907HX1M11011N
DOT-11	N11678IX5M11072N_20251004_004537	N11678IX5M11072N
DOT-11	N11908BX5M23039W_20251004_010751	N11908BX5M23039W
DOT-11	N11495IX5M13090E_20251004_010805	N11495IX5M13090E
DOT-11	N11907HX1M11011N_20251006_104859	N11907HX1M11011N
DOT-11	N11908BX5M23039W_20251007_001556	N11908BX5M23039W
DOT-11	N11678IX5M11072N_20251007_003827	N11678IX5M11072N
DOT-11	N11907HX1M11011N_20251007_112202	N11907HX1M11011N
DOT-11	N11908BX5M23039W_20251007_235616	N11908BX5M23039W
DOT-11	N11678IX5M11072N_20251008_003401	N11678IX5M11072N
DOT-11	N11907HX1M11011N_20251008_112113	N11907HX1M11011N
DOT-11	N11495IX5M13090E_20251009_002633	N11495IX5M13090E
DOT-11	N11908BX5M23039W_20251009_002715	N11908BX5M23039W
DOT-11	N11495IX5M13090E_20251009_003604	N11495IX5M13090E
DOT-11	N11678IX5M11072N_20251009_004004	N11678IX5M11072N
DOT-11	N11495IX5M13090E_20251010_001346	N11495IX5M13090E
DOT-11	N11678IX5M11072N_20251010_003334	N11678IX5M11072N
DOT-11	N11908BX5M23039W_20251010_005107	N11908BX5M23039W

Region/Division	Deployment ID	Location Code
DOT-11	N11495IX5M13090E_20251010_011150	N11495IX5M13090E
DOT-11	N11678IX5M11072N_20251011_002750	N11678IX5M11072N
DOT-11	N11908BX5M23039W_20251011_010341	N11908BX5M23039W
DOT-11	N11495IX5M13090E_20251011_024655	N11495IX5M13090E
DOT-11	N11678IX5M11072N_20251014_003224	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20251015_003130	N11678IX5M11072N
DOT-11	N11495IX5M13090W_20251015_024845	N11495IX5M13090W
DOT-11	N11908BX5M23039W_20251016_001949	N11908BX5M23039W
DOT-11	N11908BX5M23039W_20251016_002552	N11908BX5M23039W
DOT-11	N11678IX5M11072N_20251016_004403	N11678IX5M11072N
DOT-11	N11495IX5M13090E_20251016_004531	N11495IX5M13090E
DOT-11	N11678IX5M11072N_20251017_003800	N11678IX5M11072N
DOT-11	N11908BX5M23039W_20251017_003903	N11908BX5M23039W
DOT-11	N11495IX5M13090E_20251017_004438	N11495IX5M13090E
DOT-11	N11495IX5M13090W_20251017_231530	N11495IX5M13090W
DOT-11	N11495IX5M13090W_20251017_232038	N11495IX5M13090W
DOT-11	N11495IX5M13090W_20251017_232641	N11495IX5M13090W
DOT-11	N11678IX5M11072N_20251018_002513	N11678IX5M11072N
DOT-11	N11908BX5M23039W_20251018_003612	N11908BX5M23039W
DOT-11	N11495IX5M13090W_20251018_232735	N11495IX5M13090W
DOT-11	N11495IX5M13090W_20251020_225008	N11495IX5M13090W
DOT-11	N11908BX5M23039W_20251021_000506	N11908BX5M23039W
DOT-11	N11678IX5M11072N_20251021_004951	N11678IX5M11072N
DOT-11	N11908BX5M23039W_20251021_224254	N11908BX5M23039W
DOT-11	N11495IX5M13090W_20251021_232417	N11495IX5M13090W
DOT-11	N11678IX5M11072N_20251022_003755	N11678IX5M11072N
DOT-11	N11495IX5M13090W_20251022_011039	N11495IX5M13090W
DOT-11	N11495IX5M13090W_20251022_234605	N11495IX5M13090W
DOT-11	N11678IX5M11072N_20251023_001852	N11678IX5M11072N
DOT-11	N11908BX5M23039W_20251023_232846	N11908BX5M23039W
DOT-11	N11495IX5M13090W_20251023_234430	N11495IX5M13090W
DOT-11	N11678IX5M11072S_20251023_235946	N11678IX5M11072S
DOT-11	N11495IX5M13090W_20251024_234447	N11495IX5M13090W
DOT-11	N11908BX5M23039W_20251024_234508	N11908BX5M23039W
DOT-11	N11678IX5M11072N_20251025_004531	N11678IX5M11072N
DOT-11	N11495IX5M13090W_20251025_234429	N11495IX5M13090W
DOT-11	N11495IX5M13090W_20251027_230118	N11495IX5M13090W
DOT-11	N11678IX5M11072N_20251028_010653	N11678IX5M11072N
DOT-11	N11495IX5M13090W_20251028_235418	N11495IX5M13090W
DOT-11	N11678IX5M11072N_20251029_001209	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20251029_015120	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20251030_001543	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20251031_002711	N11678IX5M11072N

Region/Division	Deployment ID	Location Code
DOT-11	N11678IX5M11072N_20251101_001453	N11678IX5M11072N
DOT-11	N11495IX5M13090W_20251101_014916	N11495IX5M13090W
DOT-11	N11495IX5M13090W_20251102_002926	N11495IX5M13090W
DOT-11	N11495IX5M13090W_20251102_024903	N11495IX5M13090W
DOT-11	N11495IX5M13090W_20251103_233337	N11495IX5M13090W
DOT-11	N11678IX5M11072N_20251104_001749	N11678IX5M11072N
DOT-11	N11495IX5M13090W_20251104_233237	N11495IX5M13090W
DOT-11	N11678IX5M11072N_20251105_002139	N11678IX5M11072N
DOT-11	N11495IX5M13090W_20251105_022135	N11495IX5M13090W
DOT-11	N11678IX5M11072N_20251106_001056	N11678IX5M11072N
DOT-11	N11495IX5M13090W_20251106_001112	N11495IX5M13090W
DOT-11	N11495IX5M13090W_20251107_003535	N11495IX5M13090W
DOT-11	N11678IX5M11072N_20251107_003829	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20251108_002802	N11678IX5M11072N
DOT-11	N11495IX5M13090W_20251109_000602	N11495IX5M13090W
DOT-11	N11678IX5M11072N_20251109_003134	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20251110_001018	N11678IX5M11072N
DOT-11	N11908BX5M23039W_20251111_002247	N11908BX5M23039W
DOT-11	N11495IX5M13090E_20251111_002940	N11495IX5M13090E
DOT-11	N11678IX5M11072N_20251111_004629	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251111_012952	N11278IX2M24110E
DOT-11	N11908BX5M23039W_20251111_232139	N11908BX5M23039W
DOT-11	N11495IX5M13090E_20251112_000902	N11495IX5M13090E
DOT-11	N11678IX5M11072N_20251112_002951	N11678IX5M11072N
DOT-11	N11495IX5M13090E_20251112_010920	N11495IX5M13090E
DOT-11	N11278IX2M24110E_20251112_011542	N11278IX2M24110E
DOT-11	N11908BX5M23039W_20251113_000717	N11908BX5M23039W
DOT-11	N11678IX5M11072N_20251113_000925	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251113_004524	N11278IX2M24110E
DOT-11	N11495IX5M13090E_20251113_034809	N11495IX5M13090E
DOT-11	N11278IX2M24110E_20251113_234523	N11278IX2M24110E
DOT-11	N11908BX5M23039W_20251113_235327	N11908BX5M23039W
DOT-11	N11678IX5M11072N_20251114_003830	N11678IX5M11072N
DOT-11	N11908BX5M23039W_20251114_233823	N11908BX5M23039W
DOT-11	N11678IX5M11072N_20251114_235450	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251115_003753	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20251118_000949	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20251118_002225	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251118_235553	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20251119_002126	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20251120_001542	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251120_002512	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20251121_000653	N11278IX2M24110E

Region/Division	Deployment ID	Location Code
DOT-11	N11678IX5M11072N_20251121_002502	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20251122_003053	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251122_013521	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20251125_012548	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20251202_002248	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20251203_000056	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20251204_003149	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251204_004604	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20251205_000018	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251205_002536	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20251206_003101	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251206_010928	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20251207_012525	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20251209_000603	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251209_013042	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20251210_000221	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251210_002345	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20251210_234731	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251210_234929	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20251211_235229	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20251211_235757	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20251212_000856	N11678IX5M11072N
DOT-11	N11678IX5M11072N_20251213_001205	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251213_002136	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20251216_000430	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251216_013257	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20251217_002021	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251217_010131	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20251217_010724	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20251218_000551	N11678IX5M11072N
DOT-11	N11278IX2M24110E_20251218_001914	N11278IX2M24110E
DOT-11	N11678IX5M11072S_20251219_001839	N11678IX5M11072S
DOT-11	N11278IX2M24110W_20251219_005403	N11278IX2M24110W
DOT-11	N11278IX2M24110E_20251220_011015	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20251220_090022	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20251220_175748	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20251220_230724	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20251221_074008	N11278IX2M24110E
DOT-11	N11278IX2M24110E_20251221_095741	N11278IX2M24110E
DOT-11	N11678IX5M11072N_20251223_002418	N11678IX5M11072N
TA-Albany	T0BS0168302428E_20240104_090838	T0BS0168302428E
TA-Albany	T0BS0086700094W_20240111_085127	T0BS0086700094W
TA-Albany	T0901917518598E_20240205_073543	T0901917518598E

Region/Division	Deployment ID	Location Code
TA-Albany	T0901917518598E_20240205_081830	T0901917518598E
TA-Albany	T0BS0168302428E_20240205_085555	T0BS0168302428E
TA-Albany	T0871057909669S_20240206_085418	T0871057909669S
TA-Albany	T0901950019754W_20240207_084159	T0901950019754W
TA-Albany	T0BS0168302428E_20240207_085654	T0BS0168302428E
TA-Albany	T0BS0242801683W_20240209_095246	T0BS0242801683W
TA-Albany	T0871473114503S_20240214_213915	T0871473114503S
TA-Albany	T0871473114503S_20240215_014823	T0871473114503S
TA-Albany	T0901822618325W_20240221_083737	T0901822618325W
TA-Albany	T0901832518598W_20240222_091942	T0901832518598W
TA-Albany	T0901859819175W_20240226_073331	T0901859819175W
TA-Albany	T0BS0089401683E_20240226_081807	T0BS0089401683E
TA-Albany	T0901940819500W_20240227_083619	T0901940819500W
TA-Albany	T0BS0089401683E_20240301_080935	T0BS0089401683E
TA-Albany	T0901859819175W_20240301_095528	T0901859819175W
TA-Albany	T0871057909669S_20240304_080847	T0871057909669S
TA-Albany	T0901950019754W_20240304_101720	T0901950019754W
TA-Albany	T0901832518226E_20240308_073012	T0901832518226E
TA-Albany	T0870966910579N_20240311_091451	T0870966910579N
TA-Albany	T0901859819175W_20240312_080459	T0901859819175W
TA-Albany	T0870966910579N_20240312_081306	T0870966910579N
TA-Albany	T0901917519408W_20240313_085346	T0901917519408W
TA-Albany	T0BS0009400867E_20240313_094144	T0BS0009400867E
TA-Albany	T0901940819500W_20240314_082257	T0901940819500W
TA-Albany	T0BS0089401683E_20240314_100142	T0BS0089401683E
TA-Albany	T0BS0089401683E_20240315_093426	T0BS0089401683E
TA-Albany	T0BS0089401683E_20240318_085046	T0BS0089401683E
TA-Albany	T0BS0242801683W_20240320_092914	T0BS0242801683W
TA-Albany	T0901545016754W_20240326_083644	T0901545016754W
TA-Albany	T0870877208176S_20240326_100641	T0870877208176S
TA-Albany	T0BS0242801683W_20240327_082740	T0BS0242801683W
TA-Albany	T0901822617784E_20240329_083525	T0901822617784E
TA-Albany	T0901917518598E_20240401_092837	T0901917518598E
TA-Albany	T0901832518598W_20240402_081331	T0901832518598W
TA-Albany	T0870910009669N_20240410_090308	T0870910009669N
TA-Albany	T0871057909669S_20240415_092045	T0871057909669S
TA-Albany	T0901859819175W_20240415_092801	T0901859819175W
TA-Albany	T0871057909669S_20240415_114722	T0871057909669S
TA-Albany	T0871140210579S_20240416_072023	T0871140210579S
TA-Albany	T0901917518598E_20240416_083631	T0901917518598E
TA-Albany	T0901545016754W_20240417_061347	T0901545016754W
TA-Albany	T0870817608772N_20240417_080655	T0870817608772N
TA-Albany	T0871140210579S_20240418_234419	T0871140210579S

Region/Division	Deployment ID	Location Code
TA-Albany	T0901859818325E_20240419_091026	T0901859818325E
TA-Albany	T0871140210579S_20240420_002201	T0871140210579S
TA-Albany	T0870966910579N_20240421_222503	T0870966910579N
TA-Albany	T0870966909100S_20240421_230408	T0870966909100S
TA-Albany	T0870966910579N_20240422_201153	T0870966910579N
TA-Albany	T0901675415450E_20240423_093021	T0901675415450E
TA-Albany	T0870966910579N_20240424_202933	T0870966910579N
TA-Albany	T0901940819500W_20240425_083738	T0901940819500W
TA-Albany	T0870966910579N_20240425_210020	T0870966910579N
TA-Albany	T0901822617784E_20240426_074938	T0901822617784E
TA-Albany	T0901859818325E_20240429_085407	T0901859818325E
TA-Albany	T0BS0009400867E_20240430_090010	T0BS0009400867E
TA-Albany	T0871140210579S_20240501_082732	T0871140210579S
TA-Albany	T0901675415450E_20240501_093323	T0901675415450E
TA-Albany	T0901545016754W_20240502_075535	T0901545016754W
TA-Albany	T0870966910579N_20240502_205853	T0870966910579N
TA-Albany	T0901733416784E_20240503_080015	T0901733416784E
TA-Albany	T0BS0009400867E_20240503_100643	T0BS0009400867E
TA-Albany	T0870966910579N_20240505_230148	T0870966910579N
TA-Albany	T0BS0009400000W_20240506_103318	T0BS0009400000W
TA-Albany	T0901917518598E_20240506_113556	T0901917518598E
TA-Albany	T0901859818325E_20240506_135817	T0901859818325E
TA-Albany	T0870966910579N_20240506_232118	T0870966910579N
TA-Albany	T0871140210579S_20240507_073947	T0871140210579S
TA-Albany	T0901741817784W_20240507_080216	T0901741817784W
TA-Albany	T0901675415450E_20240507_215635	T0901675415450E
TA-Albany	T0871140210579S_20240508_223734	T0871140210579S
TA-Albany	T0901859819175W_20240509_094623	T0901859819175W
TA-Albany	T0901545016754W_20240512_220452	T0901545016754W
TA-Albany	T0870966910579N_20240512_230315	T0870966910579N
TA-Albany	T0901545016754W_20240513_004459	T0901545016754W
TA-Albany	T0871140210579S_20240513_074203	T0871140210579S
TA-Albany	T0901950019754W_20240513_082215	T0901950019754W
TA-Albany	T0901733416784E_20240513_083730	T0901733416784E
TA-Albany	T0901733416784E_20240514_072954	T0901733416784E
TA-Albany	T0871140210579S_20240514_083911	T0871140210579S
TA-Albany	T0901950019754W_20240514_094403	T0901950019754W
TA-Albany	T0901500915450W_20240515_223622	T0901500915450W
TA-Albany	T0901733416784E_20240516_093218	T0901733416784E
TA-Albany	T0871057911402N_20240516_231803	T0871057911402N
TA-Albany	T0871140210579S_20240517_075501	T0871140210579S
TA-Albany	T0871057911402N_20240519_221959	T0871057911402N
TA-Albany	T0901675415450E_20240520_005432	T0901675415450E

Region/Division	Deployment ID	Location Code
TA-Albany	T0901675415450E_20240520_033525	T0901675415450E
TA-Albany	T0871140210579S_20240520_082757	T0871140210579S
TA-Albany	T0901917518598E_20240520_092725	T0901917518598E
TA-Albany	T0871057911402N_20240520_204112	T0871057911402N
TA-Albany	T0871140210579S_20240521_082636	T0871140210579S
TA-Albany	T0901822617784E_20240521_101817	T0901822617784E
TA-Albany	T0871057911402N_20240522_003909	T0871057911402N
TA-Albany	T0901741817784W_20240522_085719	T0901741817784W
TA-Albany	T0871140210579S_20240522_091643	T0871140210579S
TA-Albany	T0871057911402N_20240522_215855	T0871057911402N
TA-Albany	T0871140210579S_20240523_083314	T0871140210579S
TA-Albany	T0BS0086700094W_20240523_092115	T0BS0086700094W
TA-Albany	T0871057911402N_20240523_231147	T0871057911402N
TA-Albany	T0871140210579S_20240524_075511	T0871140210579S
TA-Albany	T0871057911402N_20240528_085913	T0871057911402N
TA-Albany	T0870966910579N_20240528_203119	T0870966910579N
TA-Albany	T0901545016754W_20240529_084923	T0901545016754W
TA-Albany	T0871057911402N_20240529_095632	T0871057911402N
TA-Albany	T0871140210579S_20240529_202352	T0871140210579S
TA-Albany	T0871057911402N_20240530_081216	T0871057911402N
TA-Albany	T0901859819175W_20240530_103414	T0901859819175W
TA-Albany	T0871057911402N_20240530_122147	T0871057911402N
TA-Albany	T0871140210579S_20240530_203931	T0871140210579S
TA-Albany	T0871057911402N_20240531_081010	T0871057911402N
TA-Albany	T0871140210579S_20240602_235754	T0871140210579S
TA-Albany	T0871140210579S_20240603_081949	T0871140210579S
TA-Albany	T0901545016754W_20240603_083953	T0901545016754W
TA-Albany	T0870966910579N_20240603_231544	T0870966910579N
TA-Albany	T0BS0086700094W_20240604_082203	T0BS0086700094W
TA-Albany	T0871140210579S_20240604_083831	T0871140210579S
TA-Albany	T0901678417334W_20240604_084025	T0901678417334W
TA-Albany	T0871140210579S_20240605_074205	T0871140210579S
TA-Albany	T0BS0086700094W_20240605_083650	T0BS0086700094W
TA-Albany	T0871140210579S_20240606_073936	T0871140210579S
TA-Albany	T0871140210579S_20240607_072551	T0871140210579S
TA-Albany	T0871140210579S_20240610_071625	T0871140210579S
TA-Albany	T0901778417418E_20240610_083122	T0901778417418E
TA-Albany	T0901545016754W_20240610_221147	T0901545016754W
TA-Albany	T0901859819175W_20240611_084135	T0901859819175W
TA-Albany	T0901675415450E_20240611_205735	T0901675415450E
TA-Albany	T0870877208176S_20240612_011250	T0870877208176S
TA-Albany	T0901675415450E_20240612_082630	T0901675415450E
TA-Albany	T0901675415450E_20240612_201846	T0901675415450E

Region/Division	Deployment ID	Location Code
TA-Albany	T0901545016754W_20240613_104942	T0901545016754W
TA-Albany	T0BS0086700094W_20240613_110135	T0BS0086700094W
TA-Albany	T0901675415450E_20240613_201859	T0901675415450E
TA-Albany	T0871057909669S_20240613_235956	T0871057909669S
TA-Albany	T0871140210579S_20240614_074140	T0871140210579S
TA-Albany	T0871140210579S_20240614_114234	T0871140210579S
TA-Albany	T0871057909669S_20240617_035241	T0871057909669S
TA-Albany	T0901545015009E_20240617_213117	T0901545015009E
TA-Albany	T0871057909669S_20240617_235333	T0871057909669S
TA-Albany	T0901859819175W_20240618_085415	T0901859819175W
TA-Albany	T0871057909669S_20240618_231438	T0871057909669S
TA-Albany	T0901500915450W_20240619_010516	T0901500915450W
TA-Albany	T0871140210579S_20240619_073913	T0871140210579S
TA-Albany	T0901545016754W_20240619_220915	T0901545016754W
TA-Albany	T0871057909669S_20240620_000258	T0871057909669S
TA-Albany	T0901940819175E_20240620_084739	T0901940819175E
TA-Albany	T0901545016754W_20240621_001353	T0901545016754W
TA-Albany	T0871140210579S_20240621_094539	T0871140210579S
TA-Albany	T0871057909669S_20240624_004455	T0871057909669S
TA-Albany	T0BS0086700094W_20240624_084823	T0BS0086700094W
TA-Albany	T0901545016754W_20240624_202330	T0901545016754W
TA-Albany	T0870910009669N_20240624_222959	T0870910009669N
TA-Albany	T0901675415450E_20240625_014408	T0901675415450E
TA-Albany	T0901675415450E_20240625_082918	T0901675415450E
TA-Albany	T0901675415450E_20240625_194727	T0901675415450E
TA-Albany	T0870910009669N_20240625_203318	T0870910009669N
TA-Albany	T0870910009669N_20240626_003041	T0870910009669N
TA-Albany	T0901545016754W_20240626_081710	T0901545016754W
TA-Albany	T0901778417418E_20240627_075506	T0901778417418E
TA-Albany	T0901675415450E_20240627_193238	T0901675415450E
TA-Albany	T0870966910579N_20240628_011327	T0870966910579N
TA-Albany	T0870966910579N_20240628_041928	T0870966910579N
TA-Albany	T0871140210579S_20240628_081734	T0871140210579S
TA-Albany	T0901500915450W_20240630_211343	T0901500915450W
TA-Albany	T0870966910579N_20240630_224210	T0870966910579N
TA-Albany	T0871140210579S_20240701_115926	T0871140210579S
TA-Albany	T0901545016754W_20240701_211210	T0901545016754W
TA-Albany	T0871057909669S_20240701_232114	T0871057909669S
TA-Albany	T0BS0086700094W_20240702_104217	T0BS0086700094W
TA-Albany	T0901545016754W_20240702_215912	T0901545016754W
TA-Albany	T0870966910579N_20240702_230449	T0870966910579N
TA-Albany	T0871140210579S_20240703_073011	T0871140210579S
TA-Albany	T0901675415450E_20240708_201443	T0901675415450E

Region/Division	Deployment ID	Location Code
TA-Albany	T0870966910579N_20240708_225212	T0870966910579N
TA-Albany	T0870910009669N_20240709_003603	T0870910009669N
TA-Albany	T0901778418226W_20240709_092637	T0901778418226W
TA-Albany	T0901675415450E_20240709_200137	T0901675415450E
TA-Albany	T0871057911402N_20240709_201352	T0871057911402N
TA-Albany	T0BS0009400000W_20240710_085611	T0BS0009400000W
TA-Albany	T0871140210579S_20240711_092117	T0871140210579S
TA-Albany	T0901675415450E_20240711_194917	T0901675415450E
TA-Albany	T0871057911402N_20240711_222534	T0871057911402N
TA-Albany	T0901675415450E_20240714_222900	T0901675415450E
TA-Albany	T0871140210579S_20240715_004010	T0871140210579S
TA-Albany	T0871140210579S_20240715_100223	T0871140210579S
TA-Albany	T0BS0242801683W_20240716_093305	T0BS0242801683W
TA-Albany	T0BS0168302428E_20240716_122122	T0BS0168302428E
TA-Albany	T0871140210579S_20240716_194829	T0871140210579S
TA-Albany	T0901545015009E_20240716_233134	T0901545015009E
TA-Albany	T0871057909669S_20240718_232402	T0871057909669S
TA-Albany	T0901500915450W_20240718_233503	T0901500915450W
TA-Albany	T0901545016754W_20240721_200552	T0901545016754W
TA-Albany	T0871057909669S_20240722_003112	T0871057909669S
TA-Albany	T0871057909669S_20240722_030232	T0871057909669S
TA-Albany	T0871140210579S_20240722_073611	T0871140210579S
TA-Albany	T0BS0009400867E_20240723_085722	T0BS0009400867E
TA-Albany	T0871057909669S_20240723_200034	T0871057909669S
TA-Albany	T0901545016754W_20240723_222723	T0901545016754W
TA-Albany	T0901675415450E_20240724_051500	T0901675415450E
TA-Albany	T0871140210579S_20240724_074828	T0871140210579S
TA-Albany	T0901950019408E_20240725_082010	T0901950019408E
TA-Albany	T0871140210579S_20240726_092348	T0871140210579S
TA-Albany	T0871140210579S_20240726_093015	T0871140210579S
TA-Albany	T0871473114503S_20240726_094304	T0871473114503S
TA-Albany	T0871140210579S_20240726_095243	T0871140210579S
TA-Albany	T0871140210579S_20240726_102459	T0871140210579S
TA-Albany	T0871140210579S_20240726_102918	T0871140210579S
TA-Albany	T0901675415450E_20240728_215922	T0901675415450E
TA-Albany	T0871057909669S_20240728_235924	T0871057909669S
TA-Albany	T0871057909669S_20240729_000918	T0871057909669S
TA-Albany	T0901950019408E_20240729_112103	T0901950019408E
TA-Albany	T0901675415450E_20240729_215454	T0901675415450E
TA-Albany	T0870817608772N_20240730_000533	T0870817608772N
TA-Albany	T0871140210579S_20240730_072503	T0871140210579S
TA-Albany	T0BS0168302428E_20240731_084431	T0BS0168302428E
TA-Albany	T0870817608772N_20240731_234902	T0870817608772N

Region/Division	Deployment ID	Location Code
TA-Albany	T0901950019408E_20240801_083148	T0901950019408E
TA-Albany	T0871140210579S_20240801_085015	T0871140210579S
TA-Albany	T0871140210579S_20240801_090929	T0871140210579S
TA-Albany	T0871140210579S_20240801_130751	T0871140210579S
TA-Albany	T0871057909669S_20240801_205803	T0871057909669S
TA-Albany	T0871057909669S_20240801_223158	T0871057909669S
TA-Albany	T0871057909669S_20240802_030733	T0871057909669S
TA-Albany	T0871140210579S_20240802_075533	T0871140210579S
TA-Albany	T0871057909669S_20240804_230348	T0871057909669S
TA-Albany	T0871057909669S_20240805_030128	T0871057909669S
TA-Albany	T0901950019408E_20240805_084842	T0901950019408E
TA-Albany	T0901675415450E_20240805_120325	T0901675415450E
TA-Albany	T0BS0089401683E_20240806_080632	T0BS0089401683E
TA-Albany	T0871140210579S_20240807_072627	T0871140210579S
TA-Albany	T0901675415450E_20240807_100739	T0901675415450E
TA-Albany	T0901675415450E_20240807_102254	T0901675415450E
TA-Albany	T0871057909669S_20240807_223352	T0871057909669S
TA-Albany	T0901675415450E_20240808_095848	T0901675415450E
TA-Albany	T0871057909669S_20240811_224724	T0871057909669S
TA-Albany	T0901822617784E_20240812_090522	T0901822617784E
TA-Albany	T0901545016754W_20240812_103739	T0901545016754W
TA-Albany	T0870817608772N_20240812_235903	T0870817608772N
TA-Albany	T0BS0168302428E_20240813_092305	T0BS0168302428E
TA-Albany	T0901545016754W_20240813_092903	T0901545016754W
TA-Albany	T0BS0168302428E_20240813_093643	T0BS0168302428E
TA-Albany	T0870966910579N_20240813_201937	T0870966910579N
TA-Albany	T0BS0168302428E_20240814_082646	T0BS0168302428E
TA-Albany	T0901545016754W_20240814_092241	T0901545016754W
TA-Albany	T0870817608772N_20240815_001149	T0870817608772N
TA-Albany	T0901545016754W_20240815_094655	T0901545016754W
TA-Albany	T0871057909669S_20240815_210025	T0871057909669S
TA-Albany	T0871140210579S_20240816_001319	T0871140210579S
TA-Albany	T0871140210579S_20240816_072122	T0871140210579S
TA-Albany	T0BS0168302428E_20240819_090904	T0BS0168302428E
TA-Albany	T0901675415450E_20240819_102853	T0901675415450E
TA-Albany	T0871057909669S_20240819_221914	T0871057909669S
TA-Albany	T0901678416754E_20240820_090619	T0901678416754E
TA-Albany	T0BS0168302428E_20240820_091930	T0BS0168302428E
TA-Albany	T0870966910579N_20240820_193705	T0870966910579N
TA-Albany	T0871140210579S_20240821_073826	T0871140210579S
TA-Albany	T0870966910579N_20240821_201801	T0870966910579N
TA-Albany	T0BS0168302428E_20240822_075447	T0BS0168302428E
TA-Albany	T0901822617784E_20240822_083026	T0901822617784E

Region/Division	Deployment ID	Location Code
TA-Albany	T0BS0168302428E_20240822_090311	T0BS0168302428E
TA-Albany	T0870966910579N_20240823_003334	T0870966910579N
TA-Albany	T0871140210579S_20240823_072019	T0871140210579S
TA-Albany	T0870966910579N_20240826_002410	T0870966910579N
TA-Albany	T0871140210579S_20240826_094957	T0871140210579S
TA-Albany	T0BS0009400867E_20240826_102205	T0BS0009400867E
TA-Albany	T0871140210579S_20240826_231504	T0871140210579S
TA-Albany	T0BS0168302428E_20240827_075855	T0BS0168302428E
TA-Albany	T0901545016754W_20240827_101511	T0901545016754W
TA-Albany	T0871057909669S_20240827_212138	T0871057909669S
TA-Albany	T0871140210579S_20240828_071736	T0871140210579S
TA-Albany	T0901545016754W_20240828_083408	T0901545016754W
TA-Albany	T0BS0086700094W_20240828_083524	T0BS0086700094W
TA-Albany	T0871140210579S_20240829_070024	T0871140210579S
TA-Albany	T0871140210579S_20240830_065039	T0871140210579S
TA-Albany	T0871140210579S_20240903_064957	T0871140210579S
TA-Albany	T0901675415450E_20240904_094705	T0901675415450E
TA-Albany	T0870966910579N_20240904_222941	T0870966910579N
TA-Albany	T0901678417334W_20240905_081131	T0901678417334W
TA-Albany	T0871140210579S_20240906_084746	T0871140210579S
TA-Albany	T0870966910579N_20240908_233247	T0870966910579N
TA-Albany	T0901778417418E_20240909_083350	T0901778417418E
TA-Albany	T0871140210579S_20240909_085817	T0871140210579S
TA-Albany	T0871057909669S_20240909_230426	T0871057909669S
TA-Albany	T0901778417418E_20240910_080745	T0901778417418E
TA-Albany	T0871057909669S_20240911_074144	T0871057909669S
TA-Albany	T0871140210579S_20240912_071645	T0871140210579S
TA-Albany	T0BS0086700094W_20240912_075433	T0BS0086700094W
TA-Albany	T0901675415450E_20240912_080322	T0901675415450E
TA-Albany	T0871140210579S_20240913_071045	T0871140210579S
TA-Albany	T0BS0086700094W_20240913_082314	T0BS0086700094W
TA-Albany	T0901778417418E_20240913_084129	T0901778417418E
TA-Albany	T0BS0086700094W_20240916_085547	T0BS0086700094W
TA-Albany	T0901545015009E_20240916_110021	T0901545015009E
TA-Albany	T0870877208176S_20240917_000339	T0870877208176S
TA-Albany	T0871140210579S_20240917_071038	T0871140210579S
TA-Albany	T0BS0168300894W_20240917_082338	T0BS0168300894W
TA-Albany	T0871140210579S_20240917_084325	T0871140210579S
TA-Albany	T0BS0000000094E_20240917_085046	T0BS0000000094E
TA-Albany	T0901675415450E_20240918_081540	T0901675415450E
TA-Albany	T0BS0000000094E_20240918_084851	T0BS0000000094E
TA-Albany	T0870807508176N_20240918_233521	T0870807508176N
TA-Albany	T0871140210579S_20240919_072028	T0871140210579S

Region/Division	Deployment ID	Location Code
TA-Albany	T0BS000000094E_20240919_080040	T0BS000000094E
TA-Albany	T0871140210579S_20240920_071232	T0871140210579S
TA-Albany	T0901545016754W_20240923_082920	T0901545016754W
TA-Albany	T0870732408075N_20240923_090213	T0870732408075N
TA-Albany	T0BS000000094E_20240923_091225	T0BS000000094E
TA-Albany	T0871140210579S_20240923_100059	T0871140210579S
TA-Albany	T0901545016754W_20240924_091635	T0901545016754W
TA-Albany	T0BS000000094E_20240924_104533	T0BS000000094E
TA-Albany	T0901545016754W_20240925_085201	T0901545016754W
TA-Albany	T0871140210579S_20240925_085540	T0871140210579S
TA-Albany	T0BS0089401683E_20240925_085931	T0BS0089401683E
TA-Albany	T0BS000000094E_20240926_083340	T0BS000000094E
TA-Albany	T0BS000000094E_20240927_081345	T0BS000000094E
TA-Albany	T0871140210579S_20240927_081738	T0871140210579S
TA-Albany	T0BS000000094E_20240930_090556	T0BS000000094E
TA-Albany	T0901975419500E_20240930_092303	T0901975419500E
TA-Albany	T0871140210579S_20240930_101454	T0871140210579S
TA-Albany	T0BS000000094E_20241001_074554	T0BS000000094E
TA-Albany	T0901545016754W_20241001_081817	T0901545016754W
TA-Albany	T0871140210579S_20241001_085350	T0871140210579S
TA-Albany	T0BS000000094E_20241002_080117	T0BS000000094E
TA-Albany	T0870732408075N_20241002_091227	T0870732408075N
TA-Albany	T0871140210579S_20241002_092253	T0871140210579S
TA-Albany	T0901832518226E_20241002_093022	T0901832518226E
TA-Albany	T0870732408075N_20241003_084822	T0870732408075N
TA-Albany	T0901545016754W_20241003_094057	T0901545016754W
TA-Albany	T0BS000000094E_20241003_100448	T0BS000000094E
TA-Albany	T0871140210579S_20241004_090126	T0871140210579S
TA-Albany	T0BS000000094E_20241004_091403	T0BS000000094E
TA-Albany	T0871140210579S_20241007_072236	T0871140210579S
TA-Albany	T0BS000000094E_20241007_081130	T0BS000000094E
TA-Albany	T0870732408075N_20241007_085917	T0870732408075N
TA-Albany	T0901917518598E_20241007_090405	T0901917518598E
TA-Albany	T0871140210579S_20241008_072015	T0871140210579S
TA-Albany	T0BS000000094E_20241008_075058	T0BS000000094E
TA-Albany	T0870732408075N_20241008_091333	T0870732408075N
TA-Albany	T0901917518598E_20241008_094035	T0901917518598E
TA-Albany	T0871140210579S_20241009_064908	T0871140210579S
TA-Albany	T0BS000000094E_20241009_075553	T0BS000000094E
TA-Albany	T0870732408075N_20241009_090245	T0870732408075N
TA-Albany	T0871140210579S_20241010_070344	T0871140210579S
TA-Albany	T0BS000000094E_20241010_075529	T0BS000000094E
TA-Albany	T0901675415450E_20241010_085938	T0901675415450E

Region/Division	Deployment ID	Location Code
TA-Albany	T0871140210579S_20241011_070051	T0871140210579S
TA-Albany	T0BS0009400867E_20241011_082746	T0BS0009400867E
TA-Albany	T0871140210579S_20241014_065252	T0871140210579S
TA-Albany	T0BS0009400867E_20241014_081411	T0BS0009400867E
TA-Albany	T0871140210579S_20241015_070016	T0871140210579S
TA-Albany	T0901950019408E_20241015_093140	T0901950019408E
TA-Albany	T0BS0009400867E_20241015_095421	T0BS0009400867E
TA-Albany	T0871140211833N_20241016_085910	T0871140211833N
TA-Albany	T0BS0009400867E_20241017_075341	T0BS0009400867E
TA-Albany	T0901545016754W_20241017_092802	T0901545016754W
TA-Albany	T0901778417418E_20241017_104732	T0901778417418E
TA-Albany	T0871140210579S_20241018_070407	T0871140210579S
TA-Albany	T0BS0009400867E_20241018_075850	T0BS0009400867E
TA-Albany	T0871140210579S_20241019_072353	T0871140210579S
TA-Albany	T0871140210579S_20241021_073633	T0871140210579S
TA-Albany	T0BS0009400867E_20241021_091156	T0BS0009400867E
TA-Albany	T0871140210579S_20241022_064944	T0871140210579S
TA-Albany	T0BS0009400867E_20241022_083502	T0BS0009400867E
TA-Albany	T0870966910579N_20241023_074526	T0870966910579N
TA-Albany	T0871140210579S_20241023_075311	T0871140210579S
TA-Albany	T0BS0009400867E_20241023_085423	T0BS0009400867E
TA-Albany	T0BS0009400867E_20241023_122539	T0BS0009400867E
TA-Albany	T0871140210579S_20241024_070403	T0871140210579S
TA-Albany	T0BS0009400867E_20241024_105222	T0BS0009400867E
TA-Albany	T0871140210579S_20241025_071026	T0871140210579S
TA-Albany	T0BS0009400867E_20241025_085402	T0BS0009400867E
TA-Albany	T0871140210579S_20241026_074433	T0871140210579S
TA-Albany	T0BS0009400867E_20241028_080240	T0BS0009400867E
TA-Albany	T0901982619754E_20241028_104731	T0901982619754E
TA-Albany	T0BS0009400867E_20241028_131646	T0BS0009400867E
TA-Albany	T0BS0009400867E_20241029_081433	T0BS0009400867E
TA-Albany	T0871183312334N_20241029_090805	T0871183312334N
TA-Albany	T0871140210579S_20241030_081430	T0871140210579S
TA-Albany	T0BS0009400867E_20241030_082259	T0BS0009400867E
TA-Albany	T0871183312334N_20241030_093201	T0871183312334N
TA-Albany	T0871140210579S_20241031_072816	T0871140210579S
TA-Albany	T0871183312334N_20241031_084549	T0871183312334N
TA-Albany	T0BS0009400867E_20241031_090333	T0BS0009400867E
TA-Albany	T0871140210579S_20241101_071201	T0871140210579S
TA-Albany	T0BS0009400867E_20241101_091025	T0BS0009400867E
TA-Albany	T0871140210579S_20241104_073326	T0871140210579S
TA-Albany	T0901545016754W_20241104_101838	T0901545016754W
TA-Albany	T0871140210579S_20241105_073529	T0871140210579S

Region/Division	Deployment ID	Location Code
TA-Albany	T0BS0009400867E_20241105_090138	T0BS0009400867E
TA-Albany	T0871140210579S_20241105_091605	T0871140210579S
TA-Albany	T0871140210579S_20241106_074122	T0871140210579S
TA-Albany	T0BS0000000094E_20241106_080037	T0BS0000000094E
TA-Albany	T0901500914731E_20241106_110022	T0901500914731E
TA-Albany	T0871140210579S_20241107_072553	T0871140210579S
TA-Albany	T0BS0000000094E_20241107_085159	T0BS0000000094E
TA-Albany	T0BS0168302428E_20241107_092837	T0BS0168302428E
TA-Albany	T0BS0009400867E_20241108_085145	T0BS0009400867E
TA-Albany	T0BS0009400867E_20241111_081754	T0BS0009400867E
TA-Albany	T0871140210579S_20241112_071221	T0871140210579S
TA-Albany	T0BS0009400867E_20241112_084111	T0BS0009400867E
TA-Albany	T0BS0089400867W_20241112_095429	T0BS0089400867W
TA-Albany	T0871140210579S_20241113_075202	T0871140210579S
TA-Albany	T0BS0009400867E_20241113_075828	T0BS0009400867E
TA-Albany	T0901832518226E_20241113_090417	T0901832518226E
TA-Albany	T0870732408075N_20241113_111159	T0870732408075N
TA-Albany	T0871140210579S_20241114_071005	T0871140210579S
TA-Albany	T0871183312334N_20241114_081456	T0871183312334N
TA-Albany	T0BS0009400867E_20241114_090701	T0BS0009400867E
TA-Albany	T0871183312334N_20241114_095508	T0871183312334N
TA-Albany	T0871140210579S_20241115_070918	T0871140210579S
TA-Albany	T0BS0009400867E_20241115_082826	T0BS0009400867E
TA-Albany	T0871140210579S_20241118_071057	T0871140210579S
TA-Albany	T0BS0009400867E_20241118_083411	T0BS0009400867E
TA-Albany	T0901675416784W_20241118_092215	T0901675416784W
TA-Albany	T0871140210579S_20241118_114921	T0871140210579S
TA-Albany	T0871140210579S_20241119_071815	T0871140210579S
TA-Albany	T0BS0009400867E_20241119_080840	T0BS0009400867E
TA-Albany	T0871140210579S_20241120_070112	T0871140210579S
TA-Albany	T0901545016754W_20241120_093108	T0901545016754W
TA-Albany	T0871140210579S_20241121_071745	T0871140210579S
TA-Albany	T0BS0009400867E_20241122_090350	T0BS0009400867E
TA-Albany	T0871140210579S_20241125_072643	T0871140210579S
TA-Albany	T0BS0009400867E_20241125_074036	T0BS0009400867E
TA-Albany	T0870732408075N_20241125_100751	T0870732408075N
TA-Albany	T0901822617784E_20241125_103415	T0901822617784E
TA-Albany	T0871140210579S_20241126_070500	T0871140210579S
TA-Albany	T0BS0009400867E_20241126_080024	T0BS0009400867E
TA-Albany	T0871140210579S_20241127_074731	T0871140210579S
TA-Albany	T0871140210579S_20241202_070039	T0871140210579S
TA-Albany	T0BS0009400867E_20241202_084700	T0BS0009400867E
TA-Albany	T0871140210579S_20241203_074846	T0871140210579S

Region/Division	Deployment ID	Location Code
TA-Albany	T0BS0009400867E_20241203_084038	T0BS0009400867E
TA-Albany	T0871140210579S_20241204_073806	T0871140210579S
TA-Albany	T0BS0009400867E_20241204_080325	T0BS0009400867E
TA-Albany	T0870817608772N_20241204_084928	T0870817608772N
TA-Albany	T0BS0242801683W_20241206_095036	T0BS0242801683W
TA-Albany	T0BS0168302428E_20241209_082933	T0BS0168302428E
TA-Albany	T0BS0000000094E_20241210_075722	T0BS0000000094E
TA-Albany	T0871140210579S_20241210_090515	T0871140210579S
TA-Albany	T0BS0086700094W_20241212_071520	T0BS0086700094W
TA-Albany	T0BS0000000094E_20241212_080512	T0BS0000000094E
TA-Albany	T0BS0000000094E_20241213_074050	T0BS0000000094E
TA-Albany	T0BS0168302428E_20241217_091234	T0BS0168302428E
TA-Albany	T0901822618325W_20241217_102922	T0901822618325W
TA-Albany	T0901545016754W_20241217_223157	T0901545016754W
TA-Albany	T0BS0086700094W_20241218_084455	T0BS0086700094W
TA-Albany	T0901859819175W_20241218_095502	T0901859819175W
TA-Albany	T0901675415450E_20241219_210935	T0901675415450E
TA-Albany	T0901675415450E_20241220_030701	T0901675415450E
TA-Albany	T0901545016754W_20250106_091613	T0901545016754W
TA-Albany	T0901545016754W_20250107_100626	T0901545016754W
TA-Albany	T0901545016754W_20250108_091019	T0901545016754W
TA-Albany	T0BS0168300894W_20250113_082645	T0BS0168300894W
TA-Albany	T0901832518226E_20250114_095117	T0901832518226E
TA-Albany	T0BS0168300894W_20250114_095440	T0BS0168300894W
TA-Albany	T0BS0168300894W_20250115_085934	T0BS0168300894W
TA-Albany	T0901778418226W_20250115_094703	T0901778418226W
TA-Albany	T0901545016754W_20250116_095011	T0901545016754W
TA-Albany	T0BS0009400000W_20250122_084559	T0BS0009400000W
TA-Albany	T0BS0009400000W_20250123_081444	T0BS0009400000W
TA-Albany	T0901545016754W_20250123_092046	T0901545016754W
TA-Albany	T0BS0009400000W_20250124_084527	T0BS0009400000W
TA-Albany	T0BS0009400000W_20250127_095452	T0BS0009400000W
TA-Albany	T0BS0009400000W_20250128_083739	T0BS0009400000W
TA-Albany	T0BS0009400000W_20250129_082405	T0BS0009400000W
TA-Albany	T0BS0009400000W_20250130_083654	T0BS0009400000W
TA-Albany	T0BS0168300894W_20250203_090725	T0BS0168300894W
TA-Albany	T0BS0086700094W_20250203_110023	T0BS0086700094W
TA-Albany	T0BS0009400000W_20250204_082524	T0BS0009400000W
TA-Albany	T0BS0009400000W_20250204_083355	T0BS0009400000W
TA-Albany	T0901678417334W_20250204_100102	T0901678417334W
TA-Albany	T0BS0009400000W_20250205_083851	T0BS0009400000W
TA-Albany	T0901678417334W_20250205_094119	T0901678417334W
TA-Albany	T0BS0086700094W_20250211_075335	T0BS0086700094W

Region/Division	Deployment ID	Location Code
TA-Albany	T0BS0086700094W_20250212_081348	T0BS0086700094W
TA-Albany	T0BS0086700094W_20250217_095806	T0BS0086700094W
TA-Albany	T0BS0086700094W_20250217_100858	T0BS0086700094W
TA-Albany	T0BS0086700094W_20250218_081415	T0BS0086700094W
TA-Albany	T0BS0086700094W_20250219_074126	T0BS0086700094W
TA-Albany	T0BS0086700094W_20250220_074224	T0BS0086700094W
TA-Albany	T0BS0009400867E_20250220_092553	T0BS0009400867E
TA-Albany	T0BS0086700094W_20250221_082220	T0BS0086700094W
TA-Albany	T0BS0168302428E_20250224_083859	T0BS0168302428E
TA-Albany	T0BS0089401683E_20250225_093259	T0BS0089401683E
TA-Albany	T0BS0168302428E_20250226_105833	T0BS0168302428E
TA-Albany	T0BS0086700094W_20250303_085410	T0BS0086700094W
TA-Albany	T0BS0009400867E_20250303_085503	T0BS0009400867E
TA-Albany	T0901678417334W_20250303_094555	T0901678417334W
TA-Albany	T0BS0086700094W_20250304_075434	T0BS0086700094W
TA-Albany	T0901678417334W_20250304_080840	T0901678417334W
TA-Albany	T0BS0086700094W_20250306_082813	T0BS0086700094W
TA-Albany	T0BS0086700094W_20250307_082242	T0BS0086700094W
TA-Albany	T0BS0089401683E_20250310_083106	T0BS0089401683E
TA-Albany	T0BS0086700094W_20250310_085523	T0BS0086700094W
TA-Albany	T0BS0089401683E_20250311_081524	T0BS0089401683E
TA-Albany	T0BS0086700094W_20250311_083348	T0BS0086700094W
TA-Albany	T0BS0086700094W_20250312_080132	T0BS0086700094W
TA-Albany	T0901778418226W_20250312_083315	T0901778418226W
TA-Albany	T0BS0089401683E_20250312_085927	T0BS0089401683E
TA-Albany	T0BS0086700094W_20250313_075802	T0BS0086700094W
TA-Albany	T0BS0089401683E_20250313_080135	T0BS0089401683E
TA-Albany	T0901822617784E_20250313_092953	T0901822617784E
TA-Albany	T0BS0086700094W_20250314_081331	T0BS0086700094W
TA-Albany	T0BS0086700094W_20250317_090411	T0BS0086700094W
TA-Albany	T0871140210579S_20250318_081256	T0871140210579S
TA-Albany	T0BS0086700094W_20250318_081613	T0BS0086700094W
TA-Albany	T0BS0009400867E_20250318_083428	T0BS0009400867E
TA-Albany	T0901778418226W_20250318_090241	T0901778418226W
TA-Albany	T0871140210579S_20250319_075627	T0871140210579S
TA-Albany	T0BS0009400867E_20250319_085858	T0BS0009400867E
TA-Albany	T0901950019408E_20250319_090814	T0901950019408E
TA-Albany	T0871140210579S_20250320_074647	T0871140210579S
TA-Albany	T0901917518598E_20250320_085123	T0901917518598E
TA-Albany	T0BS0086700094W_20250324_083139	T0BS0086700094W
TA-Albany	T0871057911402N_20250325_080722	T0871057911402N
TA-Albany	T0BS0086700094W_20250325_082203	T0BS0086700094W
TA-Albany	T0901675415450E_20250325_111446	T0901675415450E

Region/Division	Deployment ID	Location Code
TA-Albany	T0BS0086700094W_20250326_074810	T0BS0086700094W
TA-Albany	T0871140210579S_20250326_080528	T0871140210579S
TA-Albany	T0901675415450E_20250326_093145	T0901675415450E
TA-Albany	T0BS0086700094W_20250326_130708	T0BS0086700094W
TA-Albany	T0871057911402N_20250327_080006	T0871057911402N
TA-Albany	T0BS0168300894W_20250327_083228	T0BS0168300894W
TA-Albany	T0901675415450E_20250327_085910	T0901675415450E
TA-Albany	T0BS0086700094W_20250328_081823	T0BS0086700094W
TA-Albany	T0BS0086700094W_20250331_081432	T0BS0086700094W
TA-Albany	T0901675415450E_20250401_094404	T0901675415450E
TA-Albany	T0BS0086700094W_20250402_081202	T0BS0086700094W
TA-Albany	T0901675415450E_20250402_091351	T0901675415450E
TA-Albany	T0901675415450E_20250407_091339	T0901675415450E
TA-Albany	T0870817608772N_20250407_104311	T0870817608772N
TA-Albany	T0870817608772N_20250408_085203	T0870817608772N
TA-Albany	T0870817608772N_20250408_085859	T0870817608772N
TA-Albany	T0901545016754W_20250408_091338	T0901545016754W
TA-Albany	T0BS0009400867E_20250408_094501	T0BS0009400867E
TA-Albany	T0BS0009400867E_20250408_095757	T0BS0009400867E
TA-Albany	T0BS0009400867E_20250409_082803	T0BS0009400867E
TA-Albany	T0901545015009E_20250409_094438	T0901545015009E
TA-Albany	T0901500915450W_20250410_084204	T0901500915450W
TA-Albany	T0901950019754W_20250410_092340	T0901950019754W
TA-Albany	T0BS0009400867E_20250411_084647	T0BS0009400867E
TA-Albany	T0901545015009E_20250411_091113	T0901545015009E
TA-Albany	T0BS0009400867E_20250414_081040	T0BS0009400867E
TA-Albany	T0901545015009E_20250414_090747	T0901545015009E
TA-Albany	T0871140210579S_20250414_090912	T0871140210579S
TA-Albany	T0901500915450W_20250415_095202	T0901500915450W
TA-Albany	T0870732408075N_20250415_095715	T0870732408075N
TA-Albany	T0BS0009400867E_20250415_095928	T0BS0009400867E
TA-Albany	T0901675415450E_20250415_100636	T0901675415450E
TA-Albany	T0870732408075N_20250415_125728	T0870732408075N
TA-Albany	T0901675415450E_20250416_093513	T0901675415450E
TA-Albany	T0BS0009400867E_20250417_083411	T0BS0009400867E
TA-Albany	T0901545016754W_20250417_085233	T0901545016754W
TA-Albany	T0901675415450E_20250417_092849	T0901675415450E
TA-Albany	T0901545016754W_20250418_075715	T0901545016754W
TA-Albany	T0BS0009400867E_20250418_080823	T0BS0009400867E
TA-Albany	T0870817608772N_20250421_071350	T0870817608772N
TA-Albany	T0870817608772N_20250421_072957	T0870817608772N
TA-Albany	T0BS0009400867E_20250421_080034	T0BS0009400867E
TA-Albany	T0901675415450E_20250421_091040	T0901675415450E

Region/Division	Deployment ID	Location Code
TA-Albany	T0BS0009400867E_20250422_081731	T0BS0009400867E
TA-Albany	T0901545016754W_20250422_082508	T0901545016754W
TA-Albany	T0870732408075N_20250422_103502	T0870732408075N
TA-Albany	T0BS0009400867E_20250422_131034	T0BS0009400867E
TA-Albany	T0BS0009400867E_20250422_151525	T0BS0009400867E
TA-Albany	T0BS0168302428E_20250423_083354	T0BS0168302428E
TA-Albany	T0901822617784E_20250423_091122	T0901822617784E
TA-Albany	T0901675415450E_20250423_091953	T0901675415450E
TA-Albany	T0901822617784E_20250423_093315	T0901822617784E
TA-Albany	T0901675415450E_20250423_102605	T0901675415450E
TA-Albany	T0870817608772N_20250424_082014	T0870817608772N
TA-Albany	T0BS0009400867E_20250424_082145	T0BS0009400867E
TA-Albany	T0901675415450E_20250424_093447	T0901675415450E
TA-Albany	T0901545016754W_20250425_081930	T0901545016754W
TA-Albany	T0BS0168302428E_20250428_074354	T0BS0168302428E
TA-Albany	T0870817608772N_20250428_092025	T0870817608772N
TA-Albany	T0901675415450E_20250428_124016	T0901675415450E
TA-Albany	T0BS0168302428E_20250429_075756	T0BS0168302428E
TA-Albany	T0870732408075N_20250429_080433	T0870732408075N
TA-Albany	T0901545016754W_20250429_082937	T0901545016754W
TA-Albany	T0901545016754W_20250430_082157	T0901545016754W
TA-Albany	T0870966910579N_20250430_093042	T0870966910579N
TA-Albany	T0901675415450E_20250430_094415	T0901675415450E
TA-Albany	T0901675415450E_20250430_100357	T0901675415450E
TA-Albany	T0901545016754W_20250501_085715	T0901545016754W
TA-Albany	T0901675415450E_20250501_100411	T0901675415450E
TA-Albany	T0870807508176N_20250502_071807	T0870807508176N
TA-Albany	T0901675415450E_20250502_091146	T0901675415450E
TA-Albany	T0870807508176N_20250505_071755	T0870807508176N
TA-Albany	T0870807508176N_20250505_073948	T0870807508176N
TA-Albany	T0BS0009400867E_20250505_074311	T0BS0009400867E
TA-Albany	T0901675415450E_20250505_090908	T0901675415450E
TA-Albany	T0901678416754E_20250506_091659	T0901678416754E
TA-Albany	T0901678416754E_20250506_103423	T0901678416754E
TA-Albany	T0BS0009400867E_20250507_073620	T0BS0009400867E
TA-Albany	T0901675415450E_20250507_085306	T0901675415450E
TA-Albany	T0901500915450W_20250507_101850	T0901500915450W
TA-Albany	T0870807508176N_20250508_073644	T0870807508176N
TA-Albany	T0870807508176N_20250508_074228	T0870807508176N
TA-Albany	T0BS0009400867E_20250508_075800	T0BS0009400867E
TA-Albany	T0901545016754W_20250508_082807	T0901545016754W
TA-Albany	T0870807508176N_20250509_072057	T0870807508176N
TA-Albany	T0901545016754W_20250511_214313	T0901545016754W

Region/Division	Deployment ID	Location Code
TA-Albany	T0870807508176N_20250512_071948	T0870807508176N
TA-Albany	T0BS0009400867E_20250512_080201	T0BS0009400867E
TA-Albany	T0901822618325W_20250512_083951	T0901822618325W
TA-Albany	T0870807508176N_20250512_110039	T0870807508176N
TA-Albany	T0870817608772N_20250513_065522	T0870817608772N
TA-Albany	T0BS0009400867E_20250513_080038	T0BS0009400867E
TA-Albany	T0901545016754W_20250513_085848	T0901545016754W
TA-Albany	T0BS0009400867E_20250514_074609	T0BS0009400867E
TA-Albany	T0870877208176S_20250514_075004	T0870877208176S
TA-Albany	T0870817608772N_20250515_064602	T0870817608772N
TA-Albany	T0BS0009400867E_20250515_073814	T0BS0009400867E
TA-Albany	T0901678417334W_20250515_085953	T0901678417334W
TA-Albany	T0870817608772N_20250516_072325	T0870817608772N
TA-Albany	T0901545016754W_20250516_081630	T0901545016754W
TA-Albany	T0BS0009400867E_20250516_082525	T0BS0009400867E
TA-Albany	T0BS0009400867E_20250519_082214	T0BS0009400867E
TA-Albany	T0901678417334W_20250519_083615	T0901678417334W
TA-Albany	T0901675415450E_20250519_094412	T0901675415450E
TA-Albany	T0BS0009400867E_20250520_075451	T0BS0009400867E
TA-Albany	T0901545016754W_20250520_083104	T0901545016754W
TA-Albany	T0901675415450E_20250520_085649	T0901675415450E
TA-Albany	T0BS0168302428E_20250521_081617	T0BS0168302428E
TA-Albany	T0BS0009400867E_20250521_082910	T0BS0009400867E
TA-Albany	T0901778418226W_20250521_091823	T0901778418226W
TA-Albany	T0901778418226W_20250521_094221	T0901778418226W
TA-Albany	T0BS0009400867E_20250522_081927	T0BS0009400867E
TA-Albany	T0901778418226W_20250522_082009	T0901778418226W
TA-Albany	T0BS0009400867E_20250523_072925	T0BS0009400867E
TA-Albany	T0901778418226W_20250523_082255	T0901778418226W
TA-Albany	T0901778418226W_20250523_083655	T0901778418226W
TA-Albany	T0BS0009400867E_20250527_073631	T0BS0009400867E
TA-Albany	T0901778418226W_20250527_084456	T0901778418226W
TA-Albany	T0871183312334N_20250527_084714	T0871183312334N
TA-Albany	T0901778418226W_20250527_092830	T0901778418226W
TA-Albany	T0BS0009400867E_20250528_083743	T0BS0009400867E
TA-Albany	T0901675415450E_20250528_094658	T0901675415450E
TA-Albany	T0901675415450E_20250528_095446	T0901675415450E
TA-Albany	T0BS0168302428E_20250528_102423	T0BS0168302428E
TA-Albany	T0BS0009400867E_20250529_072652	T0BS0009400867E
TA-Albany	T0870817608772N_20250529_072706	T0870817608772N
TA-Albany	T0901778418226W_20250529_081403	T0901778418226W
TA-Albany	T0870817608772N_20250530_070700	T0870817608772N
TA-Albany	T0BS0009400867E_20250530_075320	T0BS0009400867E

Region/Division	Deployment ID	Location Code
TA-Albany	T0901778418226W_20250530_080302	T0901778418226W
TA-Albany	T0901778418226W_20250530_112305	T0901778418226W
TA-Albany	T0870817608772N_20250602_075305	T0870817608772N
TA-Albany	T0BS0168302428E_20250602_083108	T0BS0168302428E
TA-Albany	T0901832518226E_20250602_093320	T0901832518226E
TA-Albany	T0BS0009400867E_20250603_080041	T0BS0009400867E
TA-Albany	T0870807508176N_20250603_080748	T0870807508176N
TA-Albany	T0901832518226E_20250603_090252	T0901832518226E
TA-Albany	T0870817608772N_20250604_071400	T0870817608772N
TA-Albany	T0BS0009400867E_20250604_081226	T0BS0009400867E
TA-Albany	T0901500915450W_20250604_103208	T0901500915450W
TA-Albany	T0BS0009400867E_20250605_070747	T0BS0009400867E
TA-Albany	T0870817608772N_20250605_074143	T0870817608772N
TA-Albany	T0901545016754W_20250605_115002	T0901545016754W
TA-Albany	T0870817608772N_20250606_071806	T0870817608772N
TA-Albany	T0BS0009400867E_20250606_073931	T0BS0009400867E
TA-Albany	T0901778418226W_20250606_074953	T0901778418226W
TA-Albany	T0870817608772N_20250609_072601	T0870817608772N
TA-Albany	T0BS0009400867E_20250609_074235	T0BS0009400867E
TA-Albany	T0901778418226W_20250609_080916	T0901778418226W
TA-Albany	T0901778418226W_20250609_084005	T0901778418226W
TA-Albany	T0BS0009400867E_20250610_062949	T0BS0009400867E
TA-Albany	T0901778418226W_20250610_081855	T0901778418226W
TA-Albany	T0870807508176N_20250610_105504	T0870807508176N
TA-Albany	T0870817608772N_20250611_074600	T0870817608772N
TA-Albany	T0BS0168302428E_20250611_082619	T0BS0168302428E
TA-Albany	T0901675415450E_20250611_090209	T0901675415450E
TA-Albany	T0BS0009400867E_20250612_065812	T0BS0009400867E
TA-Albany	T0901545016754W_20250612_091319	T0901545016754W
TA-Albany	T0901675415450E_20250612_093844	T0901675415450E
TA-Albany	T0870817608772N_20250613_065332	T0870817608772N
TA-Albany	T0BS0009400867E_20250613_071523	T0BS0009400867E
TA-Albany	T0901778418226W_20250613_080600	T0901778418226W
TA-Albany	T0870807508176N_20250616_071913	T0870807508176N
TA-Albany	T0901778418226W_20250616_073356	T0901778418226W
TA-Albany	T0BS0168302428E_20250616_081819	T0BS0168302428E
TA-Albany	T0BS0009400867E_20250617_080926	T0BS0009400867E
TA-Albany	T0901545016754W_20250617_083322	T0901545016754W
TA-Albany	T0901778418226W_20250617_090429	T0901778418226W
TA-Albany	T0BS0009400867E_20250618_070722	T0BS0009400867E
TA-Albany	T0901778418226W_20250618_075436	T0901778418226W
TA-Albany	T0901545016754W_20250618_081255	T0901545016754W
TA-Albany	T0901545016754W_20250618_081845	T0901545016754W

Region/Division	Deployment ID	Location Code
TA-Albany	T0BS0009400867E_20250619_071828	T0BS0009400867E
TA-Albany	T0870817608772N_20250619_072510	T0870817608772N
TA-Albany	T0BS0009400867E_20250619_075258	T0BS0009400867E
TA-Albany	T0901778418226W_20250619_080745	T0901778418226W
TA-Albany	T0870807508176N_20250620_065814	T0870807508176N
TA-Albany	T0BS0009400867E_20250620_072052	T0BS0009400867E
TA-Albany	T0901778418226W_20250620_074146	T0901778418226W
TA-Albany	T0901778418226W_20250623_073823	T0901778418226W
TA-Albany	T0870807508176N_20250623_075347	T0870807508176N
TA-Albany	T0901778418226W_20250623_080711	T0901778418226W
TA-Albany	T0870807508176N_20250623_081540	T0870807508176N
TA-Albany	T0BS0009400867E_20250623_091106	T0BS0009400867E
TA-Albany	T0870807508176N_20250624_072214	T0870807508176N
TA-Albany	T0BS0009400867E_20250624_073231	T0BS0009400867E
TA-Albany	T0901545016754W_20250624_084504	T0901545016754W
TA-Albany	T0870807508176N_20250625_070004	T0870807508176N
TA-Albany	T0901778418226W_20250625_071620	T0901778418226W
TA-Albany	T0BS0009400867E_20250625_073040	T0BS0009400867E
TA-Albany	T0BS0009400867E_20250626_070604	T0BS0009400867E
TA-Albany	T0870807508176N_20250626_073638	T0870807508176N
TA-Albany	T0901778418226W_20250626_074402	T0901778418226W
TA-Albany	T0BS0009400867E_20250627_071655	T0BS0009400867E
TA-Albany	T0870807508176N_20250627_074742	T0870807508176N
TA-Albany	T0901778418226W_20250627_080020	T0901778418226W
TA-Albany	T0870807508176N_20250630_071652	T0870807508176N
TA-Albany	T0BS0168302428E_20250630_080000	T0BS0168302428E
TA-Albany	T0BS0009400867E_20250701_065143	T0BS0009400867E
TA-Albany	T0BS0009400867E_20250701_074123	T0BS0009400867E
TA-Albany	T0870817608772N_20250701_080037	T0870817608772N
TA-Albany	T0901733416784E_20250701_095524	T0901733416784E
TA-Albany	T0870877208176S_20250702_064306	T0870877208176S
TA-Albany	T0BS0009400867E_20250702_072839	T0BS0009400867E
TA-Albany	T0901778418226W_20250702_081801	T0901778418226W
TA-Albany	T0BS0009400867E_20250703_071809	T0BS0009400867E
TA-Albany	T0901778418226W_20250703_074519	T0901778418226W
TA-Albany	T0BS0009400867E_20250707_065407	T0BS0009400867E
TA-Albany	T0901778418226W_20250707_075645	T0901778418226W
TA-Albany	T0BS0168302428E_20250708_083846	T0BS0168302428E
TA-Albany	T0901778418226W_20250708_090823	T0901778418226W
TA-Albany	T0BS0009400867E_20250709_070052	T0BS0009400867E
TA-Albany	T0901545016754W_20250709_090559	T0901545016754W
TA-Albany	T0BS0009400867E_20250710_064309	T0BS0009400867E
TA-Albany	T0901778418226W_20250710_074630	T0901778418226W

Region/Division	Deployment ID	Location Code
TA-Albany	T0BS0009400867E_20250711_063258	T0BS0009400867E
TA-Albany	T0901778418226W_20250711_073902	T0901778418226W
TA-Albany	T0BS0009400867E_20250714_065540	T0BS0009400867E
TA-Albany	T0870807508176N_20250714_072607	T0870807508176N
TA-Albany	T0901778418226W_20250714_090345	T0901778418226W
TA-Albany	T0870817608772N_20250715_070050	T0870817608772N
TA-Albany	T0901778418226W_20250715_073925	T0901778418226W
TA-Albany	T0BS0009400867E_20250715_081451	T0BS0009400867E
TA-Albany	T0BS0009400867E_20250716_065644	T0BS0009400867E
TA-Albany	T0870807508176N_20250716_072211	T0870807508176N
TA-Albany	T0901778418226W_20250716_075416	T0901778418226W
TA-Albany	T0BS0009400867E_20250717_064756	T0BS0009400867E
TA-Albany	T0870807508176N_20250717_071813	T0870807508176N
TA-Albany	T0901778418226W_20250717_081713	T0901778418226W
TA-Albany	T0901678417334W_20250718_020334	T0901678417334W
TA-Albany	T0901678417334W_20250718_030447	T0901678417334W
TA-Albany	T0870817608772N_20250718_070750	T0870817608772N
TA-Albany	T0901778418226W_20250718_072953	T0901778418226W
TA-Albany	T0870807508176N_20250721_073606	T0870807508176N
TA-Albany	T0901975419500E_20250721_094839	T0901975419500E
TA-Albany	T0BS0009400867E_20250722_064506	T0BS0009400867E
TA-Albany	T0870817608772N_20250722_072330	T0870817608772N
TA-Albany	T0901778418226W_20250722_074226	T0901778418226W
TA-Albany	T0901778418226W_20250722_075029	T0901778418226W
TA-Albany	T0BS0009400867E_20250722_092300	T0BS0009400867E
TA-Albany	T0870807508176N_20250723_065415	T0870807508176N
TA-Albany	T0BS0009400867E_20250723_071820	T0BS0009400867E
TA-Albany	T0901778418226W_20250723_082701	T0901778418226W
TA-Albany	T0BS0009400867E_20250724_062856	T0BS0009400867E
TA-Albany	T0870817608772N_20250724_065046	T0870817608772N
TA-Albany	T0901778418226W_20250724_074251	T0901778418226W
TA-Albany	T0870817608772N_20250724_074830	T0870817608772N
TA-Albany	T0BS0009400867E_20250725_065408	T0BS0009400867E
TA-Albany	T0870807508176N_20250725_070730	T0870807508176N
TA-Albany	T0901778418226W_20250725_075329	T0901778418226W
TA-Albany	T0901778418226W_20250725_132027	T0901778418226W
TA-Albany	T0BS0009400867E_20250728_062858	T0BS0009400867E
TA-Albany	T0870817608772N_20250728_073901	T0870817608772N
TA-Albany	T0901778418226W_20250728_095720	T0901778418226W
TA-Albany	T0870817608772N_20250729_072455	T0870817608772N
TA-Albany	T0901778418226W_20250729_073921	T0901778418226W
TA-Albany	T0BS0168300894W_20250729_081545	T0BS0168300894W
TA-Albany	T0870817608772N_20250730_065141	T0870817608772N

Region/Division	Deployment ID	Location Code
TA-Albany	T0BS0009400867E_20250730_072756	T0BS0009400867E
TA-Albany	T0901778418226W_20250730_091235	T0901778418226W
TA-Albany	T0BS0009400867E_20250731_064402	T0BS0009400867E
TA-Albany	T0870817608772N_20250731_070726	T0870817608772N
TA-Albany	T0BS0009400867E_20250801_062848	T0BS0009400867E
TA-Albany	T0870817608772N_20250801_072312	T0870817608772N
TA-Albany	T0901778418226W_20250801_073101	T0901778418226W
TA-Albany	T0870817608772N_20250801_093033	T0870817608772N
TA-Albany	T0870807508176N_20250804_080415	T0870807508176N
TA-Albany	T0BS0168302428E_20250804_084351	T0BS0168302428E
TA-Albany	T0901917518598E_20250804_093151	T0901917518598E
TA-Albany	T0870807508176N_20250805_065802	T0870807508176N
TA-Albany	T0BS0168302428E_20250805_084931	T0BS0168302428E
TA-Albany	T0901675415450E_20250805_085943	T0901675415450E
TA-Albany	T0BS0009400867E_20250806_073132	T0BS0009400867E
TA-Albany	T0BS0168300894W_20250806_083443	T0BS0168300894W
TA-Albany	T0901675415450E_20250806_092102	T0901675415450E
TA-Albany	T0BS0009400867E_20250807_063552	T0BS0009400867E
TA-Albany	T0901778418226W_20250807_082329	T0901778418226W
TA-Albany	T0901500915450W_20250807_095334	T0901500915450W
TA-Albany	T0BS0009400867E_20250808_063542	T0BS0009400867E
TA-Albany	T0901778418226W_20250808_070318	T0901778418226W
TA-Albany	T0870807508176N_20250808_072903	T0870807508176N
TA-Albany	T0BS0009400867E_20250811_062526	T0BS0009400867E
TA-Albany	T0870807508176N_20250811_073604	T0870807508176N
TA-Albany	T0901778418226W_20250811_082707	T0901778418226W
TA-Albany	T0870807508176N_20250812_070758	T0870807508176N
TA-Albany	T0BS0009400867E_20250812_082457	T0BS0009400867E
TA-Albany	T0901778417418E_20250812_083447	T0901778417418E
TA-Albany	T0870807508176N_20250813_070054	T0870807508176N
TA-Albany	T0BS0009400867E_20250813_080450	T0BS0009400867E
TA-Albany	T0901778418226W_20250813_103756	T0901778418226W
TA-Albany	T0BS0009400867E_20250814_063507	T0BS0009400867E
TA-Albany	T0870807508176N_20250814_072409	T0870807508176N
TA-Albany	T0901778417418E_20250814_084831	T0901778417418E
TA-Albany	T0870807508176N_20250815_070543	T0870807508176N
TA-Albany	T0901778418226W_20250815_071327	T0901778418226W
TA-Albany	T0BS0009400867E_20250818_065948	T0BS0009400867E
TA-Albany	T0870807508176N_20250818_074154	T0870807508176N
TA-Albany	T0901778418226W_20250818_105757	T0901778418226W
TA-Albany	T0870807508176N_20250819_070819	T0870807508176N
TA-Albany	T0901778418226W_20250819_071956	T0901778418226W
TA-Albany	T0901982619754E_20250819_091403	T0901982619754E

Region/Division	Deployment ID	Location Code
TA-Albany	T0870807508176N_20250820_065923	T0870807508176N
TA-Albany	T0BS0009400867E_20250821_064613	T0BS0009400867E
TA-Albany	T0870807508176N_20250821_070321	T0870807508176N
TA-Albany	T0901778418226W_20250821_074823	T0901778418226W
TA-Albany	T0870807508176N_20250822_070604	T0870807508176N
TA-Albany	T0BS0009400867E_20250822_070759	T0BS0009400867E
TA-Albany	T0901778418226W_20250822_083020	T0901778418226W
TA-Albany	T0901778418226W_20250822_084744	T0901778418226W
TA-Albany	T0870807508176N_20250825_070523	T0870807508176N
TA-Albany	T0901778418226W_20250825_074020	T0901778418226W
TA-Albany	T0BS0009400867E_20250825_075346	T0BS0009400867E
TA-Albany	T0870807508176N_20250826_065113	T0870807508176N
TA-Albany	T0BS0168300894W_20250826_075833	T0BS0168300894W
TA-Albany	T0901733416784E_20250826_092823	T0901733416784E
TA-Albany	T0BS0009400867E_20250827_064207	T0BS0009400867E
TA-Albany	T0870807508176N_20250827_070350	T0870807508176N
TA-Albany	T0901675415450E_20250827_092913	T0901675415450E
TA-Albany	T0BS0009400867E_20250828_063734	T0BS0009400867E
TA-Albany	T0901778418226W_20250828_082519	T0901778418226W
TA-Albany	T0901778418226W_20250829_073904	T0901778418226W
TA-Albany	T0BS0009400867E_20250902_064654	T0BS0009400867E
TA-Albany	T0871057911402N_20250902_085914	T0871057911402N
TA-Albany	T0901859819175W_20250902_091019	T0901859819175W
TA-Albany	T0870817608772N_20250903_070406	T0870817608772N
TA-Albany	T0901733416784E_20250903_084159	T0901733416784E
TA-Albany	T0870817608772N_20250903_100701	T0870817608772N
TA-Albany	T0BS0168300894W_20250903_102304	T0BS0168300894W
TA-Albany	T0871183311402S_20250904_082202	T0871183311402S
TA-Albany	T0901675415450E_20250904_083529	T0901675415450E
TA-Albany	T0BS0168300894W_20250904_085220	T0BS0168300894W
TA-Albany	T0BS0000000094E_20250905_064728	T0BS0000000094E
TA-Albany	T0870817608772N_20250905_074722	T0870817608772N
TA-Albany	T0870817608772N_20250908_072606	T0870817608772N
TA-Albany	T0901778418226W_20250908_080904	T0901778418226W
TA-Albany	T0870817608772N_20250908_082934	T0870817608772N
TA-Albany	T0BS0000000094E_20250909_063641	T0BS0000000094E
TA-Albany	T0871057911402N_20250909_082040	T0871057911402N
TA-Albany	T0BS0000000094E_20250909_094323	T0BS0000000094E
TA-Albany	T0BS0000000094E_20250909_102614	T0BS0000000094E
TA-Albany	T0901778418226W_20250910_073224	T0901778418226W
TA-Albany	T0871057911402N_20250910_084250	T0871057911402N
TA-Albany	T0901778418226W_20250911_072720	T0901778418226W
TA-Albany	T0BS0000000094E_20250912_063748	T0BS0000000094E

Region/Division	Deployment ID	Location Code
TA-Albany	T0870817608772N_20250912_072408	T0870817608772N
TA-Albany	T0901778418226W_20250912_081631	T0901778418226W
TA-Albany	T0870807508176N_20250915_070632	T0870807508176N
TA-Albany	T0BS0168300894W_20250915_082333	T0BS0168300894W
TA-Albany	T0901545016754W_20250915_091240	T0901545016754W
TA-Albany	T0BS0000000094E_20250916_074152	T0BS0000000094E
TA-Albany	T0901678416754E_20250916_090819	T0901678416754E
TA-Albany	T0871296312334S_20250916_091028	T0871296312334S
TA-Albany	T0871057909669S_20250916_210926	T0871057909669S
TA-Albany	T0BS0168300894W_20250917_083714	T0BS0168300894W
TA-Albany	T0901822617784E_20250917_085915	T0901822617784E
TA-Albany	T0871057909669S_20250917_202550	T0871057909669S
TA-Albany	T0870807508176N_20250918_080513	T0870807508176N
TA-Albany	T0901822617784E_20250918_084724	T0901822617784E
TA-Albany	T0901822617784E_20250918_091206	T0901822617784E
TA-Albany	T0BS0000000094E_20250918_101437	T0BS0000000094E
TA-Albany	T0870807508176N_20250919_070317	T0870807508176N
TA-Albany	T0BS0000000094E_20250919_080458	T0BS0000000094E
TA-Albany	T0901778418226W_20250919_081206	T0901778418226W
TA-Albany	T0BS0000000094E_20250919_100229	T0BS0000000094E
TA-Albany	T0901675415450E_20250922_083419	T0901675415450E
TA-Albany	T0871140210579S_20250922_084117	T0871140210579S
TA-Albany	T0871140210579S_20250922_085345	T0871140210579S
TA-Albany	T0BS0009400867E_20250922_091101	T0BS0009400867E
TA-Albany	T0BS0000000094E_20250923_072150	T0BS0000000094E
TA-Albany	T0871057911402N_20250923_083554	T0871057911402N
TA-Albany	T0901778418226W_20250923_090919	T0901778418226W
TA-Albany	T0BS0000000094E_20250924_065742	T0BS0000000094E
TA-Albany	T0870817608772N_20250924_070522	T0870817608772N
TA-Albany	T0901778418226W_20250924_095454	T0901778418226W
TA-Albany	T0870807508176N_20250925_070926	T0870807508176N
TA-Albany	T0901778418226W_20250925_074455	T0901778418226W
TA-Albany	T0BS0000000094E_20250926_070301	T0BS0000000094E
TA-Albany	T0901778418226W_20250926_081828	T0901778418226W
TA-Albany	T0BS0168302428E_20250929_085818	T0BS0168302428E
TA-Albany	T0901778418226W_20250929_090926	T0901778418226W
TA-Albany	T0BS0168302428E_20250930_080057	T0BS0168302428E
TA-Albany	T0901778418226W_20250930_094415	T0901778418226W
TA-Albany	T0901778418226W_20251001_073906	T0901778418226W
TA-Albany	T0BS0168302428E_20251001_075816	T0BS0168302428E
TA-Albany	T0901778418226W_20251002_080651	T0901778418226W
TA-Albany	T0BS0168302428E_20251002_084934	T0BS0168302428E
TA-Albany	T0901778418226W_20251002_103813	T0901778418226W

Region/Division	Deployment ID	Location Code
TA-Albany	T0BS0009400867E_20251003_072948	T0BS0009400867E
TA-Albany	T0901778418226W_20251003_073747	T0901778418226W
TA-Albany	T0870817608772N_20251006_072820	T0870817608772N
TA-Albany	T0870817608772N_20251006_074147	T0870817608772N
TA-Albany	T0BS0168302428E_20251006_081341	T0BS0168302428E
TA-Albany	T0901741817784W_20251006_093439	T0901741817784W
TA-Albany	T0870817608772N_20251007_065607	T0870817608772N
TA-Albany	T0BS0168302428E_20251007_065804	T0BS0168302428E
TA-Albany	T0901778418226W_20251007_091701	T0901778418226W
TA-Albany	T0870817608772N_20251008_070542	T0870817608772N
TA-Albany	T0BS0168302428E_20251008_072237	T0BS0168302428E
TA-Albany	T0870817608772N_20251008_085355	T0870817608772N
TA-Albany	T0870817608772N_20251008_090448	T0870817608772N
TA-Albany	T0870817608772N_20251008_091206	T0870817608772N
TA-Albany	T0870817608772N_20251009_065401	T0870817608772N
TA-Albany	T0BS0168302428E_20251009_070440	T0BS0168302428E
TA-Albany	T0901733416784E_20251009_083233	T0901733416784E
TA-Albany	T0BS0009400867E_20251010_071140	T0BS0009400867E
TA-Albany	T0870817608772N_20251010_072920	T0870817608772N
TA-Albany	T0901778418226W_20251010_081315	T0901778418226W
TA-Albany	T0870817608772N_20251013_070830	T0870817608772N
TA-Albany	T0901778418226W_20251013_080440	T0901778418226W
TA-Albany	T0870817608772N_20251014_072554	T0870817608772N
TA-Albany	T0870817608772N_20251014_073944	T0870817608772N
TA-Albany	T0BS0168302428E_20251014_081847	T0BS0168302428E
TA-Albany	T0901822618325W_20251014_102336	T0901822618325W
TA-Albany	T0BS0168302428E_20251015_064810	T0BS0168302428E
TA-Albany	T0901822618325W_20251015_073527	T0901822618325W
TA-Albany	T0870817608772N_20251015_074828	T0870817608772N
TA-Albany	T0901822618325W_20251016_070221	T0901822618325W
TA-Albany	T0870817608772N_20251016_072133	T0870817608772N
TA-Albany	T0901822618325W_20251016_075552	T0901822618325W
TA-Albany	T0BS0168302428E_20251016_080245	T0BS0168302428E
TA-Albany	T0870817608772N_20251016_102225	T0870817608772N
TA-Albany	T0BS0000000094E_20251017_063151	T0BS0000000094E
TA-Albany	T0870817608772N_20251017_070830	T0870817608772N
TA-Albany	T0901778418226W_20251017_073114	T0901778418226W
TA-Albany	T0901778418226W_20251017_105719	T0901778418226W
TA-Albany	T0901778418226W_20251020_080311	T0901778418226W
TA-Albany	T0870807508176N_20251020_082235	T0870807508176N
TA-Albany	T0BS0168302428E_20251020_085748	T0BS0168302428E
TA-Albany	T0BS0168302428E_20251021_070904	T0BS0168302428E
TA-Albany	T0901778418226W_20251021_074401	T0901778418226W

Region/Division	Deployment ID	Location Code
TA-Albany	T0870807508176N_20251021_075341	T0870807508176N
TA-Albany	T0901778418226W_20251022_073446	T0901778418226W
TA-Albany	T0870807508176N_20251022_075224	T0870807508176N
TA-Albany	T0BS0168302428E_20251022_075249	T0BS0168302428E
TA-Albany	T0BS0168302428E_20251023_070013	T0BS0168302428E
TA-Albany	T0901778418226W_20251023_073044	T0901778418226W
TA-Albany	T0870807508176N_20251023_074246	T0870807508176N
TA-Albany	T0BS0168302428E_20251023_075752	T0BS0168302428E
TA-Albany	T0901778418226W_20251024_072639	T0901778418226W
TA-Albany	T0870807508176N_20251024_083717	T0870807508176N
TA-Albany	T0870817608772N_20251024_105549	T0870817608772N
TA-Albany	T0901778418226W_20251027_081355	T0901778418226W
TA-Albany	T0BS0168302428E_20251027_083309	T0BS0168302428E
TA-Albany	T0871341413098S_20251027_101422	T0871341413098S
TA-Albany	T0BS0168302428E_20251028_072949	T0BS0168302428E
TA-Albany	T0901778418226W_20251028_080902	T0901778418226W
TA-Albany	T0871233412963N_20251028_093832	T0871233412963N
TA-Albany	T0870807508176N_20251029_073836	T0870807508176N
TA-Albany	T0901778418226W_20251029_080556	T0901778418226W
TA-Albany	T0BS000000094E_20251029_115845	T0BS000000094E
TA-Albany	T0BS000000094E_20251031_062748	T0BS000000094E
TA-Albany	T0901778418226W_20251031_082646	T0901778418226W
TA-Albany	T0870807508176N_20251103_070004	T0870807508176N
TA-Albany	T0901778418226W_20251103_073120	T0901778418226W
TA-Albany	T0BS0168302428E_20251103_082756	T0BS0168302428E
TA-Albany	T0BS000000094E_20251104_062858	T0BS000000094E
TA-Albany	T0901778418226W_20251104_072010	T0901778418226W
TA-Albany	T0870807508176N_20251105_072825	T0870807508176N
TA-Albany	T0901778418226W_20251105_075020	T0901778418226W
TA-Albany	T0BS0168302428E_20251105_083230	T0BS0168302428E
TA-Albany	T0870807508176N_20251106_064342	T0870807508176N
TA-Albany	T0901778418226W_20251106_082803	T0901778418226W
TA-Albany	T0BS0242801683W_20251106_090934	T0BS0242801683W
TA-Albany	T0BS000000094E_20251107_070123	T0BS000000094E
TA-Albany	T0901778418226W_20251107_082610	T0901778418226W
TA-Albany	T0870807508176N_20251110_072346	T0870807508176N
TA-Albany	T0901778418226W_20251110_081016	T0901778418226W
TA-Albany	T0901778418226W_20251110_131019	T0901778418226W
TA-Albany	T0870817608772N_20251111_070036	T0870817608772N
TA-Albany	T0901778418226W_20251111_073905	T0901778418226W
TA-Albany	T0901778418226W_20251111_075329	T0901778418226W
TA-Albany	T0870817608772N_20251112_072533	T0870817608772N
TA-Albany	T0901778418226W_20251112_080928	T0901778418226W

Region/Division	Deployment ID	Location Code
TA-Albany	T0901778418226W_20251113_071538	T0901778418226W
TA-Albany	T0BS0242801683W_20251113_085221	T0BS0242801683W
TA-Albany	T0BS0242801683W_20251113_090510	T0BS0242801683W
TA-Albany	T0901778418226W_20251114_074425	T0901778418226W
TA-Albany	T0901778418226W_20251114_081001	T0901778418226W
TA-Albany	T0870817608772N_20251117_072653	T0870817608772N
TA-Albany	T0901778418226W_20251117_080726	T0901778418226W
TA-Albany	T0BS0009400867E_20251117_085546	T0BS0009400867E
TA-Albany	T0870817608772N_20251118_064849	T0870817608772N
TA-Albany	T0BS0242801683W_20251118_091219	T0BS0242801683W
TA-Albany	T0901778418226W_20251118_091536	T0901778418226W
TA-Albany	T0870817608772N_20251118_104642	T0870817608772N
TA-Albany	T0901778418226W_20251119_070623	T0901778418226W
TA-Albany	T0870817608772N_20251119_080319	T0870817608772N
TA-Albany	T0871296312334S_20251119_085232	T0871296312334S
TA-Albany	T0901778418226W_20251120_081622	T0901778418226W
TA-Albany	T0871296312334S_20251120_082138	T0871296312334S
TA-Albany	T0871296312334S_20251120_083116	T0871296312334S
TA-Albany	T0901778418226W_20251121_065916	T0901778418226W
TA-Albany	T0BS0168302428E_20251124_090435	T0BS0168302428E
TA-Albany	T0BS0086700094W_20251124_093810	T0BS0086700094W
TA-Albany	T0BS0168302428E_20251125_075616	T0BS0168302428E
TA-Albany	T0901500915450W_20251125_090110	T0901500915450W
TA-Albany	T0BS0009400867E_20251201_094922	T0BS0009400867E
TA-Albany	T0BS0009400867E_20251203_092833	T0BS0009400867E
TA-Albany	T0BS0009400867E_20251203_140619	T0BS0009400867E
TA-Albany	T0BS0009400867E_20251204_081518	T0BS0009400867E
TA-Albany	T0BS0009400867E_20251204_093613	T0BS0009400867E
TA-Albany	T0BS0009400867E_20251205_081111	T0BS0009400867E
TA-Albany	T0BS0009400867E_20251205_092631	T0BS0009400867E
TA-Albany	T0BS0009400867E_20251208_093800	T0BS0009400867E
TA-Albany	T0BS0000000094E_20251208_123305	T0BS0000000094E
TA-Albany	T0BS0000000094E_20251208_124025	T0BS0000000094E
TA-Albany	T0BS0009400867E_20251209_082950	T0BS0009400867E
TA-Albany	T0BS0009400867E_20251210_083327	T0BS0009400867E
TA-Albany	T0BS0009400867E_20251211_082241	T0BS0009400867E
TA-Albany	T0BS0009400867E_20251212_094045	T0BS0009400867E
TA-Albany	T0BS0009400867E_20251212_133622	T0BS0009400867E
TA-Albany	T0901917518598E_20251216_081204	T0901917518598E
TA-Albany	T0BS0009400867E_20251216_083441	T0BS0009400867E
TA-Albany	T0BS0009400867E_20251217_075318	T0BS0009400867E
TA-Albany	T0901733416784E_20251217_093844	T0901733416784E
TA-Albany	T0BS0009400867E_20251217_121209	T0BS0009400867E

Region/Division	Deployment ID	Location Code
TA-Albany	T0BS0009400867E_20251218_081811	T0BS0009400867E
TA-Albany	T0BS0009400867E_20251218_111903	T0BS0009400867E
TA-Albany	T0BS0009400867E_20251222_082158	T0BS0009400867E
TA-Buffalo	T0904817347457E_20240325_101451	T0904817347457E
TA-Buffalo	T0904817347457E_20240326_084112	T0904817347457E
TA-Buffalo	T0904817347457E_20240327_104024	T0904817347457E
TA-Buffalo	T0904817347457E_20240328_082940	T0904817347457E
TA-Buffalo	T0904817347457E_20240422_105007	T0904817347457E
TA-Buffalo	T0904817347457E_20240422_111120	T0904817347457E
TA-Buffalo	T0904817347457E_20240423_090534	T0904817347457E
TA-Buffalo	T0904817347457E_20240424_085725	T0904817347457E
TA-Buffalo	T0904107841161W_20240511_063825	T0904107841161W
TA-Buffalo	T1900147302075N_20240610_235555	T1900147302075N
TA-Buffalo	T1900147302075N_20240611_213850	T1900147302075N
TA-Buffalo	T1900147302075N_20240612_220438	T1900147302075N
TA-Buffalo	T1900207501473S_20240613_225855	T1900207501473S
TA-Buffalo	T1900207501473S_20240614_234926	T1900207501473S
TA-Buffalo	T0904204042643W_20240721_071826	T0904204042643W
TA-Buffalo	T1900108000062S_20240726_235253	T1900108000062S
TA-Buffalo	T0904204042643W_20240820_001433	T0904204042643W
TA-Buffalo	T1900108000062S_20240820_011902	T1900108000062S
TA-Buffalo	T0904204042643W_20240820_235326	T0904204042643W
TA-Buffalo	T0904204042643W_20240822_000119	T0904204042643W
TA-Buffalo	T0904204042643W_20240822_233056	T0904204042643W
TA-Buffalo	T1900006201080N_20240823_005914	T1900006201080N
TA-Buffalo	T0904204042643W_20240823_233455	T0904204042643W
TA-Buffalo	T0904204042643W_20240903_225004	T0904204042643W
TA-Buffalo	T0904204042643W_20240904_225005	T0904204042643W
TA-Buffalo	T0904204042643W_20240905_233612	T0904204042643W
TA-Buffalo	T0903874438213E_20240912_224742	T0903874438213E
TA-Buffalo	T0903962538744E_20240927_041250	T0903962538744E
TA-Buffalo	T0904264343064W_20241011_234602	T0904264343064W
TA-Buffalo	T1900108000062S_20241022_102542	T1900108000062S
TA-Buffalo	T1900108000062S_20241023_104346	T1900108000062S
TA-Buffalo	T1900108000062S_20241023_110955	T1900108000062S
TA-Buffalo	T1900108000062S_20241025_014750	T1900108000062S
TA-Buffalo	T1900108000062S_20241025_015833	T1900108000062S
TA-Buffalo	T1900108000062S_20241025_102905	T1900108000062S
TA-Buffalo	T0904264342040E_20241026_234542	T0904264342040E
TA-Buffalo	T0904671546020E_20241030_093210	T0904671546020E
TA-Buffalo	T0904745747061E_20241031_093642	T0904745747061E
TA-Buffalo	T0904745747061E_20241101_081918	T0904745747061E
TA-Buffalo	T0904432444950W_20241121_081538	T0904432444950W

Region/Division	Deployment ID	Location Code
TA-Buffalo	T0903874438213E_20250304_083636	T0903874438213E
TA-Buffalo	T0903557435342E_20250304_101016	T0903557435342E
TA-Buffalo	T0903874438213E_20250311_091555	T0903874438213E
TA-Buffalo	T0903874438213E_20250311_235054	T0903874438213E
TA-Buffalo	T0903587836627W_20250312_093559	T0903587836627W
TA-Buffalo	T0903473135342W_20250409_204555	T0903473135342W
TA-Buffalo	T0903473135342W_20250410_003455	T0903473135342W
TA-Buffalo	T0904183541694E_20250417_083041	T0904183541694E
TA-Buffalo	T0904183541694E_20250417_092809	T0904183541694E
TA-Buffalo	T0904183541694E_20250421_092039	T0904183541694E
TA-Buffalo	T0904417943162E_20250421_215755	T0904417943162E
TA-Buffalo	T0904417943162E_20250422_195521	T0904417943162E
TA-Buffalo	T0904417943162E_20250423_193036	T0904417943162E
TA-Buffalo	T0904316244179W_20250424_202657	T0904316244179W
TA-Buffalo	T0904745747061E_20250425_084641	T0904745747061E
TA-Buffalo	T0904745747061E_20250425_091306	T0904745747061E
TA-Buffalo	T1900108000062S_20250428_005502	T1900108000062S
TA-Buffalo	T1900108000062S_20250428_010832	T1900108000062S
TA-Buffalo	T0903962540465W_20250428_050430	T0903962540465W
TA-Buffalo	T0904316244179W_20250428_202927	T0904316244179W
TA-Buffalo	T1900108000062S_20250429_024835	T1900108000062S
TA-Buffalo	T0904046539625E_20250430_042825	T0904046539625E
TA-Buffalo	T0904316244179W_20250430_202424	T0904316244179W
TA-Buffalo	T1900108000062S_20250501_022115	T1900108000062S
TA-Buffalo	T0903962538744E_20250501_042806	T0903962538744E
TA-Buffalo	T0904183541694E_20250501_082029	T0904183541694E
TA-Buffalo	T0904183541694E_20250502_090902	T0904183541694E
TA-Buffalo	T0904817348894W_20250505_084512	T0904817348894W
TA-Buffalo	T0904183541694E_20250505_091129	T0904183541694E
TA-Buffalo	T0903473135342W_20250505_093501	T0903473135342W
TA-Buffalo	T0904817348894W_20250506_080949	T0904817348894W
TA-Buffalo	T0904183541694E_20250506_082549	T0904183541694E
TA-Buffalo	T0904817348894W_20250507_080635	T0904817348894W
TA-Buffalo	T0904543946020W_20250507_082940	T0904543946020W
TA-Buffalo	T1900108000062S_20250508_010329	T1900108000062S
TA-Buffalo	T0904817348894W_20250508_073034	T0904817348894W
TA-Buffalo	T0903534235574W_20250508_202104	T0903534235574W
TA-Buffalo	T1900108000062S_20250509_011921	T1900108000062S
TA-Buffalo	T0904745747061E_20250509_075914	T0904745747061E
TA-Buffalo	T1900108000062S_20250512_011032	T1900108000062S
TA-Buffalo	T0903874438213E_20250512_035316	T0903874438213E
TA-Buffalo	T0904817348894W_20250512_090745	T0904817348894W
TA-Buffalo	T1900108000062S_20250513_005635	T1900108000062S

Region/Division	Deployment ID	Location Code
TA-Buffalo	T0903962540465W_20250513_035822	T0903962540465W
TA-Buffalo	T0904817348894W_20250513_081943	T0904817348894W
TA-Buffalo	T0904817348894W_20250514_083449	T0904817348894W
TA-Buffalo	T0904417943162E_20250514_204057	T0904417943162E
TA-Buffalo	T1900108000062S_20250515_004547	T1900108000062S
TA-Buffalo	T0904817348894W_20250515_080114	T0904817348894W
TA-Buffalo	T0903534235574W_20250519_201750	T0903534235574W
TA-Buffalo	T1900006201080N_20250520_002521	T1900006201080N
TA-Buffalo	T0904817348894W_20250520_084511	T0904817348894W
TA-Buffalo	T0904543946020W_20250520_090257	T0904543946020W
TA-Buffalo	T0903557435342E_20250520_203010	T0903557435342E
TA-Buffalo	T0904817348894W_20250521_075517	T0904817348894W
TA-Buffalo	T0904817348894W_20250522_071533	T0904817348894W
TA-Buffalo	T0903534235574W_20250526_234733	T0903534235574W
TA-Buffalo	T0904889449600W_20250527_083402	T0904889449600W
TA-Buffalo	T0903534235574W_20250527_202959	T0903534235574W
TA-Buffalo	T0904889449600W_20250528_080305	T0904889449600W
TA-Buffalo	T0903534235574W_20250528_210552	T0903534235574W
TA-Buffalo	T0904889449600W_20250529_072845	T0904889449600W
TA-Buffalo	T0903534235574W_20250529_202955	T0903534235574W
TA-Buffalo	T0904817347457E_20250530_090631	T0904817347457E
TA-Buffalo	T1900006201080N_20250602_014409	T1900006201080N
TA-Buffalo	T0904046541078W_20250602_090034	T0904046541078W
TA-Buffalo	T0903557435342E_20250602_203218	T0903557435342E
TA-Buffalo	T0903962538744E_20250602_221423	T0903962538744E
TA-Buffalo	T1900006201080N_20250603_003928	T1900006201080N
TA-Buffalo	T0904046541078W_20250603_080822	T0904046541078W
TA-Buffalo	T0903874438213E_20250603_215235	T0903874438213E
TA-Buffalo	T1900006201080N_20250604_005709	T1900006201080N
TA-Buffalo	T1900108001473N_20250604_111834	T1900108001473N
TA-Buffalo	T0903534235574W_20250604_205228	T0903534235574W
TA-Buffalo	T0903874438213E_20250604_215854	T0903874438213E
TA-Buffalo	T0903874438213E_20250605_032315	T0903874438213E
TA-Buffalo	T0904046541078W_20250605_084457	T0904046541078W
TA-Buffalo	T0903821338744W_20250605_224731	T0903821338744W
TA-Buffalo	T0903534235574W_20250605_235644	T0903534235574W
TA-Buffalo	T1900147302075N_20250607_005651	T1900147302075N
TA-Buffalo	T1900147302075N_20250608_012902	T1900147302075N
TA-Buffalo	T0904543946020W_20250609_092601	T0904543946020W
TA-Buffalo	T0904543946020W_20250610_083827	T0904543946020W
TA-Buffalo	T0903587836627W_20250610_211311	T0903587836627W
TA-Buffalo	T0903821338744W_20250610_220435	T0903821338744W
TA-Buffalo	T0904543946020W_20250611_080107	T0904543946020W

Region/Division	Deployment ID	Location Code
TA-Buffalo	T0903874439625W_20250611_220214	T0903874439625W
TA-Buffalo	T1900006201080N_20250612_012711	T1900006201080N
TA-Buffalo	T0904602046715W_20250612_062642	T0904602046715W
TA-Buffalo	T0904046541078W_20250612_224853	T0904046541078W
TA-Buffalo	T1900006201080N_20250613_003954	T1900006201080N
TA-Buffalo	T1900006201080N_20250616_011141	T1900006201080N
TA-Buffalo	T0903473135342W_20250616_100137	T0903473135342W
TA-Buffalo	T0904204041885E_20250617_004526	T0904204041885E
TA-Buffalo	T1900006201080N_20250617_010946	T1900006201080N
TA-Buffalo	T0903706437551W_20250617_081920	T0903706437551W
TA-Buffalo	T0904204041885E_20250617_234940	T0904204041885E
TA-Buffalo	T0904602045439E_20250618_081326	T0904602045439E
TA-Buffalo	T0904204041885E_20250619_234551	T0904204041885E
TA-Buffalo	T1900006201080N_20250623_005648	T1900006201080N
TA-Buffalo	T0904745747061E_20250623_095434	T0904745747061E
TA-Buffalo	T0904745747061E_20250624_073016	T0904745747061E
TA-Buffalo	T0903534235574W_20250624_091408	T0903534235574W
TA-Buffalo	T0904183541694E_20250625_002244	T0904183541694E
TA-Buffalo	T1900006201080N_20250625_004612	T1900006201080N
TA-Buffalo	T1900006201080N_20250630_010310	T1900006201080N
TA-Buffalo	T1900006201080N_20250702_010942	T1900006201080N
TA-Buffalo	T0904745747061E_20250707_080722	T0904745747061E
TA-Buffalo	T1900006201080N_20250708_004615	T1900006201080N
TA-Buffalo	T0904745747061E_20250708_082219	T0904745747061E
TA-Buffalo	T1900006201080N_20250709_020354	T1900006201080N
TA-Buffalo	T0904745747061E_20250709_075749	T0904745747061E
TA-Buffalo	T0904745747061E_20250710_072007	T0904745747061E
TA-Buffalo	T0903587836627W_20250714_083740	T0903587836627W
TA-Buffalo	T0903706436627E_20250715_091505	T0903706436627E
TA-Buffalo	T0904602045439E_20250718_082826	T0904602045439E
TA-Buffalo	T1900006201080N_20250721_020227	T1900006201080N
TA-Buffalo	T1900006201080N_20250722_005852	T1900006201080N
TA-Buffalo	T1900147302075N_20250723_013220	T1900147302075N
TA-Buffalo	T0903473135342W_20250723_111318	T0903473135342W
TA-Buffalo	T1900108001473N_20250725_010944	T1900108001473N
TA-Buffalo	T0903534235574W_20250728_204736	T0903534235574W
TA-Buffalo	T0903557435342E_20250729_202217	T0903557435342E
TA-Buffalo	T0903821338744W_20250730_035945	T0903821338744W
TA-Buffalo	T0903755137064E_20250730_090527	T0903755137064E
TA-Buffalo	T0903534235574W_20250730_200643	T0903534235574W
TA-Buffalo	T0903755137064E_20250731_095206	T0903755137064E
TA-Buffalo	T0903557435342E_20250731_202213	T0903557435342E
TA-Buffalo	T0903534235574W_20250801_014221	T0903534235574W

Region/Division	Deployment ID	Location Code
TA-Buffalo	T1900212102075S_20250803_013107	T1900212102075S
TA-Buffalo	T0903473135342W_20250805_075947	T0903473135342W
TA-Buffalo	T0903755137064E_20250805_091537	T0903755137064E
TA-Buffalo	T0903473135342W_20250806_072100	T0903473135342W
TA-Buffalo	T0903755137064E_20250806_092508	T0903755137064E
TA-Buffalo	T0903473135342W_20250807_072523	T0903473135342W
TA-Buffalo	T0903473135342W_20250808_080629	T0903473135342W
TA-Buffalo	T0903473135342W_20250811_080505	T0903473135342W
TA-Buffalo	T0904417943162E_20250811_224117	T0904417943162E
TA-Buffalo	T0903473135342W_20250812_075100	T0903473135342W
TA-Buffalo	T0903706436627E_20250812_090905	T0903706436627E
TA-Buffalo	T0903473135342W_20250813_073405	T0903473135342W
TA-Buffalo	T0903662737064W_20250813_094947	T0903662737064W
TA-Buffalo	T0903587836627W_20250813_192543	T0903587836627W
TA-Buffalo	T0903587836627W_20250813_193647	T0903587836627W
TA-Buffalo	T0903473135342W_20250814_073845	T0903473135342W
TA-Buffalo	T0903473135342W_20250815_073556	T0903473135342W
TA-Buffalo	T0904602046715W_20250816_065717	T0904602046715W
TA-Buffalo	T0904671546020E_20250816_071507	T0904671546020E
TA-Buffalo	T0903473135342W_20250819_081344	T0903473135342W
TA-Buffalo	T0903706437551W_20250819_085216	T0903706437551W
TA-Buffalo	T0904543946020W_20250819_092125	T0904543946020W
TA-Buffalo	T0904543946020W_20250819_104344	T0904543946020W
TA-Buffalo	T0903473135342W_20250820_074715	T0903473135342W
TA-Buffalo	T0903473135342W_20250820_074748	T0903473135342W
TA-Buffalo	T0903473135342W_20250821_080953	T0903473135342W
TA-Buffalo	T0903473135342W_20250822_074523	T0903473135342W
TA-Buffalo	T0903473135342W_20250825_073348	T0903473135342W
TA-Buffalo	T0904602045439E_20250825_081502	T0904602045439E
TA-Buffalo	T0903473135342W_20250825_085433	T0903473135342W
TA-Buffalo	T0903473135342W_20250826_075508	T0903473135342W
TA-Buffalo	T0904602045439E_20250826_080104	T0904602045439E
TA-Buffalo	T0904960048894E_20250826_082925	T0904960048894E
TA-Buffalo	T0903706437551W_20250826_091205	T0903706437551W
TA-Buffalo	T0904602045439E_20250827_075413	T0904602045439E
TA-Buffalo	T0903473135342W_20250827_081026	T0903473135342W
TA-Buffalo	T0904960048894E_20250827_082819	T0904960048894E
TA-Buffalo	T0903706437551W_20250827_093730	T0903706437551W
TA-Buffalo	T0903473135342W_20250828_071355	T0903473135342W
TA-Buffalo	T0903473135342W_20250829_083017	T0903473135342W
TA-Buffalo	T0903473135342W_20250829_084052	T0903473135342W
TA-Buffalo	T0904817348894W_20250902_085922	T0904817348894W
TA-Buffalo	T0904817348894W_20250902_091923	T0904817348894W

Region/Division	Deployment ID	Location Code
TA-Buffalo	T0903473135342W_20250902_092806	T0903473135342W
TA-Buffalo	T0903473135342W_20250903_081027	T0903473135342W
TA-Buffalo	T0903755137064E_20250903_090549	T0903755137064E
TA-Buffalo	T0903473135342W_20250903_230723	T0903473135342W
TA-Buffalo	T0903473135342W_20250904_084212	T0903473135342W
TA-Buffalo	T0903473135342W_20250905_073355	T0903473135342W
TA-Buffalo	T0903473135342W_20250908_071843	T0903473135342W
TA-Buffalo	T0903473135342W_20250908_233831	T0903473135342W
TA-Buffalo	T0903755138213W_20250909_005920	T0903755138213W
TA-Buffalo	T0903473135342W_20250909_071146	T0903473135342W
TA-Buffalo	T0903473135342W_20250910_000151	T0903473135342W
TA-Buffalo	T0903473135342W_20250910_071002	T0903473135342W
TA-Buffalo	T0903473135342W_20250911_072140	T0903473135342W
TA-Buffalo	T0904817348894W_20250911_083936	T0904817348894W
TA-Buffalo	T0903473135342W_20250912_071545	T0903473135342W
TA-Buffalo	T0903473135342W_20250915_080618	T0903473135342W
TA-Buffalo	T0904706146715E_20250915_091549	T0904706146715E
TA-Buffalo	T0903473135342W_20250916_071543	T0903473135342W
TA-Buffalo	T0903706436627E_20250917_051333	T0903706436627E
TA-Buffalo	T0903473135342W_20250917_073359	T0903473135342W
TA-Buffalo	T0903662735878E_20250917_194819	T0903662735878E
TA-Buffalo	T0903473135342W_20250918_073635	T0903473135342W
TA-Buffalo	T0904960048894E_20250918_075541	T0904960048894E
TA-Buffalo	T0903587836627W_20250919_051540	T0903587836627W
TA-Buffalo	T0903473135342W_20250919_073539	T0903473135342W
TA-Buffalo	T0903473135342W_20250919_074947	T0903473135342W
TA-Buffalo	T0903473135342W_20250922_084527	T0903473135342W
TA-Buffalo	T0903473135342W_20250923_080014	T0903473135342W
TA-Buffalo	T0903473135342W_20250923_142912	T0903473135342W
TA-Buffalo	T0903473135342W_20250924_075356	T0903473135342W
TA-Buffalo	T0903755137064E_20250924_085928	T0903755137064E
TA-Buffalo	T0903473135342W_20250925_080002	T0903473135342W
TA-Buffalo	T0903706436627E_20250926_062414	T0903706436627E
TA-Buffalo	T0903473135342W_20250926_075017	T0903473135342W
TA-Buffalo	T0903473135342W_20250929_085658	T0903473135342W
TA-Buffalo	T0903473135342W_20250930_075405	T0903473135342W
TA-Buffalo	T0903473135342W_20251001_081104	T0903473135342W
TA-Buffalo	T0903473135342W_20251002_074439	T0903473135342W
TA-Buffalo	T0903473135342W_20251003_090410	T0903473135342W
TA-Buffalo	T0903473135342W_20251006_073617	T0903473135342W
TA-Buffalo	T0903473135342W_20251007_082100	T0903473135342W
TA-Buffalo	T0903473135342W_20251008_081510	T0903473135342W
TA-Buffalo	T0903473135342W_20251008_091410	T0903473135342W

Region/Division	Deployment ID	Location Code
TA-Buffalo	T0903473135342W_20251009_083639	T0903473135342W
TA-Buffalo	T0903473135342W_20251009_095744	T0903473135342W
TA-Buffalo	T0903534235574W_20251010_070830	T0903534235574W
TA-Buffalo	T0903473135342W_20251013_074810	T0903473135342W
TA-Buffalo	T0903473135342W_20251014_080545	T0903473135342W
TA-Buffalo	T0903473135342W_20251015_075935	T0903473135342W
TA-Buffalo	T0903587836627W_20251016_061906	T0903587836627W
TA-Buffalo	T0903473135342W_20251016_082412	T0903473135342W
TA-Buffalo	T0903473135342W_20251017_082121	T0903473135342W
TA-Buffalo	T0903473135342W_20251020_095813	T0903473135342W
TA-Buffalo	T1900147301080S_20251021_010624	T1900147301080S
TA-Buffalo	T0903473135342W_20251021_074106	T0903473135342W
TA-Buffalo	T0903473135342W_20251022_080717	T0903473135342W
TA-Buffalo	T0904602046715W_20251023_084643	T0904602046715W
TA-Buffalo	T0904602046715W_20251024_085102	T0904602046715W
TA-Buffalo	T0903662737064W_20251027_090429	T0903662737064W
TA-Buffalo	T0903874438213E_20251028_040031	T0903874438213E
TA-Buffalo	T0903755138213W_20251028_092647	T0903755138213W
TA-Buffalo	T0903473135342W_20251029_080442	T0903473135342W
TA-Buffalo	T0903706436627E_20251029_092427	T0903706436627E
TA-Buffalo	T0903473135342W_20251031_090901	T0903473135342W
TA-Buffalo	T0903962540465W_20251031_131011	T0903962540465W
TA-Buffalo	T0903473135342W_20251105_233645	T0903473135342W
TA-Buffalo	T0903473135342W_20251112_231307	T0903473135342W
TA-Buffalo	T0903473135342W_20251113_231701	T0903473135342W
TA-Buffalo	T0903587836627W_20251114_080948	T0903587836627W
TA-Buffalo	T0903473135342W_20251118_002424	T0903473135342W
TA-Buffalo	T0904306442643E_20251118_102101	T0904306442643E
TA-Buffalo	T0904417943162E_20251119_150244	T0904417943162E
TA-Buffalo	T0904046539625E_20251119_230116	T0904046539625E
TA-Buffalo	T0904543946020W_20251222_020840	T0904543946020W
TA-New York	T0870074500595S_20240207_115422	T0870074500595S
TA-New York	T0870059500000S_20240410_030750	T0870059500000S
TA-New York	T0870172801631S_20240411_012206	T0870172801631S
TA-New York	T0870352704325N_20240417_022511	T0870352704325N
TA-New York	T0870132701468N_20240429_111356	T0870132701468N
TA-New York	T0870352704325N_20240502_231810	T0870352704325N
TA-New York	T0870132701468N_20240506_103857	T0870132701468N
TA-New York	T0870132701468N_20240507_115525	T0870132701468N
TA-New York	T0870246202341S_20240508_003730	T0870246202341S
TA-New York	T0870132701468N_20240508_113013	T0870132701468N
TA-New York	T0870132701468N_20240509_112008	T0870132701468N
TA-New York	T0870246202861N_20240513_222346	T0870246202861N

Region/Division	Deployment ID	Location Code
TA-New York	T0870432505112N_20240514_005328	T0870432505112N
TA-New York	T0870432505112N_20240517_005447	T0870432505112N
TA-New York	T0950042800717N_20240518_000814	T0950042800717N
TA-New York	T0870000000595N_20240520_101038	T0870000000595N
TA-New York	T0870286102462S_20240520_222512	T0870286102462S
TA-New York	T0870432505112N_20240520_235430	T0870432505112N
TA-New York	T0870432505112N_20240522_001147	T0870432505112N
TA-New York	T0870286102462S_20240522_003234	T0870286102462S
TA-New York	T0870246202861N_20240523_003055	T0870246202861N
TA-New York	T0870432505112N_20240523_005210	T0870432505112N
TA-New York	T0870132701468N_20240528_112321	T0870132701468N
TA-New York	T0950042800717N_20240529_001307	T0950042800717N
TA-New York	T0870176802341N_20240529_001731	T0870176802341N
TA-New York	T0870000000595N_20240529_094059	T0870000000595N
TA-New York	T0870146801616N_20240530_111803	T0870146801616N
TA-New York	T0870176802341N_20240530_233045	T0870176802341N
TA-New York	T0870146801616N_20240531_112709	T0870146801616N
TA-New York	T0950042800717N_20240601_102625	T0950042800717N
TA-New York	T0870246202861N_20240604_024031	T0870246202861N
TA-New York	T0870246202861N_20240605_004101	T0870246202861N
TA-New York	T0870234101768S_20240605_013114	T0870234101768S
TA-New York	T0870234101768S_20240605_020230	T0870234101768S
TA-New York	T0870132701468N_20240605_121904	T0870132701468N
TA-New York	T0870132701468N_20240606_115808	T0870132701468N
TA-New York	T0870146801327S_20240607_112430	T0870146801327S
TA-New York	T0870303402861S_20240608_011259	T0870303402861S
TA-New York	T0870286102462S_20240611_004738	T0870286102462S
TA-New York	T0870432503527S_20240611_110939	T0870432503527S
TA-New York	T0870664607255N_20240618_102904	T0870664607255N
TA-New York	T0870664607255N_20240619_104757	T0870664607255N
TA-New York	T0950078000868N_20240621_013102	T0950078000868N
TA-New York	T0870350103302S_20240626_125805	T0870350103302S
TA-New York	T0870246202341S_20240628_011434	T0870246202341S
TA-New York	T0870234102462N_20240701_094750	T0870234102462N
TA-New York	T0950042800717N_20240702_004010	T0950042800717N
TA-New York	T0870234102462N_20240702_095314	T0870234102462N
TA-New York	T0870432503527S_20240702_125743	T0870432503527S
TA-New York	T0950071700428S_20240710_021954	T0950071700428S
TA-New York	T0870146801327S_20240716_115258	T0870146801327S
TA-New York	T0870511205580N_20240729_212347	T0870511205580N
TA-New York	T0950071700428S_20240729_235734	T0950071700428S
TA-New York	T0870314403302N_20240730_102257	T0870314403302N
TA-New York	T0870330203144S_20240730_134408	T0870330203144S

Region/Division	Deployment ID	Location Code
TA-New York	T0950071700428S_20240731_000058	T0950071700428S
TA-New York	T0870314403302N_20240731_101819	T0870314403302N
TA-New York	T0870350103302S_20240731_131420	T0870350103302S
TA-New York	T0870432505112N_20240731_215556	T0870432505112N
TA-New York	T0870511204325S_20240801_231414	T0870511204325S
TA-New York	T0870592305580S_20240802_233935	T0870592305580S
TA-New York	T0870511204325S_20240805_221305	T0870511204325S
TA-New York	T0870350103302S_20240806_115535	T0870350103302S
TA-New York	T0870511204325S_20240807_204125	T0870511204325S
TA-New York	T0870234101768S_20240808_004056	T0870234101768S
TA-New York	T0870511204325S_20240812_230230	T0870511204325S
TA-New York	T0870059500745N_20240812_232426	T0870059500745N
TA-New York	T0870511204325S_20240813_220221	T0870511204325S
TA-New York	T0870059500745N_20240813_222559	T0870059500745N
TA-New York	T0870511204325S_20240814_222552	T0870511204325S
TA-New York	T0870074500595S_20240814_224530	T0870074500595S
TA-New York	T0870074500595S_20240815_214450	T0870074500595S
TA-New York	T0870558005112S_20240815_232611	T0870558005112S
TA-New York	T0870592305580S_20240816_220220	T0870592305580S
TA-New York	T0870558005112S_20240819_233144	T0870558005112S
TA-New York	T0950042800717N_20240820_010634	T0950042800717N
TA-New York	T0870350103302S_20240820_110541	T0870350103302S
TA-New York	T0870511204325S_20240820_224604	T0870511204325S
TA-New York	T0950042800717N_20240821_001628	T0950042800717N
TA-New York	T0870511204325S_20240821_222659	T0870511204325S
TA-New York	T0950042800717N_20240822_001104	T0950042800717N
TA-New York	T0950042800717N_20240822_030023	T0950042800717N
TA-New York	T0870511204325S_20240822_221224	T0870511204325S
TA-New York	T0950042800717N_20240822_235929	T0950042800717N
TA-New York	T0950120701035S_20240823_022613	T0950120701035S
TA-New York	T0870511204325S_20240823_222018	T0870511204325S
TA-New York	T0950042800717N_20240824_014251	T0950042800717N
TA-New York	T0950042800717N_20240824_082042	T0950042800717N
TA-New York	T0870314403302N_20240826_103706	T0870314403302N
TA-New York	T0870511204325S_20240826_233943	T0870511204325S
TA-New York	T0950042800717N_20240827_001414	T0950042800717N
TA-New York	T0870330203144S_20240827_104552	T0870330203144S
TA-New York	T0870511204325S_20240827_224619	T0870511204325S
TA-New York	T0950042800717N_20240828_005903	T0950042800717N
TA-New York	T0870511204325S_20240828_221917	T0870511204325S
TA-New York	T0950042800717N_20240829_001603	T0950042800717N
TA-New York	T0870511205580N_20240830_011720	T0870511205580N
TA-New York	T0870119001327N_20240903_231350	T0870119001327N

Region/Division	Deployment ID	Location Code
TA-New York	T0870511204325S_20240903_232534	T0870511204325S
TA-New York	T0870119001327N_20240904_221907	T0870119001327N
TA-New York	T0870558005112S_20240904_233822	T0870558005112S
TA-New York	T0870558005112S_20240905_230154	T0870558005112S
TA-New York	T0950086800780S_20240907_014739	T0950086800780S
TA-New York	T0870558005112S_20240909_211630	T0870558005112S
TA-New York	T0950086800780S_20240910_003834	T0950086800780S
TA-New York	T0870807507324S_20240910_074356	T0870807507324S
TA-New York	T0870558005112S_20240910_212436	T0870558005112S
TA-New York	T0950086800780S_20240910_235627	T0950086800780S
TA-New York	T0870432505112N_20240911_215924	T0870432505112N
TA-New York	T0950086800780S_20240912_002127	T0950086800780S
TA-New York	T0870432505112N_20240913_004523	T0870432505112N
TA-New York	T0950071700428S_20240913_013629	T0950071700428S
TA-New York	T0870432505112N_20240913_235207	T0870432505112N
TA-New York	T0870132701468N_20240916_122227	T0870132701468N
TA-New York	T0950074000717S_20240917_001146	T0950074000717S
TA-New York	T0870432503527S_20240917_110529	T0870432503527S
TA-New York	T0950074000717S_20240917_234642	T0950074000717S
TA-New York	T0950035300428N_20240919_005353	T0950035300428N
TA-New York	T0950042800717N_20240920_005052	T0950042800717N
TA-New York	T0950035300428N_20240921_010604	T0950035300428N
TA-New York	T0950086801035N_20240922_005055	T0950086801035N
TA-New York	T0870511204325S_20240923_230559	T0870511204325S
TA-New York	T0950042800717N_20240923_234454	T0950042800717N
TA-New York	T0870592305580S_20240924_214020	T0870592305580S
TA-New York	T0950042800717N_20240925_002812	T0950042800717N
TA-New York	T0950035300000S_20240925_005647	T0950035300000S
TA-New York	T0870432505112N_20240925_211533	T0870432505112N
TA-New York	T0950042800717N_20240926_000532	T0950042800717N
TA-New York	T0870432505112N_20240926_220015	T0870432505112N
TA-New York	T0870432505112N_20240927_234921	T0870432505112N
TA-New York	T0950042800717N_20240928_002927	T0950042800717N
TA-New York	T0870432505112N_20240928_030519	T0870432505112N
TA-New York	T0870432505112N_20240930_204353	T0870432505112N
TA-New York	T0950042800717N_20241001_004429	T0950042800717N
TA-New York	T0950042800717N_20241001_010949	T0950042800717N
TA-New York	T0950042800717N_20241001_025621	T0950042800717N
TA-New York	T0950042800717N_20241002_002107	T0950042800717N
TA-New York	T0950042800717N_20241002_025007	T0950042800717N
TA-New York	T0870432505112N_20241002_215422	T0870432505112N
TA-New York	T0950035300428N_20241003_002133	T0950035300428N
TA-New York	T0870558005923N_20241003_215607	T0870558005923N

Region/Division	Deployment ID	Location Code
TA-New York	T0950035300428N_20241003_235402	T0950035300428N
TA-New York	T0870558005112S_20241004_230449	T0870558005112S
TA-New York	T0950035300428N_20241005_001037	T0950035300428N
TA-New York	T0870558005112S_20241005_030603	T0870558005112S
TA-New York	T0870059500000S_20241005_103253	T0870059500000S
TA-New York	T0870592306646N_20241007_204614	T0870592306646N
TA-New York	T0950078000868N_20241008_002608	T0950078000868N
TA-New York	T0950103501207N_20241008_232736	T0950103501207N
TA-New York	T0870511205580N_20241009_233511	T0870511205580N
TA-New York	T0950120701035S_20241009_234853	T0950120701035S
TA-New York	T0870558005112S_20241010_223335	T0870558005112S
TA-New York	T0950120701035S_20241011_005936	T0950120701035S
TA-New York	T0870059500000S_20241012_094546	T0870059500000S
TA-New York	T0950144201207S_20241015_232538	T0950144201207S
TA-New York	T0870592306646N_20241016_101814	T0870592306646N
TA-New York	T0870592306646N_20241016_125922	T0870592306646N
TA-New York	T0870286103034N_20241017_102829	T0870286103034N
TA-New York	T0870725506646S_20241017_110140	T0870725506646S
TA-New York	T0870286103034N_20241017_111558	T0870286103034N
TA-New York	T0870286103034N_20241017_112333	T0870286103034N
TA-New York	T0870432503527S_20241018_114234	T0870432503527S
TA-New York	T0950150101442S_20241019_010630	T0950150101442S
TA-New York	T0950103501207N_20241021_112939	T0950103501207N
TA-New York	T2870057300955E_20241021_231317	T2870057300955E
TA-New York	T0950144201207S_20241022_000839	T0950144201207S
TA-New York	T2870057300955E_20241022_030906	T2870057300955E
TA-New York	T0870059500000S_20241022_112032	T0870059500000S
TA-New York	T2870057300955E_20241022_223403	T2870057300955E
TA-New York	T0950144201207S_20241023_020325	T0950144201207S
TA-New York	T0870664607255N_20241023_100355	T0870664607255N
TA-New York	T0870059500000S_20241023_110423	T0870059500000S
TA-New York	T0870664607255N_20241023_115940	T0870664607255N
TA-New York	T0950103501207N_20241024_110059	T0950103501207N
TA-New York	T2870095500573W_20241025_011013	T2870095500573W
TA-New York	T0950103501207N_20241025_104813	T0950103501207N
TA-New York	T2870095500573W_20241025_232743	T2870095500573W
TA-New York	T0870059500000S_20241030_111656	T0870059500000S
TA-New York	T0950103501207N_20241031_105941	T0950103501207N
TA-New York	T0870807507324S_20241104_102504	T0870807507324S
TA-New York	T0950074000717S_20241105_003330	T0950074000717S
TA-New York	T0870807507324S_20241105_083736	T0870807507324S
TA-New York	T0950074000717S_20241106_000142	T0950074000717S
TA-New York	T0950074000717S_20241107_023206	T0950074000717S

Region/Division	Deployment ID	Location Code
TA-New York	T0870807507324S_20241107_090554	T0870807507324S
TA-New York	T0950074000717S_20241108_004033	T0950074000717S
TA-New York	T0870807507324S_20241112_094033	T0870807507324S
TA-New York	T0870352704325N_20241112_103340	T0870352704325N
TA-New York	T0870807507324S_20241113_092302	T0870807507324S
TA-New York	T2870057300955E_20241114_002836	T2870057300955E
TA-New York	T2870057300955E_20241114_233550	T2870057300955E
TA-New York	T2870057300955E_20241115_233811	T2870057300955E
TA-New York	T0950086801035N_20241116_013135	T0950086801035N
TA-New York	T0870352704325N_20241119_105921	T0870352704325N
TA-New York	T0870352704325N_20241120_103119	T0870352704325N
TA-New York	T0950086801035N_20241127_012007	T0950086801035N
TA-New York	T2870057300955E_20241202_233925	T2870057300955E
TA-New York	T0950071700428S_20241203_002157	T0950071700428S
TA-New York	T0870286102462S_20241203_114410	T0870286102462S
TA-New York	T2870057300955E_20241203_225652	T2870057300955E
TA-New York	T0950086801035N_20241204_005728	T0950086801035N
TA-New York	T0870330203501N_20241204_104047	T0870330203501N
TA-New York	T0870330203501N_20241204_110548	T0870330203501N
TA-New York	T2870057300955E_20241204_220027	T2870057300955E
TA-New York	T2870057300955E_20241205_222342	T2870057300955E
TA-New York	T0950042800717N_20241205_233009	T0950042800717N
TA-New York	T2870057300955E_20241206_221830	T2870057300955E
TA-New York	T0950071700428S_20241207_005137	T0950071700428S
TA-New York	T2870095500573W_20241209_223608	T2870095500573W
TA-New York	T0870330203501N_20241210_103238	T0870330203501N
TA-New York	T2870095500573W_20241213_224433	T2870095500573W
TA-New York	T0870807507324S_20241217_090317	T0870807507324S
TA-New York	T2870095500573W_20241217_220303	T2870095500573W
TA-New York	T0870059500745N_20241218_102949	T0870059500745N
TA-New York	T0870807507324S_20241219_093013	T0870807507324S
TA-New York	T2870095500573W_20241219_223230	T2870095500573W
TA-New York	T0870172801631S_20241220_014959	T0870172801631S
TA-New York	T0870807507324S_20241220_091617	T0870807507324S
TA-New York	T2870095500573W_20241226_235211	T2870095500573W
TA-New York	T2870095500573W_20241227_223601	T2870095500573W
TA-New York	T0950120701035S_20250113_010507	T0950120701035S
TA-New York	T2870057300345W_20250113_122606	T2870057300345W
TA-New York	T0950120701035S_20250114_005452	T0950120701035S
TA-New York	T0950120701035S_20250114_224933	T0950120701035S
TA-New York	T0870234101768S_20250115_001113	T0870234101768S
TA-New York	T0870432503527S_20250115_104914	T0870432503527S
TA-New York	T0950120701035S_20250115_225135	T0950120701035S

Region/Division	Deployment ID	Location Code
TA-New York	T0950103500868S_20250117_021343	T0950103500868S
TA-New York	T0870176802341N_20250122_101756	T0870176802341N
TA-New York	T0870234101768S_20250122_113016	T0870234101768S
TA-New York	T0870176802341N_20250123_095313	T0870176802341N
TA-New York	T0870234101768S_20250123_100539	T0870234101768S
TA-New York	T0870234101768S_20250124_095911	T0870234101768S
TA-New York	T0870176802341N_20250124_101219	T0870176802341N
TA-New York	T0870176802341N_20250127_095950	T0870176802341N
TA-New York	T0870176802341N_20250128_094610	T0870176802341N
TA-New York	T0870176802341N_20250129_091737	T0870176802341N
TA-New York	T0870234102462N_20250129_234151	T0870234102462N
TA-New York	T0870176802341N_20250130_101353	T0870176802341N
TA-New York	T0870176802341N_20250203_110933	T0870176802341N
TA-New York	T0950103501207N_20250203_233345	T0950103501207N
TA-New York	T0870176802341N_20250204_104555	T0870176802341N
TA-New York	T0950103501207N_20250204_224311	T0950103501207N
TA-New York	T0870176802341N_20250205_111231	T0870176802341N
TA-New York	T0950103501207N_20250205_230427	T0950103501207N
TA-New York	T0950103501207N_20250206_232406	T0950103501207N
TA-New York	T0870176802341N_20250210_105447	T0870176802341N
TA-New York	T0870176802341N_20250211_095257	T0870176802341N
TA-New York	T0870303402861S_20250225_135208	T0870303402861S
TA-New York	T0870330203144S_20250304_015315	T0870330203144S
TA-New York	T0870146801327S_20250304_102858	T0870146801327S
TA-New York	T0870176802341N_20250307_011851	T0870176802341N
TA-New York	T0870146801616N_20250310_113501	T0870146801616N
TA-New York	T0950042800717N_20250311_112031	T0950042800717N
TA-New York	T0950042800717N_20250311_113639	T0950042800717N
TA-New York	T0870161601468S_20250311_113851	T0870161601468S
TA-New York	T0950042800717N_20250311_115732	T0950042800717N
TA-New York	T0870432503527S_20250313_104702	T0870432503527S
TA-New York	T0870432503527S_20250314_102057	T0870432503527S
TA-New York	T0870432505112N_20250315_013642	T0870432505112N
TA-New York	T0870286103034N_20250318_101550	T0870286103034N
TA-New York	T0870234101768S_20250324_223226	T0870234101768S
TA-New York	T0870176802341N_20250325_232517	T0870176802341N
TA-New York	T0870176802341N_20250326_233613	T0870176802341N
TA-New York	T0870234101768S_20250327_231657	T0870234101768S
TA-New York	T0870234101768S_20250327_234149	T0870234101768S
TA-New York	T0950042800717N_20250328_115947	T0950042800717N
TA-New York	T0870286103034N_20250331_122343	T0870286103034N
TA-New York	T0950042800717N_20250401_005550	T0950042800717N
TA-New York	T0950071700428S_20250402_002249	T0950071700428S

Region/Division	Deployment ID	Location Code
TA-New York	T0950042800717N_20250402_111727	T0950042800717N
TA-New York	T0950042800717N_20250403_001611	T0950042800717N
TA-New York	T0870234101768S_20250408_002049	T0870234101768S
TA-New York	T0870511204325S_20250408_215055	T0870511204325S
TA-New York	T0870234101768S_20250409_010244	T0870234101768S
TA-New York	T0870511204325S_20250409_204028	T0870511204325S
TA-New York	T0870234101768S_20250410_001520	T0870234101768S
TA-New York	T0870807507324S_20250416_094911	T0870807507324S
TA-New York	T0950086800780S_20250422_223514	T0950086800780S
TA-New York	T0950086800780S_20250422_224020	T0950086800780S
TA-New York	T0870432503527S_20250423_010714	T0870432503527S
TA-New York	T0950086801035N_20250423_120328	T0950086801035N
TA-New York	T0950086800780S_20250423_212909	T0950086800780S
TA-New York	T0870000000595N_20250424_104540	T0870000000595N
TA-New York	T0950078000740S_20250425_024527	T0950078000740S
TA-New York	T0950078000740S_20250425_225126	T0950078000740S
TA-New York	T0950078000740S_20250428_211601	T0950078000740S
TA-New York	T0950078000740S_20250429_214555	T0950078000740S
TA-New York	T0950078000740S_20250429_221630	T0950078000740S
TA-New York	T0870511205580N_20250430_095740	T0870511205580N
TA-New York	T0950078000740S_20250430_224928	T0950078000740S
TA-New York	T0950078000740S_20250501_000126	T0950078000740S
TA-New York	T0870558005112S_20250501_102717	T0870558005112S
TA-New York	T0950071700428S_20250501_224558	T0950071700428S
TA-New York	T0950071700428S_20250502_225359	T0950071700428S
TA-New York	T0950071700428S_20250503_002012	T0950071700428S
TA-New York	T0950071700428S_20250503_014137	T0950071700428S
TA-New York	T0870132701468N_20250505_104003	T0870132701468N
TA-New York	T0870132701468N_20250505_111606	T0870132701468N
TA-New York	T0950042800353S_20250507_002657	T0950042800353S
TA-New York	T0950042800353S_20250507_022040	T0950042800353S
TA-New York	T0950071700428S_20250507_234252	T0950071700428S
TA-New York	T0870146801327S_20250508_104811	T0870146801327S
TA-New York	T0950071700428S_20250516_004033	T0950071700428S
TA-New York	T0950071700428S_20250516_030040	T0950071700428S
TA-New York	T0950071700428S_20250516_231637	T0950071700428S
TA-New York	T0870132701468N_20250519_110305	T0870132701468N
TA-New York	T0950071700428S_20250520_003601	T0950071700428S
TA-New York	T0870146801327S_20250520_102302	T0870146801327S
TA-New York	T0870000000595N_20250520_103705	T0870000000595N
TA-New York	T0950042800717N_20250521_001457	T0950042800717N
TA-New York	T0950042800717N_20250521_002451	T0950042800717N
TA-New York	T0950042800717N_20250521_002537	T0950042800717N

Region/Division	Deployment ID	Location Code
TA-New York	T0870146801327S_20250527_124539	T0870146801327S
TA-New York	T2870095501006E_20250528_000829	T2870095501006E
TA-New York	T0870146801327S_20250528_103420	T0870146801327S
TA-New York	T2870100600955W_20250529_222919	T2870100600955W
TA-New York	T0870059500000S_20250530_100515	T0870059500000S
TA-New York	T0870161601468S_20250530_125053	T0870161601468S
TA-New York	T2870095500573W_20250601_233729	T2870095500573W
TA-New York	T0870161601468S_20250602_113112	T0870161601468S
TA-New York	T2870095500573W_20250602_231509	T2870095500573W
TA-New York	T0870132701468N_20250603_112633	T0870132701468N
TA-New York	T2870095500573W_20250603_232355	T2870095500573W
TA-New York	T0870161601468S_20250604_112834	T0870161601468S
TA-New York	T2870057300345W_20250605_002117	T2870057300345W
TA-New York	T0870132701468N_20250605_113156	T0870132701468N
TA-New York	T2870034500573E_20250606_004112	T2870034500573E
TA-New York	T0870146801327S_20250606_110807	T0870146801327S
TA-New York	T0870146801327S_20250609_123549	T0870146801327S
TA-New York	T0870059500745N_20250611_092033	T0870059500745N
TA-New York	T0870074500595S_20250611_121751	T0870074500595S
TA-New York	T0870432505112N_20250612_015727	T0870432505112N
TA-New York	T0870059500745N_20250612_093054	T0870059500745N
TA-New York	T0870161601468S_20250612_105058	T0870161601468S
TA-New York	T0870074500595S_20250612_123422	T0870074500595S
TA-New York	T0870161601468S_20250617_110219	T0870161601468S
TA-New York	T0870161601468S_20250617_112921	T0870161601468S
TA-New York	T0870161601468S_20250617_113948	T0870161601468S
TA-New York	T0870161601468S_20250618_111811	T0870161601468S
TA-New York	T0870234101768S_20250620_004326	T0870234101768S
TA-New York	T0870234101768S_20250624_005805	T0870234101768S
TA-New York	T2870057300955E_20250625_000256	T2870057300955E
TA-New York	T0870234101768S_20250625_020031	T0870234101768S
TA-New York	T0870146801327S_20250625_111319	T0870146801327S
TA-New York	T0870161601468S_20250626_105946	T0870161601468S
TA-New York	T2870057300955E_20250626_232140	T2870057300955E
TA-New York	T0870246202341S_20250630_005331	T0870246202341S
TA-New York	T0870146801327S_20250630_111421	T0870146801327S
TA-New York	T0870234101768S_20250701_005244	T0870234101768S
TA-New York	T0870246202341S_20250707_103352	T0870246202341S
TA-New York	T0870161601468S_20250707_112918	T0870161601468S
TA-New York	T0870161601468S_20250707_114245	T0870161601468S
TA-New York	T0870246202341S_20250708_092616	T0870246202341S
TA-New York	T0870246202341S_20250708_093034	T0870246202341S
TA-New York	T0870146801327S_20250708_104736	T0870146801327S

Region/Division	Deployment ID	Location Code
TA-New York	T0870246202341S_20250709_080635	T0870246202341S
TA-New York	T0870146801327S_20250709_110901	T0870146801327S
TA-New York	T0870146801327S_20250710_114056	T0870146801327S
TA-New York	T0870146801327S_20250711_110729	T0870146801327S
TA-New York	T0870172801631S_20250712_011030	T0870172801631S
TA-New York	T0870246202341S_20250714_080809	T0870246202341S
TA-New York	T0870246202341S_20250715_075844	T0870246202341S
TA-New York	T0870246202341S_20250716_082108	T0870246202341S
TA-New York	T0870246202341S_20250717_090108	T0870246202341S
TA-New York	T0870432505112N_20250718_014451	T0870432505112N
TA-New York	T0870132701468N_20250722_120214	T0870132701468N
TA-New York	T0870432505112N_20250723_011543	T0870432505112N
TA-New York	T0870146801327S_20250723_113952	T0870146801327S
TA-New York	T0870161601468S_20250725_113717	T0870161601468S
TA-New York	T0870246202861N_20250728_104600	T0870246202861N
TA-New York	T0870161601468S_20250728_123338	T0870161601468S
TA-New York	T0870161601468S_20250729_112251	T0870161601468S
TA-New York	T0950042800717N_20250805_234949	T0950042800717N
TA-New York	T2870108601034W_20250807_224004	T2870108601034W
TA-New York	T0950042800717N_20250808_004917	T0950042800717N
TA-New York	T0950042800717N_20250809_011407	T0950042800717N
TA-New York	T0870000000595N_20250811_104944	T0870000000595N
TA-New York	T0870234102462N_20250812_005420	T0870234102462N
TA-New York	T0870432505112N_20250812_223922	T0870432505112N
TA-New York	T0870234102462N_20250813_005104	T0870234102462N
TA-New York	T0870059500000S_20250813_102716	T0870059500000S
TA-New York	T0870246202341S_20250814_001010	T0870246202341S
TA-New York	T0870432505112N_20250814_220118	T0870432505112N
TA-New York	T0870246202341S_20250815_012516	T0870246202341S
TA-New York	T2870095500573W_20250818_005509	T2870095500573W
TA-New York	T2870057300955E_20250818_005636	T2870057300955E
TA-New York	T2870057300955E_20250818_034058	T2870057300955E
TA-New York	T2870057300955E_20250818_233850	T2870057300955E
TA-New York	T2870057300955E_20250818_235255	T2870057300955E
TA-New York	T2870095500573W_20250819_011002	T2870095500573W
TA-New York	T2870034500573E_20250819_023004	T2870034500573E
TA-New York	T0870432505112N_20250819_070507	T0870432505112N
TA-New York	T2870095500573W_20250819_232208	T2870095500573W
TA-New York	T2870095500573W_20250821_225057	T2870095500573W
TA-New York	T0870246202861N_20250822_100546	T0870246202861N
TA-New York	T2870095500573W_20250825_001712	T2870095500573W
TA-New York	T2870057300955E_20250825_015023	T2870057300955E
TA-New York	T2870095500573W_20250825_235415	T2870095500573W

Region/Division	Deployment ID	Location Code
TA-New York	T2870034500573E_20250826_011220	T2870034500573E
TA-New York	T2870095500573W_20250827_004348	T2870095500573W
TA-New York	T2870034500573E_20250827_231814	T2870034500573E
TA-New York	T2870095500573W_20250828_005314	T2870095500573W
TA-New York	T2870034500573E_20250829_010403	T2870034500573E
TA-New York	T0870592306646N_20250902_075355	T0870592306646N
TA-New York	T0870592306646N_20250902_082242	T0870592306646N
TA-New York	T2870095500573W_20250902_234317	T2870095500573W
TA-New York	T0870592306646N_20250903_092634	T0870592306646N
TA-New York	T2870095500573W_20250903_221342	T2870095500573W
TA-New York	T0870330203144S_20250904_104532	T0870330203144S
TA-New York	T0870592306646N_20250905_074156	T0870592306646N
TA-New York	T2870095500573W_20250907_224034	T2870095500573W
TA-New York	T0870172801631S_20250909_004645	T0870172801631S
TA-New York	T2870095500573W_20250909_013208	T2870095500573W
TA-New York	T2870095500573W_20250909_224239	T2870095500573W
TA-New York	T2870095500573W_20250910_224019	T2870095500573W
TA-New York	T0870330203501N_20250911_070552	T0870330203501N
TA-New York	T2870095500573W_20250911_230937	T2870095500573W
TA-New York	T0870330203501N_20250912_071052	T0870330203501N
TA-New York	T2870095500573W_20250914_234621	T2870095500573W
TA-New York	T0870592306646N_20250915_075617	T0870592306646N
TA-New York	T2870057300955E_20250915_225743	T2870057300955E
TA-New York	T0870592306646N_20250915_225939	T0870592306646N
TA-New York	T0870592306646N_20250916_070310	T0870592306646N
TA-New York	T0870592305580S_20250916_223208	T0870592305580S
TA-New York	T2870057300955E_20250916_224056	T2870057300955E
TA-New York	T0870592306646N_20250917_083112	T0870592306646N
TA-New York	T2870057300955E_20250917_224343	T2870057300955E
TA-New York	T0870592306646N_20250918_070723	T0870592306646N
TA-New York	T2870057300955E_20250918_232023	T2870057300955E
TA-New York	T0870592306646N_20250919_080415	T0870592306646N
TA-New York	T2870057300955E_20250921_225441	T2870057300955E
TA-New York	T2870108601034W_20250922_232451	T2870108601034W
TA-New York	T0870234101768S_20250923_002332	T0870234101768S
TA-New York	T2870095500573W_20250923_223931	T2870095500573W
TA-New York	T0870592306646N_20250926_072958	T0870592306646N
TA-New York	T2870095500573W_20250928_230134	T2870095500573W
TA-New York	T2870095500573W_20250929_230222	T2870095500573W
TA-New York	T2870095500573W_20250930_224456	T2870095500573W
TA-New York	T0870592306646N_20251001_080644	T0870592306646N
TA-New York	T0870592306646N_20251001_081154	T0870592306646N
TA-New York	T2870095500573W_20251001_222705	T2870095500573W

Region/Division	Deployment ID	Location Code
TA-New York	T0870592306646N_20251002_075255	T0870592306646N
TA-New York	T2870095500573W_20251002_221800	T2870095500573W
TA-New York	T0870592306646N_20251003_081458	T0870592306646N
TA-New York	T0870286102462S_20251004_081609	T0870286102462S
TA-New York	T2870057300955E_20251005_231959	T2870057300955E
TA-New York	T0870592306646N_20251006_074421	T0870592306646N
TA-New York	T2870108601034W_20251006_233922	T2870108601034W
TA-New York	T0870664605923S_20251007_095351	T0870664605923S
TA-New York	T0870592306646N_20251008_083610	T0870592306646N
TA-New York	T2870108601034W_20251008_235637	T2870108601034W
TA-New York	T0870592306646N_20251009_073610	T0870592306646N
TA-New York	T2870057300955E_20251009_234958	T2870057300955E
TA-New York	T0870286102462S_20251011_081520	T0870286102462S
TA-New York	T2870100600955W_20251013_232536	T2870100600955W
TA-New York	T2870095500573W_20251014_220532	T2870095500573W
TA-New York	T2870095500573W_20251015_224335	T2870095500573W
TA-New York	T2870095500573W_20251016_221147	T2870095500573W
TA-New York	T0870352704325N_20251017_021719	T0870352704325N
TA-New York	T2870108601034W_20251020_232926	T2870108601034W
TA-New York	T0870432503527S_20251021_103156	T0870432503527S
TA-New York	T2870108601034W_20251021_223242	T2870108601034W
TA-New York	T2870108601034W_20251022_222401	T2870108601034W
TA-New York	T2870108601034W_20251023_230253	T2870108601034W
TA-New York	T2870095500573W_20251024_220943	T2870095500573W
TA-New York	T0870286102462S_20251025_081618	T0870286102462S
TA-New York	T2870095500573W_20251026_224144	T2870095500573W
TA-New York	T0870234101768S_20251028_010125	T0870234101768S
TA-New York	T0870352704325N_20251028_115850	T0870352704325N
TA-New York	T0870172801631S_20251028_214828	T0870172801631S
TA-New York	T0870432503527S_20251029_124259	T0870432503527S
TA-New York	T2870100600955W_20251029_223608	T2870100600955W
TA-New York	T0870246202861N_20251101_100008	T0870246202861N
TA-New York	T0870234101768S_20251103_225832	T0870234101768S
TA-New York	T0870176802341N_20251107_000221	T0870176802341N
TA-New York	T0950120701442N_20251107_003349	T0950120701442N
TA-New York	T0950120701442N_20251107_021241	T0950120701442N
TA-New York	T0870592306646N_20251110_075447	T0870592306646N
TA-New York	T0870592306646N_20251111_082554	T0870592306646N
TA-New York	T0870592306646N_20251112_080142	T0870592306646N
TA-New York	T0870592306646N_20251113_075150	T0870592306646N
TA-New York	T0870592306646N_20251113_080349	T0870592306646N
TA-New York	T0870176802341N_20251114_012535	T0870176802341N
TA-New York	T0870664605923S_20251120_221519	T0870664605923S

Region/Division	Deployment ID	Location Code
TA-New York	T2870034500573E_20251202_011341	T2870034500573E
TA-New York	T2870034500573E_20251203_001415	T2870034500573E
TA-New York	T2870057300955E_20251204_004033	T2870057300955E
TA-New York	T2870057300955E_20251204_221218	T2870057300955E
TA-New York	T0950042800717N_20251209_002319	T0950042800717N
TA-New York	T0950042800717N_20251209_234424	T0950042800717N
TA-New York	T0950071700428S_20251211_001832	T0950071700428S
TA-New York	T0950071700428S_20251211_235608	T0950071700428S
TA-New York	T2870057300345W_20251215_223530	T2870057300345W
TA-New York	T2870057300345W_20251217_222647	T2870057300345W
TA-Syracuse	T0902872228853W_20240415_125311	T0902872228853W
TA-Syracuse	T0902764427317E_20240415_225921	T0902764427317E
TA-Syracuse	T0902872228853W_20240416_084122	T0902872228853W
TA-Syracuse	T0902872228853W_20240416_110137	T0902872228853W
TA-Syracuse	T0902731727644W_20240416_212041	T0902731727644W
TA-Syracuse	T0902872228853W_20240417_100855	T0902872228853W
TA-Syracuse	T0902731727644W_20240417_193517	T0902731727644W
TA-Syracuse	T0902885329550W_20240418_110231	T0902885329550W
TA-Syracuse	T0902955028853E_20240419_095048	T0902955028853E
TA-Syracuse	T0902955028853E_20240422_100752	T0902955028853E
TA-Syracuse	T0902955028853E_20240423_081345	T0902955028853E
TA-Syracuse	T0902955028853E_20240424_080117	T0902955028853E
TA-Syracuse	T0902955028853E_20240425_075615	T0902955028853E
TA-Syracuse	T0902955028853E_20240425_084920	T0902955028853E
TA-Syracuse	T0902310022327E_20240429_092205	T0902310022327E
TA-Syracuse	T0902310022327E_20240430_085916	T0902310022327E
TA-Syracuse	T0902310022327E_20240501_075224	T0902310022327E
TA-Syracuse	T0902731727644W_20240501_115427	T0902731727644W
TA-Syracuse	T0902310022327E_20240502_082243	T0902310022327E
TA-Syracuse	T0902731727644W_20240502_085751	T0902731727644W
TA-Syracuse	T0902310022327E_20240503_080122	T0902310022327E
TA-Syracuse	T0902731727644W_20240503_083918	T0902731727644W
TA-Syracuse	T0902310022327E_20240506_081709	T0902310022327E
TA-Syracuse	T0902731727644W_20240506_085034	T0902731727644W
TA-Syracuse	T0902731727644W_20240507_080605	T0902731727644W
TA-Syracuse	T0902310022327E_20240507_083306	T0902310022327E
TA-Syracuse	T0902731727644W_20240508_105139	T0902731727644W
TA-Syracuse	T0902310022327E_20240508_105704	T0902310022327E
TA-Syracuse	T0902310022327E_20240509_083322	T0902310022327E
TA-Syracuse	T0902731727644W_20240509_084743	T0902731727644W
TA-Syracuse	T0902310022327E_20240510_074548	T0902310022327E
TA-Syracuse	T0902232723100W_20240513_105836	T0902232723100W
TA-Syracuse	T0902232723100W_20240514_093514	T0902232723100W

Region/Division	Deployment ID	Location Code
TA-Syracuse	T0903205731329E_20240515_092602	T0903205731329E
TA-Syracuse	T0902803127644E_20240516_092749	T0902803127644E
TA-Syracuse	T0902310022327E_20240516_101329	T0902310022327E
TA-Syracuse	T0902232723100W_20240517_082835	T0902232723100W
TA-Syracuse	T0902731727644W_20240517_090031	T0902731727644W
TA-Syracuse	T0902310022327E_20240520_083226	T0902310022327E
TA-Syracuse	T0902885329550W_20240520_123202	T0902885329550W
TA-Syracuse	T0902885329550W_20240520_124919	T0902885329550W
TA-Syracuse	T0901982620637W_20240521_094452	T0901982620637W
TA-Syracuse	T0902374623450E_20240521_110040	T0902374623450E
TA-Syracuse	T0901982620637W_20240522_084729	T0901982620637W
TA-Syracuse	T0902345023746W_20240522_113328	T0902345023746W
TA-Syracuse	T0902128320637E_20240529_101238	T0902128320637E
TA-Syracuse	T0902872228031E_20240529_104830	T0902872228031E
TA-Syracuse	T0901982620637W_20240530_085707	T0901982620637W
TA-Syracuse	T0902232723100W_20240603_082530	T0902232723100W
TA-Syracuse	T0902063721283W_20240604_095859	T0902063721283W
TA-Syracuse	T0902612626280W_20240605_072856	T0902612626280W
TA-Syracuse	T0902158321932W_20240605_083337	T0902158321932W
TA-Syracuse	T0902232723100W_20240606_074325	T0902232723100W
TA-Syracuse	T0902872228031E_20240606_103239	T0902872228031E
TA-Syracuse	T0902232723100W_20240607_082842	T0902232723100W
TA-Syracuse	T0902955028853E_20240607_091819	T0902955028853E
TA-Syracuse	T0902128320637E_20240610_083737	T0902128320637E
TA-Syracuse	T0902872228031E_20240610_095142	T0902872228031E
TA-Syracuse	T0902128320637E_20240611_080713	T0902128320637E
TA-Syracuse	T0902872228031E_20240611_103808	T0902872228031E
TA-Syracuse	T0902063719826E_20240612_073959	T0902063719826E
TA-Syracuse	T0902872228031E_20240612_092923	T0902872228031E
TA-Syracuse	T0902872228031E_20240613_095939	T0902872228031E
TA-Syracuse	T0902872228031E_20240613_100114	T0902872228031E
TA-Syracuse	T0902872228031E_20240613_123426	T0902872228031E
TA-Syracuse	T0902872228031E_20240613_131624	T0902872228031E
TA-Syracuse	T0902803128722W_20240618_092558	T0902803128722W
TA-Syracuse	T0901982620637W_20240618_101109	T0901982620637W
TA-Syracuse	T0902063721283W_20240619_084000	T0902063721283W
TA-Syracuse	T0902885328722E_20240621_081122	T0902885328722E
TA-Syracuse	T0902764427317E_20240621_100015	T0902764427317E
TA-Syracuse	T0902128320637E_20240624_112347	T0902128320637E
TA-Syracuse	T0902803128722W_20240625_093538	T0902803128722W
TA-Syracuse	T0902128320637E_20240625_101318	T0902128320637E
TA-Syracuse	T0902731727644W_20240626_084907	T0902731727644W
TA-Syracuse	T0902063719826E_20240626_110714	T0902063719826E

Region/Division	Deployment ID	Location Code
TA-Syracuse	T0902731727644W_20240627_093306	T0902731727644W
TA-Syracuse	T0902731727644W_20240628_082054	T0902731727644W
TA-Syracuse	T0902310022327E_20240715_104358	T0902310022327E
TA-Syracuse	T0902310022327E_20240716_073505	T0902310022327E
TA-Syracuse	T0902955028853E_20240716_121704	T0902955028853E
TA-Syracuse	T0902310022327E_20240716_135909	T0902310022327E
TA-Syracuse	T0902310022327E_20240717_083947	T0902310022327E
TA-Syracuse	T0902310022327E_20240717_133135	T0902310022327E
TA-Syracuse	T0902310022327E_20240717_135633	T0902310022327E
TA-Syracuse	T0902310022327E_20240718_073923	T0902310022327E
TA-Syracuse	T0902310022327E_20240718_081544	T0902310022327E
TA-Syracuse	T0902310022327E_20240718_102204	T0902310022327E
TA-Syracuse	T0902310022327E_20240718_113801	T0902310022327E
TA-Syracuse	T0902310022327E_20240719_082635	T0902310022327E
TA-Syracuse	T0902885329550W_20240719_102345	T0902885329550W
TA-Syracuse	T0902158321932W_20240722_094858	T0902158321932W
TA-Syracuse	T0902955028853E_20240722_110257	T0902955028853E
TA-Syracuse	T0902310022327E_20240723_074718	T0902310022327E
TA-Syracuse	T0902955028853E_20240723_112406	T0902955028853E
TA-Syracuse	T0902310022327E_20240724_072827	T0902310022327E
TA-Syracuse	T0902955028853E_20240724_210017	T0902955028853E
TA-Syracuse	T0902310022327E_20240725_073854	T0902310022327E
TA-Syracuse	T0902885329550W_20240725_220629	T0902885329550W
TA-Syracuse	T0902310022327E_20240726_075019	T0902310022327E
TA-Syracuse	T0902885329550W_20240726_214011	T0902885329550W
TA-Syracuse	T0902310022327E_20240729_073112	T0902310022327E
TA-Syracuse	T0902232723100W_20240729_110552	T0902232723100W
TA-Syracuse	T0902310022327E_20240730_072055	T0902310022327E
TA-Syracuse	T0902885329550W_20240730_200437	T0902885329550W
TA-Syracuse	T0902310022327E_20240731_083055	T0902310022327E
TA-Syracuse	T0902955028853E_20240731_211223	T0902955028853E
TA-Syracuse	T0902310022327E_20240801_072959	T0902310022327E
TA-Syracuse	T0902885329550W_20240801_211407	T0902885329550W
TA-Syracuse	T0902310022327E_20240802_073124	T0902310022327E
TA-Syracuse	T0902955028853E_20240802_215648	T0902955028853E
TA-Syracuse	T0902200522327W_20240805_092214	T0902200522327W
TA-Syracuse	T0902731727644W_20240805_210155	T0902731727644W
TA-Syracuse	T0902310022327E_20240806_082316	T0902310022327E
TA-Syracuse	T0902731727644W_20240806_202659	T0902731727644W
TA-Syracuse	T0902310022327E_20240807_081754	T0902310022327E
TA-Syracuse	T0902731727644W_20240807_205227	T0902731727644W
TA-Syracuse	T0902310022327E_20240808_075913	T0902310022327E
TA-Syracuse	T0902310022327E_20240812_074623	T0902310022327E

Region/Division	Deployment ID	Location Code
TA-Syracuse	T0902232723100W_20240812_080102	T0902232723100W
TA-Syracuse	T0902232723100W_20240813_074616	T0902232723100W
TA-Syracuse	T0902310022327E_20240813_075527	T0902310022327E
TA-Syracuse	T0902232723100W_20240815_074438	T0902232723100W
TA-Syracuse	T0902310022327E_20240815_080020	T0902310022327E
TA-Syracuse	T0902232723100W_20240816_073725	T0902232723100W
TA-Syracuse	T0902310022327E_20240816_090432	T0902310022327E
TA-Syracuse	T0902310022327E_20240816_092003	T0902310022327E
TA-Syracuse	T0902232723100W_20240819_071700	T0902232723100W
TA-Syracuse	T0902310022327E_20240819_091740	T0902310022327E
TA-Syracuse	T0902232723100W_20240820_074649	T0902232723100W
TA-Syracuse	T0902232722005E_20240820_092632	T0902232722005E
TA-Syracuse	T0903261733502W_20240821_080028	T0903261733502W
TA-Syracuse	T0902232723100W_20240822_071930	T0902232723100W
TA-Syracuse	T0903261733502W_20240822_081422	T0903261733502W
TA-Syracuse	T0903261733502W_20240823_071659	T0903261733502W
TA-Syracuse	T0902232723100W_20240823_073208	T0902232723100W
TA-Syracuse	T0903261733502W_20240823_073636	T0903261733502W
TA-Syracuse	T0902232723100W_20240823_080551	T0902232723100W
TA-Syracuse	T0903261733502W_20240826_072011	T0903261733502W
TA-Syracuse	T0902345023100E_20240826_085912	T0902345023100E
TA-Syracuse	T0902063719826E_20240827_092737	T0902063719826E
TA-Syracuse	T0902158321932W_20240827_094941	T0902158321932W
TA-Syracuse	T0902158321932W_20240828_091704	T0902158321932W
TA-Syracuse	T0902232723100W_20240828_103219	T0902232723100W
TA-Syracuse	T0902232723100W_20240829_074025	T0902232723100W
TA-Syracuse	T0902310022327E_20240829_075231	T0902310022327E
TA-Syracuse	T0902310022327E_20240830_073945	T0902310022327E
TA-Syracuse	T0902232723100W_20240830_074733	T0902232723100W
TA-Syracuse	T0902232723100W_20240903_090323	T0902232723100W
TA-Syracuse	T0902232722005E_20240903_112103	T0902232722005E
TA-Syracuse	T0902232722005E_20240904_084640	T0902232722005E
TA-Syracuse	T0902803127644E_20240904_191657	T0902803127644E
TA-Syracuse	T0902128320637E_20240905_090230	T0902128320637E
TA-Syracuse	T0902803127644E_20240905_193055	T0902803127644E
TA-Syracuse	T0902310022327E_20240906_073319	T0902310022327E
TA-Syracuse	T0902764428031W_20240906_192245	T0902764428031W
TA-Syracuse	T0902764427317E_20240909_090518	T0902764427317E
TA-Syracuse	T0902128320637E_20240909_091259	T0902128320637E
TA-Syracuse	T0902764427317E_20240910_075157	T0902764427317E
TA-Syracuse	T0903205731329E_20240910_101221	T0903205731329E
TA-Syracuse	T0902232723100W_20240911_074004	T0902232723100W
TA-Syracuse	T0902310022327E_20240911_082758	T0902310022327E

Region/Division	Deployment ID	Location Code
TA-Syracuse	T0902232723100W_20240911_090651	T0902232723100W
TA-Syracuse	T0902232723100W_20240913_071453	T0902232723100W
TA-Syracuse	T0902310022327E_20240913_074429	T0902310022327E
TA-Syracuse	T0902232723100W_20240916_072315	T0902232723100W
TA-Syracuse	T0902232722005E_20240916_090826	T0902232722005E
TA-Syracuse	T0902232723100W_20240917_073548	T0902232723100W
TA-Syracuse	T0902200521932E_20240917_095120	T0902200521932E
TA-Syracuse	T0902232723100W_20240918_072546	T0902232723100W
TA-Syracuse	T0902193222005W_20240918_093952	T0902193222005W
TA-Syracuse	T0902232723100W_20240919_073207	T0902232723100W
TA-Syracuse	T0902310022327E_20240919_102915	T0902310022327E
TA-Syracuse	T0902310022327E_20240920_074616	T0902310022327E
TA-Syracuse	T0902232723100W_20240920_080101	T0902232723100W
TA-Syracuse	T0902200522327W_20240923_085921	T0902200522327W
TA-Syracuse	T0902885329550W_20240923_225444	T0902885329550W
TA-Syracuse	T0902310022327E_20240924_073318	T0902310022327E
TA-Syracuse	T0902232723100W_20240924_085529	T0902232723100W
TA-Syracuse	T0902310022327E_20240925_075047	T0902310022327E
TA-Syracuse	T0902310022327E_20240925_085629	T0902310022327E
TA-Syracuse	T0902193221583E_20240925_090417	T0902193221583E
TA-Syracuse	T0902232723100W_20240926_072802	T0902232723100W
TA-Syracuse	T0902310022327E_20240926_075740	T0902310022327E
TA-Syracuse	T0902310022327E_20240927_074639	T0902310022327E
TA-Syracuse	T0902232723100W_20240927_074735	T0902232723100W
TA-Syracuse	T0902232723100W_20240927_111411	T0902232723100W
TA-Syracuse	T0902310022327E_20240930_091125	T0902310022327E
TA-Syracuse	T0902310023450W_20240930_100707	T0902310023450W
TA-Syracuse	T0902310022327E_20241001_073810	T0902310022327E
TA-Syracuse	T0902310023450W_20241001_103325	T0902310023450W
TA-Syracuse	T0902232723100W_20241002_083336	T0902232723100W
TA-Syracuse	T0902422023746E_20241002_085158	T0902422023746E
TA-Syracuse	T0902422023746E_20241002_120952	T0902422023746E
TA-Syracuse	T0902232723100W_20241003_071901	T0902232723100W
TA-Syracuse	T0902310022327E_20241003_075107	T0902310022327E
TA-Syracuse	T0902310022327E_20241004_071118	T0902310022327E
TA-Syracuse	T0902232723100W_20241004_072859	T0902232723100W
TA-Syracuse	T0902310022327E_20241004_100415	T0902310022327E
TA-Syracuse	T0902310022327E_20241004_110507	T0902310022327E
TA-Syracuse	T0902232723100W_20241007_080004	T0902232723100W
TA-Syracuse	T0902345023100E_20241007_093307	T0902345023100E
TA-Syracuse	T0902232723100W_20241008_074527	T0902232723100W
TA-Syracuse	T0902232722005E_20241008_084443	T0902232722005E
TA-Syracuse	T0902232723100W_20241009_073558	T0902232723100W

Region/Division	Deployment ID	Location Code
TA-Syracuse	T0902128320637E_20241010_090559	T0902128320637E
TA-Syracuse	T0902310022327E_20241011_073856	T0902310022327E
TA-Syracuse	T0902232723100W_20241011_075918	T0902232723100W
TA-Syracuse	T0902310022327E_20241016_075700	T0902310022327E
TA-Syracuse	T0902232723100W_20241016_075825	T0902232723100W
TA-Syracuse	T0902310022327E_20241017_075903	T0902310022327E
TA-Syracuse	T0902232723100W_20241017_083402	T0902232723100W
TA-Syracuse	T0902310022327E_20241018_074329	T0902310022327E
TA-Syracuse	T0902232723100W_20241018_074912	T0902232723100W
TA-Syracuse	T0902310022327E_20241021_074421	T0902310022327E
TA-Syracuse	T0903061130065E_20241021_093930	T0903061130065E
TA-Syracuse	T0902310022327E_20241021_111516	T0902310022327E
TA-Syracuse	T0902310022327E_20241022_074116	T0902310022327E
TA-Syracuse	T0902232723100W_20241022_075207	T0902232723100W
TA-Syracuse	T0902310022327E_20241023_075346	T0902310022327E
TA-Syracuse	T0903061130065E_20241023_090910	T0903061130065E
TA-Syracuse	T0902310022327E_20241024_073953	T0902310022327E
TA-Syracuse	T0902232723100W_20241024_081144	T0902232723100W
TA-Syracuse	T0902232723100W_20241025_073829	T0902232723100W
TA-Syracuse	T0902310022327E_20241025_075406	T0902310022327E
TA-Syracuse	T0902955028853E_20241028_091610	T0902955028853E
TA-Syracuse	T0902885329550W_20241028_092014	T0902885329550W
TA-Syracuse	T0901975419826W_20241029_112348	T0901975419826W
TA-Syracuse	T0902955028853E_20241030_075450	T0902955028853E
TA-Syracuse	T0902885329550W_20241030_080118	T0902885329550W
TA-Syracuse	T0902955028853E_20241030_110127	T0902955028853E
TA-Syracuse	T0902955028853E_20241031_075640	T0902955028853E
TA-Syracuse	T0902885329550W_20241031_080041	T0902885329550W
TA-Syracuse	T0902955028853E_20241031_080520	T0902955028853E
TA-Syracuse	T0902885329550W_20241101_073858	T0902885329550W
TA-Syracuse	T0902955028853E_20241101_080556	T0902955028853E
TA-Syracuse	T0902885329550W_20241104_075623	T0902885329550W
TA-Syracuse	T0902128320637E_20241104_092610	T0902128320637E
TA-Syracuse	T0902955028853E_20241105_073201	T0902955028853E
TA-Syracuse	T0902885329550W_20241105_074729	T0902885329550W
TA-Syracuse	T0902885329550W_20241106_075027	T0902885329550W
TA-Syracuse	T0902885329550W_20241107_074828	T0902885329550W
TA-Syracuse	T0902955028853E_20241107_075059	T0902955028853E
TA-Syracuse	T0902885329550W_20241107_123212	T0902885329550W
TA-Syracuse	T0902955028853E_20241108_073421	T0902955028853E
TA-Syracuse	T0902885329550W_20241108_074435	T0902885329550W
TA-Syracuse	T0902955028853E_20241112_073206	T0902955028853E
TA-Syracuse	T0902764427317E_20241112_095626	T0902764427317E

Region/Division	Deployment ID	Location Code
TA-Syracuse	T0902955028853E_20241113_072808	T0902955028853E
TA-Syracuse	T0902731727644W_20241113_095538	T0902731727644W
TA-Syracuse	T0902955028853E_20241114_075320	T0902955028853E
TA-Syracuse	T0902885329550W_20241114_080830	T0902885329550W
TA-Syracuse	T0902955028853E_20241115_071536	T0902955028853E
TA-Syracuse	T0902885329550W_20241115_074412	T0902885329550W
TA-Syracuse	T0902955028853E_20241119_062217	T0902955028853E
TA-Syracuse	T0902885329550W_20241119_065445	T0902885329550W
TA-Syracuse	T0902955028853E_20241119_084945	T0902955028853E
TA-Syracuse	T0902885329550W_20241120_071552	T0902885329550W
TA-Syracuse	T0902955028853E_20241120_072531	T0902955028853E
TA-Syracuse	T0903534234731E_20241120_093535	T0903534234731E
TA-Syracuse	T0902955028853E_20250331_185241	T0902955028853E
TA-Syracuse	T0902646027317W_20250401_093609	T0902646027317W
TA-Syracuse	T0902885329550W_20250401_185925	T0902885329550W
TA-Syracuse	T0902885329550W_20250401_214752	T0902885329550W
TA-Syracuse	T0902803127644E_20250402_100448	T0902803127644E
TA-Syracuse	T0902200521932E_20250411_084509	T0902200521932E
TA-Syracuse	T0902200521932E_20250414_081126	T0902200521932E
TA-Syracuse	T0902200521932E_20250414_110628	T0902200521932E
TA-Syracuse	T0903534234731E_20250414_213836	T0903534234731E
TA-Syracuse	T0903534234731E_20250415_014244	T0903534234731E
TA-Syracuse	T0902200521932E_20250415_064625	T0902200521932E
TA-Syracuse	T0903534234731E_20250415_202639	T0903534234731E
TA-Syracuse	T0902193222005W_20250416_075834	T0902193222005W
TA-Syracuse	T0903534234731E_20250416_203210	T0903534234731E
TA-Syracuse	T0902200521932E_20250417_071259	T0902200521932E
TA-Syracuse	T0902200521932E_20250417_111713	T0902200521932E
TA-Syracuse	T0903534234731E_20250417_201226	T0903534234731E
TA-Syracuse	T0902200521932E_20250418_072906	T0902200521932E
TA-Syracuse	T0902200521932E_20250421_072816	T0902200521932E
TA-Syracuse	T0903534234731E_20250421_081613	T0903534234731E
TA-Syracuse	T0903534234731E_20250422_071900	T0903534234731E
TA-Syracuse	T0903534234731E_20250422_075133	T0903534234731E
TA-Syracuse	T0902200521932E_20250422_090658	T0902200521932E
TA-Syracuse	T0902200521932E_20250423_072909	T0902200521932E
TA-Syracuse	T0903534234731E_20250423_073237	T0903534234731E
TA-Syracuse	T0902200521932E_20250424_072934	T0902200521932E
TA-Syracuse	T0903534234731E_20250424_081654	T0903534234731E
TA-Syracuse	T0902193222005W_20250424_104215	T0902193222005W
TA-Syracuse	T0902193222005W_20250425_072853	T0902193222005W
TA-Syracuse	T0903534234731E_20250425_082912	T0903534234731E
TA-Syracuse	T0903534234731E_20250428_070630	T0903534234731E

Region/Division	Deployment ID	Location Code
TA-Syracuse	T0903534234731E_20250428_145000	T0903534234731E
TA-Syracuse	T0903205731329E_20250428_190029	T0903205731329E
TA-Syracuse	T0903205731329E_20250428_210806	T0903205731329E
TA-Syracuse	T0903534234731E_20250429_065443	T0903534234731E
TA-Syracuse	T0903534234731E_20250429_082454	T0903534234731E
TA-Syracuse	T0903205731329E_20250429_210138	T0903205731329E
TA-Syracuse	T0903534234731E_20250430_070540	T0903534234731E
TA-Syracuse	T0903132932057W_20250430_200054	T0903132932057W
TA-Syracuse	T0903534234731E_20250501_064559	T0903534234731E
TA-Syracuse	T0903132932057W_20250501_204924	T0903132932057W
TA-Syracuse	T0903534234731E_20250502_071729	T0903534234731E
TA-Syracuse	T0902200521932E_20250505_071632	T0902200521932E
TA-Syracuse	T0903534234731E_20250505_071657	T0903534234731E
TA-Syracuse	T0902200521932E_20250506_071845	T0902200521932E
TA-Syracuse	T0903534234731E_20250506_074635	T0903534234731E
TA-Syracuse	T0903534234731E_20250507_071342	T0903534234731E
TA-Syracuse	T0902200521932E_20250507_073341	T0902200521932E
TA-Syracuse	T0902200521932E_20250507_074404	T0902200521932E
TA-Syracuse	T0902200521932E_20250508_065804	T0902200521932E
TA-Syracuse	T0903534234731E_20250508_075013	T0903534234731E
TA-Syracuse	T0903534234731E_20250508_132903	T0903534234731E
TA-Syracuse	T0903534234731E_20250509_063444	T0903534234731E
TA-Syracuse	T0903534234731E_20250512_071259	T0903534234731E
TA-Syracuse	T0902200521932E_20250512_073818	T0902200521932E
TA-Syracuse	T0902200521932E_20250513_072319	T0902200521932E
TA-Syracuse	T0903534234731E_20250513_073655	T0903534234731E
TA-Syracuse	T0903534234731E_20250514_064151	T0903534234731E
TA-Syracuse	T0902200521932E_20250514_072212	T0902200521932E
TA-Syracuse	T0902200521932E_20250514_073022	T0902200521932E
TA-Syracuse	T0902200521932E_20250515_071203	T0902200521932E
TA-Syracuse	T0903534234731E_20250515_074556	T0903534234731E
TA-Syracuse	T0902200521932E_20250516_072032	T0902200521932E
TA-Syracuse	T0903534234731E_20250516_082329	T0903534234731E
TA-Syracuse	T0903534234731E_20250519_071537	T0903534234731E
TA-Syracuse	T0902193222005W_20250519_074650	T0902193222005W
TA-Syracuse	T0903534234731E_20250520_071307	T0903534234731E
TA-Syracuse	T0902193222005W_20250520_075719	T0902193222005W
TA-Syracuse	T0903534234731E_20250521_070942	T0903534234731E
TA-Syracuse	T0902193222005W_20250521_080253	T0902193222005W
TA-Syracuse	T0903534234731E_20250522_071516	T0903534234731E
TA-Syracuse	T0902200521932E_20250523_073048	T0902200521932E
TA-Syracuse	T0903534234731E_20250523_092518	T0903534234731E
TA-Syracuse	T0902200521932E_20250523_134843	T0902200521932E

Region/Division	Deployment ID	Location Code
TA-Syracuse	T0902200521932E_20250527_072916	T0902200521932E
TA-Syracuse	T0903534234731E_20250527_073021	T0903534234731E
TA-Syracuse	T0903534234731E_20250527_073937	T0903534234731E
TA-Syracuse	T0903534234731E_20250528_074500	T0903534234731E
TA-Syracuse	T0902200521932E_20250528_095443	T0902200521932E
TA-Syracuse	T0903534234731E_20250529_071156	T0903534234731E
TA-Syracuse	T0902200521932E_20250529_074522	T0902200521932E
TA-Syracuse	T0902200521932E_20250530_071346	T0902200521932E
TA-Syracuse	T0903534234731E_20250530_083739	T0903534234731E
TA-Syracuse	T0903534234731E_20250530_085413	T0903534234731E
TA-Syracuse	T0903534234731E_20250602_070438	T0903534234731E
TA-Syracuse	T0902374624220W_20250602_081101	T0902374624220W
TA-Syracuse	T0903534234731E_20250602_103615	T0903534234731E
TA-Syracuse	T0902374624220W_20250602_140132	T0902374624220W
TA-Syracuse	T0902200521932E_20250603_071521	T0902200521932E
TA-Syracuse	T0902200521932E_20250603_072428	T0902200521932E
TA-Syracuse	T0903534234731E_20250603_073101	T0903534234731E
TA-Syracuse	T0902374624220W_20250604_074944	T0902374624220W
TA-Syracuse	T0903534234731E_20250604_075904	T0903534234731E
TA-Syracuse	T0903534234731E_20250605_071418	T0903534234731E
TA-Syracuse	T0902374624220W_20250605_074536	T0902374624220W
TA-Syracuse	T0903534234731E_20250605_081956	T0903534234731E
TA-Syracuse	T0902374624220W_20250605_114229	T0902374624220W
TA-Syracuse	T0903534234731E_20250606_072256	T0903534234731E
TA-Syracuse	T0902374624220W_20250606_072521	T0902374624220W
TA-Syracuse	T0902374624220W_20250606_095829	T0902374624220W
TA-Syracuse	T0902374624220W_20250609_074239	T0902374624220W
TA-Syracuse	T0902374624220W_20250610_074222	T0902374624220W
TA-Syracuse	T0902374624220W_20250610_080135	T0902374624220W
TA-Syracuse	T0903473134084E_20250611_001707	T0903473134084E
TA-Syracuse	T0902374624220W_20250611_075220	T0902374624220W
TA-Syracuse	T0902374624220W_20250611_125144	T0902374624220W
TA-Syracuse	T0902374624220W_20250611_140049	T0902374624220W
TA-Syracuse	T0902374624220W_20250612_075740	T0902374624220W
TA-Syracuse	T0903534234731E_20250612_075928	T0903534234731E
TA-Syracuse	T0902374624220W_20250613_074817	T0902374624220W
TA-Syracuse	T0903534234731E_20250613_075541	T0903534234731E
TA-Syracuse	T0902374624220W_20250613_090324	T0902374624220W
TA-Syracuse	T0902200521932E_20250616_072635	T0902200521932E
TA-Syracuse	T0903534234731E_20250616_074301	T0903534234731E
TA-Syracuse	T0902200521932E_20250617_063955	T0902200521932E
TA-Syracuse	T0903534234731E_20250617_075022	T0903534234731E
TA-Syracuse	T0902200521932E_20250618_064951	T0902200521932E

Region/Division	Deployment ID	Location Code
TA-Syracuse	T0903534234731E_20250618_073831	T0903534234731E
TA-Syracuse	T0902200521932E_20250619_070215	T0902200521932E
TA-Syracuse	T0903534234731E_20250619_084945	T0903534234731E
TA-Syracuse	T0903534234731E_20250620_071921	T0903534234731E
TA-Syracuse	T0902200521932E_20250620_073504	T0902200521932E
TA-Syracuse	T0903534234731E_20250623_073516	T0903534234731E
TA-Syracuse	T0902374624220W_20250623_092421	T0902374624220W
TA-Syracuse	T0902200521932E_20250624_072325	T0902200521932E
TA-Syracuse	T0903534234731E_20250624_074808	T0903534234731E
TA-Syracuse	T0902200521932E_20250625_062203	T0902200521932E
TA-Syracuse	T0903534234731E_20250625_073952	T0903534234731E
TA-Syracuse	T0902200521932E_20250626_065528	T0902200521932E
TA-Syracuse	T0903534234731E_20250626_075230	T0903534234731E
TA-Syracuse	T0902200521932E_20250627_070506	T0902200521932E
TA-Syracuse	T0903534234731E_20250627_090421	T0903534234731E
TA-Syracuse	T0902200521932E_20250630_070145	T0902200521932E
TA-Syracuse	T0903534234731E_20250630_072945	T0903534234731E
TA-Syracuse	T0902200521932E_20250630_105513	T0902200521932E
TA-Syracuse	T0902200521932E_20250701_065340	T0902200521932E
TA-Syracuse	T0903534234731E_20250701_073600	T0903534234731E
TA-Syracuse	T0902200521932E_20250702_070631	T0902200521932E
TA-Syracuse	T0903534234731E_20250702_073030	T0903534234731E
TA-Syracuse	T0902200521932E_20250703_065108	T0902200521932E
TA-Syracuse	T0902200521932E_20250707_065517	T0902200521932E
TA-Syracuse	T0903534234731E_20250708_005436	T0903534234731E
TA-Syracuse	T0902200521932E_20250708_070416	T0902200521932E
TA-Syracuse	T0902200521932E_20250708_133252	T0902200521932E
TA-Syracuse	T0903534234731E_20250709_001522	T0903534234731E
TA-Syracuse	T0902200521932E_20250709_070256	T0902200521932E
TA-Syracuse	T0903534234731E_20250710_002528	T0903534234731E
TA-Syracuse	T0902200521932E_20250710_062707	T0902200521932E
TA-Syracuse	T0903534234731E_20250710_225538	T0903534234731E
TA-Syracuse	T0902200521932E_20250711_073453	T0902200521932E
TA-Syracuse	T0903534234731E_20250712_000634	T0903534234731E
TA-Syracuse	T0903534234731E_20250712_010432	T0903534234731E
TA-Syracuse	T0902374624220W_20250714_084117	T0902374624220W
TA-Syracuse	T0903534234731E_20250714_224819	T0903534234731E
TA-Syracuse	T0902374624220W_20250715_082320	T0902374624220W
TA-Syracuse	T0903534234731E_20250716_005734	T0903534234731E
TA-Syracuse	T0902374624220W_20250716_082153	T0902374624220W
TA-Syracuse	T0902374624220W_20250717_083534	T0902374624220W
TA-Syracuse	T0903534234731E_20250718_000708	T0903534234731E
TA-Syracuse	T0902374624220W_20250718_081639	T0902374624220W

Region/Division	Deployment ID	Location Code
TA-Syracuse	T0903534234731E_20250718_234354	T0903534234731E
TA-Syracuse	T0902374624220W_20250721_075441	T0902374624220W
TA-Syracuse	T0903534234731E_20250721_230611	T0903534234731E
TA-Syracuse	T0903534234731E_20250722_003258	T0903534234731E
TA-Syracuse	T0902374624220W_20250722_075915	T0902374624220W
TA-Syracuse	T0903534234731E_20250722_225919	T0903534234731E
TA-Syracuse	T0902374624220W_20250723_083204	T0902374624220W
TA-Syracuse	T0903534234731E_20250723_084541	T0903534234731E
TA-Syracuse	T0903534234731E_20250723_223134	T0903534234731E
TA-Syracuse	T0903534234731E_20250723_230740	T0903534234731E
TA-Syracuse	T0902374624220W_20250724_080816	T0902374624220W
TA-Syracuse	T0903534234731E_20250724_082324	T0903534234731E
TA-Syracuse	T0903473134084E_20250724_232759	T0903473134084E
TA-Syracuse	T0903473134084E_20250725_010246	T0903473134084E
TA-Syracuse	T0902374624220W_20250725_080354	T0902374624220W
TA-Syracuse	T0903534234731E_20250725_093908	T0903534234731E
TA-Syracuse	T0902374624220W_20250728_080010	T0902374624220W
TA-Syracuse	T0903534234731E_20250728_080438	T0903534234731E
TA-Syracuse	T0903534234731E_20250728_232036	T0903534234731E
TA-Syracuse	T0903534234731E_20250729_075253	T0903534234731E
TA-Syracuse	T0902200521932E_20250729_090320	T0902200521932E
TA-Syracuse	T0903534234731E_20250729_231535	T0903534234731E
TA-Syracuse	T0903534234731E_20250730_074042	T0903534234731E
TA-Syracuse	T0902374624220W_20250730_074338	T0902374624220W
TA-Syracuse	T0903534234731E_20250730_074629	T0903534234731E
TA-Syracuse	T0903534234731E_20250730_233303	T0903534234731E
TA-Syracuse	T0902374624220W_20250731_071810	T0902374624220W
TA-Syracuse	T0903534234731E_20250731_090320	T0903534234731E
TA-Syracuse	T0903473134084E_20250731_231858	T0903473134084E
TA-Syracuse	T0902374624220W_20250801_080730	T0902374624220W
TA-Syracuse	T0903534234731E_20250801_081535	T0903534234731E
TA-Syracuse	T0902374624220W_20250804_081024	T0902374624220W
TA-Syracuse	T0903534234731E_20250804_235527	T0903534234731E
TA-Syracuse	T0902374624220W_20250805_075712	T0902374624220W
TA-Syracuse	T0903534234731E_20250805_232744	T0903534234731E
TA-Syracuse	T0902374624220W_20250806_075545	T0902374624220W
TA-Syracuse	T0903534234731E_20250806_225943	T0903534234731E
TA-Syracuse	T0902374624220W_20250807_075258	T0902374624220W
TA-Syracuse	T0903534234731E_20250807_231233	T0903534234731E
TA-Syracuse	T0902374624220W_20250808_080140	T0902374624220W
TA-Syracuse	T0902374624220W_20250811_081408	T0902374624220W
TA-Syracuse	T0903534234731E_20250811_223759	T0903534234731E
TA-Syracuse	T0902374624220W_20250812_074724	T0902374624220W

Region/Division	Deployment ID	Location Code
TA-Syracuse	T0902764428031W_20250812_200747	T0902764428031W
TA-Syracuse	T0903534234731E_20250812_223515	T0903534234731E
TA-Syracuse	T0902374624220W_20250813_075900	T0902374624220W
TA-Syracuse	T0902764428031W_20250813_194712	T0902764428031W
TA-Syracuse	T0903534234731E_20250813_222454	T0903534234731E
TA-Syracuse	T0902374624220W_20250814_075742	T0902374624220W
TA-Syracuse	T0902374624220W_20250814_104356	T0902374624220W
TA-Syracuse	T0902764428031W_20250814_204927	T0902764428031W
TA-Syracuse	T0903534234731E_20250815_002822	T0903534234731E
TA-Syracuse	T0902374624220W_20250815_075730	T0902374624220W
TA-Syracuse	T0902764428031W_20250815_194551	T0902764428031W
TA-Syracuse	T0903534234731E_20250815_231854	T0903534234731E
TA-Syracuse	T0902374624220W_20250818_075533	T0902374624220W
TA-Syracuse	T0903534234731E_20250818_095054	T0903534234731E
TA-Syracuse	T0903534234731E_20250818_234817	T0903534234731E
TA-Syracuse	T0902374624220W_20250819_075820	T0902374624220W
TA-Syracuse	T0902374624220W_20250820_073727	T0902374624220W
TA-Syracuse	T0902374624220W_20250821_081350	T0902374624220W
TA-Syracuse	T0903534234731E_20250821_235932	T0903534234731E
TA-Syracuse	T0902374624220W_20250822_073545	T0902374624220W
TA-Syracuse	T0902374624220W_20250825_075512	T0902374624220W
TA-Syracuse	T0903534234731E_20250825_093853	T0903534234731E
TA-Syracuse	T0902374624220W_20250825_131737	T0902374624220W
TA-Syracuse	T0902374624220W_20250826_085938	T0902374624220W
TA-Syracuse	T0902374624220W_20250827_080410	T0902374624220W
TA-Syracuse	T0903534234731E_20250828_072752	T0903534234731E
TA-Syracuse	T0903534234731E_20250828_073501	T0903534234731E
TA-Syracuse	T0902374624220W_20250828_074803	T0902374624220W
TA-Syracuse	T0902374624220W_20250829_074655	T0902374624220W
TA-Syracuse	T0903534234731E_20250829_075013	T0903534234731E
TA-Syracuse	T0902374624220W_20250829_080027	T0902374624220W
TA-Syracuse	T0903534234731E_20250902_082938	T0903534234731E
TA-Syracuse	T0902374624220W_20250902_083758	T0902374624220W
TA-Syracuse	T0903534234731E_20250902_223100	T0903534234731E
TA-Syracuse	T0902374624220W_20250903_072846	T0902374624220W
TA-Syracuse	T0903534234731E_20250903_074336	T0903534234731E
TA-Syracuse	T0902374624220W_20250904_083917	T0902374624220W
TA-Syracuse	T0903534234731E_20250904_104027	T0903534234731E
TA-Syracuse	T0903534234731E_20250904_224143	T0903534234731E
TA-Syracuse	T0903534234731E_20250905_083722	T0903534234731E
TA-Syracuse	T0902374624220W_20250905_083735	T0902374624220W
TA-Syracuse	T0902374624220W_20250908_080829	T0902374624220W
TA-Syracuse	T0902374624220W_20250908_084903	T0902374624220W

Region/Division	Deployment ID	Location Code
TA-Syracuse	T0902374624220W_20250909_082912	T0902374624220W
TA-Syracuse	T0902374624220W_20250910_080043	T0902374624220W
TA-Syracuse	T0903534234731E_20250910_223246	T0903534234731E
TA-Syracuse	T0902374624220W_20250911_075757	T0902374624220W
TA-Syracuse	T0903534234731E_20250911_223406	T0903534234731E
TA-Syracuse	T0902374624220W_20250912_072934	T0902374624220W
TA-Syracuse	T0902374624220W_20250915_072559	T0902374624220W
TA-Syracuse	T0903534234731E_20250915_231133	T0903534234731E
TA-Syracuse	T0902374624220W_20250916_075748	T0902374624220W
TA-Syracuse	T0903534234731E_20250916_225608	T0903534234731E
TA-Syracuse	T0903534234731E_20250917_013313	T0903534234731E
TA-Syracuse	T0902374624220W_20250917_080150	T0902374624220W
TA-Syracuse	T0902374624220W_20250918_074135	T0902374624220W
TA-Syracuse	T0903534234731E_20250918_224223	T0903534234731E
TA-Syracuse	T0902374624220W_20250919_072511	T0902374624220W
TA-Syracuse	T0903534234731E_20250919_223012	T0903534234731E
TA-Syracuse	T0902374624220W_20250922_075932	T0902374624220W
TA-Syracuse	T0903534234731E_20250923_003122	T0903534234731E
TA-Syracuse	T0902374624220W_20250923_073344	T0902374624220W
TA-Syracuse	T0903534234731E_20250923_235922	T0903534234731E
TA-Syracuse	T0902374624220W_20250924_074032	T0902374624220W
TA-Syracuse	T0903534234731E_20250925_003521	T0903534234731E
TA-Syracuse	T0902374624220W_20250925_074616	T0902374624220W
TA-Syracuse	T0902374624220W_20250925_082116	T0902374624220W
TA-Syracuse	T0902374624220W_20250925_120949	T0902374624220W
TA-Syracuse	T0903534234731E_20250926_011006	T0903534234731E
TA-Syracuse	T0902374624220W_20250926_082622	T0902374624220W
TA-Syracuse	T0903534234731E_20250926_233127	T0903534234731E
TA-Syracuse	T0902374624220W_20250929_080929	T0902374624220W
TA-Syracuse	T0903534234731E_20250929_232619	T0903534234731E
TA-Syracuse	T0903534234731E_20250930_062907	T0903534234731E
TA-Syracuse	T0902374624220W_20250930_075934	T0902374624220W
TA-Syracuse	T0903534234731E_20250930_225734	T0903534234731E
TA-Syracuse	T0902374624220W_20251001_075836	T0902374624220W
TA-Syracuse	T0903534234731E_20251001_230349	T0903534234731E
TA-Syracuse	T0902374624220W_20251002_074620	T0902374624220W
TA-Syracuse	T0903534234731E_20251002_231930	T0903534234731E
TA-Syracuse	T0902374624220W_20251003_084109	T0902374624220W
TA-Syracuse	T0903534234731E_20251006_080730	T0903534234731E
TA-Syracuse	T0902374624220W_20251006_083013	T0902374624220W
TA-Syracuse	T0903534234731E_20251006_230721	T0903534234731E
TA-Syracuse	T0903534234731E_20251007_081146	T0903534234731E
TA-Syracuse	T0902374624220W_20251007_083359	T0902374624220W

Region/Division	Deployment ID	Location Code
TA-Syracuse	T0902374624220W_20251008_084924	T0902374624220W
TA-Syracuse	T0903534234731E_20251008_231533	T0903534234731E
TA-Syracuse	T0903534234731E_20251009_014816	T0903534234731E
TA-Syracuse	T0902374624220W_20251009_075009	T0902374624220W
TA-Syracuse	T0903534234731E_20251009_235511	T0903534234731E
TA-Syracuse	T0902200521932E_20251013_064509	T0902200521932E
TA-Syracuse	T0903534234731E_20251013_230240	T0903534234731E
TA-Syracuse	T0902200521932E_20251014_070541	T0902200521932E
TA-Syracuse	T0903534234731E_20251014_235838	T0903534234731E
TA-Syracuse	T0902200521932E_20251015_063247	T0902200521932E
TA-Syracuse	T0903534234731E_20251015_231105	T0903534234731E
TA-Syracuse	T0902200521932E_20251016_080056	T0902200521932E
TA-Syracuse	T0903534234731E_20251016_233716	T0903534234731E
TA-Syracuse	T0902200521932E_20251017_065954	T0902200521932E
TA-Syracuse	T0903534234731E_20251017_231113	T0903534234731E
TA-Syracuse	T0902200521932E_20251020_071644	T0902200521932E
TA-Syracuse	T0903534234731E_20251021_005024	T0903534234731E
TA-Syracuse	T0903534234731E_20251021_005944	T0903534234731E
TA-Syracuse	T0902200521932E_20251021_063443	T0902200521932E
TA-Syracuse	T0903534234731E_20251021_234131	T0903534234731E
TA-Syracuse	T0902200521932E_20251022_072510	T0902200521932E
TA-Syracuse	T0903534234731E_20251022_105742	T0903534234731E
TA-Syracuse	T0903534234731E_20251022_233209	T0903534234731E
TA-Syracuse	T0903534234731E_20251022_234257	T0903534234731E
TA-Syracuse	T0902200521932E_20251023_071304	T0902200521932E
TA-Syracuse	T0903534234731E_20251023_095052	T0903534234731E
TA-Syracuse	T0903534234731E_20251023_231510	T0903534234731E
TA-Syracuse	T0902200521932E_20251024_065823	T0902200521932E
TA-Syracuse	T0903534234731E_20251024_080122	T0903534234731E
TA-Syracuse	T0903534234731E_20251024_080331	T0903534234731E
TA-Syracuse	T0903534234731E_20251024_080743	T0903534234731E
TA-Syracuse	T0903534234731E_20251024_225905	T0903534234731E
TA-Syracuse	T0902200521932E_20251027_071656	T0902200521932E
TA-Syracuse	T0903534234731E_20251027_085802	T0903534234731E
TA-Syracuse	T0902063721283W_20251027_093529	T0902063721283W
TA-Syracuse	T0902063721283W_20251027_095155	T0902063721283W
TA-Syracuse	T0903534234731E_20251027_230655	T0903534234731E
TA-Syracuse	T0903534234731E_20251028_023730	T0903534234731E
TA-Syracuse	T0902200521932E_20251028_063119	T0902200521932E
TA-Syracuse	T0902345023100E_20251028_084623	T0902345023100E
TA-Syracuse	T0903534234731E_20251028_090526	T0903534234731E
TA-Syracuse	T0903534234731E_20251028_224645	T0903534234731E
TA-Syracuse	T0902200521932E_20251029_065953	T0902200521932E

Region/Division	Deployment ID	Location Code
TA-Syracuse	T0902128320637E_20251029_084639	T0902128320637E
TA-Syracuse	T0903534234731E_20251029_224214	T0903534234731E
TA-Syracuse	T0902200521932E_20251030_072340	T0902200521932E
TA-Syracuse	T0902200521932E_20251031_070641	T0902200521932E
TA-Syracuse	T0902764428031W_20251105_080527	T0902764428031W
TA-Syracuse	T0903534234731E_20251105_083628	T0903534234731E
TA-Syracuse	T0903534234731E_20251106_075324	T0903534234731E
TA-Syracuse	T0903534234731E_20251106_231255	T0903534234731E
TA-Syracuse	T0903534234731E_20251107_053203	T0903534234731E
TA-Syracuse	T0903534234731E_20251107_080457	T0903534234731E
TA-Syracuse	T0903534234731E_20251107_224046	T0903534234731E
TA-Syracuse	T0902158321932W_20251110_091613	T0902158321932W
TA-Syracuse	T0903534234731E_20251110_094345	T0903534234731E
TA-Syracuse	T0903534234731E_20251111_110645	T0903534234731E
TA-Syracuse	T0902128320637E_20251113_091409	T0902128320637E
TA-Syracuse	T0902128320637E_20251118_082947	T0902128320637E
TA-Syracuse	T0903534234731E_20251118_232432	T0903534234731E
TA-Syracuse	T0902128320637E_20251119_083020	T0902128320637E
TA-Syracuse	T0902872228031E_20251119_101254	T0902872228031E

Applied filters:date is on or after 1/1/2024 and is before 1/1/2026